

INS. CASE OWNER:

CC 3/CTI1702

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Email

Call

Repair Cost:

SS

(days) Reduction:

%

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

SS

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

SS

Loss of Rental (LOR):

SS

(2 days) x \$129.28

Loss of Use (LOU):

SS

(\$ 50 x 2 days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

Global Sum SS: 1380.00

Email

Call

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI17022839/K1zb3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 01-12-2017



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 6051D	Veh. Inspected	SHA 8519T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	01/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	29/11/2017	Inspection Date	30/11/2017
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI17022839/K1zb3

Date: 01.12.2017

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.


SHA8519T

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 30.11.2017 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	2,222.38
Revised Estimate Amount	: S\$	950.48
"Check" Items Amount	: S\$	986.20
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
Rear Portion



Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: 2 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

Shu Pei (LKKAUTO)

From: Shu Pei (LKKAUTO)
Sent: Monday, 11 December, 2017 10:46 AM
To: Zayyer (LKKAUTO); Jowyn Tay
Cc: Admin A; Vivian Lau (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving GB36051D (OI : SNM17D06910/C02/1) and SHA8519T (TP : LKK REF - CC3/CTI17022839/K1zb3) on 29.11.2017

WITHOUT PREJUDICE

Dear Jowyn,

We refer to the above matter.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Zayyer (LKKAUTO)
Sent: Tuesday, 5 December, 2017 9:03 AM
To: Jowyn Tay <jowyn.tay@sg.cntaiping.com>; Shu Pei (LKKAUTO) <shupeil@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; Vivian Lau (LKKAUTO) <vivianlau@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving GBB6051D (OI : SNM17D06910/C02/1) and SHA8519T (TP : LKK REF - CC3/CTI17022839/K1zb3) on 29.11.2017

Dear Jowyn,

Noted with thanks.

Best Regards,

Zayyer | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841 2409, email: zayyer@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jowyn Tay [<mailto:jowyn.tay@sg.cntaiping.com>]
Sent: Monday, 4 December, 2017 5:47 PM
To: Shu Pei (LKKAUTO) <shupeil@lkkauto.com>; Zayyer (LKKAUTO) <zayyer@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; Jowyn Tay <jowyn.tay@sg.cntaiping.com>

Subject: RE: Direct Settlement - Accident Involving GBB6051D (OI : SNM17D06910/C02/1) and SHA8519T (TP : LKK REF - CC3/CTI17022839/K1zb3) on 29.11.2017

Importance: High

Dear Zayyer &/or Shu Pei,

Please note that our insured has yet to report the accident and we attached our letter for your immediate attention.

Thank you.

Regards,

Jowyn Tay

Deputy Claims Executive

Motor Division

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6174

Fax: 6224 7175 / 6224 7478

Email: claimsdept@sg.cntaiping.com

jowyn.tay@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAuto) [<mailto:shupeil@lkkauto.com>]

Sent: Friday, 1 December, 2017 3:46 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Joel Goh <joel.goh@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Jowyn Tay <jowyn.tay@sg.cntaiping.com>; Admin A <admin-a@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; Zayyer (LKKAuto) <zayyer@lkkauto.com>

Subject: Direct Settlement - Accident Involving GBB6051D (OI : CAI - TBA) and SHA8519T (TP : LKK REF - CC3/CTI17022839/K1zb3) on 29.11.2017

WITHOUT PREJUDICE

Dear Jowyn,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHA 8519T at M/s ComfortDelGro Engineering Pte Ltd - Loyang.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

Kindly take note that the case handler in-charge is Zayyer and he can be contacted at DID: 6841 2409.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.cntaiping.com
Co. Reg. No. 200208384E

Our Reference: **SNM17D06910/C02/1**

Date: **04 DECEMBER 2017**

via Ordinary & Registered Mail

**YONG WEN FOOD (S) PTE LTD
24 PENJURU ROAD
#05-06 CWT COMMODITY HUB
SINGAPORE 609128**

Dear Sir / Madam

**ACCIDENT INVOLVING GBB6051D AND SHA8519T ON 29 NOVEMBER 2017
ALONG SLIP ROAD FROM DELTA ROAD TOWARDS GANGES AVE**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHA8519T**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will soon contact you for more information about the accident. Kindly render your assistance and co-operation accordingly.

We understand that you or your driver has not filed an accident report within 24 hours as per Motor Claims Framework. We would urge you to comply with the condition to file your accident report with your vehicle (whether damaged or not) to us **IMMEDIATELY** through **LKK Auto Consultants Pte Ltd** or any of our **authorized workshops**. You may log onto our website www.sg.cntaiping.com for location of the respective workshops.

We regret to advice that we and/or **LKK Auto Consultants Pte Ltd** will not be handling the third party claim and your **NO CLAIM DISCOUNT** will be penalized upon renewal of your policy if you fail to comply with the condition of reporting.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC: LKK Auto Consultants Pte Ltd

Attn : ZAYYER
Ref : CC3/CT117022839/K1zb3
Contact No : 6841 2409
via Email : zayyer@lkkauto.com

CC: Agent - (AN0421A) - VITESSE SOLUTIONS

F02/LKKDSANR-2013



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/CTI17022839/K1zb3

12 December 2017

YONG WEN FOOD (S) PTE LTD
24 PENJURU ROAD
#05-06 CWT COMMODITY HUB
SINGAPORE 609128

Dear Sir / Madam,

**ACCIDENT INVOLVING GBB 6051D AND SHA 8519T ON 29 NOVEMBER 2017
ALONG/ AT SLIP ROAD FROM DELTA ROAD TOWARDS GANGES AVE**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** to settle a **THIRD PARTY** claim against you for an accident which happened on the above-mentioned date and location.

Our record shows that to date, you/your driver have not reported the accident to us. We would appreciate it if you could urgently file a report at any of **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** Authorized workshops/reporting centre. You may refer to your Certificate of Insurance for the list of the reporting centre.

Please note you had been notified via post from **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** dated 04 DECEMBER 2017.

To enable us to look into the matter immediately, please let us hear from you within **seven (7)** days from date of this letter (by 19 DECEMBER 2017).

Please be reminded that in accordance with the terms and conditions under your policy, failure of compliance, our principal M/s **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** reserves the right to repudiate liability.

If you need further assistance or clarifications, please contact the undersigned.

Yours faithfully,

Zay Yer
Case Handler
DID: 6841 2409
FAX: 6741 4108
Email: zayyer@lkkauto.com

c.c. *China Taiping Insurance (Singapore) Pte Ltd*
(Motor Claims Dept)

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 3786701

JC NO.305093597

CUSTOMER CITYCAB PTE LTD 7010070 CUSTOMER NO 383 SIN MING DRIVE Singapore SINGAPORE 575717 65551188 (R) (P) (O)	REGN NO	SHA8519T	MILEAGE
	MAKE	HYUNDAI	FUEL E.....1/2.....F
	MODEL	I-40	DATE/TIME IN 30.11.2017 10:44
	YR OF MANU	26.11.2015	TARGET DATE
	CHASSIS CODE	KMHLB41UMGU080681	COMPLETION DATE/TIME:

COUNT CARD NO.

JOB DESCRIPTION

Accident Date: 29.11.2017
NATURE: 3P 29.11.17/B

3/NO	LABOR CODE	DESCRIPTION
------	------------	-------------

ECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

Vehicle No.: SHA8519T

FZ CHINA LKK

Vehicle No.:

SHA8519T

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

China

FZ

CITYCAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 8519T

DATE 11/30/2017 14:34

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper ✓			\$ 603.60	
	Rear Bumper Reinforcement ?			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH)?		\$ 180.00	\$ 360.00	
	Rear Bumper Sponge ?			\$ 143.40	
	Rear Bumper Under Cover ?			\$ 225.00	
	Rear Bumper Clips 10 pcs ✓			\$ 22.00	
	SUB TOTAL			\$ 1,858.35	
	LESS 20%			\$ 371.67	
	DISCOUNTED TOTAL			\$ 1,486.68	
	Rear Bumper Reverse Sensor ✓			\$ 135.70	Nett
	Rear Bumper Rubber Mat ✓			\$ 50.00	Nett
				\$ 185.70	
	Labour Charge				
	Panel Beating			\$ 200.00	200
	Spray Painting Charge			\$ 200.00	180
	Wiring Charge			\$ 30.00	X
	Remove/Refix Reverse Sensor			\$ 120.00	20
	TOTAL LABOUR			\$ 550.00	
	ESTIMATE TOTAL			\$ 2,222.38	
Kaler (KKE) ✓ 30/11/17 1435hrs. 2 Days. PIP Before Paint photo.					
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before after spray painting • To display damaged parts during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary (if any) must be resurveyed and is subject to final approval from Insurance Company					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

FZ

REPAIR ESTIMATE*

DATE 11/30/2017 14:34

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper — <i>Rebrand</i>			\$ 603.60
	Rear Bumper Reinforcement <i>Xsu</i>			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) <i>Xsu</i>		\$ 180.00	\$ 360.00
	Rear Bumper Sponge <i>Xsu</i>			\$ 143.40
	Rear Bumper Under Cover <i>Xsu</i>			\$ 225.00
	Rear Bumper Clips 10 pcs — <i>new</i>			\$ 22.00
	SUB TOTAL			\$ 1,858.35
	LESS 20%			\$ 371.67
	DISCOUNTED TOTAL			\$ 1,486.68
	Rear Bumper Reverse Sensor <i>At an</i>			\$ 135.70
	Rear Bumper Rubber Mat — <i>new</i>			\$ 50.00
				\$ 185.70
	Labour Charge			
	Panel Beating			\$ 200.00 <i>200</i>
	Spray Painting Charge			\$ 200.00 <i>180</i>
	Wiring Charge			\$ 30.00 <i>Xm</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>20</i>
	TOTAL LABOUR			\$ 550.00
	ESTIMATE TOTAL			\$ 2,222.38
	<i>Kalir (Krk)</i>			
	<i>30/11/17 1435hrs.</i>			
	<i>2 Days.</i>			
	<i>P/P</i>			
	<i>Before Paint photo.</i>			
	LKK Auto Consultants hence notify the Repairer of the following: <ul style="list-style-type: none"> To resurvey before and after painting To display damaged parts during resurvey Parts prices are subject to a 10% variation Third party survey is on a "Without prejudice" basis No legal implication of liability Supplementary items must be approved and is subject to final approval from the insurance company 			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 02.12.2017
Time: 08:52:24
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305093597
REGN NO : SHA8519T
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 26.11.2015
DATE/TIME IN : 30.11.2017 10:44
ACCIDENT DATE : 29.11.2017

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	603.60	20.00	482.88
0002	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10	22.00	20.00	17.60
0003	04-01-0103-1150-A	I40VC PROTECTOR MAT	1	50.00	2.00-	50.00

SUB-TOTAL : 550.48

JOB NATURE

0000 L	PANEL BEATING	200.00
0001 L	SPRAY PAINTING CHARGE	180.00
0002 L	REMOVE/REFIX REVERSE SENSOR	20.00

SUB-TOTAL : 400.00

TOTAL : 950.48

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305093597

Date : 02.12.2017

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHA8519T

Date of Accident : 29.11.2017

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA --- GBB6051D
2. The finalized amount shall be:

(a) Spare Parts after List discount	\$550.48
(b) Labour Charges	\$400.00
Total for Part-By-Part Repair Cost	\$950.48
(c.) Lumpsum Repair (if applicable)	20%
Total for Lumpsum repair cost after Less:	\$0.00
Final Lumpsum Repair cost	

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : FAUZY BIN MOKHTAR

Tel : 62148319

Fax : 65468156

Signature : 

Name : Calvin

Date : 4/12/17

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CT117022839/K1zb3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 17-01-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 6051D	Veh. Inspected	SHA 8519T
Policy No.	DMCVSN3066971701	Coverage (\$)	0.00
Claim No.	SNM17D06910/C02/1	Excess (\$)	0.00
Assign From		Assign Date	30/11/2017

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KMHLB41UMGU080681	Colour	YELLOW
Odometer	381831	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	7 mm
L/H Front Tyre	205/60 R16	WEST LAKE	7 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	7 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/11/2017	Inspection Date	30/11/2017
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 8519T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	603.60	603.60
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	504.35	-
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$180.00	SERVICEABLE	360.00	-
1	REAR BUMPER SPONGE	SERVICEABLE	143.40	-
1	REAR BUMPER UNDER COVER	SERVICEABLE	225.00	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-371.67	-125.12
			1,486.68	500.48
SPECIAL NETT ITEMS				
1	REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	135.70	-
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
			185.70	50.00
LABOUR				
	PANEL BEATING.		200.00	200.00
	SPRAY PAINTING CHARGE.		200.00	180.00
	WIRING CHARGE.	NOT NECESSARY	30.00	-
	REMOVE/REFIX REVERSE SENSOR.		120.00	20.00
			550.00	400.00
GRAND TOTAL			2,222.38	950.48
RECOMMENDED COST OF REPAIRS				950.48

Report Ref No. CC3/CT117022839/K1zb3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.