

RECEIVED 7 FEB 2010

PRELIMINARY ADVICE		Date/Time:	Sent By:	Post-Repair Photos:	<input type="checkbox"/>	<input type="checkbox"/>
				Others:	<input type="checkbox"/>	<input type="checkbox"/>
FINALIZATION		Date/Time:	Confirm with:	Confirm by:		
Repair Cost:	SS	( ) days	Reduction:	%	Email <input type="checkbox"/>	Call <input type="checkbox"/>
FINAL SETTLEMENT		Date/Time: 9/2/18	Confirm with Cecilia	Email <input type="checkbox"/>	Call <input type="checkbox"/>	
Total Liability:	%	100 (Agreed/ Assessed)	BOLA S/N No.:	10	If NO or B 28, Ass. Lia:	
Repair Cost:	SS	2996.00				
Loss of Rental (LOR):	SS	485.46 (45 days) x 107.88				
Loss of Use (LOU):	SS	(S x days)				
Loss of Income (LOI):	SS	225.00 (S 50 x 45 days)				
LOR only <input type="checkbox"/>	LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/>	LOR + LOI <input type="checkbox"/>	(Tick only one)		
GIA/LTA Search	SS	5.35				
Medical:	SS					
Disbursement:	SS	(e.g. Tow/ Independent)				
Legal Cost	SS					
Total:	SS	3711.81	Global Sum SS:	3710.00		
FINAL PAYMENT		Date/Time:	Confirm with:	Email <input type="checkbox"/>	Call <input type="checkbox"/>	
Payee 1:	SS	3710.00	Name 1:	COMFORTDELGRD ENGINEERING PTIE LTD		
Payee 2: (Strike if N.A.)	SS		Name 2:			
Payee 3: (Strike if N.A.)	SS		Name 3:			





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG17022846/K1ub3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 01-12-2017



Code : AIG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLT 988C	Veh. Inspected	SHA 7367X
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	01/12/2017

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	29/11/2017	Inspection Date	30/11/2017
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Team: IN    ARC Repair TP(CLSO)1		<b>JOB CARD</b> Sales Order:		JC NO:305093596	
CUSTOMER		REGN NO: SHA7367X		MILEAGE	
/MS COMFORT TRANSPORTATION PTE LTD		MAKE: HYUNDAI		FUEL	
CUSTOMER NO: 7010045		MODEL: SONATA		E: 1/2 F	
ADDRESS: 383 SIN MING DRIVE		30.11.2017 09:50		DATE/TIME IN	
Singapore SINGAPORE 575717		YR OF MANU: 30.12.2011		TARGET DATE	
65508755 (R) (P)		CHASSIS CODE: KMHE141VMB820563		COMPLETION DATE/TIME	
COUNT CARD NO:					

Accident Date: 29.11.2017  
NATURE: 3P 29.11.2017

JOB DESCRIPTION

S/NO	LABOR CODE	DESCRIPTION
		ALA - taxi left front damage
		LKE / Kalvi -

CHECKED & PASSED OUT BY: _____		CUSTOMER'S SIGNATURE _____	
SERVICE ADVISOR			
Acknowledgement Slip		Exit Pass	
Vehicle No: SHA7367X		Vehicle No: SHA7367X	
Signature/Date		Name of Service Advisor	
To be returned to Service Reception upon collection		To be kept by Security Guard	

# COMFORTDELGRO ENGINEERING

Our Job Ref No : 305093596

Date : 04/12/17

ComfortDelGro Engineering Pte Ltd  
59 Layan Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN


Vehicle Reg No. : SHA7367X


Date of Accident: 29.11.2017

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AIG SLT988C
2. The finalized amount shall be:
  - (a) Spare Parts after List discount \_\_\_\_\_
  - (b) Labour Charges \_\_\_\_\_
  - Total for Part-By-Part Repair Cost** \_\_\_\_\_
  - (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: \_\_\_\_\_  
**Final Lumpsum Repair cost** \$2,800.00
3. Estimated normal period for repairs: 3 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : Larry Ng  
Tel : 6214 8316  
Fax : 6546 8156

Signature :   
Name : K. H. L.  
Date : 4/12/17

## For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee	\$5.35			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_

S/No	DESCRIPTION	QTY	ESTIMATE	REMARKS
1	Ball Joint	1	\$84.00	
<b>TOTAL:</b>			<b>\$84.00</b>	

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHA7367X

MAKE : HYUNDAI

MODEL : SONATA

Date : 30.11.2017

AIG

DOA: 29.11.17

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	Front Bumper			\$ 538.80
1	Front Bumper Top Bracket - LH			\$ 22.40
1	Front Bumper Side Bracket - LH			\$ 14.30
1	Front Bumper Protector - LH			\$ 29.20
10	Front Bumper clips		\$2.20	\$ 22.00
1	Headlamp - LH			\$ 797.90
1	Front Fender - LH			\$ 593.00
1	Front Fender Shield - LH			\$ 86.00
1	Front Fender Retainer - LH			\$ 9.20
1	Headlamp Support Panel			\$ 1,023.00
1	Front Wheel Cover - LH			\$ 145.00
1	Front Suspension Lower Arm - LH			\$ 685.20
1	Front Wheel Bearing & Hub - LH			\$ 258.50
1	Front Absorber - LH			\$ 203.70
1	Front Absorber Mounting - LH			\$ 72.00
1	Steering Tie Rod End - LH			\$ 66.50
1	Front Wheel Cover - LH			\$ 145.00

Ball Joint - Best \$84

SUB TOTAL

LESS 20%

DISCOUNTED TOTAL

1 Front Tyre - LH

1 Advertisement - Frt Fender LH

## Labour Charge

1 Panel Beating

1 Spray Painting Charge

1 Wiring Charge

1 Tuff Kote

1 Remove/refit Front Undercarriage

1 Front Wheel Alignment

TOTAL LABOUR

ESTIMATE TOTAL

LKK Auto Consultants hence notify the Repairer of the following:

• To display damaged part to the repairer

• Parts price and labour cost

• Third party insurance policy

• To display damaged part to the repairer

• Parts price and labour cost

• Third party insurance policy

• To display damaged part to the repairer

• Parts price and labour cost

• Third party insurance policy

• To display damaged part to the repairer

• Parts price and labour cost

• Third party insurance policy

• To display damaged part to the repairer

• Parts price and labour cost

• Third party insurance policy

Page 1 of 1

Approved by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

As subject to the insurance policy conditions.

Larry Ng

Kalan (Kalan)

30/11/17 15:55

30/11/17

4/5

After Repair

103.10 207.00 Nett

100.00

\$ 307.00

\$ 600.00 400

\$ 400.00 260

\$ 50.00 20

\$ 80.00 20

\$ 200.00 100

\$ 120.00 60

\$ 1,450.00

\$ 5,526.36

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHA7367X

MAKE : HYUNDAI

MODEL : SONATA

Date : 30.11.2017

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	Front Bumper			\$ 538.80
1	Front Bumper Top Bracket - LH ?			\$ 22.40
1	Front Bumper Side Bracket - LH ?			\$ 14.30
1	Front Bumper Protector - LH x repair			\$ 29.20
10	Front Bumper clips		\$2.20	\$ 22.00
1	Headlamp - LH			\$ 797.90
1	Front Fender - LH			\$ 593.00
1	Front Fender Shield - LH ?			\$ 86.00
1	Front Fender Retainer - LH ?			\$ 9.20
1	Headlamp Support Panel ?			\$ 1,023.00
1	Front Wheel Cover - LH			\$ 145.00
1	Front Suspension Lower Arm - LH ?			\$ 685.20
1	Front Wheel Bearing & Hub - LH ?			\$ 258.50
1	Front Absorber - LH ?			\$ 203.70
1	Front Absorber Mounting - LH ?			\$ 72.00
1	Steering Tie Rod End - LH ?			\$ 66.50
1	Front Wheel Cover - LH X			\$ 145.00

SUB TOTAL

\$ 4,711.70

LESS 20%

942.34

DISCOUNTED TOTAL

\$ 3,769.36

1	Front Tyre - LH X	207.00	Nett
1	Advertisement - Frt Fender LH	100.00	

\$ 307.00

## Labour Charge

1	Panel Beating	
1	Spray Painting Charge	
1	Wiring Charge	
1	Tuff Kote	
1	Remove/refit Front Undercarriage	
1	Front Wheel Alignment	

Kellie Kelly

A 30/11/2017 15:55 hr

3 Pgs

45

After Repair &amp; Lb

\$	600.00	400
\$	400.00	360
\$	50.00	20
\$	80.00	20
\$	200.00	100?
\$	120.00	60

TOTAL LABOUR

\$ 1,450.00

LKK Auto Consultants hence notify the Repairer of the following:

- To ensure bodywork is properly painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

ESTIMATE TOTAL

\$ 5,526.36

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Page 1 of 1  
 Acknowledged by repairer  
 Signature:  
 Date:



S4A-7367X

54A-7267X

DATE	NAME OF DRIVER	MILEAGE READING				MILEAGE TRAVELLED (KM)	HOURS OPERATED (H:M)		DATE
							FROM	TO	
25/11/17	Ken	86	87	12		30	16.55	17.20	
26/11/17	Sunday	90	75			363	0715	1920	
27/11/17	For	93	54			279	0833	181	
		95	97			243	1815	0225	
28/11	For Tues	98	80			283	0715	1930	
29/11/17	For	70	18			309	0856	1942	
30/11/17	Tues. For	70	30			217	0700	1200	
30/11/17	From 30/11/17 Tues to 4/12/17 Monday								
30.11.17	ACCIDENT						0950	-	
04.12.17	REPAIR						1115	-	

Our Ref : T 1117 / SHA7367X /CL(st)  
Your Ref: \_\_\_\_\_  
Date : 5-Jan-18

**AIG ASIA PACIFIC INSURANCE PTE LTD**  
**CHARTIS Building**  
**78 Shenton Way**  
**#07-16**  
**Singapore 079120**

**Attn : Motor Claims Department WITHOUT PREJUDICE**

Dear Sir

**ACCIDENT INVOLVING OUR TAXI SHA7367X YOUR INSURED SLT 988C**  
**AND OTHER \_\_\_\_\_ ON 29.11.17**

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No : SHA7367X which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving SLT 988C we are submitting these claim for your consideration on behalf of the claimants.

#### TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 2,996.00
2	<u>5</u> days Loss of Rental @ \$ 107.88 per day	\$ 539.40
3	Survey Report Fees <i>(Surveyed by M/s LKK)</i>	\$ -
4	GIA / LTA Search Fees	\$ 5.35
5	GIA / Police Report Fees	\$ -
6	Towing / Medical / Transportation	\$ -
<b>Sub Total :</b>		<b>\$ 3,540.75</b>

#### HIRER'S CLAIM

7	<u>5</u> days Loss of Income @ \$ 80.00 per days	\$ 400.00
<b>Total Claims :</b>		<b>\$ 3,940.75</b>

We enclosed herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs : 6 pcs.
- b) LTA search slip/s of : SLT 988C
- c) GIA / Police report/s of : SHA7367X
- d) Letter of authority from owner / hirer / operator
  - ( X ) Photograph/s of Accident Scene ( ) Certificate of Insurance
  - ( ) Witness statement/s ( x ) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

*Cecilia Lee*

Executive

CDGE Claims Department

Tel : 6214 8354 Fax: 6214 1843 Email : [cecilialee@sparkcarcare.com](mailto:cecilialee@sparkcarcare.com)

This is a computer generated letter. No signature is required.

CDGE Taxi Claims Dept  
59 Loyang Drive 4th Flr  
Singapore 508969

ComfortDelGro Engineering Pte Ltd  
205 Braddell Road Singapore 579701

Mainline +65 6383 6280  
Facsimile +65 6280 9755

[www.cdge.com.sg](http://www.cdge.com.sg)

Company Registration No: 109600499V

#### Workshops

**Braddell**  
205 Braddell Road  
Singapore 579701

**Loyang**  
59 Loyang Drive  
Singapore 508969

**Sin Ming**  
383 Sin Ming Drive  
Singapore 575717

**Pandan**  
45 Pandan Road  
Singapore 609286

**Ubi**  
320 Ubi Road 3  
Singapore 408649

**Senoko**  
24 Senoko Loop  
Singapore 758156

**Sungei Kadut**  
7 Sungei Kadut Way  
Singapore 728791

**Yishun**  
501 Yishun Industrial Park A  
Singapore 768732



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG17022846/K1ub3

13 DECEMBER 2017

**CHONG SHU PING AVRIL**

19 PASIR RIS RISE

#11-39

SINGAPORE 518089

Dear Sir/Madam,

**ACCIDENT INVOLVING SLT 988C & SHA 7367X ON 29/11/2017**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING

Case Handler

DID: 6841 2360

FAX: 6741 4108

Email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)

c.c. *AIG Asia Pacific Insurance Pte Ltd*  
*(Motor Claims Dept)*

**LETTER OF AUTHORISATION**

(NAF / PAF)

**ACCIDENT INVOLVING  
ALONG****SONATA SHA7367X , SLT 988C****ON 29-Nov-17 17:25****CLAYMORE HILL X CLAYMORE HILL(IN FRONT SHAW CENTRE)**

I / We

**GOH CHENG CHUAN**(Hirer) NRIC No.: **S0379877A**

and/or

**KOH KAH BOON**(Relief) NRIC No.: **S1289057E**

Taxi Number

**SHA7367X**

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of **"ComfortDelGro Engineering Pte Ltd"**.

Date

**30-Nov-2017**


Name of Hirer

**GOH CHENG CHUAN**

Hirer NRIC

**S0379877A**

Signature :



Address

**32 TELOK BLANGAH RISE #08-257  
090032**

Contact No.

**93204962**

Name of Relief

**KOH KAH BOON**

Relief NRIC

**S1289057E**

Signature :



Address

**113 BUKIT PURMEI ROAD 12-222  
090113**

Contact No.

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, COMFORTDELGRO ENGINEERING PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$3,710.00 (Global Sum) for vehicle no. SHA 7367X that was damaged pursuant to the accident which occurred on 29/11/2017 (date) along CLAYMORE HILL X CLAYMORE HILL (IN FRONT SHAW CENTRE) (location) involving vehicle no/s SLT 988C.

This is pursuant to the inspection conducted on 30/11/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner COMFORT TRANSPORTATION PTE LTD ("the third party claimant") of vehicle no. SHA 7367X make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SHA 7367X (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

- 9 FEB 2018 - 9 FEB 2018

Dated this \_\_\_\_\_ (day) of \_\_\_\_\_ (month) 20\_\_ (year)



Signed by appointed surveyor

CLAIMS DEPARTMENT  
COMFORTDELGRO ENGINEERING PTE LTD  
205 BRADDELL ROAD  
SINGAPORE 579701

Signed by "the workshop" (with chop)

Please forward your cheque made payable to:-  
**COMFORTDELGRO ENGINEERING PTE LTD**

"The contents of this document apply to vehicle damages only.  
All personal injuries and damages arising therefrom are excluded  
from the ambit and application of this document"

GST REG. NO. M2-8921817-3

## TAX INVOICE

8010004

AIG ASIA PACIFIC INSURANCE PTE LTD

#08-16 78 SHENTON WAY, CHARTIS BUILD  
SINGAPORE 079120

CONTACT NO: 64193000 3225094

VEHICLE NO  
SHA7367X

MAKE  
HYUNDAI

MODEL  
SONATA

DATE OF REG  
30.12.2011

CHASSIS CODE  
KMHE41VMB820563

INV. NO/DATE  
91349419 30.12.2017

JOB NO.  
305093596

ODOMETER READING

JOB TYPE

Description : 3P 29.11.2017

### Invoice for Lump Sum Repair

Total Lump Sum Repair Amt	2,800.00
Add GST @ 7.000 %	196.00
<b>Total Invoice amount</b>	<b>2,996.00</b>

Issued by : CHEWHEELING 02.01.2018 16:53:25  
Repair Type : CLSO/57/57  
Payment Type/Term : /Credit 30 days

ComfortDelGro Engineering Pte Ltd  
A member of COMFORTDELGRO

Head Office:  
205 Braddell Road  
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.

Our Ref: CT17111016

Date: 02 January 2018



## TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON	29/11/2017 @ 17:25 hrs
ALONG	CLAYMORE HILL X CLAYMORE HILL (IN FRONT SHAW CENTRE)
INVOLVING	SLT988C

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHA7367X** (the "Taxi"). The Taxi was hired to **GOH CHENG CHUAN IC NO S0379877A** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$107.88** per day (inclusive of GST).

Please be advised that the Taxi was insured with **First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay  
Executive, Fleet Safety

This is a computer generated letter. No signature is required.

**Enquire Vehicle Insurer**

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SLT988C	29 Nov 2017 / 17:25:00	Successful	A04	AIG ASIA PACIFIC INSURANCE PTE. LTD.

[Previous](#)[OK](#)



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Dec 2017 <a href="#">Edit Reg</a>		30 Nov 2017 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$2,800.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,800.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

Insured:	<b>CHONG SHU PING, AVRIL (ZHUANG SHUPING)</b> , ID: S8609377D		
Main Claimant:	<b>COMFORT TRANSPORTATION PTE LTD</b> , Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	<b>SHA7367X</b>	Date of Loss:	29/11/2017 17:00 - :59
Claim Type:	<b>TP / 23564995045G</b>	Policy/Cover Note No.:	1700060190 (Comprehensive) Coverage: 05/10/2017 - 04/10/2018
Vehicle Reg. No. (Insured):	<b>SLT988C</b>	Policy No. (Claimant):	D-1572701MFSH
		Excess:	
Repairer:	<b>ComfortDelGro Engineering Pte Ltd (Loyang)</b> 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Syed-Yusoff, Saliha</b> ] Saliha.Syed-Yusoff@aig.com		
Claimant's Insurer:	<b>MS First Capital Insurance Ltd (HQ)</b> - Tel: 62222311		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KALVIN ANG WEI KUN</b> ] ... [Final Rpt due 12/12/2017]		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SHA7367X (2356499504SG)

[SLT988C]

TP

COMFORT TRANSPORTATION PTE LTD

Nov 29 2017 5:00PM

[CHONG SHU PING, AVRIL (ZHUANG SHUPING)]

ComfortDelGro Engineering Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail			Print		
1	13/12/17 11:14		Video - Accident From:OD - Reg. No: SLT988C, Claimant: CHONG SHU PING, AVRIL (ZHUANG SHUPING)															Load MP4		
Letters/Correspondences															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	(Draft)		Third Party Express Settlement - Payment Breakdown															Edit		
Assessment Reports															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail			Print		
1	04/12/17 12:16		Accident Statement From:OD - Reg. No: SLT988C, Claimant: CHONG SHU PING, AVRIL (ZHUANG SHUPING)															Load HTM		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	01/12/17 17:04		General View															Load JPG <input checked="" type="checkbox"/>		
2	01/12/17 17:04		General View															Load JPG <input checked="" type="checkbox"/>		
3	01/12/17 17:04		General View															Load JPG <input checked="" type="checkbox"/>		
4	01/12/17 17:04		General View															Load JPG <input checked="" type="checkbox"/>		
5	01/12/17 17:04		General View															Load JPG <input checked="" type="checkbox"/>		
6	01/12/17 17:04		General View															Load JPG <input checked="" type="checkbox"/>		
7	01/12/17 17:04		General View															Load JPG <input checked="" type="checkbox"/>		
8	01/12/17 17:04		General View															Load JPG <input checked="" type="checkbox"/>		
9	01/12/17 17:04		General View															Load JPG <input checked="" type="checkbox"/>		
10	01/12/17 17:04		General View															Load JPG <input checked="" type="checkbox"/>		
11	01/12/17 17:04		General View															Load JPG <input checked="" type="checkbox"/>		
12	01/12/17 17:04		General View															Load JPG <input checked="" type="checkbox"/>		
13	01/12/17 17:04		General View															Load JPG <input checked="" type="checkbox"/>		
14	01/12/17 17:04		General View															Load JPG <input checked="" type="checkbox"/>		
15	01/12/17 17:04		General View															Load JPG <input checked="" type="checkbox"/>		
16	01/12/17 17:04		General View															Load JPG <input checked="" type="checkbox"/>		
17	01/12/17 17:04		General View															Load JPG <input checked="" type="checkbox"/>		
18	01/12/17 17:04		General View															Load JPG <input checked="" type="checkbox"/>		
19	01/12/17 17:04		General View															Load JPG <input checked="" type="checkbox"/>		
20	01/12/17 17:04		General View															Load JPG <input checked="" type="checkbox"/>		
21	01/12/17 17:04		General View															Load JPG <input checked="" type="checkbox"/>		
22	01/12/17 17:05		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
23	01/12/17 17:05		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
24	01/12/17 17:05		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		

25	01/12/17 17:05	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
26	01/12/17 17:05	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
27	01/12/17 17:05	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
28	01/12/17 17:05	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
29	01/12/17 17:05	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
30	01/12/17 17:05	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
31	04/12/17 08:20	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
32	04/12/17 08:20	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
33	04/12/17 08:20	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>				1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/12/17 15:28	TP GIA REPORT	1	Load PDF	
2	01/12/17 15:28	TP ESTIMATE- MARKED	1	Load PDF	
3	13/02/18 09:37	WORKSHOP INVOICE	1	Load PDF	
4	13/02/18 09:37	AUTHORISATION TO ACT FORM	1	Load PDF	
5	13/02/18 09:37	WORKSHOP INVOICE	1	Load PDF	
6	13/02/18 09:37	AUTHORISATION TO ACT FORM	1	Load PDF	
7	13/02/18 09:37	Release Voucher	1	Load PDF	
8	13/02/18 09:37	RENTAL RECEIPT	1	Load PDF	
9	13/02/18 09:37	LTA SEARCH	1	Load PDF	
10	13/02/18 09:37	LETTER TO OI	1	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLT988C (Insd veh)	Model:	HYUNDAI SONATA 2.0 (A)
	SHA7367X (TP veh)		
Date of Accident:	29/11/2017		

Global Sum Settlement	:	<input checked="" type="checkbox"/> [ X ] Yes	<input type="checkbox"/> [ ] No
Repair Estimate	:	\$	5,985.11
Final Repair Cost	:	\$	3,710.00
Loss of Use	:	\$	4.50 days at \$50.00 per day
Rental (if any)	:	\$	4.50 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	3,710.00

Is Third Party Workshop GIA Registered? ☒ [ X ] YES ☐ [ ] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: \_\_\_\_\_  
 10  
 BOLA Liability: \_\_\_\_\_ 100 \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)  
 \* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	ComfortDelGro Engineering Pte Ltd	:	\$ 3,710.00
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

13 Feb  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG17022846/K1UB3Q

Date: 13/02/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700060190  
 Claimant Vehicle No: SHA7367X Insured Vehicle No: SLT988C  
 Date of Loss: 29/11/2017 Nature of Claim: TP Claim No: 2356499504SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SHA7367X  
 Make & Model: HYUNDAI SONATA, 2.0 (A) Engine No: D4EAB043683  
 Reg. Date: 30/12/2011 (Man. Year: 2011) Chassis No: KMHET41VMBA820563  
 Colour: Blue Odometer: 870298 km  
 Engine Capacity: 1991 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
 Front Left Side: West Lake 7 mm Rear Left Side: West Lake 7 mm  
 Front Right Side: West Lake 7 mm Rear Right Side: West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,143.56	2,549.42	1,594.14	38.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	960.00	490.00	33.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,593.56</b>	<b>3,509.42</b>	<b>2,084.14</b>	<b>37.26</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,800.00</b>		
(S\$)	5,593.56	2,800.00	2,793.56	49.94
+ GST 7.00/7.00% (S\$)	391.55	196.00	195.55	49.94
<b>Nett Amount (S\$)</b>	<b>5,985.11</b>	<b>2,996.00</b>	<b>2,989.11</b>	<b>49.94</b>
+ Loss of Use (4.5 x S\$50.00/day) (S\$)		225.00		
+ Car Rental (4.5 x S\$107.88/day) (S\$)		485.46		
+ Doc/Search Fee (S\$)		5.35		
<b>Nett Liability (S\$)</b>		<b>3,711.81</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,710.00</b>		

## INSPECTION

Date of Assignment: 30/11/2017

Date Inspected: 30/11/2017 Inspected At: ComfortDelGro Engineering Pte Ltd  
(Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 3.0 days

---

**Adjuster:** KALVIN ANG WEI KUN

**Manager:** THIN THIN HLAING

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	538.80 FL	*538.80 FL
2	1		*FRONT BUMPER TOP BRACKET -LH	Serviceable	22.40 FL	*- FL
3	1		*FRONT BUMPER SIDE BRACKET -LH	Serviceable	14.30 FL	*- FL
4	1		*FRONT BUMPER PROTECTOR -LH	Repair	29.20 FL	*- FL
5	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
6	1		*HEADLAMP LH	Cracked	797.90 FL	*797.90 FL
7	1		*FRONT FENDER -LH	Dented	593.00 FL	*593.00 FL
8	1		*FRONT FENDER SHIELD -LH	Serviceable	86.00 FL	*- FL
9	1		*FRONT FENDER RETAINER -LH	Serviceable	9.20 FL	*- FL
10	1		*HEADLAMP SUPPORT PANEL	Serviceable	1,023.00 FL	*- FL
11	1		*FRONT WHEEL COVER -LH	Grazed	145.00 FL	*145.00 FL
12	1		*FRONT SUSPENSION LOWER ARM -LH	Bent	685.20 FL	*685.20 FL
13	1		*FRONT WHEEL BEARING & HUT-LH	Serviceable	258.50 FL	*- FL
14	1		*FRONT ABSORBER -LH	Serviceable	203.70 FL	*- FL
15	1		*FRONT ABSORBER MOUNTING -LH	Serviceable	72.00 FL	*- FL
16	1		*STEERING TIE ROD END -LH	Bent	66.50 FL	*66.50 FL
17	1		*FRONT WHEEL COVER -LH	Serviceable	145.00 FL	*- FL
18	1		*BALL JOINT	Bent	84.00 FL	*84.00 FL
19	1		*FRONT TYRE -LH (50%)	Cut	207.00 FS	*103.50 FS
20	1		*ADVERTISEMENT -FRT FENDER LH	Necessary	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	5,102.70	3,135.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	959.14	586.48
Total Parts (\$\$)	4,143.56	2,549.42

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	600.00	400.00
2	SPRAY PAINTING CHARGE	New	400.00	360.00
3	WIRING CHARGE	New	50.00	20.00
4	TUFF KOTE	New	80.00	20.00
5	REMOVE/REFIX FRONT UNDERCARRIAGE	New	200.00	100.00
6	FRONT WHEEL ALIGNMENT	New	120.00	60.00
Gross Labour Cost (S\$)			1,450.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >