

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA7367X

MAKE : HYUNDAI

MODEL : SONATA

Date : 30.11.2017

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	Front Bumper ✓			\$ 538.80
1	Front Bumper Top Bracket – LH ?			\$ 22.40
1	Front Bumper Side Bracket – LH ?			\$ 14.30
1	Front Bumper Protector – LH <i>x repair</i>			\$ 29.20
10	Front Bumper clips ✓		\$2.20	\$ 22.00
1	Headlamp – LH ✓			\$ 797.90
1	Front Fender – LH ✓			\$ 593.00
1	Front Fender Shield – LH ?			\$ 86.00
1	Front Fender Retainer – LH ?			\$ 9.20
1	Headlamp Support Panel ?			\$ 1,023.00
1	Front Wheel Cover – LH ✓			\$ 145.00
1	Front Suspension Lower Arm – LH ?			\$ 685.20
1	Front Wheel Bearing & Hub- LH ?			\$ 258.50
1	Front Absorber – LH ?			\$ 203.70
1	Front Absorber Mounting – LH ?			\$ 72.00
1	Steering Tie Rod End – LH ?			\$ 66.50
1	Front Wheel Cover - LH X			\$ 145.00
SUB TOTAL				\$ 4,711.70
LESS 20%				942.34
DISCOUNTED TOTAL				\$ 3,769.36
1	Front Tyre – LH X			207.00
1	Advertisement – Frt Fender LH ✓			100.00
				Nett
				\$ 307.00
Labour Charge				
1	Panel Beating			\$ 600.00 <i>400</i>
1	Spray Painting Charge			\$ 400.00 <i>360</i>
1	Wiring Charge			\$ 50.00 <i>20</i>
1	Tuff Kote			\$ 80.00 <i>20</i>
1	Remove/refix Front Undercarriage			\$ 200.00 <i>100?</i>
1	Front Wheel Alignment			\$ 120.00 <i>60</i>
TOTAL LABOUR				\$ 1,450.00
ESTIMATE TOTAL				\$ 5,266.36

Larry Ng

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Page 1 of 1
Acknowledged by Repairer
Signature:
Date: