

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 04 Dec 2017

Preliminary Advice

Insured Vehicle No : FBC1647M

TP Vehicle No : SGK288X

Accident Date : 28/11/2017

Make : HONDA SHUTTLE

Assignment Date : 01/12/2017

Date of Inspection : 01/12/2017

Est. Duration of Repair : 3.00

Inspection At : COMPLETE VMS PTE LTD (HQ)

176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX
SINGAPORE 575721

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,416.04
Revised Amount	:S\$	1,878.56
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,878.56

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.