

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AIG ASIA PACIFIC INSURANCE PTE LTD	DATE	: 29-Nov-17
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLE 5069B		
MODEL	: HONDA VEZEL 1.5X CVT		
CHASSIS NO	:		
<u>ACCIDENT DETAILS</u>	DATE : 29-Nov-17		
	TIME : 11:50AM		
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BONNET <i>Debed</i>	1	\$ 1,130.00	\$ 1,130.00
2	FRONT BONNET TOP LOCK <i>new</i>	1	\$ 142.00	\$ 142.00
3	FRONT BONNET LOWER CATCH <i>new</i>	1	\$ 89.40	\$ 89.40
4	FRONT BONNET SIDE RUBBER LH <i>new</i>	1	\$ 72.80	\$ 72.80
5	FRONT BONNET HINGE <i>new</i>	2	\$ 63.00	\$ 126.00
6	FRONT BUMPER <i>Debed</i>	1	\$ 760.80	\$ 760.80
7	FRONT BUMPER SIDE RETAINER <i>new LIT</i>	2	\$ 58.00	\$ 116.00
8	FRONT GRILLE <i>new could</i>	1	\$ 588.20	\$ 588.20
9	HID HEADLAMP LH <i>could</i>	1	\$ 1,920.00	\$ 1,920.00
10	HEADLAMP LOWER BRACKET LH <i>could</i>	1	\$ 74.00	\$ 74.00
11	FRONT FENDER LH <i>Disbed</i>	1	\$ 630.00	\$ 630.00
12	FRONT FENDER INNER COWLING LH <i>Debed</i>	1	\$ 168.00	\$ 168.00
13	FRONT WHEEL HOUSE PANEL LH <i>Ryic</i>	1	\$ 1,130.60	\$ 1,130.60
14	WHEEL ARCH LH <i>lit</i>	1	\$ 255.80	\$ 255.80
15	FRONT SIDE MIRROR ASSY LH <i>lit</i>	1	\$ 855.30	\$ 855.30
16	FRONT DOOR LH <i>Ryic</i>	1	\$ 1,255.00	\$ 1,255.00

6147.1
4917.68

TOTAL PRICE \$9,313.90
LESS 20% \$ 1,862.78
SUB TOTAL PRICE \$7,451.12

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
-----	-------------	-----	-------------	--------------

1	FRONT NUMBER PLATE <i>xl n</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
2	FRONT BONNET SIDE RUBBER CLIPS(SET) <i>nn n</i>	1	\$ 15.00	\$ 15.00	<i>+</i>
3	FRONT BUMPER CLIPS(SET) <i>xl</i>	1	\$ 20.00	\$ 20.00	<i>✓</i>
4	FRONT BUMPER GRILLE CLIPS(SET) <i>nn</i>	1	\$ 20.00	\$ 20.00	<i>+</i>
5	HEADLAMP CLIPS(SET) <i>nn</i>	1	\$ 20.00	\$ 20.00	<i>✓</i>
6	FRONT FENDER SEALANT <i>nn n</i>	1	\$ 100.00	\$ 100.00	<i>+</i>
7	FRONT FENDER INNER COWLING CLIPS(SET) <i>nn</i>	1	\$ 20.00	\$ 20.00	<i>✓</i>
8	FRONT WHEEL HOUSE PANEL SEALANT <i>nn n</i>	1	\$ 100.00	\$ 100.00	<i>+</i>
9	WHEEL ARCH CLIP(SET) <i>nn</i>	1	\$ 22.00	\$ 22.00	<i>✓</i>

82

TOTAL

\$367.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,400.00	<i>600</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	<i>880</i>	
3	MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	<i>x</i>	
4	WIRING CHECK	\$ 150.00	<i>30</i>	
5	TO REFOCUS HEADLAMP BEAM	\$ 250.00	<i>x</i>	
6	TO TRANSFER FRONT DOOR MECHNISIM	\$ 150.00	<i>x</i>	

TOTAL

\$3,330.00

1510

ESTIMATE REPORT

TOTAL PARTS COST : \$7,818.12
TOTAL LABOUR COST : \$3,330.00
TOTAL REPAIR COST : \$11,148.12

h/s Admin

total: 6509.68

h/s: 52K.

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

30/11/17.

05 days.

5.21C

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: