

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05677

Vehicle Insured : SGS7776R  
Accident Date : 20-Nov-2017

Date : 30-Nov-2017

Our Ref : 217182 (AXA) / CHAN

PAGE : 1

LIM PUAY HIAN  
53 SUNRISE AVENUE  
#01-17  
Singapore 806748

*Not Authorised*  
*1. B1*  
*Recovery Bk part*

*2 day*

## ESTIMATED COST OF REPAIR FOR AUDI A4 1.4 SFE1973M

1 pc Rear bumper fascia  
1 pc Rear bumper lower spoiler  
1 pc Rear bumper reinforcement  
2 pcs Rear bumper reflector  
2 pcs Rear bumper parking sensor

*Ref/Bk* 1,610.30 ✓  
    *Sm* 176.96 X  
    *R* 659.79 X  
    *Sm* 57.22 X  
@ S\$ 28.61  
@ S\$199.23 398.46 7  
-----  
2,902.73  
Less 10% : 290.27  
-----

2,612.46

To putty and spray replaced parts

350.00 *250*

To remove, cut-out damaged parts,  
panel beating, welding, align,  
refix and to renew above parts

400.00 *250*

To remove & rewire parking sensor  
wire

40.00 ✓

Total : S\$ 3,402.46  
=====

Singapore Dollars Three Thousand Four Hundred  
and Two and Cents Forty Six Only

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: