

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLF 4752 M.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid & rear kid lid auto sensor. Check function.	S/N	\$ 360.00	✓
2	To renew RHS 1/4 glass and rear windscreen to facillitate fender renewal.	S/N	\$ 600.00	✓
3	To remove and transfer rear lid's conveniece lock system, wire harness for tail lights.	S/N	\$ 480.00	✓
4	To remove and reinstall rear seat, back rest, hat tray,abcd pillar trims, luggage compartment trims, seat belt. Dislodge roof liner and disengage curtain airbag etc.	S/N	\$ 1,400.00	✓
SUBTOTAL LABOUR CHARGES		:	<u>\$ 2,840.00</u>	