

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #07-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 01 Dec 2017

**Preliminary Advice**

Vehicle No	: SLT338D	Accident Date	: 22/11/2017
Make	: AUDI A5	Policy No.	: 1700063410
Assignment Date	: 01/12/2017	Excess	: S\$0.00
Date of Inspection	: 01/12/2017	Est. Duration of Repair	: 0.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (HQ) 55 UBI ROAD 1 SINGAPORE 408699		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	197,593.00
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	TOTAL LOSS
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	250,000.00
Pre-Accident Value	:S\$	220,000.00
COE / PARF Rebate	:S\$	90,834.00
Salvage Value	:S\$	
Margin for Repair	:S\$	129,166.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : According to repairer, they expected to have further supplementary.