

60 Woodlands Industrial Park E4 Singapore 757705 Tel: 65 6362 3422 Fax: 65 6368 7420

## **SMRT Vehicle Repair Estimate**

| Group : Buses / <u>Taxis</u> / Commercial                                  |                                       |
|--|---------------------------------------|
| Reg. No. : SHB 5660G   | Ref. No. : TAX/11/17/2181             |
| Make / Model : PRIUS   | Reg. Date : 25-Jan-17                 |
| Chassic No : <u>JTDKN36U705768891</u>                                      | Mileage : 166030 KM                   |
| Name of Driver : LEE TIEN HUAT   | Rental/Replacement Vehicle : Yes / No |
| Date/Time of Accident : 28/11/2017 19:00                                   | The damages on the vehicle are as     |
| Surveyer is Required ? <u>YES</u> / NO NO                                  | indicated in the following diagram :  |
| If Yes, VICOM / LKK / AIS / Others MSIG :                                  | _                                     |
| Vehicle is Towed Back ? YES / NO Date / Time :                             | _                                     |
| Accident reporting date : 29/11/2017                                       | _                                     |
| Type of Accident : Skid / <u>Head-Rear</u> / Head-On / Side Swipe / Others |                                       |
| Special Instruction to ARC, if any :                                       |                                       |
|  |                                       |
|  |                                       |
| Signed :   | Date :                                |
|  |                                       |
| Accident Repair Job Card No : Dat  | te Prepared :                         |
|  | pair Complete :                       |
| Quotation from ARC   | Adjusted by Surveyor, if applicable   |
| Total Labour Charges : \$ 338.0  |                                       |
| Total Spray Painting Charges : \$ 378.0                                    |                                       |
| Total Material Charges : \$ 1,509.4  |                                       |
| Other Charges : \$ 180.0   |                                       |
| TOTAL : \$ 2,405.4   |                                       |
|  | Repair, if any :                      |
| No. of Repair Days : [ 3 ] day   |                                       |
| Signature : Prepared by: PHUA - 30/11/2017 - 10:12.                        | Adjusted by:                          |

| QN No.  | Invoice No.        | Invoice Date           |                   |  |  |  |  |
|---|--------------------|------------------------|-------------------|--|--|--|--|
| Signed :  |                    | Date                   | Date :            |  |  |  |  |
|   |                    |                        | Ref No.:          |  |  |  |  |
|   |                    |                        | Page (2)          |  |  |  |  |
| Part 1 - Labour Works                                 |                    |                        |                   |  |  |  |  |
| Job Scope   |                    | Quotation from ARC     |                   |  |  |  |  |
| O REPAIR REAR PORTION                                 |                    | \$ 338.00              | 200               |  |  |  |  |
| Total Labour  |                    | \$ 338.00              | \$0.00            |  |  |  |  |
|   |                    |                        |                   |  |  |  |  |
| Part 2 - Spray Painting 8                             | & Panel Beating Re | elated Works           |                   |  |  |  |  |
| Job Scope   |                    | Quotation from ARC     |                   |  |  |  |  |
| O REPSRAY REAR BUMPER                                 |                    | \$ 378.00              | 700               |  |  |  |  |
|   |                    |                        |                   |  |  |  |  |
|   |                    |                        |                   |  |  |  |  |
|   |                    |                        |                   |  |  |  |  |
|   |                    | 41                     |                   |  |  |  |  |
|   |                    |                        |                   |  |  |  |  |
|   |                    |                        |                   |  |  |  |  |
|   |                    |                        |                   |  |  |  |  |
|   |                    |                        |                   |  |  |  |  |
| Total Spray Painting & Pane                           | Beating            | \$ 378.00              | \$0.00            |  |  |  |  |
| Total Spray Painting & Panel                          | l Beating          | \$ 378.00              | \$0.00            |  |  |  |  |
| Total Spray Painting & Panel                          | I Beating          | \$ 378.00              | \$0.00            |  |  |  |  |
| Total Spray Painting & Panel                          | I Beating          | \$ 378.00              | \$0.00            |  |  |  |  |
| Total Spray Painting & Panel Part 3 - Other Costs - A |                    |                        |                   |  |  |  |  |
|   |                    |                        |                   |  |  |  |  |
| Part 3 - Other Costs - A                              | ccident and Accide | ent Repair Related Exp | penses Page ( 3 ) |  |  |  |  |

| Total Other Costs | \$180.00 | \$0.00 |
|-------------------|----------|--------|

## Part 4 - Spare Parts / Material Usage

Ref No.:

|             | To be completed by Ser                             | vice Ad | viso        | r, ARC                                      |                            |               |                           |  |  |
|-------------|--|---------|-------------|---|----------------------------|---------------|---------------------------|--|--|
| Part Number | Parts Description                                  | Qty     |             | List Price                                  | Discount (%)               |               | al Price                  | Check ( C )<br>Repair (R)<br>Replace ( / ) | Not given (X<br>Repair (R)<br>Check (C)<br>Replace (/) |
| 52159-47905 | BUMPER REAR  | 1       | \$          | 458.60                                      | 25.00%                     | \$            | 343.95                    | R /  | 1  |
| 52023-12240 | BUMPER REINFORCEMENT REAR                          | 1       | \$          | 205.70                                      | 25.00%                     | \$            | 154.27                    | 3.1  | 1  |
|             | PIXEL STICKER                                      | 1       | \$          | 60.00                                       | 0.00%                      | \$            | 60.00                     | INEG                                       | 1  |
|             |  |         |             |   |                            |               |                           |  |  |
|             |  |         |             |   |                            |               |                           |  |  |
|             |  |         |             |   |                            |               |                           |  |  |
|             |  |         |             |   |                            |               |                           |  |  |
|             |  | -       |             |   |                            |               |                           |  |  |
|             |  |         |             |   |                            |               |                           |  |  |
|             |  |         |             |   |                            |               |                           |  |  |
|             |  | -       |             |   | -                          |               |                           |  |  |
|             |  |         |             |   |                            |               |                           |  |  |
|             |  | -       |             |   |                            |               |                           |  |  |
|             |  |         |             |   |                            |               |                           |  |  |
|             |  | 1       | (Villation) |   |                            |               |                           |  |  |
|             |  |         | - 8         | KK Auto (                                   | er of the fo               | HOV           | vina:                     | ly   |  |
|             |  |         | 0           | To display d                                | before/after<br>amaged par | spra<br>(s) d | y painting<br>luring resu | rvey                                       |  |
|             | Sebastian.   |         | -           | Parts prices Third party :                  | urvey is on                | a W           | ithout Preju              | udice" basis                               |  |
|             | 30/11/2017.  |         |             | No illegal m<br>Supplement<br>is subject to | ary item(s) r              | nust          | be resurve                | yed <u>and</u><br>ce Company               |  |
|             | - Part by part repair.<br>- Quistion Mark Item Pho | to .    | A           | cknowledge                                  |                            |               |                           | - Joinpany                                 |  |
|             | - Photo After Paint.                               |         |             | ignature:<br>ate:                           |                            |               |                           |  |  |

2 dans

| TOTAL MATERIALS | \$ 724.30 | \$ 558.22  |  |
|-----------------|-----------|------------|--|
|                 |           | \$1,509.49 |  |

.

٠.

| Surveryor Remark: |  |  |
|-------------------|--|--|
|                   |  |  |
|                   |  |  |
|                   |  |  |