

ASS. REC. BY:

REF: CS/40117022866/

b

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Jenny Lew

of 401

Date/Time: 12-41pm @ 11/12/17

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 5588L

Insured:

YM 8763P

at Workshop m/s

Goldbell Engineering

Tel:

8816 2798

of Blk K, Pandan Loop Ind. Estate # 01-12 12 8230

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 29/11/2017

CA / REV / REP. / REV 24 HRS

wp

29 tanjong penjun 609 026

H.O.D. Endorsement:

Date/Time: 2:07pm @ 1/12/17

Person Contacted: Andy

Vehicle IN ☒ OUT

Date/Time

Action/Instruction (✓) Estimate

SKW 5588L - X

YM 8763P - X

01/12/17 11:48pm Jenny call to cancel claim, owner withdraw claim.

6/6

Nivitha (LKK Auto)

From: LEW JENNY <jennylew@uoi.com.sg>
Sent: Friday, 1 December, 2017 12:41 PM
To: Andy Ooi Lee Keong; sur@lkkauto.com; assignments@lkkauto.com
Cc: William Go Shaw Chan
Subject: RE: Accident case between SKW5588L (LIBERTY INS) and YM8763P (UOI INS) at inside compound of 12 tuas road
Attachments: SKW5588L.zip

WITHOUT PREJUDICE

Dear Andy,

We will appoint LKK as per requested.

Dear Shiau Chan,

Please arrange to survey at 29 Tanjong Penjuru Singapore 609026.

password: uoi123

Thank You.

Warmest Regards

Jenny
Claims Department

DID : 6 4909 329 Fax : 6 327 3869/72

United Overseas Insurance Limited

Company Registration Number: 197100152-R UOB EMAIL DISCLAIMER Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Andy Ooi Lee Keong [mailto:AndyOoiLK@goldbell.com.sg]
Sent: Friday, 1 December, 2017 12:30 PM
To: LEW JENNY <jennylew@uoi.com.sg>
Cc: William Go Shaw Chan <WilliamGoSC@goldbell.com.sg>
Subject: RE: Accident case between SKW5588L (LIBERTY INS) and YM8763P (UOI INS) at inside compound of 12 tuas road

Hi Ms Jenny ,

I would like to choose LKK AUTO for survey the vehicle .

Thank & regards

Andy Ooi Lee Keong | Goldbell Engineering Pte Ltd Customer Service Advisor, Motor Claims

DID: +65 6458 9596 | Tel: +65 6458 9596 | Fax: +65 6458 7172 |
Mobile: +65 8816 2798 | Web: <http://www.goldbell.com.sg>
Address: Goldbell Engineering Pte Ltd (Pandan) Blk K, Pandan Loop Ind. Estate, #01-12 Singapore 128230

From: LEW JENNY [mailto:jennylew@uoi.com.sg]
Sent: Friday, 1 December 2017 11:57 AM
To: Andy Ooi Lee Keong <AndyOoiLK@goldbell.com.sg>
Cc: William Go Shaw Chan <WilliamGoSC@goldbell.com.sg>
Subject: RE: Accident case between SKW5588L (LIBERTY INS) and YM8763P (UOI INS) at inside compound of 12 tuas road

WITHOUT PREJUDICE

Dear Andy,

We refer to your email dated 1.12.2017.

Pursuant to the amended Pre-action Protocol for Non-Injury Motor Accident (NIMA), we enclose a list of our Surveyors, for your attention.

In this case, we propose to appoint M/s Express Adjustment Service.

Please revert to the undersigned within two (2) working days whether you have any objections to the appointment of any of our Surveyors; failing which we shall proceed to carry out the survey of your client's vehicle by our appointed Surveyors.

Please note that we are not responsible for any delay on your part or whatsoever reason.

We reserve all our right in relation to this matter.

Thank You.

Warmest Regards

Jenny
Claims Department

DID : 6 4909 329 Fax : 6 327 3869/72

United Overseas Insurance Limited

Company Registration Number: 197100152-R UOB EMAIL DISCLAIMER Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Andy Ooi Lee Keong [mailto:AndyOoiLK@goldbell.com.sg]
Sent: Friday, 1 December, 2017 10:56 AM
To: LEW JENNY <jennylew@uoi.com.sg>
Cc: William Go Shaw Chan <WilliamGoSC@goldbell.com.sg>
Subject: Accident case between SKW5588L (LIBERTY INS) and YM8763P (UOI INS) at inside compound of 12 tuas road

Hi Motor claims
Attached is the GIA report for your necessary action.

REMARK : The vehicle is with the owner,

location in GOLDBELL ENGINEERING PTE LTD (PENJURU)

29 Tanjong Penjuru Singapore 609026

Best Regards,

Andy Ooi Lee Keong | Goldbell Engineering Pte Ltd Customer Service Advisor, Motor Claims

DID: +65 6458 9596 | Tel: +65 6458 9596 | Fax: +65 6458 7172 |

Mobile: +65 8816 2798 | Web: <http://www.goldbell.com.sg>

Address: Goldbell Engineering Pte Ltd (Pandan) Blk K, Pandan Loop Ind. Estate, #01-12 Singapore 128230