

REF: CS /LAW17022867 / Kib₂

Special Instructions:

From (Person): Theresa Lim of Beggars & Din Date/Time: 24-11-2017
Estimated Cost: _____ Bill to: _____

US: \$ 20100.00

Third Parties:

Claimant:

Surveyor: Pro-Option 2 Farmer

Workshop: T2 B Myers

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SFU 7855Y Insured: SKN 6171X
at Workshop m/s T & B motor Tel: 6458 0296
of 160 Sin Ming Drive # 402

Policy No: _____ Claim No: SD/2017-012459

Sum Insured: _____ Excess: _____

Make of Veh: _____
(Client's Record) _____

05.12.2017 (Tuesday) @ 10:30am - 11am

SJE

H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: _____ Confirmed with _____ Final Fig _____, _____ days (Red \$ _____ / _____ %; Original 7 days)
Date/Time: 8/2/18 Submit Final Fig 88700, 04 days (Red \$ 11400 / 56 %; Original 7 days)

Date/Time: 8/2/18 Submit Final Fig 88700, 04 days (Red \$ 11400 / 56 %; Original 7 days)

Date/Time	Action/Instruction
	STU TSPBY - NGA / INCI 5004 152 / 01
	3KN GRIX - X
	11 Feb 88 Fed /
	RECEIVED 11 FEB 2013

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Date: _____

Basic & Add

Transport

Photos

Others

Total

1) Date/Time _____ File Pass to _____

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____


6) Date/Time _____ File Return to _____

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop in s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: STU 78554 Page: 01 15
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mer 8200 1991
 Colour: M. Black A/C Insured / Std / Nil / NA
 So Reading: 56216 T. Radio Insured / Std / Nil / NA
 Eng No: _____
 C No: W00 21203 42B 025499
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: Nil / S/Rim / STD A/Rim or
 Tyre Size: Continental 245/40ZR18
Apollo
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: 3 mm R/Bal: 6 mm
 L/Bal: 3 mm L/Bal: 6 mm
 D.O.A: _____ D.O.I: 5/12/17
 Survey held at: _____
 Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Date/Time: File Pass to?

☐

Preli. Report

Days Of Repair:

☐

Final Report

Resurvey No. of Trip:

Date/Time: File Return to?

Survey Fee

Transportation

Date: _____

Add Fee:

☐

Site Insp: \$

☐

Interview: \$

☐

Tech. Insp: \$

☐

Witness: \$

Report Format:

Lump Sum / I.B. to \$

S.H.P.P. L.B.

Fuels

Taxes

TOTAL




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BOGAARS & DIN		Ref : CS/LAW17022867/Kgb		
20 HAVELOCK ROAD		Date : 01-12-2017		
#03-02/03 CENTRAL SQUARESINGAPORE 059765		Code : L013		
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SKN 6171X	Veh. Inspected	SFU 7855Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	SD/2017-012459	Excess (\$)	0.00	
Assign From	THERESA LIM	Assign Date	24/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	18/01/2017	Inspection Date	05/12/2017	
Survey held at	160 SIN MING DRIVE #08-03			
Repairer	T & B MOTOR REPAIRS SERVICES PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Catherine Chong (LKK Auto)

From: Theresa Lim <theresa@bogaars-din.com>
Sent: Friday, 24 November, 2017 4:59 PM
To: assignments@lkkauto.com
Cc: Savliwala Din
Subject: APPOINTMENT OF AN SINGLE JOINT EXPERT - OUR REF: SD/2017-012459
Attachments: ltr.lkk.pdf; GIA SFU7855Y.pdf; SKN6171X.pdf; Inspectn report.repair bill.pdf

Dear Mr Kong

We refer to the above caption subject.

Our covering letter dated 24 November 2017 and its enclosures are in the attachments.

As the file is too large, I will be sending you in a separate email the Re-inspection report of FormTeam.

We hope to receive your report shortly.

Thank you.

Regards
Theresa Lim
Bogaars & Din
7500A Beach Road #16-324 Singapore 199591
Tel: (65) 6538 8188 Fax: (65) 6538 5655
Email: theresa@bogaars-din.com
Website: <http://bogaars-din.com>

6337 8700 - melody
Cheng Han Lim

Privileged /Confidential Information may be contained in this message (and attachment, if any). If you are not the addressee indicated in this message (or responsible for the delivery of the message to such person), you may not copy or deliver or otherwise distribute this message in any form to anyone. In such case, you should destroy this message, and notify us immediately. Please note that communications by email may not be confidential and we do not make any warranties in this respect. If you or your employer does not consent to communications in email with your lawyers, please advise us immediately. Opinions, conclusions and other information expressed in this message are not given or endorsed by M/s Bogaars & Din unless otherwise indicated by an authorized representative independent of this message.

Your Ref: (To be advised)
Our Ref: SD/2017-012459/tl

Bogaars & Din
7500A Beach Road
#16-324 The Plaza
Singapore 199591

24 November 2017

www.bogaars-din.com

M/s LKK Auto Consultants Pte Ltd
Singapore

BY EMAIL

We do not accept service of court documents by fax

Attn: Mr Kenneth Kong

Business Registration No:
53131105L

Dear Sirs

**MC/MC NO. 12089/2017
ACCIDENT INVOLVING SFU 7855Y & SKN 6171X ON 18.01.2017
ALONG PAYA LEBAR STREET**

We refer to the above suit.

Both the Plaintiff and the Defendant and the Defendant's insurers are unable to come to an agreement about what the reasonable cost of repairs to the Plaintiff's car should be.

We both have agreed to appoint your Mr Kenneth Kong as the single joint expert and give us your opinion about what the reasonable cost of repairs should be.

Both parties have also agreed to bear responsibility for your costs equally in the first instance.

All of the following documents are enclosed.

1. GIA report of SFU 7855Y and photographs;
2. GIA report of SKN 6171X and photographs;
3. Inspection report and photographs of Pro-Option Services;
4. Repair bill; and
5. Re-inspection report and photographs of FormTeam Adjusters Pte Ltd.

If you are requiring a physical inspection of the Plaintiff's car, please let M/s Cheonghoh Law Corporation know about this and they will assist you in arranging for the physical inspection.

ADVOCATES & SOLICITORS | COMMISSIONERS FOR OATHS | NOTARIES PUBLIC

Page 2

24 November 2017

M/s LKK Auto Consultants Pte Ltd

We look forward to receiving your report shortly.

Yours faithfully



Savliwala Din
BOGAARS & DIN

Encs

cc clients

cc M/s CheongHoh Law Corporation

Your Ref: LCH.my/ct/SMTB-70062.17

Fax: 6337 3700

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/01/2017 10:49
Date Of Accident	18/01/2017 10:00
Exact Location Of Accident	T-JUNCTION OF UPP PAYA LEBAR RD & LOR PAYA LEBAR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFU7855Y
Insured/Policyholder	
Name Of Registered Owner	LIU JIANG ZHONG
NRIC No	S6963207F
Email Address	JIANGZHINGLIU@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-91732577
Alternative Phone No	OTHERS-91732577

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3002821701
Cover Note Number	

Driver

Name of Driver	LIU JIANG ZHONG
NRIC No	S6963207F
Date Of Birth	09/07/1969
Occupation	OUTDOOR
Date Of Driving Pass	28/04/2009
Driving Experience	7 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91732577
Fax Number	
Contact Number	OTHERS-91732577
Email Address	JIANGZHINGLIU@YAHOO.COM.SG

Address	BLK 142 YISHUN RING ROAD #06-34
Postcode	760142
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	UNKNOWN - REFER TO SKETCH PLAN.
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
Have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKN6171X
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
 8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
 - (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan





Describe Circumstances of the Accident


on 18/1/2017 I was driving
 along upper paha Lebar Road straight
 ahead suddenly I saw a mercedes
 come toward my left when
 I try to avoid is too late she
 hit on my rear left. we
 take photo and move off
 I wish to state I got full
 CCTV very clear video she never check
 and stop at the stop line and dash
 out hit my car.

Declaration

We declare the foregoing particulars are true in every respect.


 Policyholder's Signature / Date &
 Time AM 6-248 19/01/17


 Driver's Signature (If driver is not the policyholder) / Date
 & Time


 Witnessed by Reporting Centre
 Personnel

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/01/2017 14:51
Date Of Accident	18/01/2017 09:30
Exact Location Of Accident	LORONG PAYA LEBAR TURNING INTO PAYA LEBAR ST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKN6171X
Insured/Policyholder	
Name Of Registered Owner	LIM CHOON KOOI
NRIC No	S1515332F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97272085
Alternative Phone No	OFFICE-97272085

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100377517
Cover Note Number	

Driver

Name of Driver	LIM TZE QI
NRIC No	S8414388Z
Date Of Birth	15/05/1984
Occupation	INDOOR
Date Of Driving Pass	19/06/2006
Driving Experience	10 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97272084
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	20 WOODLANDS CRESCENT #13-42
Postcode	738081
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - DAUGHTER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	UNKNOWN - REFER SKETCH PLAN
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
Have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFU7855Y
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repeal the policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

6. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;



(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.


(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes

 2 pm 19/1 Policyholder's Signature / Date & Time	 2 pm 19/1 Driver's Signature (if driver is not the policyholder) / Date & Time	Eric Lee Ming Hui DID : 6771 4336 HP : 9181 7717 Email : eric.lee@cyclecarriage.com.sg Cycle & Carriage Industries Pte Ltd Customer Service Centre - Pandan Loop Witnessed by Reporting Centre Personnel
---	---	---

Sketch Plan



Sketch Plan #2

Describe Circumstances of the Accident


I WAS TURNING INTO PAYA LEBAR STREET FROM LORONG PAYA LEBAR WHEN VEHICLE B(SFU7855Y) HIT MY FRONT PORTION.


Declaration

I/We declare for foregoing particulars are true in every respect.

Please note that you have 14 calender days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)


2 pm
14/1
Policyholder's Signature / Date & Time


2 pm
14/1
Driver's Signature (If driver is not the policyholder) / Date & Time

Eric Lee Ming Hui
DID : 6771 4336 HP : 9181 7717
Email : eric.lee@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop
Witnessed by Reporting Centre Personnel

T & B MOTOR REPAIRS SERVICES PTE LTD

BLK 20 SIN MING ROAD #01-28 SINGAPORE 575678
Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640
E-Mail : tbmotor@hotmail.sg
Buss. Reg. No. : 199001597D

PHOTOCOPY

LIU JIANG ZHONG
BLK 142 YISHUN RING ROAD #06-34
760142

Attention : Motor Claim Department

Final Repair Bill : T1001901

Date : 03/04/2017
Vehicle Num. : SFU7855Y
Make/Model : MERCEDES BENZ E200
Chassis/Eng# :
Accident Date : 18/01/2017
Claim No. :
Reference :
Policy No. : DMPCSN3002821701

Amount S\$

LUMP SUM REPAIRS

INCLUSIVE OF SUPPLYING PARTS AND LABOUR,
PANEL BEATING AND SPRAY PAINTING

20,100.00

SingDollars . Twenty Thousand One Hundred Only

E. & O.E.

Total S\$:

20,100.00

=====


for T & B MOTOR REPAIRS SERVICES PTE LTD

PRO-OPTION SERVICES

Mailing address: Blk 1898 Rivervale Drive, #04-1004, Singapore 542189

Tel: 6315 1239, Fax: 6315 3298, Mobile: 9061 0543

Liu Jiang Zhong
Blk 142 Yishun ring Road
#06-34
Singapore 760142

Invoice no:	POS039/17
Date:	3 April 2017
Report no:	39M0117.TB
Vehicle :	SFU7855Y

INVOICE

No	Item Description	Qty	Unit Price	Total Amount(\$)
01	Being charges for the inspection of the accident vehicle, transport and photographs.			908.00
SGD(\$): Nine hundred and eight only			Payable Amount:	908.00

"Cheque should be crossed and made payable to "Pro-Option Services"

PRO-OPTION SERVICES

.....
Authorised Signature

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Tel: 6315 1239, Fax: 6315 3298, Mobile: 9061 0543

ACCIDENT VEHICLE INSPECTION REPORT

Report no : 39M0117.TB
Vehicle no : SFU7855Y

1 REFERENCE

Date of inspection : 20 January 2017
Requested by : Liu Jiang Zhong
Blk 142 Yishun ring Road
#06-34
Singapore 760142
Type of survey : Independent
Repairer : T & B Motor Repairs Services Pte Ltd
Blk 20 Sin Ming Road, #01-28, Singapore 575678
Date of accident : 18 January 2017

2 VEHICLE DATA

Make/model : Mercedes Benz E200 Sedan (R18)
Chassis no : WDD21203428025499
Engine no : 27492030191406
Date of registration : 27 January 2015
Engine capacity : 1991 cc
Colour : Black

3 STATIC CONDITION CHECK

Steering : Serviceable
Foot brakes : Serviceable
Hand brakes : Serviceable
Paintwork : Good
General Condition : Good

4 TIRE CONDITION CHECK

	<u>RH/MAKE</u>	<u>LH/MAKE</u>	<u>SIZE</u>
Front tread	: 5 mm/Continental	5 mm/Continental	245/45ZR18
Rear tread	: 5 mm/Continental	5 mm/Continental	245/45ZR18

5 BRIEF DESCRIPTION OF DAMAGE

Rear bumper scraped/deformed, rear LH fender scraped, rear LH tyre rim scraped/grazed, rear left undercarriage/suspension parts damaged, etc. Please see para. 8 of this report for more details.

6 REMARKS

This inspection is carried out on a "WITHOUT PREJUDICE" basis and I have not authorized any repairs.

7 RECOMMENDATION

Cost of repairs : \$20,100.00 (lump sum)
Estimated no of days : Seven (7)



FORMTEAM ADJUSTERS PTE LTD

No.33, Ubi Ave 3
#02-15, Vertex
Singapore 408868

Tel : (65) 6509 1788
Fax : (65) 6509 6221

Email: claims@fta.com.sg

Co.Reg No: 201212134W

GST Reg No: 201212134W

Our Reference : FTA/AHA/1705/7252/RI

Your Reference: 5675229200SG

Date : 09-Jun-2017

Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
Singapore 079120

Attention : Ms Pauline Tham

Dear Sir/Mdm,

RE-INSPECTION OF VEHICLE NO . SFU 7855Y

Pursuant to your instructions on 05 May 2017, we have conducted a reinspection of the above vehicle at 160 Sin Ming Drive #08-03 S'575722 on 05 Jun 2017.

We recommend a repair cost of \$5,800.00 (see report) based on lump sum repair and the estimated duration of repairs would take 04 days.

We also enclosed our note of charges for your consideration.

Thank you for this assignment.

Your faithfully

FormTeam Adjusters Pte Ltd
Adjusters & Surveyors (Licensed Appraiser)

Axel Lee
Automobile Appraiser

(Email : axellee@fta.com.sg)

Encl. Re-inspection Report

AUTOMOBILE ASSESSMENT REPORT

PAGE : 1

Our Reference : FTA/AHA/1705/7252/RI

Your Reference : 5675229200SG

Date : 09-Jun-2017

Attention : Ms Pauline Tham

TO : Motor Claims Department

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16

Singapore 079120

Dear Sir/Madam,

Vehicle No : SFU 7855Y

Model : Mercedes E200

Mileage : 45808 km

Chassis No : WDD2120342B025499

Workshop : M/S T&B Motor Repair Services Pte Ltd

Pursuant to your instructions on **05 May 2017**, we have conducted a reinspection of the above vehicle at **160 Sin Ming Drive #08-03 S'575722** on **05 Jun 2017**.

We are pleased to submit hereunder our adjustment which we trust should serve your purpose: -

QTY	DESCRIPTION	CONDITION	REMARKS	SUBMITTED	REVISED
	<u>PARTS REPLACEMENT-LIST ITEMS</u>				
1	Rear Bumper	Scraped/ Deformed		1,479.50	1,479.50
1	Rear Bumper Side Moulding LH	Scraped		134.20	134.20
1	Rear Bumper Side Moulding RH	To Reuse		-	-
1	Rear Bumper Side Exhaust Heater Cover LH	Reuse		88.00	-
1	Rear Bumper Side Exhaust Heater Cover RH	To Reuse		-	-
1	Rear Bumper Lower Centre Bracket	Na		-	-
10	Rear Bumper Heater Cover Rivet	Necessary		66.00	66.00
1	Rear Bumper Side Mud Cover LH	Na		-	-
1	Rear Bumper Side Retainer LH	Necessary		33.00	33.00
1	Rear Bumper Side Retainer RH	Necessary		33.00	33.00
1	Rear Bumper Side Garnish LH	To Reuse		-	-
1	Rear Bumper Side Garnish RH	To Reuse		-	-
1	Rear Bumper Side Reverse Sensor LH	Scraped/ Shorted		264.00	264.00

FORMTEAM ADJUSTERS PTE LTD

PAGE : 2

Our Reference : FTA/AHA/1705/7252/RI

Your Reference : 5675229200SG

QTY	DESCRIPTION	CONDITION	REMARKS	SUBMITTED	REVISED
1	Rear Bumper Mud Cover LH	Bent/Deformed		247.50	247.50
1	Rear Floor Board Under Heater Cover	Reuse		132.00	-
1	Rear Shock Absorber LH	Bent/Jammed		605.00	605.00
1	Rear Wheel ABS Sensor Wire LH	To Reuse		-	-
1	Rear Wheel ABS Sensor Wire RH	To Reuse		-	-
1	Rear Wheel Knuckle Arm LH	Bent/Distorted		1,925.00	1,925.00
1	Rear Wheel Bearing Hub Assy LH	Rattled/Notchy		275.00	275.00
1	Rear Tie Rod Arm LH	Not Fitted		242.00	-
1	Rear Pushing Strut Arm LH	Bent		225.50	225.50
1	Rear Strut Arm LH	Bent		209.00	209.00
1	Rear Camber Arm LH	Bent		237.60	237.60
1	Rear Drive Shaft LH	Reuse		308.00	-
1	Rear Stabilizer Bar LH	Reuse		228.80	-
1	Rear Stabilizer Bar Link LH	Bent		60.50	60.50
1	Rear Axle Frame Assy	Reuse		2,337.50	-
1	Rear Axle Differential	Reuse		9,372.00	-
1	Rear Turning Auyle Pick-Up	Reuse		473.00	-
1	Rear Brake Disc	To Reuse		-	-
Sub-Total				18,976.10	5,794.80
Discount Percentage 10%				1,897.61	579.48
Total Parts List Items				17,078.49	5,215.32
<u>PARTS REPLACEMENT-SPECIAL NETT ITEMS</u>					
1	Rear Tyre LH	No Photo Show Damaged		495.00	-
1	Rear Tyre RH	Not Consistent		495.00	-
1	Rear Tyre Sport Rim (Set)	Scraped/ Grazed		3,920.00	800.00
1	Rear Tyre Sport Rim Centre Cover LH	Scraped		35.20	35.20
1	Rear Shock Absorber RH	Not Necessary		-	-
Total Parts Special Nett Items				4,945.20	835.20
Total Parts				22,023.69	6,050.52

FORMTEAM ADJUSTERS PTE LTD

PAGE : 3

Our Reference : FTA/AHA/1705/7252/RI

Your Reference: 5675229200SG

QTY	DESCRIPTION	SUBMITTED	REVISED
	<u>LABOUR & MISC</u>		
1	Computerized wheel alignment.	120.00	100.00
2	Computer tyre high speed balancing.	90.00	30.00
3	Remove & replace reverse sensors.	120.00	80.00
4	Checking & repairing wiring.	60.00	40.00
5	Remove & refix exhaust pipe to facilitate the removal of the undercarriage parts.	240.00	-
6	Spray painting on affected portions.	600.00	400.00
7	Remove/refix and replace rear undercarriage parts.	1,200.00	200.00
8	Labour charge for repairing, adjusting, knocking, welding the damaged parts, straightening the above. (including all repair parts)	600.00	400.00
	Total Labour Amount	3,030.00	1,250.00
	Total Parts and Labour	25,053.69	7,300.52

FORMTEAM ADJUSTERS PTE LTD

PAGE : 4

Our Reference : FTA/AHA/1705/7252/RI

Your Reference: 5675229200SG

QTY	DESCRIPTION	SUBMITTED	REVISED
	Our Recommended Repair Cost (see remarks)	\$20,100.00	\$5,800.00

REMARKS :


Our recommended Lump Sum Repair Cost is **\$5,800.00** (instead of the submitted repair cost of **\$20,100.00** .In normal circumstances, repairs to the vehicle would take approximately **04 days** to complete. Please find enclosed our note of charges for your kind attention.

Disclaimer


This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by **FORMTEAM ADJUSTERS PTE LTD** for any reliance on this report by any third party, unless with the permission of the addressee.

Yours faithfully,

FORMTEAM ADJUSTERS PTE LTD



Frankie Pang
AMSAE(AUST), AMIRTE, AMSOE,
MASPACI, MSAAA
Licensed Appraiser



Axel Lee
Automobile Appraiser



FORMTEAM ADJUSTERS PTE. LTD.
33 UBI AVENUE 3 #02-15 VERTEX
SINGAPORE 408868

Tel : 6509 1788 Fax : 6509 6221
UEN No : 201212134W
GST Reg No : 201212134W

Tax Invoice

Bill To:

AIG Asia Pacific Insurance Pte Ltd
78, Shenton Way #08-16
Singapore 079120

Attn: Ms Pauline Tham

Invoice No :	13008088
Date :	12/6/2017
Your Ref :	5675229200SG
Our Ref :	FTA/AHA/1705/7252/RI

Description	Amount (S\$)
Resurvey Fee for No. : SFU 7855Y	S\$200.00

We would appreciate your cheque crossed and make payable to :
FORMTEAM ADJUSTERS PTE LTD

E. & O. E

Total	S\$200.00
Add: GST	S\$14.00
Total Inc GST	S\$214.00
Less: Deposit	S\$0.00
Balance Due	S\$214.00

FORMTEAM ADJUSTERS PTE LTD

RECEIVED BY	DATE	COMPANY STAMP

8 ASSESSMENT OF DAMAGE AND COSTS

Report no: 39MO117.TB
Vehicle no: SFU7855Y

A SPARE PARTS

	Description	Qty	Assessed Condition	Repairer's	Revised	
				Amount	Amount	
1	Rear bumper	1	scraped/deformed	1,479.50	1,479.50	
2	Rear bumper side moulding LH	1	scraped	134.20	134.20	
3	Rear bumper side moulding RH	1	to reuse *	134.20	0.00	
4	Rear bumper side exhaust pipe heater cover LH	1	bent	88.00	88.00	X
5	Rear bumper side exhaust pipe heater cover RH	1	to reuse *	88.00	0.00	
6	Rear bumper lower centre bracket	1	NA	18.70	0.00	
7	Rear bumper heater cover rivet	10	necessary	66.00	66.00	
8	Rear bumper side mud cover LH	1	NA	134.20	0.00	
9	Rear bumper side retainer LH	1	necessary	33.00	33.00	
10	Rear bumper side retainer RH	1	necessary	33.00	33.00	
11	Rear bumper side garnish LH	1	to reuse *	38.50	0.00	
12	Rear bumper side garnish RH	1	to reuse *	38.50	0.00	
13	Rear bumper side reverse sensor LH	1	scraped/shorted	264.00	264.00	
14	Rear bumper mud cover LH	1	bent/deformed	247.50	247.50	
15	Rear floor board under heater cover	1	bent	132.00	132.00	X
16	Rear shock absorber LH	1	bent/jammed	605.00	605.00	
17	Rear wheel ABS sensor wire LH	1	to reuse *	379.50	0.00	
18	Rear wheel ABS sensor wire RH	1	to reuse *	379.50	0.00	
19	Rear wheel knuckle arm LH	1	bent/distorted	1,925.00	1,925.00	
20	Rear wheel bearing hub assy LH	1	rattled/notchy	275.00	275.00	
21	Rear tie rod arm LH	1	bent	242.00	242.00	
22	Rear pushing strut arm LH	1	bent	225.50	225.50	
23	Rear strut arm LH	1	bent	209.00	209.00	
24	Rear camber arm LH	1	bent	237.60	237.60	
25	Rear drive shaft LH	1	bent/wobbled	308.00	308.00	X
26	Rear stabiliser bar LH	1	bent	228.80	228.80	X
27	Rear stabiliser bar link LH	1	bent	60.50	60.50	X
28	Rear axle frame assy	1	warped/distorted	2,337.50	2,337.50	X
29	Rear axle differential	1	bearing rattled	9,372.00	9,372.00	X
30	Rear turning angle pick-up	1	shorted	473.00	473.00	X
31	Rear brake disc	1	to reuse *	203.00	0.00	
Subtotal of the above				20,390.20	18,976.10	
Discount 10% / 10%				2,039.02	1,897.61	
Subtotal 1:				18,351.18	17,078.49	
32	Rear tyre LH	1	Lip deformed	495.00	495.00	X
33	Rear tyre RH	1	Lip deformed	495.00	495.00	X
34	Rear tyre sport rim (set)	1	scraped/grazed	3,920.00	3,920.00	
35	Rear tyre sport rim center cover LH	1	scraped	35.20	35.20	
36	Rear shock absorber RH	1	Necessary (50%)	605.00	302.50	
Subtotal 2:				4,945.20	4,945.20	
Total cost of parts:				23,296.38	22,023.69	

(Special nett)

Report no: 39M0117.TB
Vehicle no: SFU7855Y

B LABOUR

1 Computerised wheel alignment	180.00	120.00	100
2 Computer tyre high speed balancing.	160.00	90.00	300
3 Remove & replace reverse sensors.	180.00	120.00	600
4 Checking & repairing wiring.	100.00	60.00	300
5 Remove & refix exhaust pipe to facilitate the removal of the undercarriage parts.	280.00	240.00	200 X
6 Spray painting on affected portions.	980.00	600.00	500
7 Remove /refix and replce rear undercarriage parts.	1,500.00	1,200.00	200
8 Labour charge for repairing, adjusting, knocking, welding the damaged prts, straightening the above.	880.00	600.00	400

Total cost of labour:

4,260.00	3,030.00
----------	----------

Total cost of repair:

27,556.38	25,053.69
-----------	-----------

28/6/58

9 **CONCLUSION**

Report no: 39M0117.TB
Vehicle no: SFU7855Y

The actual damage sustained by the vehicle was carefully inspected and assessed during the inspection and the assessment is appended in para. 8 of this report. The degree of damage sustained by individual part(s) is/are carefully assessed before the part(s) is/are recommended to be either replaced or repaired.

The revised or adjusted cost of repairs to restore the vehicle is \$25,053.69 .


However, after considering the age and condition of the vehicle and the availability of good second hand parts in the market, the repairs are therefore recommended to be undertaken on a contract lump sum basis of \$20,100.00 and the estimated number of days for the repairs would Seven (7) working days.

The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its pre-accident condition.

Note: By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged part(s) with used, reconditioned or new part(s), or to repair the part(s) to a roadworthy condition.

We have not authorised any repairs and would like to revert the recommendations for your consideration and decision.

Yours faithfully



.....
Liaw Leong San
Licensed Automotive Appraiser



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

BOGAARS & DIN

Ref : CS/LAW17022867/Knbe2

7500A BEACH ROAD
#16-324 THE PLAZA
SINGAPORE 199591

Date : 09-02-2018



Code : L013

1. Policy Particulars - THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SKN 6171X	Veh. Inspected	SFU 7855Y
Policy No.		Coverage (\$)	0.00
Claim No.	SD/2017-012459	Excess (\$)	0.00
Assign From	THERESA LIM	Assign Date	24/11/2017

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ E200 (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WDD2120342B025499	Colour	METALLIC BLACK
Odometer	56216	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/40Z R18	CONTINENTAL	3 mm
L/H Front Tyre	245/40Z R18	CONTINENTAL	3 mm
R/H Rear Tyre	245/40Z R18	APOLLO	6 mm
L/H Rear Tyre	245/40Z R18	APOLLO	6 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.
--

5. General Information

Accident Date	18/01/2017	Inspection Date	05/12/2017
Survey held at	160 SIN MING DRIVE #08-03		
Repairer	T & B MOTOR REPAIRS SERVICES PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFU 7855Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	REPLACED	1,479.50	1,479.50
1	REAR BUMPER SIDE MOULDING LH	REPLACED	134.20	134.20
1	REAR BUMPER SIDE MOULDING RH	TO REUSE	134.20	-
1	REAR BUMPER SIDE EXHAUST PIPE HEATER COVER LH (BENT)	NOT CONSISTENT WITH THE IMPACT	88.00	-
1	REAR BUMPER SIDE EXHAUST PIPE HEATER COVER RH	TO REUSE	88.00	-
1	REAR BUMPER LOWER CENTRE BRACKET	NOT CONSISTENT WITH THE IMPACT	18.70	-
10	REAR BUMPER HEATER COVER RIVET	REPLACED	66.00	66.00
1	REAR BUMPER SIDE MUD COVER LH	NOT CONSISTENT WITH THE IMPACT	134.20	-
1	REAR BUMPER SIDE RETAINER LH	REPLACED	33.00	33.00
1	REAR BUMPER SIDE RETAINER RH	REPLACED	33.00	33.00
1	REAR BUMPER SIDE GARNISH LH	TO REUSE	38.50	-
1	REAR BUMPER SIDE GARNISH RH	TO REUSE	38.50	-
1	REAR BUMPER SIDE REVERSE SENSOR LH	REPLACED	264.00	264.00
1	REAR BUMPER MUD COVER LH	REPLACED	247.50	247.50
1	REAR FLOOR BOARD UNDER HEATER COVER (BENT)	NOT CONSISTENT WITH THE IMPACT	132.00	-
1	REAR SHOCK ABSORBER LH	REPLACED	605.00	605.00
1	REAR WHEEL ABS SENSOR WIRE LH	TO REUSE	379.50	-
1	REAR WHEEL ABS SENSOR WIRE RH	TO REUSE	379.50	-
1	REAR WHEEL KNUCKLE ARM LH	REPLACED	1,925.00	1,925.00
1	REAR WHEEL BEARING HUB ASSY LH	REPLACED	275.00	275.00
1	REAR TIE ROD ARM LH	REPLACED	242.00	242.00
1	REAR PUSHING STRUT ARM LH	REPLACED	225.50	225.50
1	REAR STRUT ARM LH	REPLACED	209.00	209.00
1	REAR CAMBER ARM LH	REPLACED	237.60	237.60
1	REAR DRIVE SHAFT LH	REPAIRED SEE LABOUR	308.00	-
1	REAR STABILISER BAR LH (BENT)	NOT CONSISTENT WITH THE IMPACT	228.80	-

Report Ref No. CS/LAW17022867/Knbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR STABILISER BAR LINK LH (BENT)	NOT CONSISTENT WITH THE IMPACT	60.50	-
1	REAR AXLE FRAME ASSY (WARPED/DISTORTED)	NOT CONSISTENT WITH THE IMPACT	2,337.50	-
1	REAR AXLE DIFFERENTIAL (BEARING RATTLED)	NOT CONSISTENT WITH THE IMPACT	9,372.00	-
1	REAR TURNING AUYLE PICK-UP (SHORTED)	NOT CONSISTENT WITH THE IMPACT	473.00	-
1	REAR BRAKE DISC	TO REUSE	203.00	-
	LESS 10% DISCOUNT		-2,039.02	-597.63
			18,351.18	5,378.67
	<u>SPECIAL NETT ITEMS</u>			
1	REAR TYRE LH (SN) (LID DEFORMED)	NOT CONSISTENT WITH THE IMPACT	495.00	-
1	REAR TYRE RH (SN) (LID DEFORMED)	NOT CONSISTENT WITH THE IMPACT	495.00	-
1	SET REAR TYRE SPORT RIM (SN)	REPLACED	3,920.00	3,920.00
1	REAR TYRE SPORT RIM CENTER COVER LH (SN)	REPLACED	35.20	35.20
1	REAR SHOCK ABSORBER RH (SN) (50%)	REPLACED	605.00	302.50
			5,550.20	4,257.70
	<u>LABOUR</u>			
	COMPUTERISED WHEEL ALIGNMENT.		180.00	100.00
	COMPUTER TYRE HIGH SPEED BALANCING.		160.00	30.00
	REMOVE & REPLACE REVERSE SENSORS.		180.00	60.00
	CHECKING & REPAIRING WIRING.		100.00	30.00
	REMOVE & REFIX EXHAUST PIPE TO FACILITATE THE REMOVAL OF THE UNDERCARRIAGE PARTS.	NOT NECESSARY	280.00	-
	SPRAY PAINTING ON AFFECTED PORTIONS.		980.00	500.00
	REMOVE/REFIX AND REPLACE REAR UNDERCARRIAGE PARTS. INCLUSIVE OF THE REPAIR OF REAR DRIVE SHAFT LH.		1,500.00	200.00
	LABOUR CHARGE FOR REPAIRING, ADJUSTING, KNOCKING, WELDING THE DAMAGED PRTS, STRAIGHTENING THE ABOVE.		880.00	400.00
			4,260.00	1,320.00
	GRAND TOTAL		28,161.38	10,956.37

Report Ref No. CS/LAW17022867/Knbe2



**RECOMMENDED COST OF LUMP SUM REPAIRS
(TO ITS PRE-ACCIDENT CONDITION)**

8,700.00

Report Ref No. CS/LAW17022867/Knbe2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.