

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHF562T - EQ

Not As per
21 Sep 8 26502

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF562T - JHOW

VF1ABL15AUC278131

RENAULT

LATITUDE

29.11.2017

EQ**PART****LIST**

1	1	BUMPER COVER REAR	\$	1,108.46	
2	1	BUMPER LOWER REAR	\$	768.84	
3	1	BUMPER BRACKET CTR REAR	\$	113.47	
4	1	BUMEP R BRACKET SIDE RH REAR	\$	135.97	
5	1	BUMEP R RETAINER RH REAR	\$	44.99	
6	1	BUMPER REFLECTOR RH	\$	43.61	
7	1	ROCKER PANEL OUTER RH	\$	987.49	
8	1	FENDER PANEL REAR RH	\$	3,299.13	
9	1	TAILLAMP RH	\$	552.55	
10	1	TAILLAMP PANEL RH	\$	986.70	
11	1	DOOR PANEL REAR RH	\$	2,844.66	
12	1	DOOR GUIDE REAR RH	\$	176.82	X
13	1	DOOR HINGE UPPER RH	\$	274.50	X
14	1	DOOR HINGE LOWER RH	\$	300.55	X
15	1	DOOR CHECK REAR RH	\$	203.06	X
16	1	DOOR LOCK REAR RH	\$	908.75	X
17	1	DOOR GRAB HANDLE REAR RH	\$	210.96	X
18	1	DOOR HANDLE OUTER REAR RH	\$	126.49	
19	1	DOOR HANDLE CAP REAR RH	\$	35.52	X
20	1	DOOR HANDLE SEAL REAR RH	\$	7.89	
21	1	DOOR HANDLE COVER REAR RH	\$	13.22	
22	1	DOOR HANDLE MODULE REAR RH	\$	133.60	
23	1	DOOR FINISHER REAR RH	\$	423.10	
24	1	DOOR WHEATHESTRIIP REAR RH	\$	410.66	
25	1	DOOR SEAL REAR RH	\$	162.02	
26	1	DOOR WAIST SEAL OUTER REAR RH	\$	334.69	
27	1	DOOR MOULDING REAR RH	\$	176.82	
28	1	DOOR PANEL FRT RH	\$	2,844.66	

TOTAL	\$	17,629.17
10%	\$	1,762.92
	\$	15,866.26

Specical Nett

TRANS-CAB AUTO SERVICES PTE LTD

AAD1711-317

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHF562T - EQ

1	1SET	PARKING AID	\$	700.00	} X
2	1SET	REAR BUMPER CLIP	\$	66.00	
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	
4	1SET	BUMEP R BRACKET SIDE CLIP RH RR	\$	10.00	
5	1SET	BUMEP R RETAINER RH CLIP RR	\$	20.00	
6	1SET	BUMPER LOWER REAR RIVET	\$	22.00	
7	1SET	BUMPER LOWER REAR CLIP	\$	66.00	
8	1	TAILLAMP CLIP RH	\$	5.00	
9	2	REAR WINDSCREEN SELANT	\$	80.00	
10	1	WINDSCREEN MOULDING	\$	100.00	
11	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	
12	1	DOOR STICKER "Trans-cab"	\$	80.00	
13	1	DOOR STICKER "Classic"	\$	30.00	
14	1	DOOR STICKER "6555-3333"	\$	80.00	

TOTAL	\$	1,392.00
TOTAL PARTS	\$	17,258.26

Putty And Spray Painting Of The Affected Portion.

\$ 3,000.00 300

To reinstall rear bumper parking sensor.

\$ 170.00 X

To Rust-Proofing Of The Affected Areas.

\$ 170.00 30

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,800.00 200

To transfer of rear fender fittings, attachment and perform water seepage test.

\$ 380.00 X

To transfer of rear windscreen fittings and conduct water seepage test.

\$ 170.00 X

To check steering geometry and computer wheel alignment

\$ 220.00 X

To transfer of door fittings, attachment and perform water seepage test.

\$ 170.00 60

To transfer of tire, rim and on wheel balancing.

\$ 170.00 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-317**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHF562T - EQ

Towing Fees

\$ *nn* 120.00 *X***TOTAL** \$ **7,370.00****Over All Total** \$ **24,628.26****(PARTS BY PARTS)****Repair Days**~~10 Days~~*2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: