

M/S AIG ASIA PACIFIC INS PTE LTD
CHARTIS BUILDING
78 SHENTON WAY #08-16
SINGAPORE 079120

Zaini

ESTIMATE

DATE : 30/11/2017
ACC DATE : 29/11/2017
REF NO. : VFIX-TP20170376
POLICY NO :

Attention: Motor Claim Department

RE : VEHICLE NO. SKQ7391E NISSAN SYLPHY

DESCRIPTION	AMOUNT S\$
1 1 REAR BOOT LID <i>Dented</i>	850.90 ✓
2 2 REAR BOOT LID HINGE R+L <i>seen</i>	89.60 179.20 +
3 1 REAR BUMPER <i>Dented</i>	683.60 ✓
4 2 REAR BUMPER BRACKET <i>Bent</i>	45.80 91.60 ? ✓
5 2 REAR BUMPER SIDE RETAINER R+L <i>seen</i>	32.70 65.40 ✓
6 2 REAR TAIL LAMP PANEL LH <i>Pyre</i>	164.80 329.60 +
7 2 REAR BUMPER SIDE RETAINER R+L <i>seen</i>	32.70 65.40 +
8 3 REAR BUMPER SPONGE <i>Dented</i>	35.60 106.80 ✓
9 1 REAR BUMPER LOWER SPOILER <i>Dented</i>	588.00 ✓
10 1 REAR END PANEL <i>Dented</i>	491.80 ✓
11 1 REAR FLOOR PANEL BOARD <i>seen</i>	615.20 +
	4,067.50
	LESS 30%
	1,220.25
	\$ 2,847.25

2878.10

2014.67

NETT ITEMS	AMOUNT S\$
1 1 REAR BOOT LID TOP AIR SPOILER <i>seen</i>	257.40 N +
2 1 REAR BOOT LID LOCK TOP <i>Dented</i>	97.90 N -
3 1 BOOT LID LOCK LOWER <i>seen</i>	50.60 N +
4 1 BOOT LID LOGO <i>seen</i>	35.20 N -
5 1 BOOT LID EMBLEM (SYHPHY)	66.40 N -
6 1 BOOT LID EMBLEM (SIGNATURE) <i>seen</i>	62.30 N -
7 1 BOOT LID EMBLEM (XTRONIC CVT)	85.20 N -
8 1 BOOT LID CHROME TOP <i>seen</i>	125.30 N +
9 1 BOOT LID CHROME LOWER <i>cut</i>	115.50 N -
10 1 BOOT LID WEATHERSTRIP <i>cut</i>	79.20 N -
11 2 BOOT LID REFLECTOR R+L <i>seen LH cut</i>	86.40 172.80 N +
12 2 TAIL LAMP <i>cut LH, RH cracked</i>	172.90 345.80 N +
13 4 TAIL LAMP CLIP <i>seen</i>	5.10 20.40 N -
14 1 REAR WINDSCREEN MOULDING <i>seen</i>	175.00 N +
15 1 REAR END PANEL GARNISH <i>Dented</i>	167.80 N ✓

16	4	REAR END PANEL GARNISH CLIP	7.90	31.60	N
17	1	REMOTE CONTROL SENSOR		233.60	N
18	2	REAR BUMPER REFLECTOR R+L	41.60	83.20	N
				\$	2,205.20
				Less 10%	220.52
				\$	1,984.68

1236.20
1112.58

SPECIAL NETT ITEMS	AMOUNT S\$
--------------------	------------

1	8	REAR BUMPER CLIP	4.50	36.00	S/N
2	1	REAR REVERSE SENSOR		250.00	S/N
3	1	REAR REVERSE CAMERA		350.00	S/N
				\$	636.00

256

LABOUR & MISCELLANEOUS:	AMOUNT S\$
-------------------------	------------

1	To remove damaged body panels with all necessary components/attachments apply hot-works where necessary straighten rear floor panel repair/reshape dented panels in accordance with factory specifications,replace new parts refit align into position refit all necessary components/attachments	1,400.00
2	To spray paint replaced/repaired body panels inclusive of preparatory works and painting materials	1,200.00
3	To install reverse sensor,wire harness,control box check funtion	100.00
4	To transfer rear boot lid components	100.00
		\$ 2,800.00

GRAND TOTAL : \$ 8,267.93

LKK Auto Consumer hence notify the Repairer of the following

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Vfix Auto Service Pte Ltd



SINGAPORE DOLLARS : EIGHT THOUSAND TWO HUNDRED SIXTY SEVEN & CENTS NINETY THREE ONLY

Adrian Lj
4/s 06 Days.
01/12/17.

total: 5073.25
h/s: AK