

INS. CASE OWNER:

CC 6 / AIG170

LKK:

IDAC

Surveyor:

RASHM / WUP

DOI:

ASSIGNMENT

1-12-17

Date / Time:

1-12-17

Registered in Merimen:

4-12-17

Pre-assign / CCU / FTE



Insured Vehicle No.:

EGY 938SR

Name of Insured:

KON BUAY KHA

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

29/11/17

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

CHEAH SIONH WOON

Driver Tel No.:

9723 6238

(VL- YES / NO)

Claim No.:

693166007254

Policy No.:

200431396-02

Make / Model:

Mitsubishi Synergy

Place of Accident:

AIRPORT ROAD

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

Shu SIS2T



INSRS:

WSP:

Tel:

Liability:

RMKS:

Soon San



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

5/12

7/17

12/12 @ 2:40

Spoke to OJD, he confirmed the accident details. Informed TP claim and he agree to settle.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

THIN 12/12

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

31/01/18

Confirm with:

M. Soon

Email

Call

Final Liability:

%

100

(Agreed)

Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

6000.00

Loss of Rental (LOR):

S\$

1000.00

(

10 days)

x

100

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

Legal Cost

S\$

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

7000.00

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

7000.00

Name 1:

SOON SAN MOTOR TRADING

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

RECEIVED 01 FEB 2010

COPY 11/2/18

ASSIGNMENT

From: _____ Date: 01-12-2017

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop via Soon Sun

of Blk 3006 Ubi Rd 1 #01-390

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Ball. or Market Value:	33K	
IDAC Accident Rpt:		Consistent? : Yes or No
GIA / FR Seen:		Consistent? : Yes or No
Est. Repairs:	12 days	Res: Yes or No
Lum Sum:	20 %	3 Val: Yes or No
CA / REV / REP. / 24 HRS		

Date: _____ Person Contacted: _____

Date / Time	Action / Instruction
-------------	----------------------

Van No SKU 5152T Yr Reg 2007 MMBY
Type (M.Cycle) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make TOYOTA VIOS J Auto cc 1497
Colour GREEN AC Insured / Std / Nil / NA
So Reading 171477 T Radio Insured / Std / Nil / NA
Eng No
C No MR053H49305001496
Gen. Cond: Good / (Fair) / Poor / Burnt
Steering: (in order) / Jammed / Leaked / Burnt or
Brake: (in order) / Jammed / Leaked / Burnt or
Modi Nil / (S/Rim) / STD A/Rim or
Tyre Size: F: 195/55 R15
R:

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/
TOYO/YOKO or *CONTAMINANT*

Front		Rear	
R.Bal.	5 mm	R.Bal.	5 mm
L.Bal.	5 mm	L.Bal.	5 mm
D.O.A.	29/11/17	D.O.I.	01/12/17
Survey held at		Scow San	
Des. of Damages: Frt. / Rear / O/S / N/S / U/C / Rooftop or			

The U/C / Chassis frame / Body Structure affected due to collision.

LIS - \$ 6000 (Red: 3 6308.57 / 51%)

☐ : Prelim. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Add Fee:	<input type="checkbox"/>	Site Insp.	\$
	<input type="checkbox"/>	Interview	\$
	<input type="checkbox"/>	Tech. Insp.	\$
	<input type="checkbox"/>	Witnessing	\$

Report Format :

Lump Sum / I.B.I.: 15

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG17022913/R1ua3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 04-12-2017



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGY 9385R	Veh. Inspected	SGU 5152T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	04/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	29/11/2017	Inspection Date	01/12/2017
Survey held at	SOON SAN MOTOR TRADING BLK 3006 UBI ROAD 1 #01-390 SINGAPORE 408716		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	4365D

Vehicle Details

Vehicle No.	SGU5152T
Vehicle to be Exported	No
Intended De-registration Date	01 Dec 2017
Vehicle Make	<u>TOYOTA</u>
Vehicle Model	<u>VIOS J AUTO</u>
Primary Colour	Silver
Manufacturing Year	2007
Engine No.	1NZX545876
Chassis No.	MR053HY9305001496
Maximum Power Output	80.0 kW (107 bhp)
Open Market Value	\$12,441.00
Original Registration Date	<u>17 May 2007</u>
First Registration Date	17 May 2007
Transfer Count	2
Actual ARF Paid	\$13,686.00

Intended PARF Rebate Details

PARF Eligibility	Forfeited
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	<u>30 Apr 2022</u>
COE Category	E - Open Category
COE Period(Years)	5
PQP Paid	\$25,115.00
COE Rebate Amount	\$22,170.00
Total Rebate Amount	\$22,170.00

33,000
22,170

10,830
//

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 01 Dec 2017

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG BUILDING

S,pore 079120

Accident date:29/11/17

Date:30/11/17

Estimate cost to repair vel: SGU 5152T (Toyota Vios) claims under vel: SGY 9385R.

1pce boot lid	\$ 601.75	77	/
2pcs boot lid hinges@59.50	119.00	X	5uc
1pce boot lid top lock	95.10	77	/
1pce boot lid lower lock	35.00	77	/
1pce boot lid vios plate	35.10	acc	/
1pce boot lid emblem	45.00	acc	/
1pce boot lid J plate	20.20	acc	/
1pce boot lid centre garnish cover	168.20	DE	/
2pcs boot lid number lamps@42.10	84.20	X	5uc
1pce boot lid rubber	103.10	acc	/
2pcs rear fenders@804.80	1,609.60	RH-LH	(1pc) 804.80 LH-XSUC
2pcs rear fender inner trim cover@245.10	490.20	cut	/
10pcs rear fender trim cover clips@8	80.00	acc	S/N *
2pcs tai lamps@385.10	770.20	acc	/
2pcs tai lamps inner panels@85.20	170.40	DI-LH	(1pc) 85.20 RH-BUC
1pce rear bumper	398.10	DE	/
1set rear bumper reverse sensors	450.00	2erc	acc S/N *
2pcs rear bumper reflectors@42.10	84.20	X	CR2
2pcs rear bumper top side clips@10	20.00	acc	S/N *
10pcs rear bumper inner clips@5	50.00	acc	S/N *
2pcs rear bumper side holders@45	90.00	acc	/
2pcs tai lamp lower holders@40	80.00	T.C.R4	/
1pce rear panel	689.25	77	/
1pce rear panel lower lock cover	85.90	77	/
1pce rear spare tyer panel	880.90	R	/
1set rear spare tyer panel paddling	285.00	X	stann

SOON SAN MOTOR TRADING

Bik.3006,UBI ROAD 1,#01-390 SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG BUILDING

S,pore 079120

Accident date:29/11/17

Date:30/11/17

Rashid
Hp 90010068

12 days

01/12 L/S
01/12 @ 1150

Reg after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To repair before start spray painting
- To repair - avoid scratch during repair
- To repair - avoid damage
- To repair - avoid "without Prejudice" basis
- To repair - avoid "without Prejudice" basis
- To repair - avoid "without Prejudice" basis
- To repair - avoid "without Prejudice" basis
- To repair - avoid "without Prejudice" basis
- To repair - avoid "without Prejudice" basis
- To repair - avoid "without Prejudice" basis

Estimate cost to repair vel: SGU 5152T (Toyota Vios) claims under vel: SGY 9385R.

2pcs rear inner side holders@S214.20	\$ 428.40	page2	Dr (1pc) 214.20
1pce rear spare tyer top cover	120.10		X sue
1pce rear windscreen outer rubber	85.10		X sue
1pce rear windscreen tape from	45.10		X sue
1pce rear windscreen inner sealant	140.00		X sue
1pce rear exhaust pipe	680.90		X sue
1pce rear exhaust pipe outer chrome	120.00		X sue
2pcs rear exhaust pipe rubber holder@S20	40.00		X sue
1set rear shock absorber	398.00		X sue
	\$ 9,598.10		
	2,399.52		
	\$ 7,198.57		
Rear number plate with cover	100.00		CAD - 35 S/N
To rustproof	200.00		100
To check wiring	80.00		30
To remove/refit rear windscreen	140.00		120
To dismantle/renew reverse sensors	100.00		60
To dismantle/renew rear exhaust pipe	100.00		60
To remove/refit rear interior to effect repair	100.00		60
To dismantle/renew rear undercarriage	200.00		X
To computer wheel alignment	140.00		X
To remove/refit rear petrol tank to effect repair	200.00		X
To remove/refit roof insulator to effect repair	150.00		X
To dismantle/renew accident portion	1,800.00		1200 1400
To spray paint	1,800.00		1200
Total:	\$12,308.57		

5661.50
25%
4246.12

311.490

3030

45-6000
12 days

4246.12
490.10
3030.00
7766.22
20%
6212.97

SOON SAN MOTOR TRADING

Bik.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG BUILDING

Singapore 079120

Accident date:29/11/17

Date:30/11/17

Estimate cost to repair vel: SGU 5152T (Toyota Vios) claims under vel: SGY 9385R.

1pce boot lid	\$ 601.75	DT ✓
2pcs boot lid hinges@\$59.50	119.00	X
1pce boot lid top lock	95.10	DT ✓
1pce boot lid lower lock	35.00	DT ✓
1pce boot lid vios plate	35.10	Rec ✓
1pce boot lid emblem	45.00	Rec ✓
1pce boot lid J plate	20.20	Rec ✓
1pce boot lid centre garnish cover	168.20	DE ✓
2pcs boot lid number lamps@\$42.10	84.20	X
1pce boot lid rubber	103.10	Rec ✓
2pcs rear fenders@\$804.80	1,609.60	RH - DT ✓ (1pc)
2pcs rear fender inner trim cover@\$245.10	490.20	wt ✓
10pcs rear fender trim cover clips@\$8	80.00	Rec - S/N
2pcs tai lamps@\$385.10	770.20	DT ✓
2pcs tai lamps inner panels@\$85.20	170.40	DT - LH ✓ (1pc)
1pce rear bumper	398.10	DE ✓
1set rear bumper reverse sensors	450.00 200	Rec - S/N
2pcs rear bumper reflectors@\$42.10	84.20	DE ✓
2pcs rear bumper top side clips@\$10	20.00	Rec - S/N
10pcs rear bumper inner clips@\$5	50.00	Rec - S/N
2pcs rear bumper side holders@\$45	90.00	Rec ✓
2pcs tai lamp lower holders@\$40	80.00	DT ✓
1pce rear panel	689.25	DT ✓
1pce rear panel lower lock cover	85.90	DT ✓
1pce rear spare tyer panel	880.90	R
1set rear spare tyer panel paddling	285.00	X

SOON SAN MOTOR TRADING

Bik.3006,UBI ROAD 1,#01-390 SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG BUILDING

S,pore 079120

Accident date:29/11/17

Date:30/11/17

Rahul
Hp 90010066
12 days
L/S
01/12/17 @ 1150
Reg after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices must be subject to confirmation
- The repair must be on a "Without Prejudice" basis
- The repair must be allowed
- Supplemental work must be resurveyed and is subject to final approval from Insurance Company

Accepted by Repairer
Signature:
Date:

Estimate cost to repair vel: SGU 5152T (Toyota Vios) claims under vel: SGY 9385R.

2pcs rear inner side holders@\$214.20	\$ 428.40	page2 <i>OK (1pc)</i>
1pce rear spare tyer top cover	120.10	<i>X</i>
1pce rear windscreen outer rubber	85.10	<i>new</i>
1pce rear windscreen tape from	45.10	<i>new s/n</i>
1pce rear windscreen inner sealant	140.00	<i>new 60 s/n</i>
1pce rear exhaust pipe	680.90	<i>? 24</i>
1pce rear exhaust pipe outer chrome	120.00	<i>? X</i>
2pcs rear exhaust pipe rubber holder@\$20	40.00	<i>? X</i>
1set rear shock absorber	398.00	<i>X</i>
	\$ 9,598.10	
	2,399.52	
	\$ 7,198.57	
Rear number plate with cover	100.00	<i>CRA - 35 s/n</i>
To rustproof	200.00	<i>100</i>
To check wiring	80.00	<i>30</i>
To remove/refit rear windscreen	140.00	<i>120</i>
To dismantle/renew reverse sensors	100.00	<i>60</i>
To dismantle/renew rear exhaust pipe	100.00	<i>60</i>
To remove/refit rear interior to effect repair	100.00	<i>60</i>
To dismantle/renew rear undercarriage	200.00	<i>X</i>
To computer wheel alignment	140.00	<i>X</i>
To remove/refit rear petrol tank to effect repair	200.00	<i>X</i>
To remove/refit roof insulator to effect repair	150.00	<i>X</i>
To dismantle/renew accident portion	1,800.00	<i>1200 1400</i>
To spray paint	1,800.00	<i>1200</i>
Total:	\$12,308.57	

SOON SAN MOTOR TRADING

Bik.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG BUILDING

Singapore 079120

Accident date:29/11/17

Date:29/01/18

Dear sir/madam:-

Accident involving SGU 5152T & SGY 9385R along JUNC OF PAYA LEBER RD AND AIRPORT RD.

We understand that you are the insurer of vel: SGY 9385R.

I/We wish to inform you that my/our vehicle SGU 5152T have been completed repair to my/our

Satisfaction by M/S SOON SAN MOTOR TRADING we therefore propose to claims from you as follow:-

Cost of repair	\$6,000.00
Car rental 1 day \$120 X 10	1,200.00
Loss of use 1day \$120 X 2	200.00
<hr/>	
Total:	\$7,400.00

Please let us have reply soonest possible

Thank you

Your faithfully

SOON SAN MOTOR TRADING
Signature

" The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG17022913/R1ua3

14 DECEMBER 2017

KOH PUAY HUA
BLK 601C PUNGGOL CENTRAL
#06-632
SINGAPORE 823601

Dear Sir/Madam,

ACCIDENT INVOLVING SGY 9385R & SGU 5152T ON 29/11/2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING
Case Handler
DID: 6841 2360
FAX: 6741 4108
Email: thinthin@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)


AUTHORIZATION TO ACT



I, Tan Chin Kok (the third party claimant) of EX 306 A, #1397 Anchorvale Lnk, S1 541306 (address), owner of SGU 5152T (vehicle no.) hereby authorize Soon San Motor Trading ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SGU 5152T that was damaged pursuant to the accident which occurred on 29/11/17 (date) along Paya Lebar Rd turning to Airport Rd (location) involving vehicle no/s SGY 9385R ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 30/11/2017 (day) of _____ (month) 20__ (year)


Signed by "the third party claimant"
(with chop if applicable)


Signed by "the workshop" 
(with chop)

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."

SOON SAN MOTOR TRADING

Block 3006, Ubi Road 1, #01-390, Singapore 407800

Tel : 68414555 Fax : 67473546

DISCHARGE VOUCHER

My / Our Toyota Vios
Claim No. Vehicle No. SGU 5152 T
I / We Tan chin Kok
NRIC No. S1574365D of BIK 306 A, #13-97
Anchorvale Link, S1 541306

hereby declares that I have received my / our motor vehicle No.
SGU 5152 T from the above company in satisfactory condition

after repairs and have no further claims what-so-ever for the repairs
done which have been involved in an accident on 29/11/17

The repairs were done to my satisfaction and what ever money due

Please pay to the repairers

Thank You.

Signature.....

Date : 11/12/17

" The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, SOON SAN MOTOR TRADING ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$ 6,000.00 (Repair Cost), S\$ 1,000.00 (Loss of Rental/Use), S\$ --- (Disbursement) for vehicle no. SGU 5152T that was damaged pursuant to the accident which occurred on 29/11/2017 (date) along AIRPORT ROAD (location) involving vehicle no/s SGY 9385R. This is pursuant to the inspection conducted on 01/12/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner TAN CHIN KOK ("the third party claimant") of vehicle no. SGU 5152T make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SGU 5152T (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 31 (day) of 01 (month) 2018 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."

SOON SAN MOTOR TRADING

Blok.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG BUILDING

Singapore 079120

Accident date:29/11/17


Date:29/01/18

Final bill cost to repair vehicle: SGU 5152T (Toyota Vios) claims under vehicle: SGY 9385R.

To lump sum repair

Total: \$6,000.00 nett

(Singapore Dollars: Six Thousand Only)


Signature

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



WIN WIN RENT-A-CAR PTE LTD

Invoice

TAN CHIN KOK
BLK 306 A ANCHORVALE LINK
#13-97
S(541306)

Invoice No : WPLIN0001637
Invoice Date : 11/12/2017
Due Date : 11/12/2017
VHA No : 1941
Referral ID : S021


Description :	Amount
Rental for 10 Day/s @ \$120 per Day	\$1,200

Vehicle No : SJH8287B

Vehicle Description : Honda Fit 1.3G A

Rental Period : 29/11/2017 to 09/12/2017

Total Amount Payable : \$1,200



WIN WIN RENT-A-CAR PTE LTD

8 Kaki Bukit Ave 4 #06-04 Premier@Kaki Bukit Singapore 415875



Tel: 6315 8479 H/P: 9833 0807

VHA No: 1941

10PLIN 1637

UEN: 201505115E

VEHICLE RENTAL AGREEMENT


HIRER'S PARTICULAR		Vehicle No: <u>STH82F7B</u> Replace Veh No:	
Name: (as in I/C) <u>TAN CHIN KOK</u>		Mileage Out: <u>150478</u> Mileage Out:	
NRIC/PASSPORT No: <u>1574365D</u>		Make & Model: <u>FIAT</u> Auto / Manual Group:	
Address (Res): <u>BLK 306A ANCHORAGE LINK #13-973 (34106)</u>		Out : Date <u>29/11/17</u> Time: <u>2250</u>	
Name & Address of Employer		HIRE / PERIOD EXPIRY Time:	
Occupation: Driving Exp:		NON-WAIVER EXCESS-\$ <u>2000/-</u>	
Driving Licence No: D/L Type: Local / International		CHARGES	
Issue Date: Date of Birth: <u>17/12/63</u>		Daily <u>10</u> @ \$ <u>120</u> per day <u>81200</u>	
Tel: (O) (R) HP / PG		Weekly @ \$ per week	
ADDITIONAL DRIVER'S PARTICULARS		Monthly @ \$ per month	
Name: (as in I/C)		Hours @ \$ per hour	
NRIC/PASSPORT No:		Others @ \$	
Address (Res):		CDW @ \$ per day/month	
Driving License No: D/L Type: Local / International		PAI @ \$ per day/month	
Issue Date: Date of Birth:		Delivery/Collection Service	
Occupation: Driving Exp:		SUB-TOTAL \$	
VEHICLE CHECK LIST		PETROL LEVEL	
D - DENTS S - SCRATCHES A - ACCIDENTS		Out E 1/4 1/2 3/4 F	
INDICATE: RIGHT FRONT TOP LEFT		In E 1/4 1/2 3/4 F	
		EXTENSION	
ACCESSORIES CHECK		Misc.	
<input type="checkbox"/> Ashtray <input type="checkbox"/> Cig Lighter <input type="checkbox"/> S/Tyre		TOTAL CHARGES \$	
<input type="checkbox"/> STD Tools <input type="checkbox"/> Jack <input type="checkbox"/> Hub Caps		Hirer's Signature 	
<input type="checkbox"/> Radio/Cass <input type="checkbox"/> CD <input type="checkbox"/> Cartridges		Additional Driver's Signature	

I have read and agree to the terms and condition on both sides of the agreement. If I have presented a charge/credit card for payment. I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given WIN WIN RENT-A-CAR PTE LTD in connection with this agreement is true.

IMPORTANT

- ONLY PERSON ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY. INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY WIN WIN RENT-A-CAR PTE LTD.

RETURN OF VEHICLE: THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN * SINGAPORE OF HIRER / DRIVER * FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO WIN WIN RENT-A-CAR PTE LTD AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	SIGNATURE OF HIRER/DRIVER
<u>9/12</u>	<u>1430</u>				

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Nov 2017 Edit Reg		01 Dec 2017 00:00 Edit Adj Rpt	S\$6,000.00 Edit Estimates	S\$6,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:		KOH PUAY HUA, ID: S01109211							
Main Claimant:		TAN CHIN KOK, ID: S1574365D							
Vehicle Reg. No.:		SGU5152T	Date of Loss:	29/11/2017 21:00 - :59					
Claim Type:		TP / 6931660072SG	Policy/Cover Note No.:	2100431396 (Comprehensive)					
Vehicle Reg. No. (Insured):		SGY9385R	Policy No. (Claimant):	7VPF1702070					
		Excess:							
Repairer:		Soon San Motor Trading (HQ) BLK 3006 UBI ROAD 1 #01-390, 408700 Ubi - Tel: 68414445							
Handling Insurer:		AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com							
Claimant's Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 13/12/2017]							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGU5152T (6931660072SG)**
[SGY9385R]
TP
TAN CHIN KOK
Nov 29 2017 9:00PM
[KOH PUAY HUA]
Soon San Motor Trading

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser
Letters/Correspondences					1 per page <input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	1	Edit	
Assessment Reports					1 per page <input type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	05/12/17 11:01	Accident Statement From: SC - Reg. No: SGY9385R, Claimant: KOH PUAY HUA	1	Load HTM	
Documentation					1 per page <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/12/17 11:03	TP GIA REPORT	1	Load PDF	
2	04/12/17 11:09	TP ESTIMATE - MARKED	1	Load PDF	
3	07/02/18 11:50	WORKSHOP INVOICE	1	Load PDF	
4	07/02/18 11:50	AUTHORISATION TO ACT FORM	1	Load PDF	
5	07/02/18 11:50	Release Voucher	1	Load PDF	
6	07/02/18 11:50	RENTAL RECEIPT	1	Load PDF	
7	07/02/18 11:50	LETTER TO OI	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGY9385R (Insd veh)	Model:	TOYOTA VIOS 1.5 J (A)
	SGU5152T (TP veh)		
Date of Accident:	29/11/2017		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	12,357.27
Final Repair Cost	:	\$	6,000.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	1,000.00 10 days
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	7,000.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Soon San Motor Trading	:	\$ 7,000.00
2)		:	\$

JOANNE LEE KHANG MIN

07 Feb
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG17022913/R1UA3Q2

Date: 07/02/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100431396
Claimant Vehicle No: SGU5152T **Insured Vehicle No:** SGY9385R
 Date of Loss: 29/11/2017 Nature of Claim: TP Claim No: 6931660072SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGU5152T**
 Make & Model: TOYOTA VIOS, 1.5 J (A) Engine No: 1NZX545876
 Reg. Date: 17/05/2007 (Man. Year: 2007) Chassis No: MR053HY9305001496
 Colour: Grey Odometer: 171477 km
 Engine Capacity: 1497 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15
 Front Left Side: Continental 5 mm Rear Left Side: Continental 5 mm
 Front Right Side: Continental 5 mm Rear Right Side: Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,347.27	4,736.22	2,611.05	35.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,010.00	3,030.00	1,980.00	39.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,357.27	7,766.22	4,591.05	37.15
Approved Total (Overridden) (S\$)		6,000.00		
Nett Amount (S\$)	12,357.27	6,000.00	6,357.27	51.45
+ Car Rental (10.0 x S\$100.00/day) (S\$)		1,000.00		
Nett Liability (S\$)		7,000.00		

INSPECTION

Date of Assignment: 01/12/2017
 Date Inspected: 01/12/2017 Inspected At: Soon San Motor Trading (HQ)
 BLK 3006 UBI ROAD 1 #01-390
 Singapore 408700
 Estimated Period of Repair: 12.0 days

Adjuster: MOHD RASUL

Manager: THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BOOT LID	Bent	601.75 FL	*601.75 FL
2	2	*BOOT LID HINGES	Serviceable	119.00 FL	*- FL
3	1	*BOOT LID TOP LOCK	Bent	95.10 FL	*95.10 FL
4	1	*BOOT LID LOWER LOCK	Bent	35.00 FL	*35.00 FL
5	1	*BOOT LID VIOS PLATE	Necessary	35.10 FL	*35.10 FL
6	1	*BOOT LID EMBLEM	Necessary	45.00 FL	*45.00 FL
7	1	*BOOT LID J PLATE	Necessary	20.20 FL	*20.20 FL
8	1	*BOOT LID CENTRE GARNISH COVER	Deformed	168.20 FL	*168.20 FL
9	2	*BOOT LID NUMBER LAMPS	Serviceable	84.20 FL	*- FL
10	1	*BOO LID RUBBER	Necessary	103.10 FL	*103.10 FL
11	1	*REAR FENDERS	O/S Bent / N/S Serviceable	1,609.60 FL	*804.80 FL
12	2	*REAR FENDER INNER TRIM COVER	Cut	490.20 FL	*490.20 FL
13	10	*REAR FENDER TRIM COVER CLIPS	Necessary	80.00 FS	*80.00 FS
14	2	*TAIL LAMPS	Broken	770.20 FL	*770.20 FL
15	1	*TAIL LAMPS INNER PANELS	N/S Bent / O/S Serviceable	170.40 FL	*85.20 FL
16	1	*REAR BUMPER	Deformed	398.10 FL	*398.10 FL
17	1	*SET REAR BUMPER REVERSE SENSORS	Not Working	337.50 FS	*200.00 FS
18	2	*REAR BUMPER REFLECTORS	Cracked	84.20 FL	*84.20 FL
19	2	*REAR BUMPER TOP SIDE CLIPS	Necessary	20.00 FS	*20.00 FS
20	10	*REAR BUMPER INNER CLIPS	Necessary	50.00 FS	*50.00 FS
21	2	*REAR BUMPER SIDE HOLDERS	Necessary	90.00 FL	*90.00 FL
22	2	*TAIL LAMP LOWER HOLDERS	Cracked	80.00 FL	*80.00 FL
23	1	*REAR PANEL	Bent	689.25 FL	*689.25 FL
24	1	*REAR PANEL LOWER LOCK COVER	Bent	85.90 FL	*85.90 FL
25	1	*REAR SPARE TYRE PANEL	Repair	880.90 FL	*- FL
26	1	*SET REAR SPARE TYRE PANEL PADDLING	Not Necessary	285.00 FL	*- FL
27	2	*REAR INNER SIDE HOLDERS	Deformed (1PCS ONLY)	428.40 FL	*214.20 FL
28	1	*REAR SPARE TYER TOP COVER	Serviceable	120.10 FL	*- FL
29	1	*REAR WINDSCREEN OUTER RUBBER	Necessary	85.10 FL	*85.10 FL
30	1	*REAR WINDSCREEN TAPE FROM	Necessary	45.10 FS	*45.10 FS
31	1	*REAR WINDSCREEN INNER SEALANT	Necessary	105.00 FS	*60.00 FS
32	1	*REAR EXHAUST PIPE	Bent	680.90 FL	*680.90 FL
33	1	*REAR EXHAUST PIPE OUTER CHROME	Serviceable	120.00 FL	*- FL
34	2	*REAR EXHAUST PIPE RUBBER HOLDER	Serviceable	40.00 FL	*- FL
35	1	*SET REAR SHOCK ABSORBER	Serviceable	398.00 FL	*- FL
36	1	*REAR NUMBER PLATE WITH COVER	Cracked	100.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,550.50	6,151.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,203.23	1,415.38
Total Parts (\$\$)	7,347.27	4,736.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RUSTPROOF	New	200.00	100.00
2	TO CHECK WIRING	New	80.00	30.00
3	TO REMOVE/REFIT REAR WINDSCREEN	New	140.00	120.00
4	TO DISMANTLE /RENEW REVERSE SENSORS	New	100.00	60.00
5	TO DISMANTLE /RENEW REAR EXHAUST PIPE	New	100.00	60.00
6	TO REMOVE/REFTI REAR INTERIOR TO EFFECT REPAIR	New	100.00	60.00
7	TO DISMANTLE/RENEW REAR UNDERCARRIAGE	New	200.00	0.00
8	TO COMPUTER WHEEL ALIGNMENT	New	140.00	0.00
9	TO REMOVE/REFIT REAR PETROL TANK TO EFFECT REPAIR	New	200.00	0.00
10	TO REMOVE /REFIT ROOF INSULATOR TO EFFECT REPAIR	New	150.00	0.00
11	TO DISMANTLE/RENEW ACCIDENT PORTION	New	1,800.00	1,400.00
12	TO SPRAY PAINT	New	1,800.00	1,200.00
Gross Labour Cost (S\$)			5,010.00	3,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >