

SOON SAN MOTOR TRADING

Bik.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG BUILDING

S,pore 079120

Accident date:29/11/17

Date:30/11/17

Estimate cost to repair vel: SGU 5152T (Toyota Vios) claims under vel: SGY 9385R.

1pce boot lid	\$ 601.75	BT ✓
2pcs boot lid hinges@\$59.50	119.00	X
1pce boot lid top lock	95.10	BT ✓
1pce boot lid lower lock	35.00	BT ✓
1pce boot lid vios plate	35.10	nee ✓
1pce boot lid emblem	45.00	nee ✓
1pce boot lid J plate	20.20	nee ✓
1pce boot lid centre garnish cover	168.20	DE ✓
2pcs boot lid number lamps@\$42.10	84.20	X
1pce boot lid rubber	103.10	nee ✓
2pcs rear fenders@\$804.80	1,609.60	RH-LA ✓ (1pc)
2pcs rear fender inner trim cover@\$245.10	490.20	wt ✓
10pcs rear fender trim cover clips@\$8	80.00	nee - s/n
2pcs tai lamps@\$385.10	770.20	hmo ✓
2pcs tai lamps inner panels@\$85.20	170.40	BT - LH ✓ (1pc)
1pce rear bumper	398.10	DE ✓
1set rear bumper reverse sensors	450.00 200	nee - s/n
✓ 2pcs rear bumper reflectors@\$42.10	84.20	CR4 ✓
2pcs rear bumper top side clips@\$10	20.00	nee - s/n
10pcs rear bumper inner clips@\$5	50.00	nee - s/n
2pcs rear bumper side holders@\$45	90.00	nee ✓
✓ 2pcs tai lamp lower holders@\$40	80.00	CR4 ✓
1pce rear panel	689.25	BT ✓
1pce rear panel lower lock cover	85.90	BT ✓
1pce rear spare tyer panel	880.90	R
1set rear spare tyer panel paddling	285.00	X

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390 SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG BUILDING

S,pore 079120

Accident date:29/11/17

Date:30/11/17

Rashid
Hp 90010068

12 days

L/S
01/12/17 @ 1150

Reply after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices subject to confirmation
- Third party settlement on a "Without Prejudice" basis
- No legal action(s) is allowed
- Supplemental claim(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate cost to repair vel: SGU 5152T (Toyota Vios) claims under vel: SGY 9385R.

2pcs rear inner side holders@\$214.20	\$ 428.40	page2 <i>OK (1pc)</i>
1pce rear spare tyer top cover	120.10	<i>X</i>
1pce rear windscreen outer rubber	85.10	<i>new</i>
1pce rear windscreen tape from	45.10	<i>new s/n</i>
1pce rear windscreen inner sealant	140.00	<i>new 60 s/n</i>
✓ 1pce rear exhaust pipe	680.90	<i>? 24</i>
✓ 1pce rear exhaust pipe outer chrome	120.00	<i>? X</i>
✓ 2pcs rear exhaust pipe rubber holder@\$20	40.00	<i>? X</i>
1set rear shock absorber	398.00	<i>X</i>
	\$ 9,598.10	
	2,399.52	
	\$ 7,198.57	
Rear number plate with cover	100.00	<i>CR4 - 35 s/n</i>
To rustproof	200.00	<i>100</i>
To check wiring	80.00	<i>30</i>
To remove/refit rear windscreen	140.00	<i>120</i>
To dismantle/renew reverse sensors	100.00	<i>60</i>
To dismantle/renew rear exhaust pipe	100.00	<i>60</i>
To remove/refit rear interior to effect repair	100.00	<i>60</i>
To dismantle/renew rear undercarriage	200.00	<i>X</i>
To computer wheel alignment	140.00	<i>X</i>
To remove/refit rear petrol tank to effect repair	200.00	<i>X</i>
To remove/refit roof insulator to effect repair	150.00	<i>X</i>
To dismantle/renew accident portion	1,800.00	<i>1200 1400</i>
To spray paint	1,800.00	<i>1200</i>
Total:	\$12,308.57	