

22/03/2002

ASS. REC. BY:

REF:

CS/FCL7022921/G0002

Special Instruction:

Surveyor: GR

ASSIGNMENT (Office)

From (Person): WG Karen Tan of FCL

Date/Time: 01.12.2017 633pm

Estimated Cost: Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

F5116K

Insured:

SHC 1066T

at Workshop m/s

Tong Ark Motor

Tel:

6337 9912

of

89 Short St #01-02/03

Policy No:

D-15072701MFSH

Claim No:

D17010320MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02.11.2017

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time:

04.12.2017 9:31am

Person Contacted:

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	F5116K - x
	SHC 1066T - CS / ATG14022925 / H11cm3.2
05/12/17 @	2.01pm REVERSED to Karen by email.

DS: 04/12/17

XPR

REP: FCL

ASSIGNMENT

C2022)

From: Date: 04-12-2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. F 5116K
at Workshop in Tong Ark Motor
of 89 Street St #01-02/03

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / FR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'DS'

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: F5116K Rep: 12 Jul 1982

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make: Vespa SPR 1 cc 150

Colour: Green A.O: Insured / Std / NI / NA

Sp. Reading: 30448 T.Radio: Insured / Std / NI / NA

Eng/No:

C No: 383940

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Good / Jammed / Leaked / Burnt or

Brakes: In Good / Jammed / Leaked / Burnt or

Modi: Mil S/Rim / STD A/Rim or

Tyre Size: F: 3.50-10

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. mm L/Bal. mm

D.O.A. D.O.I. 04-12-17

Survey held at w/s

Des. of Damages: Fr / Rear / D/S / N/S / U/C / Rooftop or

and

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Inspected at 1100 with 2nd. (Red \$ 885.90, 45%)

REC'D 21 JAN 2016

Date/Time File Pass to?

☐

: Preli. Report

☐

: Final Report

Date/Time File Return to?

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation

Printed

Checked

Total

Add Fee: ☐ Site Insp \$

☐ Interview \$

☐ Tech. Ins. \$

☐ Clean up \$

Report Format:

Lump Sum / I.B.H. \$

TP
1100

100

50

50

37


237

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17022921/Gqb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 04-12-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 1066T	Veh. Inspected	F 5116K
Policy No.		Coverage (\$)	0.00
Claim No.	D17010320MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	01/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	02/11/2017	Inspection Date	04/12/2017
Survey held at	TONG AIK MOTORS SUPPLY CO. 89 SHORT STREET GOLDEN WALL CENTER #05-07 SINGAPORE 180011		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Survey Department Check List (Case Handler)

Reference No.: *CA117022921 GNB*
 Policy Type: OD / TP / TP RES / TL / EVA

F5116k

Admin (*Cath*): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Case Handler		Typist	
Y-Date	N-Date	Y-Date	N-Date
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			

Surveyor (*Guo Bīang*): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

<i>✓</i>			
----------	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

<i>✓</i>			
----------	--	--	--

Check By: *[Signature]* *20/1/18*
 Case Handler Date

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	06-11-2017	Our Ref No. D17010320MFSH
Accident Date	02-11-2017	Claim Type. Third Party
Insured Vehicle	SHC1066T	Third Party Vehicle. F5116K
Survey Location	89 SHORT STREET #01-02/03 GOLDEN WALL CENTRE	
Contact Person.	NA	
Contact No.	6337 9912/ 0	Fax No. 6337 9246
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TONG AIK MOTOR SUPPLY CO	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/229860)



PRI Documents



Close



PRI Header Details

Claim No	D17010320MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & TO
Workshop Name	TONG AIK MOTOR SUPPLY CO (Contact Person : NA)	Survey Location & Contact Details	89 SHORT STREET #01-02/03 GOLDEN WALL (Mobile: 0 , Phone: 6337 9912 , Fax: 6337 92 EmailId: VESCOM100@HOTMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC1066T	TP Vehicle No	F5116k
PRI Recieved Date	01-12-2017 07:28:57 PM	Surveyor Appointed Date	01-12-2017 06:32:43 PM	Surveyor Accept Date	04-12-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	04-12-2017	Upload Survey Report *:	
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents

File Name

Action

Surveyor Job Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 5 December, 2017 2:21 PM
To: 'Claim Workflow System'; assignments
Cc: KARENTAN@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17010320MFSH/1
Attachments: CSFCI17022921Gqb.pdf

Dear Karen,

Enclosed herewith preliminary advice of F 5116K.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 4 December, 2017 9:34 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17010320MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Friday, 1 December, 2017 6:33 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; KARENTAN@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17010320MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17010320MFSH
Our Ref: CS/FCI17022921/Gqb

Date: 05 December 2017

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. F 5116K .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/12/2017 at the premises of M/s TONG AIK MOTOR . and have the following to report:-

Workshop Estimate Amount	: S\$ <u>1,985.90</u> .
Revised Estimate Amount	: S\$ <u>1,230.70</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the front portion and o/s body.



Yours faithfully

Guo Qiang
Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	8003Z

Vehicle Details

Vehicle No.	F5116K
Vehicle to be Exported	No
Intended De-registration Date	05 Dec 2017
Vehicle Make	VESPA
Vehicle Model	SPRI
Primary Colour	Silver
Manufacturing Year	1982
Engine No.	389142
Chassis No.	383940
Maximum Power Output	-
Open Market Value	\$0.00
Original Registration Date	12 Jul 1982
First Registration Date	12 Jul 1982
Transfer Count	4
Actual ARF Paid	\$0.00

Intended PARF Rebate Details

PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	30 Jun 2022
COE Category	D - Motorcycle
COE Period(Years)	10
PQP Paid	\$1,871.00
COE Rebate Amount	\$1,122.00
Total Rebate Amount	\$1,122.00

The information contained herein is correct as at 05 Dec 2017

OK



**SINGAPORE
POLICE FORCE**



T/20171105/2118

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

4 of 4

Report No. T/20171105/2118

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 1 WOOL ZHAO HONG

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

05/11/2017 19:16

Officer In Charge Of Case:

TP / GIT /

Insp NORHIDAWATI BINTE AHMAD

Contact No.: 65476310

Classification Of Case:

SN 008

Authentication Stamp

NP168

Signature

Singapore Police Force



SINGAPORE POLICE FORCE



T/20171105/2118

1 of 4

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

Report No. T/20171105/2118

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/11/2017 19:16			Vide Report No.: F/20171102/0194		Station Diary No.: 85
Name of Informant: DENNIS FOO FONG SOON			Address: APT BLK 360C ADMIRALTY DRIVE #03-38 SINGAPORE 753360		
ID Type / ID No.: NRIC NO / S7818003Z			Contact No.: Home/Office: Mobile: 90934625		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 39	Date of Birth: 22/06/1979	Type of Informant: Rider		
Race: Chinese			Language: English	Institution / School Name:	
Occupation: FITNESS TRAINER			Driving Licence Information: Class: 2B Date of Expiry:		

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 02/11/2017 20:30	Type of Location: T-Junction
Location: Junction of Road 1 and Road 2 SELETAR WEST LINK SELETAR AEROSPACE DRIVE T Junction				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: Yes

Vehicle No.	Vehicle Type	Make	Model	Color	Damage	No. of Persons Injured
F5116K	Motorcycle	VESPA	SPRI	Silver	Seriously Damaged	0
SHC1066T	Car	HYUNDAI		Blue	Slightly Damaged	1

Vehicle No.	Insurer	Policy No.	Start Date	End Date
F5116K	NTUC Income Insurance Co-Operative Limited	5064499101-03	04/03/2017	03/03/2018



SINGAPORE POLICE FORCE



T/20171105/2118

2 of 4

Report No. T/20171105/2118

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

CONTINUATION OF REPORT

Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	DENNIS FOO FONG SOON	ID No.	S7818003Z
Related Vehicle	F5116K (Motorcycle)	Contact No.	90934625
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	02/11/2017	Date Discharge	03/11/2017
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Name	LIM YONG SENG	ID No.	S7497118J
Related Vehicle	SHC1066T (Car)	Contact No.	98202209
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 02/11/2017 at about 2030hrs, I was riding my Piaggio Vespa mint green in colour F5416K along the extreme left lane along Seletar West Link. Just when my vehicle was approaching the T-junction of Aerospace Drive, I saw the traffic light at the junction turned Green. I then slowed down my vehicle as I was approaching the junction and I was going straight. However, I noticed that on the middle lane, there are a row of vehicles which was moving off when the traffic light turned Green.

Out of sudden, a Hyundai taxi from the middle lane from the row of vehicles suddenly turned left and cut into my lane and side swipe my vehicle causing me to fall. The taxi driver then stopped his vehicle along Aerospace Drive near to the T-junction and he came out to assist me. I was conscious after the collision but my motorcycle was unable to start. I have exchanged particulars with the taxi driver and also took some photographs of the scene.

I then check the damage on my motorcycle and realized that my motorcycle have sustained the following damages:

- 1) The rim came off;
- 2) Right handle broken;
- 3) Right mirror broken;
- 4) Right signal light broken;
- 5) Right frame broken;



**SINGAPORE
POLICE FORCE**



T/20171105/2118

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

3 of 4

Report No. T/20171105/2118

CONTINUATION OF REPORT

- 6) ERP unit broken;
- 7) Engine unable to start.

A passerby saw the accident and assisted to call for ambulance. Shortly after, the Traffic Police and ambulance arrived at the scene. I was conveyed to Khoo Teck Puat Hospital with abrasion on my right palm, my left elbow and both knees and toes. I was then discharged on the 03/11/2017 morning about 0130hrs and was given 3 days MC. While I was in the A&E, I received a call from TP IO Dylan and he advised me to lodge a Traffic Accident Report reference incident F/20171102/0194.

I would like to inform that the Taxi driver has a male passenger at the front passenger seat. However, both of them were not injured. The two left passenger doors of the Taxi sustained some scratches.

TONG AIR MOTORS SUPPLY CO

the Repairer of the following:
 • Parts prices are subject to confirmation
 • Third party survey is on a "No Fault" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurer

89, Short Street, #01-02/03

Golden Wall Centre

Singapore 188216

Acknowledged by Repairer: 63379912 / 63370201 Fax: 63379246

Signature: E-mail: vescom100@hotmail.com

Date:

4 Days business repair.

04/12/17

Que Corp.

5/12/17

To: FIRST Capital Insurance

Attention: Motor Claim Dept

Quotations To Repair Scooter F5116K With Your Insured Vehicle SHC1066T

Quotations To Repair Scooter F5116K

- 1) Change 1p Front mudguard x ^{Front mudguard} \$ 78.00
- 2) Change 1p, RH lever / ^{RH Lever} \$ 12.50
- 3) Change 1p RH Mirror / ^{RH Mirror} Cut \$ 36.00
- 4) Change 1p set Floor rail / ^{Floor rail} Cut \$ 88.00
- 5) Change 1p Front shield / ^{Front Shield} Cut \$ 38.00
- 6) Change 1p Kick starter / ^{Kick starter} BT \$ 68.50

Beading Beeding
 Kick starter Pedal
 321-00 243
 32-10

7) Align ft fork & handle
 Alignment alignment

288.90 218.7
 145.00 60

8) Knocking Front Body tie
 floorboard RH side
 floorboard cont. cont.

320.00 ~~200~~ 250

9) Spray

800.00 ~~400~~ 500

10) Transport 2 way 10AC -shop

80.00 /

11) Labour charges

180.00 100

12) Change 1p Ft. no plate ^{Nec}

12.00 /

13) Change 1p ERP IU unit

160.00 /

\$ 1985.90

1280.7

20% 1100

Remarks: any new unsecured damaged item during the process of repair, a supplementary quotation will be advise.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FC117022921/Gqbe2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 02-02-2018	
			Code : FC12	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1066T	Veh. Inspected	F 5116K	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17010320MFSH	Excess (\$)	0.00	
Assign From	KAREN TAN	Assign Date	01/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	VESPA SPRI	c.c	150	
Engine No.	HIDDEN	Year of Reg.	1982	
Chassis No.	383940	Colour	GREEN	
Odometer	30448	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	3.50-10	DUNLOP	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	3.50-10	DUNLOP	5 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/11/2017	Inspection Date	04/12/2017	
Survey held at	89 SHORT ST #01-02/03			
Repairer	TONG AIK MOTORS SUPPLY CO.			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. F 5116K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT MUDGUARD	TO REPAIR SEE LABOUR	78.00	-
1	RH LEVER	BROKEN	12.50	12.50
1	RH MIRROR	CUT	36.00	36.00
1	SET FLOOR RAIL	CUT	88.00	88.00
1	FRONT SHIELD BEADING	CUT	38.00	38.00
1	KICK STARTER PEDAL	BENT	68.50	68.50
	LESS 10% DISCOUNT		-32.10	-24.30
			288.90	218.70
	<u>SPECIAL NETT ITEMS</u>			
1	FRT NO. PLATE (SN)	NECESSARY	12.00	12.00
			12.00	12.00
	<u>LABOUR</u>			
	FRT FORK & HANDLE ALIGNMENT.		145.00	60.00
	KNOCKING FRONT BODY TIE FLOORBOARD RH SIDE COWL. INCLUSIVE OF THE REPAIR OF FRONT MUDGUARD.		320.00	250.00
	SPRAY.		800.00	500.00
	TRANSPORT 2 WAY IDAC - SHOP.		80.00	80.00
	LABOUR CHARGES.		180.00	100.00
	CHANGE 1PC ERP IU UNIT.		160.00	160.00
			1,685.00	1,150.00
	GRAND TOTAL		1,985.90	1,380.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,100.00

Report Ref No. CS/FC117022921/Gqbe2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.