

22/03/2002

ASS. REC. BY:

REF:

CS/AXA17022933 / Sgb n2

Special Instruction:

Surveyor

Sebastian

ASSIGNMENT (Office)

Munimen

From (Person):

Yvonne Ang

of

AXA

Date/Time: 01-12-2017 4:55pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SBP 36P

Insured:

at Workshop m/s

Trans Eurokars

Tel:

6360 2846

of

12 Sungai Kadut Ave

Policy No:

P815926

Claim No:

C0461413

Sum Insured:

Excess:

RM 4000.00

Make of Veh:

D.O.A.

28-11-2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

04-12-17 9:08am

Person Contacted:

Eva

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	Pending Driving Licence
	SBP 36P - x	
05/12/17 @ 3:28pm	revert to Yvonne Ang via Munimen.	
06/12/17 @ 2:14pm	checked with Birdie Ong, can proceed authorize repair	
06/12/17 @ 2:18pm	Informed Eva C/A to Ex: \$4000 by email.	
30/4/18 @ 1:20pm	2nd revert to Yvonne Ang via Munimen. (Supplementary).	
30/5/18 @ 3:48pm	Yvonne Ang informed C/A at \$46899.36 via Munimen.	

Mafman

ASSIGNMENT

From: _____ Date: 04.12.2017

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SBP 36P

at Workshop m/s

Eurekars

of

12 Dungei Kadut Ave

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

4000.00


(Client's Record)

Make of Veh: _____

Pending Driving License

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

\$330K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SBP36P

Yr Regn: 1/8/2016

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Porsche Cayman GT4 cc 3800

Colour: Black. A/C Insured / Std / NI / NA

Sp. Reading 10328 T/Radio: Insured / Std / NI / NA

Eng/No: _____

O/No: WP02229829K190037

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/35 ZR20

R: 295/30 ZR20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Dunlop

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 28/11/2017 D.O.I. 4/12/2017

Survey held at Eurekars

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

31/5/18 @ 10.43am confirmed with Jessica Anai Ag B 46899.36, 11 days.
 CRD @ 13157.42, 22%

RECEIVED 26 JUN 2018

Date/Time File Pass to?

☐ : Preli. Report
☐ : Final Report

Date/Time File Return to?

2

Days Of Repair: 11

Resurvey No. of Trip: 2

Survey Fee:

Transportation

Add Fee:

☐ Site Insp. \$
☐ Interview \$
☐ Tech. Insp. \$
☐ Weekend \$

S - RS \$

Phone

Others

Report Format: MER-0D

Lump Sum / I.B.I. \$

46899.36

TOTAL

300

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/AXA17022923/Sqb

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 04-12-2017



Code : AXA2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SBP 36P
Policy No.	P1815926	Coverage (\$)	0.00
Claim No.	C0461413	Excess (\$)	4,000.00
Assign From	MERIMEN (YVONNE ANG)	Assign Date	01/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	28/11/2017	Inspection Date	04/12/2017
Survey held at	TRANS EUROKARS PTE LTD 12 SUNGEI KADUT AVE SINGAPORE 729648		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Richard Ang

Date: 30 Apr 2018

Preliminary Advice

Vehicle No : SBP36P
Make : PORSCHE CAYENNE
Assignment Date : 01/12/2017
Date of Inspection : 04/12/2017
Inspection At : TRANS EUROKARS

Accident Date : 28/11/2017
Policy No. : P1815926
Excess : S\$4,000.00
Est. Duration of Repair : 11.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	60,056.78	(ESTIMATE \$42,164.08 + SUPPLEMENTARY \$17,892.70)
Revised Amount	:S\$	46,899.36	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	46,899.36	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	330,000.00
COE / PARF Rebate	:S\$	166,843.00
Salvage Value	:S\$	
Margin for Repair	:S\$	163,157.00

Remarks

- (X) The vehicle is repairable at our adjusted amount.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Kindly let us have your authorisation on supplementary.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Birdie Ong Lay Hong

Date: 05 Dec 2017

Preliminary Advice

Vehicle No	: SBP36P	Accident Date	: 28/11/2017
Make	: PORSCHE CAYENNE	Policy No.	: P1815926
Assignment Date	: 01/12/2017	Excess	: S\$4,000.00
Date of Inspection	: 04/12/2017	Est. Duration of Repair	: 11.00
Inspection At	: TRANS EUOKARS		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	42,164.08
Revised Amount	:S\$	30,561.92
Check Items (Estimated)	:S\$	3,792.80
Total	:S\$	34,354.72

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	330,000.00
COE / PARF Rebate	:S\$	166,843.00
Salvage Value	:S\$	
Margin for Repair	:S\$	163,157.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : WE HAVE INSPECTED THE VEHICLE SBP 36P ON 04/12/2017 AT 11.39am. DRIVER'S DRIVING LICENSE COPY UPLOADED.

...CLAIM SUBFOLDER...(New Assignment)

Pending Driver License

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Dec 2017		01 Dec 2017 16:55 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MADELIENE LEE SUH SHIN, ID: S1555936E, Tel: +6598486336		
Vehicle Reg. No.:	SBP36P	Date of Loss:	28/11/2017 11:00 - :59
Claim Type:	OD / C0461413	Policy/Cover Note No.:	P1815926 (Comprehensive)
		Excess:	S\$4,000.00
Repairer:	- Not Applicable - (-)		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Yvonne Ang Ching Ching - 6880 4461]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/12/2017]		
Driver/Custodian:	MADELIENE LEE SUH SHIN (), NRIC: S1555936E, Tel: +6598486336		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SG AXA Insurance SM AXA SGP - Motor Survey

From: eva.kok@eurokars.com.sg
Sent: Friday, December 01, 2017 2:24 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: janice.syn@porsche.com.sg; rickteo@eurokars.com.sg
Subject: Claiming Own Damage for Vehicle No: SJD831D Policy Holder: MADELIENE LEE SUH SHIN
Attachments: ESTIMATE- SBP36P.pdf
Categories: Kushal

Dear Sir / Mdm,

RE: Claiming Own Damage for Vehicle No: SBP36P Policy Holder: MADELIENE LEE SUH SHIN

We write to request your kind attention to the above

Attached you will find the necessary documents for your kind perusal and approval.

Kindly arrange for a survey to the said vehicle at 12 Sungei Kadut Ave Singapore 729648. (vehicle in our workshop)

Should you have any queries, please feel free to call the under sign.

Please avoid 12pm – 1pm lunch hour.

Thank you.

Eva Kok
Insurance Claims Officer
Trans Eurokars Pte Ltd
12 Sungei Kadut Avenue
Singapore 729648
Dir: +65 6360 2846 Fax: +65 6369 3003 Email: eva.kok@eurokars.com.sg
Website: www.eurokarsgroup.com



*****DISCLAIMER*****

This email and any attachments there to be intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group.
Any use of the information contained herein (including, but not limited to, total or partial reproduction, communication, or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you have received this email in error, please notify the sender immediately and delete it.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 31 May 2018 10:42 AM
To: jessicahs@eurokars.com.sg
Cc: stanley@eurokars.com.sg; SUR
Subject: RE: FINALIZATION AXA OD - SBP36P.xls

Dear Jessica,

Confirm final fig \$46,899.36 before excess \$4,000.00 & GST and 11 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jessicahs@eurokars.com.sg [mailto:jessicahs@eurokars.com.sg]
Sent: Wednesday, 16 May 2018 10:37 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: stanley@eurokars.com.sg; SUR <sur@lkkauto.com>
Subject: RE: FINALIZATION AXA OD - SBP36P.xls

Dear Shiau Chan,

Can we have this confirmation.

It's almost one month already.

Thank you very much.

Regards,

Jessica Shastri

Admin Executive – Insurance Claims

Eurokars Group of Companies

(Porsche, Rolls Royce, Saab, Mini, Mazda, Mc.Laren)

Eurokars Centre

12 Sungei Kadut Avenue

Singapore 729648

Tel: +65 63633003

DID: +65 63602863

Fax: +65 63602899

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Friday, April 27, 2018 6:02 PM
To: Jessica Harry Shastri <jessicahs@eurokars.com.sg>

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	01 Dec 2017 14:47	Cim Veh Model Changed	(200730) PORSCHE CAYENNE TURBO (A).		[I] Kushal Shah
2	01 Dec 2017 14:47	Cim Created	Reg No: SBP36P. Policy No: P1815926. Acct Date: 2017/11/28. Claim Type: OD. Insurer: AXA Insurance Pte Ltd (HQ). Ins.Status => Incoming Claim		[I] Kushal Shah
3	01 Dec 2017 16:55	Cim Registration Modified	Excess: 0.00 -> 4000.00.		[I] Yvonne Ang Ching Ching
4	01 Dec 2017 16:55	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ);; RR Region: Ext Adj. Suggested Adj. : Chow Automobile Assessor & Surveyor.		[I] Yvonne Ang Ching Ching
5	01 Dec 2017 16:55	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/12/12		[I] Yvonne Ang Ching Ching
6	01 Dec 2017 16:55	Adj Mandate Set	Approved:40000.00.Reinsp:Adj decides.		[I] Yvonne Ang Ching Ching
7	01 Dec 2017 17:02	Assignment 1st Accessed			[A] CATHERINE CHONG KAI LING
8	04 Dec 2017 13:15	Adj Adjuster Assigned	[None] -> Sebastian Yeang Wai Keen		[A] CATHERINE CHONG KAI LING
9	05 Dec 2017 13:56	Adj Rpt Initiated			[A] SHIAU CHAN
10	05 Dec 2017 13:56	Cim Details Notified			[A] SHIAU CHAN
11	05 Dec 2017 15:27	Cim Registration Modified	Rep:1137->200406.		[I] Birdie Ong Lay Hong
12	05 Dec 2017 15:28	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/12/12		[A] SHIAU CHAN
13	05 Dec 2017 15:28	Adj Mandate Request	Cur.Reg:34354.72:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE INSPECTED THE VEHICLE SBP 36P ON 04/12/2017 AT 11.39am. DRIVER'S DRIVING LICENSE COPY UPLOADED.		[A] SHIAU CHAN
14	06 Dec 2017 14:14	Adj Mandate Request Cancelled			[A] SHIAU CHAN
15	06 Dec 2017 14:27	Ins Rep Instructions Sent	Pending claim approval		[A] SHIAU CHAN
16	30 Apr 2018 13:19	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/12/12		[A] SHIAU CHAN
17	30 Apr 2018 13:20	Adj Mandate Request	Cur.Reg:46899.36:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. Kindly let us have your authorisation on supplementary.		[A] SHIAU CHAN
18	30 May 2018 15:48	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/12/12		[I] Yvonne Ang Ching Ching
19	30 May 2018 15:48	Adj Mandate Set	Approved:46899.36.		[I] Yvonne Ang Ching Ching

Date From



Date To



Audit Type None

Go

ACTIVITY

[06/12/2017 14:27] SHIAU CHAN:
WE HAVE AUTHORISE REPAIR ON 06/12/2017 AT 2.18pm.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1658344	05/12/2017 13:56	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SBP36P		10.70

Shiau Chan (LKKAUTO)

From: ANG Richard <richard.angbs@axa.com.sg>
Sent: Wednesday, 30 May 2018 3:35 PM
To: Shiau Chan (LKKAUTO); Bryan Ang (LKKAUTO)
Cc: ANG Yvonne; KHOR Saw Theng; TAN Mary; TAN Jas; Olivia Lau (LKKAUTO); SUR
Subject: RE: FINALIZATION AXA OD - SBP36P.xls

Dear Shiau Chan,

Your email of even date refers.

The supplementary items are approved. Please proceed to finalise the repair cost with the workshop.

Thank you.

Regards,

Richard Ang | Specialist, Motor (Property) Claims
AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg
Email: richard.angbs@axa.com.sg
Customer Care No. 1800 8804888



**GLOBAL INSURANCE
BRAND
FOR THE 8TH
CONSECUTIVE YEAR**

Please consider the environment before printing this message

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Wednesday, May 30, 2018 9:51 AM
To: ANG Richard <richard.angbs@axa.com.sg>; Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>
Cc: ANG Yvonne <yvonne.ang@axa.com.sg>; KHOR Saw Theng <sawtheng.khor@axa.com.sg>; TAN Mary <mary.tan@axa.com.sg>; TAN Jas <jas.tan@axa.com.sg>; Olivia Lau (LKKAUTO) <olivialau@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: FINALIZATION AXA OD - SBP36P.xls

Dear Richard,

According to our surveyor, at the time of inspection, the insured's vehicle was test driven and found to veer gradually to the left. Upon making a U-turn, the steering wheel could not automatically return to centre. Some manual pulling of the steering wheel had to be done.

In order to identify the root cause, an alignment test was done. The results shown in the attachment is the result of the insured's vehicle, where value stated in red is out of spec.

Trans Eurokars tried to align the undercarriage parts back to the original position, however they unable to do so. Furthermore, the steering system of the vehicle is electronically controlled. Electronically controlled system is very sensitive towards impact, no doubt there is no physical damage visible but it is possible for the impact force to cause electronic damage.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ANG Richard [<mailto:richard.angbs@axa.com.sg>]

Sent: Wednesday, 30 May 2018 9:33 AM

To: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>

Cc: ANG Yvonne <yvonne.ang@axa.com.sg>; KHOR Saw Theng <sawtheng.khor@axa.com.sg>; TAN Mary <mary.tan@axa.com.sg>; TAN Jas <jas.tan@axa.com.sg>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; Olivia Lau (LKKAuto) <olivialau@lkkauto.com>

Subject: RE: FINALIZATION AXA OD - SBP36P.xls

Importance: High

Hi Bryan,

We spoke on 28.5.18.

Please let us have your surveyor's reply by today.

Thank you.

Regards,

Richard Ang | Specialist, Motor (Property) Claims

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg

Email: richard.angbs@axa.com.sg

Customer Care No. 1800 8804888



**GLOBAL INSURANCE
BRAND
FOR THE 8TH
CONSECUTIVE YEAR**

Please consider the environment before printing this message

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: jessicahs@eurokars.com.sg [<mailto:jessicahs@eurokars.com.sg>]

Sent: Monday, May 28, 2018 2:38 PM

To: stanley@eurokars.com.sg; KHOR Saw Theng <sawtheng.khor@axa.com.sg>

Cc: sur@lkkauto.com; bryanang@lkkauto.com; siewsc@lkkauto.com; olivialau@lkkauto.com; TAN Mary <mary.tan@axa.com.sg>; NG Stacey <stacey.ng@axa.com.sg>; ANG Yvonne <yvonne.ang@axa.com.sg>

Subject: RE: FINALIZATION AXA OD - SBP36P.xls

Dear Saw Theng,

Can we have the confirmation ? We have been patiently waiting but still no respond from yoursides.

Thank you very much.

Regards,

Jessica Shastri

Admin Executive – Insurance Claims

Eurokars Group of Companies

(Porsche, Rolls Royce, Saab, Mini, Mazda, Mc.Laren)

Eurokars Centre

12 Sungei Kadut Avenue

Singapore 729648

Tel: +65 63633003

DID: +65 63602863

Fax: +65 63602899

From: Jessica Harry Shastri

Sent: Friday, May 25, 2018 9:34 AM

To: Stanley Ngu <stanley@eurokars.com.sg>; sawtheng.khor@axa.com.sg

Cc: SUR <sur@lkkauto.com>; Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Olivia Lau (LKKAUTO) <olivialau@lkkauto.com>; mary.tan@axa.com.sg; stacey.ng@axa.com.sg; ANG Yvonne <yvonne.ang@axa.com.sg>

Subject: RE: FINALIZATION AXA OD - SBP36P.xls

Dear Saw Theng,

The below matter refers.

We have yet to receive the mandate from your office. Please assist.

Thank you very much.

Regards,

Jessica Shastri

Admin Executive – Insurance Claims

Eurokars Group of Companies

(Porsche, Rolls Royce, Saab, Mini, Mazda, Mc.Laren)

Eurokars Centre

12 Sungei Kadut Avenue

Singapore 729648

Tel: +65 63633003

DID: +65 63602863

Fax: +65 63602899

From: Stanley Ngu

Sent: Tuesday, May 22, 2018 11:15 AM

To: sawtheng.khor@axa.com.sg

Cc: SUR <sur@lkkauto.com>; Jessica Harry Shastri <jessicahs@eurokars.com.sg>; Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Olivia Lau (LKKAUTO) <olivialau@lkkauto.com>; mary.tan@axa.com.sg; stacey.ng@axa.com.sg; ANG Yvonne <yvonne.ang@axa.com.sg>

Subject: RE: FINALIZATION AXA OD - SBP36P.xls

Dear Saw Theng

Shiau Chan (LKKAUTO)

To: ANG Richard; SUR
Cc: ANG Yvonne
Subject: RE: AXA Ref: C0461413. OD Survey for SBP36P - Mandate request

Dear Richard,

According to our surveyor, at the time of inspection, the insured's vehicle was test driven and found to veer gradually to the left. Upon making a U-turn, the steering wheel could not automatically return to centre. Some manual pulling of the steering wheel had to be done.

In order to identify the root cause, an alignment test was done. The results shown in the attachment is the result of the insured's vehicle, where value stated in red is out of spec.

Trans Eurokars tried to align the undercarriage parts back to the original position, however they unable to do so. Furthermore, the steering system of the vehicle is electronically controlled. Electronically controlled system is very sensitive towards impact, no doubt there is no physical damage visible but ~~is~~ possible for the impact force to cause electronic damage.

It is

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)

Sent: Thursday, 3 May 2018 4:40 PM

To: ANG Richard <richard.angbs@axa.com.sg>; SUR <sur@lkkauto.com>

Cc: ANG Yvonne <yvonne.ang@axa.com.sg>

Subject: RE: AXA Ref: C0461413. OD Survey for SBP36P - Mandate request

Dear Richard,

Thank you for the email.

We will check and revert to you.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ANG Richard [<mailto:richard.angbs@axa.com.sg>]

Sent: Thursday, 3 May 2018 4:35 PM

To: SUR <sur@lkkauto.com>

Cc: ANG Yvonne <yvonne.ang@axa.com.sg>

Subject: AXA Ref: C0461413. OD Survey for SBP36P - Mandate request

Dear all,

Measurement printout

VAS car standard measurement
 Beissbarth & VAS 6767 (SL)
 M * R * * OK * VOLKSWAGEN AG / 23.00 / 2534 / C
 Date: 05.01.2018 14:23:19
 Version (program) v3.003102/v3.003102
 Version (FW) v5.0b1604

VOLKSWAGEN AG

Version (target data) VOLKSWAGEN AG v23.00
 Serial number 0Y9803098
 Last service 12.08.2017
 STUTTGART AUTO PTE LTD
 12 SUNGEI KADUT AVENUE
 SINGAPORE

SINGAPORE			
Customer	Order		
Vehicle	WP0ZZZ9BZGK190037	Operator:	29696
VIN:	SBP36P		
Registration:	10330 KM		
Odometer:			
Vehicle:	VOLKSWAGEN AG v23.00		
Reason:	PORSCHE * 981 Cayman GT4 * Production: 2015 - * 20"		
	CHANGE RL, FL WHEEL RIM		
Rear Axle	Initial Measurement	Target Data	Final Measurement
Camber	left	-0°05' [-1°30'] +0°05'	-1°30'
	right	[0°05']	-1°32'
Cross Camber	left	-0°01' [+0°05'] +0°01'	+0°05'
	right	[0°10']	+0°08'
Individual Toe	left	-0°02' [+0°10'] +0°02'	+0°00'
	right		+0°09'
Cross Toe	left	-0°08'	-0°15'
	right		+0°00'
Total Toe			
Setback			
Geometrical driving axis			
Front Axle	Initial Measurement	Target Data	Final Measurement
Castor 20°	left	-0°30' [+10°00'] +0°30'	+9°24'
	right		+9°23'
K.P.I. 20°	left		+17°16'
	right		+17°15'
Toe out on turns	left	-0°30' [-1°22'] +0°30'	-1°21'
	right		-1°25'
Camber	left	-0°03' [-1°30'] +0°03'	-1°32'
	right	[0°03']	-1°33'
Cross Camber	left		+0°01'
	right	-0°01' [+0°01'] +0°01'	+0°00'
Individual Toe	left	-0°02' [+0°02'] +0°02'	+0°00'
	right		+0°07'
Total Toe			
Setback			
Included Angle 20°	left		+15°44'
	right		+15°43'
Max Steer to Left	left		+36°48'
	right		+32°23'
Max Steer to Right	left		+31°14'
	right		+35°00'

Measurement printout

VAS car standard measurement

Baseline © - VAS 6167 (SL)
M+R+OK - VOLKSWAGEN AG / 23.00 / 2524 / C
Date: 05.01.2018 14:23:19
Version (program)
v5.0a3102/v5.0a3102

Version (FWA)
v5.0a1804

Version (target data)
VOLKSWAGEN AG v23.00

Serial number
QY9800368

Last service
12.08.2017

VOLKSWAGEN AG

STUTTGART AUTO PTE LTD
12 SUNGEI KADUT AVENUE
SINGAPORE

Customer

Vehicle

VIN:

Registration:

Odometer:

Vehicle:

Reason:

WP0ZZZ98ZGK190037

S8P26P

10330 KM

VOLKSWAGEN AG v23.00

PORSCHE * 981 Cayman GT4 * Production: 2015 - * 20"

CHANGE RL, FL WHEEL RIM

Order

Operator:

29696

Vehicle / Tyre inspection

Front Axle

Tyre Manufacturer

Tyre Pressure

DUNLOP

2.0 BAR

DUNLOP

2.0 BAR

Rear Axle

Tyre Manufacturer

Tyre Pressure

DUNLOP

2.3 BAR

DUNLOP

2.3 BAR

Measurement printout

VAS car standard measurement

Bersterb © VAS 8767 (SL)

M * R+ ** OK * VOLKSWAGEN AG / 23.00 / 2024 / C

Date: 05.01.2018 14:23:19

Version (program)	Version (FWW)	Version (target data)	Serial number	Last service
v5.0b2102v5.0b3102	v5.0b1604	VOLKSWAGEN AG v23.00	Q70600086	12.08.2017

VOLKSWAGEN AG

STUTTGART AUTO PTE LTD
12 SUNGELI KADUT AVENUE
SINGAPORE

Customer

Vehicle

VIN: WP0ZZZ9BZGK190037

Registration: SBF36P

Odometer: 10330 KM

Vehicle: VOLKSWAGEN AG v23.00

Porsche * 981 Cayman GT4 * Production: 2015 - * 20*

Reason: CHANGE RL, FL WHEEL RIM

Rear Axle		Initial Measurement	Target Data	Final Measurement
Camber	left	-1°22'	-0°05' [-1°30'] +0°05'	-1°30'
	right	-1°36'		-1°32'
Cross Camber		+0°13'	[0°05']	+0°02'
Individual Toe	left	+0°14'	-0°01' [+0°05'] +0°01'	+0°05'
	right	-0°02'		+0°08'
Cross Toe		+0°15'	[0°16']	+0°00'
Total Toe		+0°12'	-0°02' [+0°16'] +0°02'	+0°09'
Setback		-0°09'		-0°15'
Geometrical driving axis		-0°08'		+0°00'
Front Axle		Initial Measurement	Target Data	Final Measurement
Caster 20°	left	+9°41'	-0°30' [+10°00'] +0°30'	+9°24'
	right	+9°33'		+9°23'
K.P.I. 20°	left	+2°58'		+17°16'
	right	+1°49'		+17°15'
Toe out on turns	left	-1°17'	-0°30' [-1°22'] +0°30'	-1°21'
	right	-1°28'		-1°25'
Camber	left	-1°31'	-0°03' [-1°30'] +0°03'	-1°32'
	right	-1°37'		-1°33'
Cross Camber		+0°05'	[0°03']	+0°01'
Individual Toe	left	-0°22'	-0°01' [+0°01'] +0°01'	+0°00'
	right	-0°16'		+0°00'
Total Toe		-0°40'	-0°02' [+0°02'] +0°02'	+0°00'
Setback		-0°03'		-0°07'
Included Angle 20°	left	+1°27'		+15°44'
	right	+0°11'		+15°43'
Max Steer to Left	left	+36°54'		+36°48'
	right	+32°23'		+32°23'
Max Steer to Right	left	+31°17'		+31°14'
	right	+35°08'		+35°00'

Measurement printout

VAS car standard measurement

Beleborn © * VAS 6787 (SL)

M * R * * * OK * VOLKSWAGEN_AG / 23.00 / 2524 / C

Date: 05.01.2018 14:23:19

Version (program)	Version (FWA)	Version (target date)	Serial number	Last service
v3.0b3102/v3.0b3102	v3.0b1804	VOLKSWAGEN_AG v23.00	Q71860366	12.08.2017

VOLKSWAGEN AG

Customer			
Vehicle		Order	
VIN:	WPOZZZ9BZGK190037	Operator:	29696
Registration:	SBP3BP		
Odometer:	10330 KM		
Vehicle:	VOLKSWAGEN AG v23.00		
Reason:	PORSCHE * 981 Cayman GT4 * Production: 2015 - * 20"		
	CHANGE RL, FL WHEEL RIM		

Vehicle / Tyre inspection

Front Axle		
Tyre Manufacturer	DUNLOP	DUNLOP
Tyre Pressure	2.0 BAR	2.0 BAR
Rear Axle		
Tyre Manufacturer	DUNLOP	DUNLOP
Tyre Pressure	2.3 BAR	2.3 BAR

Dear _____

Attachment is the alignment ^{report} of the claimant's vehicle.

According to TransEumaker, during test drive the vehicle are steered at one side after the accident. No doubt there are no physical damage seen on the parts, however it is shown by numbers in the alignment report due to ~~the~~ those parts are electronically controlled thus they are very sensitive towards impact.

Dear _____

According to TransEumaker, during test drive the vehicle are steered at one side after the accident. In order to ~~find~~ identify the root cause, an alignment test ^{was} done. The results shown in the attachment is the result of the ~~claimant's~~ ^{insured's} vehicle, where value stated in red is out of spec.

~~TransEumaker said that there~~

~~for those vehicle variables~~

TransEumaker ~~is~~ tried to align ~~the~~ the undercarriage parts back to the original position, however they are ~~unable~~ ^{unable} due to the ~~of the vehicle~~ ^{systems} fault to do so. On top of Furthermore ~~that~~, the Steering ~~gear~~ ^{systems} is electronically controlled. Electronically controlled parts are very sensitive towards impact, no doubt there ~~is~~ ^{is} no physical damage visible but ~~high possibility of damage if impact force is exerted.~~ possible for the impact force to cause electronic damage.

According to our survey, at the time of inspection, ~~we~~ ^{found} the insured vehicle ~~was~~ was test driven and ~~found~~ ^{found} to ~~veer~~ gradually to the left. Upon making a U-turn, the steering wheel could not ~~set~~ automatically returned to centre. Some manual pulling of the steering ~~wheel~~ ^{wheel} had to be done.

Shiau Chan (LKKAUTO)

From: ANG Richard <richard.angbs@axa.com.sg>
Sent: Thursday, 3 May 2018 4:35 PM
To: SUR
Cc: ANG Yvonne
Subject: AXA Ref: C0461413. OD Survey for SBP36P - Mandate request

Dear all,

We refer to the mandate request from Merimen.

Please advise us for the supplementary list for no.4, 11, 19, 20 & 24, why the items are approved when we cannot see any physical damage on them.

Thank you.

Regards,

Richard Ang | Specialist, Motor (Property) Claims
AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg
Email: richard.angbs@axa.com.sg
Customer Care No. 1800 8804888



Please consider the environment before printing this message

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 6 December, 2017 2:18 PM
To: eva.kok@eurokars.com.sg; SUR
Cc: assignments
Subject: RE: SBP 36P

Dear Eva,

As instructed by our client **AXA Insurance**, please proceed to repair the insured vehicle **SBP 36P (Excess \$4,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 5 December, 2017 2:03 PM
To: eva.kok@eurokars.com.sg; SUR <sur@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>
Subject: FW: SBP 36P

Dear Eva,

Received with thanks.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: eva.kok@eurokars.com.sg [<mailto:eva.kok@eurokars.com.sg>]
Sent: Tuesday, 5 December, 2017 2:01 PM
To: admin-d@lkkauto.com
Subject: RE: SBP 36P

Sis,

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	5936E

Vehicle Details

Vehicle No.	SBP36P
Vehicle to be Exported	No
Intended De-registration Date	04 Dec 2017
Vehicle Make	PORSCHE
Vehicle Model	CAYMAN GT4 (981) 6MT E6
Primary Colour	Black
Manufacturing Year	2016
Engine No.	008299
Chassis No.	WP0ZZZ98ZGK190037
Maximum Power Output	283.0 kW (379 bhp)
Open Market Value	\$103,180.00
Original Registration Date	01 Aug 2016
First Registration Date	01 Aug 2016
Transfer Count	0
Actual ARF Paid	\$157,724.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	31 Jul 2026
PARF Rebate Amount	\$118,293.00

Intended COE Rebate Details

COE Expiry Date	31 Jul 2026
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$56,089.00
COE Rebate Amount	\$48,550.00
Total Rebate Amount	\$166,843.00

The information contained herein is correct as at 04 Dec 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/11/2017 11:11
Date Of Accident	28/11/2017 15:00
Exact Location Of Accident	ALONG NAMLY AVE TOWARDS BUKIT TIMAH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBP36P
Insured/Policyholder	
Name Of Registered Owner	MADELIENE LEE SUH SHIN
NRIC No	S1555936E
Email Address	MADLEEMADLEE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98486336
Alternative Phone No	OTHERS-98486336

Vehicle Particulars

Manufacturer	PORSCHE
Model	CAYMAN GTH
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPX/P1815926
Cover Note Number	

Driver

Name of Driver	MADELIENE LEE SUH SHIN
NRIC No	S1555936E
Date Of Birth	20/12/1962
Occupation	INDOOR
Date Of Driving Pass	06/02/1980
Driving Experience	37 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98486336
Fax Number	
Contact Number	OTHERS-98486336
Email Address	MADLEEMADLEE@GMAIL.COM

Address	6B VICTORIA PARK ROAD
Postcode	266532
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN & STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD3518J
Vehicle Make/Model/Colour	NISSAN
Details Of Properties	
Name of Driver	GANESAN RAJU
NRIC/Passport Number	G21199431C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: *Janice Syn*
NRIC/FIN No.:



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 28 Nov 2017 at around 1500 hours, I was driving along Namly Avenue toward Bukit Timah Road. Vehicle B was driving very slowly so I overtook him but he then suddenly turned right and hit onto the left side of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Janice Syn

STUTTGART AUTO
NO:12 SUNGEI KADUT AVE (S) 729648 (FAX NO. 63602899)
ESTIMATED COST OF REPAIRS

AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		NAME : Ms Madeliene Lee Suh Shin	*WIP : 29696
ATTN : MOTOR CLAIM DEPT		ADDRESS : 6B Victoria Park Road Singapore 266532	DATE : 01.12.2017
FAX : 68804838 / 68804739	TEL :		
VEH NO : SBP36P	DATE IN :	CONTACT PERSON :	RICK 63602445
CHASSIS NO : WP0ZZZ98ZGK190037	MILEAGE :	TYPE OF CLAIM :	OD
MODEL : Cayman GT4	DATE REG : 01.08.2017	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description	QTY	PART NO	(NETT) PRICES
1	WING (LH) ✓ DT	1	P981-503-031-00-GRV	\$ 1,022.00
2	WHEEL-HOUSING LINER ✓ Defam.	1	P981-504-501-82-	\$ 400.00
3	RIVET ✓ NSC	3	P999-591-712-40-	\$ 3.00
4	SILL COVER ✓ cut	1	P981-504-661-81-	\$ 870.70
5	COVER ✓ cut	1	P981-504-567-81-	\$ 849.40
6	ADHESIVE TAPE ✓ NEC	1	P981-505-869-80-	\$ 56.80
7	LINING Bumper ✓ cut	1	P981-505-313-81-	\$ 2,095.40
8	SPOILER ✓ NEC ✓	1	P981-505-525-80-1E0	\$ 539.30
9	SPOILER ✓	1	P981-505-527-80-1E0	\$ 95.00
10	ADHESIVE FILM LH ✓ NEC	1	P981-505-627-80-	\$ 18.60
11	BLIND RIVET ✓ NEC	4	P999-190-191-30-	\$ 20.00
12	RETAINER PLATE Headlamp Washer Jet ✓ NEC	1	P981-505-661-02-	\$ 58.80
13	P981-505-662-02-/RETAINER PLATE ✓ NEC	1	P981-505-762-02-	\$ 58.10
14	SPOILER ✓ 7.210	1	P981-505-528-80-1E0	\$ 95.00
15	ADHESIVE FILM RH ✓ NEC	1	P981-505-628-80-	\$ 18.60
16	LINING ✓ Defam.	1	P981-505-991-80-	\$ 1,910.40
17	PROTECTIVE FILM ? ✓ NN	1	P981-505-691-00-	\$ 16.60
18	PROTECTIVE FILM ?	1	P981-505-692-00-	\$ 16.60
19	P981-531-911-03-GRV/DOOR ✓ DT	1	P981-531-911-05-GRV	\$ 1,467.40
20	ROOF FRAME SEAL ✓ NEC	1	P981-537-481-01-	\$ 285.50
21	GASKET ✓ Door Rubber NEC	1	P981-537-377-02-	\$ 464.10
22	COVER FOR WINDOW GUIDE LH ✓ NEC cut	1	P991-537-551-03-1E0	\$ 10.70
23	GASKET ✓ NEC	1	P991-537-085-01-03C	\$ 251.00
24	DOOR HANDLE BASIC LEFT PRI ✓ cut	1	P991-537-613-02-	\$ 56.40
25	INSULATION DOOR ✓ NEC	1	P997-556-531-01-	\$ 35.70
26	MIRROR BASE ✓ DMG	1	P981-731-229-01-	\$ 391.10
27	SCREW ✓ NEC	1	P999-073-192-01-	\$ 4.90
28	REPAIR KIT Screw Assy (Side Mirror) ✓ NEC	1	P991-731-919-00-	\$ 26.30
29	GASKET ✓ NEC	1	P981-731-835-00-	\$ 27.30
30	ADAPTER BLACK MAT ✓ NEC	1	P981-731-829-00-OK1	\$ 60.30
31	GASKET Side Mirror ✓ NEC	1	P981-731-833-00-	\$ 27.30
32	BRACKET Side Mirror ✓ NEC ?	1	P991-731-221-01-	\$ 34.40
33	WIRING HARNESS ✓ NEC	1	P991-622-713-00-	\$ 123.10
34	MIRROR GLASS X NN	1	P991-731-047-01-	\$ 1,054.20
35	ADJUSTING MOTOR ?	1	P7PP-959-578-D -	\$ 228.70
36	HOUSING PRIME COATED ✓ DMG	1	P991-731-631-01-G2L	\$ 292.30
37	PLATE ?	1	P991-731-519-01-	\$ 154.70
38	COVER BLACK MAT ✓ NEC	1	P991-731-729-00-OK1	\$ 545.90
39	HOUSING PRIME COATED ✓ NEC	1	P991-731-629-01-G2L	\$ 202.80
40	HEADLAMP LH ?	1	P981-631-263-01-	\$ 4,290.00

41	P991-631-255-05-/INDICATOR LIGHT (LH) ✓ CRK	1	P991-631-255-06-	\$ 133.00
42	DISC WHEEL PLATINUM SATIN - REAR ✓ cut	1	P981-362-166-81-OB5	\$ 4,107.90
43	HUB CAP PLATINUM SATIN-MAT X <i>not</i>	1	P9P2-601-147- -OB5	\$ 159.60
44	DISC WHEEL PLATINUM SATIN - FRONT ✓ cut	1	P981-362-162-80-OB5	\$ 3,613.70
			SUB TOTAL	\$ 26,192.60
			LESS 20%	\$ 5,238.52
			Total Parts	\$ 20,954.08
	Labour Description			
1	TO REMOVE / REPLACE DAMAGED FRONT / REAR BUMPER, LH FRONT FENDER, LH DOOR, LH SIDE SKIRT & OTHER AFFECTED BODY PARTS INCLUDING PANEL BEAT / STRAIGHTEN BODY PANELS & FITTINGS WHICHEVER NECESSARY INCLUDING ALIGNMENT OF BODY STRUCTURE. <i>1400/day</i>			\$ 9,800.00
				<i>7000</i>
2	TO SPRAY PAINT FRONT / REAR BUMPER, LH FRONT FENDER, LH FRONT DOOR, LH SIDE SKIRT, LH REAR FENDER & LH WING MIRROR HOUSING. <i>1200 / pane / bumper</i>			\$ 6,800.00
				<i>1000 / pane</i> <i>6400</i>
3	TO CARRY OUT BODY ANTI-RUST TO AFFECTED AREAS.			\$ 200.00
				<i>100</i>
4	TO CHECK ELECTRICAL WIRING SYSTEM FOR PROPER FUNCTION ABILITY INCLUDING PARKING ASSIST SENSORS. NETT			\$ 250.00
5	TO REMOVE / REFIT DOORS INCLUDE WINDOW MECHANISM FROM DAMAGE DOOR TO NEW DOOR & CHECK FUNCTION ABILITY NETT			\$ 700.00
6	TO CHECK STEERING GEOMETRY & CONDUCT WHEEL ALIGNMENT ACCORDING TO SPECIFICATIONS. NETT			\$ 680.00
7	TO REMOVE / REPLACE TYRES & RIMS @ \$60/- NETT			\$ 120.00
8	TO SUPPLY 2 PCS TYRE \$980.00 ea X <i>Oil Damage</i>			\$ 1,960.00
9	TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES AFTER ACCIDENT REPAIR. NETT			\$ 600.00
10	SUNDRIES <i>11 days -</i>			\$ 700.00
				<i>Revert</i> <i>Excess : \$4000</i> <i>50</i>
	LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed			
			TOTAL LABOUR	\$ 21,210.00
			TOTAL PARTS	\$ 20,954.08
			GRAND TOTAL	\$ 42,164.08

Please note that this is **only an estimate** based on our visual inspection. However, should there be any additional work be found necessary in the course of repair and thus additional parts, materials and labor cost will be deemed necessary, you will be informed accordingly prior to any action taken. In view of this, expected delays will be inevitable and therefore additional working days will be required. As such the loss of use and other incidentals will be adjusted accordingly.

Signature:
Date:

Sebastian.
- Part by part repair.
- Question Mark 2-ten Photo.
- Photo Before Paint.
90036121
sebastian.yeang@lkkauto.com.

STUTTGART AUTO
NO:12 SUNGEI KADUT AVE (S) 729648 (FAX NO. 63602899)
FINALIZATION COST OF REPAIRS

AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		NAME : Ms Madeliene Lee Suh Shin ADDRESS : 6B Victoria Park Road Singapore 266532	WIP : 29696 DATE: 01.12.2017
ATTN :	MOTOR CLAIM DEPT	TEL :	
FAX :	68804838 / 68804739		
VEH NO :	SBP36P	DATE IN :	CONTACT PERSON :
CHASSIS NO :	WP0ZZZ98ZGK190037	MILEAGE :	RICK 63602445
MODEL :	Cayman GT4	DATE REG. : 01.08.2017	TYPE OF CLAIM : OD
		POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description	QTY	PART NO	REVISED	(NETT) PRICES
1	WING (LH)	1	P981-503-031-00-GRV	\$ 1,022.00	\$ 1,022.00
2	WHEEL-HOUSING LINER	1	P981-504-501-82-	\$ 400.00	\$ 400.00
3	RIVET	3	P999-591-712-40-	\$ 3.00	\$ 3.00
4	SILL COVER	1	P981-504-661-81-	\$ 870.70	\$ 870.70
5	COVER	1	P981-504-567-81-	\$ 849.40	\$ 849.40
6	ADHESIVE TAPE	1	P981-505-869-80-	\$ 56.80	\$ 56.80
7	LINING	1	P981-505-313-81-	\$ 2,095.40	\$ 2,095.40
8	SPOILER	1	P981-505-525-80-1E0	\$ 539.30	\$ 539.30
9	SPOILER	1	P981-505-527-80-1E0	\$ 95.00	\$ 95.00
10	ADHESIVE FILM LH	1	P981-505-627-80-	\$ 18.60	\$ 18.60
11	BLIND RIVET	4	P999-190-191-30-	\$ 20.00	\$ 20.00
12	RETAINER PLATE	1	P981-505-661-02-	\$ 58.10	\$ 58.80
13	P981-505-662-02-/RETAINER PLATE	1	P981-505-762-02-	\$ 58.10	\$ 58.10
14	SPOILER	1	P981-505-528-80-1E0	\$ 95.00	\$ 95.00
15	ADHESIVE FILM RH	1	P981-505-628-80-	\$ 18.60	\$ 18.60
16	LINING	1	P981-505-991-80-	\$ 1,910.40	\$ 1,910.40
17	PROTECTIVE FILM	1	P981-505-691-00-	\$ -	\$ 16.60
18	PROTECTIVE FILM	1	P981-505-692-00-	\$ -	\$ 16.60
19	P981-531-911-03-GRV/DOOR	1	P981-531-911-05-GRV	\$ 1,467.40	\$ 1,467.40
20	ROOF FRAME SEAL	1	P981-537-481-01-	\$ 285.50	\$ 285.50
21	GASKET	1	P981-537-377-02-	\$ 464.10	\$ 464.10
22	COVER FOR WINDOW GUIDE LH	1	P991-537-551-03-1E0	\$ 10.70	\$ 10.70
23	GASKET	1	P991-537-085-01-03C	\$ 251.00	\$ 251.00
24	DOOR HANDLE BASIC LEFT PRI	1	P991-537-613-02-	\$ 56.40	\$ 56.40
25	INSULATION DOOR	1	P997-556-531-01-	\$ 35.70	\$ 35.70
26	MIRROR BASE	1	P981-731-229-01-	\$ 391.10	\$ 391.10
27	SCREW	1	P999-073-192-01-	\$ 4.90	\$ 4.90
28	REPAIR KIT	1	P991-731-919-00-	\$ 26.30	\$ 26.30
29	GASKET	1	P981-731-835-00-	\$ 27.30	\$ 27.30
30	ADAPTER BLACK MAT	1	P981-731-829-00-OK1	\$ 60.30	\$ 60.30
31	GASKET	1	P981-731-833-00-	\$ 27.30	\$ 27.30
32	BRACKET	1	P991-731-221-01-	\$ 34.40	\$ 34.40
33	WIRING HARNESS	1	P991-622-713-00-	\$ 123.10	\$ 123.10
34	MIRROR GLASS	1	P991-731-047-01-	\$ -	\$ 1,054.20
35	ADJUSTING MOTOR	1	P7PP-959-578-D -	\$ -	\$ 228.70
36	HOUSING PRIME COATED	1	P991-731-631-01-G2L	\$ 292.30	\$ 292.30
37	PLATE	1	P991-731-519-01-	\$ -	\$ 154.70
38	COVER BLACK MAT	1	P991-731-729-00-OK1	\$ 545.90	\$ 545.90
39	HOUSING PRIME COATED	1	P991-731-629-01-G2L	\$ 202.80	\$ 202.80

40	HEADLAMP LH	1	P981-631-263-01-	\$ -	\$ 4,290.00
41	P991-631-255-05-/INDICATOR LIGHT (LH)	1	P991-631-255-06-	\$ 133.00	\$ 133.00
42	DISC WHEEL PLATINUM SATIN - REAR	1	P981-362-166-81-OB5	\$ 4,107.90	\$ 4,107.90
43	HUB CAP PLATINUM SATIN-MAT	1	P9P2-601-147- -OB5	\$ -	\$ 159.60
44	DISC WHEEL PLATINUM SATIN - FRONT	1	P981-362-162-80-OB5	\$ 3,613.70	\$ 3,613.70
SUPPLEMENTARY PARTS					
1	LOGO	1	P981-559-251-80-	\$ 207.20	LN
2	LOGO PORSCHE, BLACK	1	P991-559-235-90-	\$ 182.40	LN
3	MICROSWITCH	1	P991-613-171-00-	\$ 94.40	LN
4	Steering gear	1	P991-347-006-18-	\$ 5,344.50	LN
5	HEXAGON-HEAD BOLT M 12 X 1.5 X 105	2	P999-072-864-01-	\$ 22.80	LN
6	HEXAGON NUT M 12 X 1.5	2	PN -909-167-01-	\$ 12.40	LN
7	HEXAGON-HEAD BOLT M 12 X 1.5 X 50	2	P999-072-863-01-	\$ 21.00	LN
8	HEXAGON-HEAD BOLT	4	P999-072-836-01-	\$ 32.40	LN
9	HEX-HD NUT (AC05) M 12 X 1.5	4	P999-084-449-09-	\$ 36.00	LN
10	HEXAGON NUT, M10 (AE01) & (WF71)	2	P999-084-123-09-	\$ 13.80	LN
11	CONTROL ARM FRONT AXLE	2	P991-341-043-03-	\$ 1,457.20	LN
12	HEXAGON-HEAD BOLT AM 14 X 1.5 X 92	2	P999-072-892-01-	\$ 27.40	LN
13	HEXAGON-HEAD BOLT M 12 X 1.5 X 105	2	P999-072-864-01-	\$ 22.80	LN
14	Lid	2	P999-703-561-40-	\$ 35.40	LN
15	HEXAGON-HEAD BOLT	2	P999-072-876-01-	\$ 42.40	LN
16	LOCKING NUT, M12 (AE01), (WA18) & (AC05)	2	P999-084-445-01-	\$ 10.20	LN
17	HEXAGON NUT M6	2	P900-380-015-01-	\$ 4.00	LN
18	HEXAGON NUT M 14 X 1.5	2	P900-380-012-01-	\$ 9.80	LN
19	WISHBONE	1	P991-341-041-87-	\$ 5,370.60	LN
20	JOINT	2	P991-347-322-00	\$ 1,026.20	LN
21	HEXAGON NUT	2	P999-034-037-01	\$ 58.20	LN
22	CLAMPING RING	4	P991-347-375-01	\$ 139.60	LN
23	BELLOWS TRACK ROD	2	P991-347-191-01	\$ 327.00	LN
24	TRACK ROD	2	P991-347-131-00	\$ 1,055.00	LN 15842.70
SUB TOTAL				\$ 35,824.20	\$ 26,192.60
LESS 20%				\$ 7,164.84	\$ 5,238.52
Total Parts				\$ 28,659.36	\$ 20,954.08
Labour Description					
1	TO REMOVE / REPLACE DAMAGED FRONT / REAR BUMPER, LH FRONT FENDER, LH DOOR, LH SIDE SKIRT & OTHER AFFECTED BODY PARTS INCLUDING PANEL BEAT / STRAIGHTEN BODY PANELS & FITTINGS WHICHEVER NECESSARY INCLUDING ALIGNMENT OF BODY STRUCTURE.			\$ 7,000.00	\$ 9,800.00
2	TO SPRAY PAINT FRONT / REAR BUMPER, LH FRONT FENDER, LH FRONT DOOR, LH SIDE SKIRT, LH REAR FENDER, & LH WING MIRROR HOUSING.			\$ 6,400.00	\$ 6,800.00
3	TO CARRY OUT BODY ANTI-RUST TO AFFECTED AREAS.			\$ 100.00	\$ 200.00

4	TO CHECK ELECTRICAL WIRING SYSTEM FOR PROPER FUNCTION ABILITY INCLUDING PARKING ASSIST SENSORS.	NETT	\$ 250.00	\$ 250.00
5	TO REMOVE / REFIT DOORS INCLUDE TRANSFER WINDOW MECHANISM FROM DAMAGE DOOR TO NEW DOOR & CHECK FUNCTION ABILITY	NETT	\$ 700.00	\$ 700.00
6	TO CHECK STEERING GEOMETRY & CONDUCT WHEEL ALIGNMENT ACCORDING TO SPECIFICATIONS.	NETT	\$ 680.00	\$ 680.00
7	TO REMOVE / REPLACE TYRES & RIMS @ \$60/-	NETT	\$ 120.00	\$ 120.00
8	TO SUPPLY 2 PCS TYRE \$980.00 ea		\$ -	\$ 1,960.00
9	TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES AFTER ACCIDENT REPAIR.	NETT	\$ 600.00	\$ 600.00
10	SUNDRIES.		\$ 50.00	\$ 100.00
SUPPLEMENTARY LABOUR				
1	TO REMOVE /REPLACE STEERING RACK SYSTEM,BALL JOINT LINKAGES INCLUDE CENTRALIZED STEERING WHEEL CALIBRATION OF STEERING & TEST DRIVE		\$ 2,340.00	
TOTAL LABOUR			\$ 18,240.00	\$ 21,210.00
TOTAL PARTS			\$ 28,659.36	\$ 20,954.08
GRAND TOTAL			\$ 46,899.36	\$ 42,164.08
LESS EXCESS			\$ (4,000.00)	
TOTAL AFTER EXCESS			\$ 42,899.36	
GST 7 %			\$ 3,002.96	
TOTAL AFTER GST			\$ 45,902.32	

NUMBER OF DAYS: 12 WORKING DAYS(EXCLUDE WAITING FOR SURVEY,AUTHORIZATION,PARTS,SAT,SUN & PH)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AXA Insurance Pte Ltd
8 Shenton Way #24-01, AXA Tower
Singapore 068811

Our File No: CS/AXA17022923/SQBN2

Date: 27/06/2018

REFERENCE

Insured/Claimant: MADELIENE LEE SUH SHIN
Date of Loss: 28/11/2017

Policy No: P1815926

Nature of Claim: OD

Claim No: C0461413

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SBP36P
Make & Model: PORSCHE CAYENNE, TURBO (A)
Reg. Date: 01/08/2016 (Man. Year: 2016)
Colour: Black
Engine Capacity: 3800 cc
Market Value/New Car Price: S\$330,000.00
Sum Insured (\$\$): Market Value/New Car Price

Engine No: 008299
Chassis No: WP0ZZZ98ZGK190037
Odometer: 10328 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35 ZR20 Rear Tyre Size: 295/30 ZR20
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	33,496.24	28,709.36	4,786.88	14.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	23,450.00	18,190.00	5,260.00	22.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	56,946.24	46,899.36	10,046.88	17.64
- Excess (\$\$)	4,000.00	4,000.00	0.00	0.00
(\$\$)	52,946.24	42,899.36	10,046.88	18.98
+ GST 7.00/7.00% (\$\$)	3,706.24	3,002.96	703.28	18.98
Nett Amount (\$\$)	56,652.48	45,902.32	10,750.16	18.98

INSPECTION

Date of Assignment: 01/12/2017

Date Inspected: 04/12/2017

Inspected At:

Stuttgart Auto Pte Ltd (HQ)
12 Sungei Kadut Ave
Singapore 729648

Estimated Period of Repair: 11.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2018)	
Parts: M1-SUV	PORSCHE CAYENNE TURBO (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SBP36P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WING (LH) (CONSISTENT)	Dented	1,022.00 FL	*1,022.00 FL
2	1		*WHEEL-HOUSING LINER (CONSISTENT)	Deformed	400.00 FL	*400.00 FL
3	3		*RIVET (CONSISTENT)	Necessary	3.00 FL	*3.00 FL
4	1		*SILL COVER (CONSISTENT)	Cut	870.70 FL	*870.70 FL
5	1		*COVER (CONSISTENT)	Cut	849.40 FL	*849.40 FL
6	1		*ADHESIVE TAPE (CONSISTENT)	Necessary	56.80 FL	*56.80 FL
7	1		*LINING BUMPER (CONSISTENT)	Cut	2,095.40 FL	*2,095.40 FL
8	1		*SPOILER } (CONSISTENT)	Necessary	539.30 FL	*539.30 FL
9	1		*SPOILER } (CONSISTENT)	Necessary	95.00 FL	*95.00 FL
10	1		*ADHESIVE FILM LH (CONSISTENT)	Necessary	18.60 FL	*18.60 FL
11	4		*BLIND RIVET (CONSISTENT)	Necessary	20.00 FL	*20.00 FL
12	1		*RETAINER PLATE (CONSISTENT)	Necessary	58.80 FL	*58.10 FL
13	1		*P981-505-662-02-/RETAINER PLATE (CONSISTENT)	Necessary	58.10 FL	*58.10 FL
14	1		*SPOILER } (CONSISTENT)	Necessary	95.00 FL	*95.00 FL
15	1		*ADHESIVE FILM RH } (CONSISTENT)	Necessary	18.60 FL	*18.60 FL
16	1		*LINING (CONSISTENT)	Deformed	1,910.40 FL	*1,910.40 FL
17	1		*PROTECTIVE FILM (CONSISTENT)	Not Necessary	16.60 FL	*- FL
18	1		*PROTECTIVE FILM (CONSISTENT)	Not Necessary	16.60 FL	*- FL
19	1		*P981-531-911-03-GRV/DOOR (CONSISTENT)	Dented	1,467.40 FL	*1,467.40 FL
20	1		*ROOF FRAME SEAL (CONSISTENT)	Necessary	285.50 FL	*285.50 FL
21	1		*GASKET (CONSISTENT)	Necessary	464.10 FL	*464.10 FL
22	1		*COVER FOR WINDOW GUIDE LH (CONSISTENT)	Cut	10.70 FL	*10.70 FL
23	1		*GASKET (CONSISTENT)	Necessary	251.00 FL	*251.00 FL
24	1		*DOOR HANDLE BASIC LEFT PRI (CONSISTENT)	Cut	56.40 FL	*56.40 FL
25	1		*INSULATION DOOR (CONSISTENT)	Necessary	35.70 FL	*35.70 FL
26	1		*MIRROR BASE (CONSISTENT)	Damaged	391.10 FL	*391.10 FL
27	1		*SCREW (CONSISTENT)	Necessary	4.90 FL	*4.90 FL
28	1		*REPAIR KIT (CONSISTENT)	Necessary	26.30 FL	*26.30 FL
29	1		*GASKET (CONSISTENT)	Necessary	27.30 FL	*27.30 FL
30	1		*ADAPTER BLACK MAT (CONSISTENT)	Necessary	60.30 FL	*60.30 FL
31	1		*GASKET (CONSISTENT)	Necessary	27.30 FL	*27.30 FL
32	1		*BRACKET (CONSISTENT)	Necessary	34.40 FL	*34.40 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
33	1		*WIRING HARNESS (CONSISTENT)	Necessary	123.10 FL	*123.10 FL
34	1		*MIRROR GLASS (CONSISTENT)	Not Necessary	1,054.20 FL	*- FL
35	1		*ADJUSTING MOTOR (CONSISTENT)	Not Necessary	228.70 FL	*- FL
36	1		*HOUSING PRIME COATED (CONSISTENT)	Damaged	292.30 FL	*292.30 FL
37	1		*PLATE (CONSISTENT)	Not Necessary	154.70 FL	*- FL
38	1		*COVER BLACK MAT (CONSISTENT)	Necessary	545.90 FL	*545.90 FL
39	1		*HOUSING PRIME COATED (CONSISTENT)	Necessary	202.80 FL	*202.80 FL
40	1		*HEADLAMP LH (CONSISTENT)	Not Necessary	4,290.00 FL	*- FL
41	1		*P991-631-255-05-/INDICATOR LIGHT (LH) (CONSISTENT)	Cracked	133.00 FL	*133.00 FL
42	1		*DISC WHEEL PLATINUM SATIN-REAR (CONSISTENT)	Cut	4,107.90 FL	*4,107.90 FL
43	1		*HUB CAP PLATINUM SATIN-MAT (CONSISTENT)	Not Necessary	159.60 FL	*- FL
44	1		*DISC WHEEL PLATINUM SATIN-FRONT (CONSISTENT)	Cut	3,613.70 FL	*3,613.70 FL
45	1		*LOGO (CONSISTENT)	Necessary	207.20 FL	*207.20 FL
46	1		*LOGO PORSCHE BLACK (CONSISTENT)	Necessary	182.40 FL	*182.40 FL
47	1		*MICROSWITCH (CONSISTENT)	Necessary	94.40 FL	*94.40 FL
48	1		*STEERING GEAR (CONSISTENT)	Damaged	5,344.50 FL	*5,344.50 FL
49	2		*HEXAGON-HEAD BOLT M 12X1.5X105 (CONSISTENT)	Necessary	22.80 FL	*22.80 FL
50	2		*HEXAGON NUT M 12X1.5 (CONSISTENT)	Necessary	12.40 FL	*12.40 FL
51	2		*HEXAGON-HEAD BOLT M 12X1.5X50 (CONSISTENT)	Necessary	21.00 FL	*21.00 FL
52	4		*HEXAGON-HEAD BOLT (CONSISTENT)	Necessary	32.40 FL	*32.40 FL
53	4		*HEX-HD NUT (AC05) M12X1.5 (CONSISTENT)	Necessary	36.00 FL	*36.00 FL
54	2		*HEXAGON NUT M10 (AE01) & (WF71) (CONSISTENT)	Necessary	13.80 FL	*13.80 FL
55	2		*CONTROL ARM FRONT AXLE (CONSISTENT)	Damaged	1,457.20 FL	*1,457.20 FL
56	2		*HEXAGON-HEAD BOLT AM 14X1.5X92 (CONSISTENT)	Necessary	27.40 FL	*27.40 FL
57	2		*HEXAGON-HEAD BOLT M12X1.5X105 (CONSISTENT)	Necessary	22.80 FL	*22.80 FL
58	2		*LID (CONSISTENT)	Necessary	35.40 FL	*35.40 FL
59	2		*HEXAGON-HEAD BOLT (CONSISTENT)	Necessary	42.40 FL	*42.40 FL
60	2		*LOCKING NUT,M12 (AE01)(WA18) & (AC05) (CONSISTENT)	Necessary	10.20 FL	*10.20 FL
61	2		*HEXAGON NUT M6 (CONSISTENT)	Necessary	4.00 FL	*4.00 FL
62	2		*HEXAGON NUT M14X1.5 (CONSISTENT)	Necessary	9.80 FL	*9.80 FL
63	2		*WISHBONE (CONSISTENT)	Damaged	5,370.60 FL	*5,370.60 FL
64	2		*JOINT (CONSISTENT)	Damaged	1,026.20 FL	*1,026.20 FL
65	2		*HEXAGON NUT (CONSISTENT)	Necessary	58.20 FL	*58.20 FL
66	4		*CLAMPING RING (CONSISTENT)	Necessary	139.60 FL	*139.60 FL
67	2		*BELLOWS TRACK ROD (CONSISTENT)	Damaged	327.00 FL	*327.00 FL
68	2		*TRACK ROD (CONSISTENT)	Damaged	1,055.00 FL	*1,055.00 FL
69	1		*SUNDRIES (CONSISTENT)	Necessary	100.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	41,845.30	35,874.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	8,349.06	7,164.84
Total Parts (\$\$)	33,496.24	28,709.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE/REPLACE DAMAGED FRONT/REAR BUMPER,LH FRONT FENDER,LH DOOR,LH SIDE SKIRT & OTHER AFFECTED BODY PARTS INCLUDING PANEL BEAT/STRAIGHTEN BODY PANELS & FITTINGS WHICHEVER NECESSARY INCLUDING ALIGNMENT OF BODY STRUCTURE	New	9,800.00	7,000.00
2	TO SPRAY PAINT FRONT/REAR BUMPER,LH FRONT FENDER,LH FRONT DOOR,LH SIDE SKIRT,LH REAR FENDER & LH WING MIRROR HOUSING	New	6,800.00	6,400.00
3	TO CARRY OUT BODY ANTI-RUST TO AFFECTED AREAS	New	200.00	100.00
4	TO CHECK ELECTRICAL WIRING SYSTEM FOR PROPER FUNCTION ABILITY INCLUDING PARKING ASSIST SENSORS	New	250.00	250.00
5	TO REMOVE/REFIT DOORS INCLUDE TRANSFER WINDOW MECHANISM FROM DAMAGE DOOR TO NEW DOOR & CHECK FUNCTION ABILITY	New	700.00	700.00
6	TO CHECK STEERING GEOMETRY & CONDUCT WHEEL ALIGNMENT ACCORDING TO SPECIFICATIONS	New	680.00	680.00
7	TO REMOVE/REPLACE TYRES & RIMS	New	120.00	120.00
8	TO SUPPLY 2 PCS TYRE	New	1,960.00	-
9	TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES AFTER ACCIDENT REPAIR	New	600.00	600.00
10	TO REMOVE/REPLACE STEERING RACK SYSTEM,BALL JOINT LINKAGES INCLUDE CENTRALIZED STEERING WHEEL CALIBRATION OF STEERING & TEST DRIVE	New	2,340.00	2,340.00
Gross Labour Cost (\$\$)			23,450.00	18,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >