

**MSIG INSURANCE (SINGAPORE) PTE LTD**4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807**Revised****ATTN : MOTOR CLAIMS DEPARTMENT**

DATE : 28/03/2018

Accident Involving SFU8238Y & SKH2444S on 27/11/2017**Direct Settlement Claim**

Dear Sirs

We refer to our Letter of demand dated 02/01/2018. Enclosed is Revised Invoice for your kind perusal.

1) Revised Invoice No : 23300910	\$ 6,667.49
2) GIA Search	\$ 2.00
3) Car Rental: Invoice No: 14889	\$ 535.00

TOTAL	\$ 7,204.49
--------------	--------------------

Please pay **Eurokars Habitat Pte Ltd** the sum of **\$6,669.49** and **Eurokars Leasing Pte Ltd** the sum of **\$535.00** as soon as possible and mail your cheque to **12 Sungei Kadut Avenue Singapore 729648.**

Yours faithfully,

Stanley Ngu
Manager - Body & Paint Division
DID :63602845
FAX:63602899
e-mail : stanley@eurokars.com.sg

Eurokars Habitat Pte Ltd

Distributor of MINI Vehicles and Parts

TAX INVOICE
27 Leng Kee Road Singapore 150098
Tel: (+65) 6473 3777 Fax: (+65) 6473 0500



CUSTOMER: MSIG INSURANCE(SINGAPORE) PTE LTD		DATE IN: 11/12/2017
ADDRESS: 4 SHENTON WAY		DATE PRINTED: 23/03/2018
#21-01		JOB NO: 14798
SGX CENTRE 2		CSO/OP CODE: Phipps Sarah
SINGAPORE 068807		TEL NO:
MODEL: MINI 5 DOOR COOPER RHD		REGN NO: SFU8238Y
CHASIS NO: WMWXS52040T825313		REGN DATE: 12/12/2014
ENGINE NO: 53569006B38A15A		MILEAGE: 26178
DESCRIPTION: BODY REPAIR		REQUISITION NO: Phipps Sarah

ITEM	DESCRIPTION	AMOUNT
SUB	TO REPLACE REAR BUMPER.TO REPAIR LHR & ALL AREAS AFFECTED	1,680.00
SUB	TO RESPRAY REAR BUMPER & LHR FENDER	1,600.00
SUB	TO CARRY OUT BODY CAVITY PRESERVATION	150.00
SUB	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	560.00
SUB	TO TRANSFER REVERSE SENSORS	420.00
SUB	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTION	180.0
SUB	TO CONDUCT REPROGRAMMING AFTER ACCIDENT REPAIR	280.00
SUB	SUNDRIES	50.00
SUB	TO MOUNT 1PC SPORT RIM & CONDUCT FULL WHEEL ALIGNMENT	120.00
51.12.7.403.266	PDC HOLDER O 1.0 48.78 0.00	48.78
51.12.7.403.267	PDC HOLDER O 1.0 48.78 0.00	48.78
07.14.7.411.141	BLIND RIVET 4.0 3.48 0.00	13.92
51.77.7.318.829	COVER,WHEEL 1.0 95.28 0.00	95.28
36.11.6.855.111	DISK WHEEL 1.0 960.78 0.00	960.78
66.20.9.283.203	DECOUPLING R 4.0 5.94 0.00	23.76

Parts 1191.30
Surcharge
Labour 4,760.00
Menus 280.00

Net 6231.30
G.S.T. 7% 436.19
Total 6667.49
Paid 0.00
Amount Due 6667.49

NOTE: MINI car that are found with non-approved tuning or conversion installed are not subject to MINI Warranty and the warranty of the car will be void accordingly.

CUSTOMER'S SIGNATURE

AUTHORIZED SIGNATURE

GST REGN. NO. M90364005A

CO. REGN. NO. 199806095Z

Eurokars Habitat Pte Ltd

Distributor of MINI Vehicles and Parts

27 Leng Kee Road Singapore 159099
Tel: (+65) 6473 3777 Fax: (+65) 6473 0500

TAX INVOICE

Invoice No: M90364005A



PAGE NO: 1

CUSTOMER: MSIG INSURANCE(SINGAPORE) PTE LTD
ADDRESS: 4 SHENTON WAY
#21-01
SGX CENTRE 2
SINGAPORE 068807
MODEL: MINI 5 DOOR COOPER RHD
CHASIS NO: WMWXS52040T825313
ENGINE NO: 53569006B38A15A
DESCRIPTION: BODY REPAIR

DATE IN: 11/12/2017
DATE PRINTED: 23/03/2018
JOB NO: 14798
CSO/OP CODE: Phipps Sarah
TEL NO:
REGN NO: SFU8238Y
REGN DATE: 12/12/2014
MILEAGE: 26178
REQUISITION NO: Phipps Sarah

ITEM	DESCRIPTION	AMOUNT
SUB	TO REPLACE REAR BUMPER.TO REPAIR LHR & ALL AREAS AFFECTED	1,680.00
SUB	TO RESPRAY REAR BUMPER & LHR FENDER	1,600.00
SUB	TO CARRY OUT BODY CAVITY PRESERVATION	150.00
SUB	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	560.00
SUB	TO TRANSFER REVERSE SENSORS	420.00
SUB	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTION	180.00
SUB	TO CONDUCT REPROGRAMMING AFTER ACCIDENT REPAIR	280.00
SUB	SUNDRIES	50.00
SUB	TO MOUNT 1PC SPORT RIM & CONDUCT FULL WHEEL ALIGNMENT	120.00
51.12.7.403.266	PDC HOLDER O 1.0 48.78 0.00	48.78
51.12.7.403.267	PDC HOLDER O 1.0 48.78 0.00	48.78
07.14.7.411.141	BLIND RIVET 4.0 3.48 0.00	13.92
51.77.7.318.829	COVER,WHEEL 1.0 95.28 0.00	95.28
36.11.6.855.111	DISK WHEEL 1.0 960.78 0.00	960.78
66.20.9.283.203	DECOUPLING R 4.0 5.94 0.00	23.76

Parts 1191.30
Surcharge -
Labour 4,760.00
Menus 280.00

Net 6231.30
G.S.T. 7% 436.19
Total 6667.49
Paid 0.00
Amount Due 6667.49

NOTE: MINI car that are found with non-approved tuning or conversion installed are not subject to MINI Warranty and the warranty of the car will be void accordingly.

CUSTOMER'S SIGNATURE

AUTHORIZED SIGNATURE

GST REGN. NO. M90364005A

CO. REGN. NO. 199806095Z