

**Veron Chen (LKKAuto)**

---

**From:** Simon Ho (LKKAuto)  
**Sent:** Tuesday, 13 March 2018 1:08 PM  
**To:** stanley@eurokars.com.sg  
**Cc:** Veron Chen (LKKAuto); KKLau; Sebastian Yeang (LKK Auto); jessicahs@eurokars.com.sg  
**Subject:** RE: SFU8238Y DOA:27/11/2017

Dear Stanley,

Item No. 1 – rear bumper in the below parts list.

Best Regards,

Simon Ho  
LKK Auto Consultants Pte Ltd  
phone: 6256-3561 | email: [simonho@lkkauto.com](mailto:simonho@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** stanley@eurokars.com.sg [<mailto:stanley@eurokars.com.sg>]  
**Sent:** Tuesday, 13 March, 2018 9:38 AM  
**To:** Simon Ho (LKKAuto)  
**Cc:** Veron Chen (LKKAuto); KKLau; Sebastian Yeang (LKK Auto); jessicahs@eurokars.com.sg  
**Subject:** RE: SFU8238Y DOA:27/11/2017

Dear Simon

Please see attached and advise, which are the item you looking at to remove?



EUROKARS HABITAT PTE LTD  
NO:12 SUNGEI KADUT, SINGAPORE 729648  
FINALIZATION COST OF REPAIRS



<b>MSIG INSURANCE SINGAPORE P/L</b>		<b>NAME :</b> MS WINNIE MOK		<b>WIP :</b> 14798	
4 SHENTON WAY #21-01		<b>ADDRESS :</b> 10 PULASAN ROAD		<b>EXCESS :</b>	
SGX CENTRE 2		#01-07		<b>DATE:</b> 28-Nov-17	
SINGAPORE 068807		SINGAPORE 424378			
<b>ATTN. :</b> MOTOR CLAIMS		<b>TEL :</b> 96364546 (MR.CHAM @ 97777850)			
<b>FAX :</b>					
<b>VEH NO :</b>	SFU8238Y	<b>DATE IN :</b>		<b>CONTACT PERSON :</b>	JOBI THOMAS 6360 2446
<b>CHASSIS NO :</b>	WMWXS52040T825313	<b>MILEAGE :</b>		<b>TYPE OF CLAIM :</b>	THIRD PARTY CLAIM
<b>MODEL :</b>	MINI COOPER F55	<b>DATE REG.:</b>	12-Dec-14	<b>POLICY NO. :</b>	
<b>NATURE OF WORKS</b>					
<b>S/NO</b>	<b>Parts Description</b>			<b>REVISED</b>	<b>PRICES</b>
		<b>QTY</b>			
1	REAR BUMPER	1	M51.12.7.380.024	\$ 772.86	\$ 772.86
2	REAR BUMPER SENSOR HOLDER RH	1	M51.12.7.403.266	\$ 48.78	\$ 48.78
3	REAR BUMPER SENSOR HOLDER LH	1	M51.12.7.403.267	\$ 48.78	\$ 48.78
4	REAR BUMPER SPOILER	1	M51.12.7.380.030	\$ -	\$ 254.64
5	REAR BUMPER BLIND RIVET	4	M07.14.7.411.141	\$ 13.92	\$ 13.92
6	REAR WHEEL ARCH LH	1	M51.77.7.318.829	\$ 95.28	\$ 95.28
7	REAR BUMPER FOGLAMP CHROME	1	M51.12.7.365.737	\$ -	\$ 92.10
8	SPORT RIM	1	M36.11.6.855.111	\$ 960.78	\$ 960.78
9	SPORT RIM CAP	1	M36.13.6.857.149	\$ -	\$ 30.42
10	REAR SENSOR GASKET	4	B66.20.9.283.203	\$ 23.76	\$ 23.76
			<b>TOTAL PARTS</b>	\$ 1,964.16	\$ 2,341.32
					\$ -
			<b>TOTAL PARTS COST</b>	\$ 1,964.16	\$ 2,341.32



Thanks and regards

**Stanley Ngu**

Manager

Body & Paint Division

**Eurokars Group of Companies**

**(Porsche, Rolls Royce, Mini, Mazda, McLaren)**

Eurokars Centre

12 Sungei Kadut Avenue

Singapore 729648

Tel: +65 63633003

DID: +65 63602845

Fax: +65 63602899

**From:** Stanley Ngu

**Sent:** Tuesday, 13 March 2018 9:07 AM

**To:** 'Simon Ho (LKKAuto)' <[SimonHo@lkkauto.com](mailto:SimonHo@lkkauto.com)>; Jessica Harry Shastri <[jessicahs@eurokars.com.sg](mailto:jessicahs@eurokars.com.sg)>

**Cc:** Veron Chen (LKKAuto) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>; KK Lau <[kklau@lkkauto.com](mailto:kklau@lkkauto.com)>; Sebastian Yeang (LKK Auto)

<[SebastianYeang@lkkauto.com](mailto:SebastianYeang@lkkauto.com)>; Jobi Thomas <[jobithomas@eurokars.com.sg](mailto:jobithomas@eurokars.com.sg)>

**Subject:** RE: SFU8238Y DOA:27/11/2017

Dear Simon

I will look into it and revert to you.

Dear Jessica

Please assist to take this file out and investigate on the rear bumper damaged.



Thanks and regards

**Stanley Ngu**

Manager

Body & Paint Division

**Eurokars Group of Companies**

**(Porsche, Rolls Royce, Mini, Mazda, McLaren)**

Eurokars Centre

12 Sungei Kadut Avenue

Singapore 729648

Tel: +65 63633003

DID: +65 63602845

Fax: +65 63602899

---

**From:** Simon Ho (LKKAuto) [<mailto:SimonHo@lkkauto.com>]

**Sent:** Monday, 12 March 2018 2:49 PM

**To:** Stanley Ngu <[stanley@eurokars.com.sg](mailto:stanley@eurokars.com.sg)>

**Cc:** Veron Chen (LKKAuto) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>; KKLau <[kklau@lkkauto.com](mailto:kklau@lkkauto.com)>; Sebastian Yeang (LKK Auto) <[SebastianYeang@lkkauto.com](mailto:SebastianYeang@lkkauto.com)>

**Subject:** SFU8238Y DOA:27/11/2017

Dear Stanley,

As spoken to you last Friday during our tele-conversation regards to the above.

The damaged on the rear bumper shown on the photos was repairable , thus we need your personal attention to assist to look into the matter.

FYI, our client opinion of this matter is the hairline scratched on the rear bumper are within repair.

Much appreciated for your kind assistant in this matter.

Looking forward to hear your favourable reply soonest possible.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: [simonho@lkkauto.com](mailto:simonho@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)