

Veron Chen (LKKAuto)

From: stanley@eurokars.com.sg
Sent: Tuesday, 13 March 2018 9:38 AM
To: Simon Ho (LKKAuto)
Cc: Veron Chen (LKKAuto); KKLau; Sebastian Yeang (LKK Auto); jessicahs@eurokars.com.sg
Subject: RE: SFU8238Y DOA:27/11/2017

Dear Simon

Please see attached and advise, which are the item you looking at to remove?



EUROKARS HABITAT PTE LTD
NO:12 SUNGEI KADUT, SINGAPORE 729648
FINALIZATION COST OF REPAIRS



MSIG INSURANCE SINGAPORE P/L 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807 ATTN. : MOTOR CLAIMS FAX :		NAME : MS WINNIE MOK ADDRESS : 10 PULASAN ROAD #01-07 SINGAPORE 424378 TEL : 96364546 (MR.CHAM @ 97777850)		WIP : 14798 EXCESS : DATE: 28-Nov-17	
VEH NO :	SFU8238Y	DATE IN :		CONTACT PERSON :	JOBI THOMAS 6360 2446
CHASSIS NO :	WMWXS52040T825313	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MINI COOPER F55	DATE REG.:	12-Dec-14	POLICY NO. :	
NATURE OF WORKS					
S/NO	Parts Description				
	QTY		REVISED	PRICES	
1	REAR BUMPER	1	M51.12.7.380.024	\$ 772.86	\$ 772.86
2	REAR BUMPER SENSOR HOLDER RH	1	M51.12.7.403.266	\$ 48.78	\$ 48.78
3	REAR BUMPER SENSOR HOLDER LH	1	M51.12.7.403.267	\$ 48.78	\$ 48.78
4	REAR BUMPER SPOILER	1	M51.12.7.380.030	\$ -	\$ 254.64
5	REAR BUMPER BLIND RIVET	4	M07.14.7.411.141	\$ 13.92	\$ 13.92
6	REAR WHEEL ARCH LH	1	M51.77.7.318.829	\$ 95.28	\$ 95.28
7	REAR BUMPER FOGLAMP CHROME	1	M51.12.7.365.737	\$ -	\$ 92.10
8	SPORT RIM	1	M36.11.6.855.111	\$ 960.78	\$ 960.78
9	SPORT RIM CAP	1	M36.13.6.857.149	\$ -	\$ 30.42
10	REAR SENSOR GASKET	4	B66.20.9.283.203	\$ 23.76	\$ 23.76
TOTAL PARTS				\$ 1,964.16	\$ 2,341.32
					\$ -
TOTAL PARTS COST				\$ 1,964.16	\$ 2,341.32



Thanks and regards

Stanley Ngu
Manager

Body & Paint Division

Eurokars Group of Companies
(Porsche, Rolls Royce, Mini, Mazda, McLaren)

Eurokars Centre
12 Sungei Kadut Avenue
Singapore 729648
Tel: +65 63633003
DID: +65 63602845
Fax: +65 63602899

From: Stanley Ngu

Sent: Tuesday, 13 March 2018 9:07 AM

To: 'Simon Ho (LKKAuto)' <SimonHo@lkkauto.com>; Jessica Harry Shastri <jessicahs@eurokars.com.sg>

Cc: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; KKLau <kklau@lkkauto.com>; Sebastian Yeang (LKK Auto) <SebastianYeang@lkkauto.com>; Jobi Thomas <jobithomas@eurokars.com.sg>

Subject: RE: SFU8238Y DOA:27/11/2017

Dear Simon

I will look into it and revert to you.

Dear Jessica

Please assist to take this file out and investigate on the rear bumper damaged.



Thanks and regards

Stanley Ngu

Manager
Body & Paint Division

Eurokars Group of Companies
(Porsche, Rolls Royce, Mini, Mazda, McLaren)

Eurokars Centre
12 Sungei Kadut Avenue
Singapore 729648
Tel: +65 63633003
DID: +65 63602845
Fax: +65 63602899

From: Simon Ho (LKKAuto) [<mailto:SimonHo@lkkauto.com>]

Sent: Monday, 12 March 2018 2:49 PM

To: Stanley Ngu <stanley@eurokars.com.sg>

Cc: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; KKLau <kklau@lkkauto.com>; Sebastian Yeang (LKK Auto) <SebastianYeang@lkkauto.com>

Subject: SFU8238Y DOA:27/11/2017

Dear Stanley,

As spoken to you last Friday during our tele-conversation regards to the above.

The damaged on the rear bumper shown on the photos was repairable , thus we need your personal attention to assist to look into the matter.

FYI, our client opinion of this matter is the hairline scratched on the rear bumper are within repair.

Much appreciated for your kind assistant in this matter.

Looking forward to hear your favourable reply soonest possible.

Best Regards,

Simon Ho
LKK Auto Consultants Pte Ltd
phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)