
























PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0483-17-N51

30 October 2017

ACCIDENT VEHICLE SURVEY REPORT

Wuan Yew Fong
Blk 127 Pasir Ris St 11 #13-391
Singapore 510127

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SKK5651A	<i>Odometer:</i>	210106km
<i>Make & Model:</i>	Toyota Rush 1.5A	<i>Colour:</i>	Grey
<i>Chassis number:</i>	J200E0007979	<i>Date of accident:</i>	26/04/2017
<i>Year of Regn.:</i>	06/11/2006	<i>Date inspected:</i>	28/04/2017
<i>Repairer at:</i>	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	03/05/2017

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.





