

SMRT Accident Vehicle Repair Estimates

EQ

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB234L
 Ref. No : TAX/11/17/2185
 Reg. Date : 01/01/1900 7/2/2019.
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : LIM GHIM SENG
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 30/11/2017 02:00:00 PM
 Accident Reported Date / Time : 30/11/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024093381
 Special Instruction to ARC, if any :
 GT5871G
 Prepared Date : 01/12/2017 08:22:28 AM



Sebastian.
 1/12/2017.
 - Imp Sum Repair.
 - Question Mark Item Photo.
 - Photo After Paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,014.00	0.00
Total Spray Painting Charges :	2,430.00	0.00
Total Material Charges :	4,332.38	4,420.80
Other Charges :	1,165.00	0.00
TOTAL :	8,941.38	0.00
Lum Sum Total :	8,950.00	0.00
No. of Repair Days :	6.00	0.00
Prepared / Adjusted By :		5 days
Arc / Surveyor Sing Off Date :	01/12/2017 09:03:43 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 01/12/2017 09:03:43 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	1,014.00	0.00 600
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO RESPRAY FRONT DOOR LH	378.00	0.00 200
TO RESPRAY REAR DOOR LH	378.00	0.00 200
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 100
TO RESPRAY REAR FENDER LH	378.00	0.00 200
TO RESPRAY RIM	180.00	0.00 50
RESPRAY WHEEL CAP	180.00	0.00 X
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY DOOR HANDLE	180.00	0.00 50
Total Spray Painting & Panel Beating	2,610.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00 30
TO TRANSFER DOOR MECHANISM	240.00	0.00 120
TO REMOVE / REFIT SEAT	120.00	0.00 50
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 ✓
TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	0.00 30
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	1,165.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
53802-47050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace <i>R</i>	No
75442-47030			NAME PLATE (PRIUS)	1	60.80	25.00	45.60	Replace	Replace <i>✓ NEC</i>	No
67002-47070		6505529	DOOR FRT/LH	1	894.40	25.00	670.80	Replace	Replace <i>✓ DT</i>	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace <i>✓ NEC</i>	No
69210-74030			DOOR OUTER HANDLE FRT/LH	1	370.80	25.00	278.10	Replace	Replace <i>R</i>	No
67004-47080		6505487	DOOR RR/LH	1	954.50	25.00	715.87	Replace	Replace <i>✓ PUN</i>	No
			PIXEL STICKER	1	60.00	0.00	60.00	Replace	Replace <i>✓ NEC</i>	No
68760-20122			HINGE UPPER LHR, DOOR	1	81.70	25.00	61.27	Replace	Replace <i>?</i>	No
68780-52031			HINGE LOWER LHR, DOOR	1	72.20	25.00	54.15	Replace	Replace <i>?</i>	No
68630-47031			CHECK ASSY, RR DOOR,	1	150.30	25.00	112.72	Replace	Replace <i>?</i>	No
75852-47900			MOULDING BODY, LH	1	673.60	25.00	505.20	Replace	Replace <i>R</i>	No
61602-47091		6505476	FENDER RR/LH	1	766.80	25.00	575.10	Replace	Replace <i>✓ DT</i>	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace <i>✓ NEC</i>	No
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace <i>✓ NEC</i>	No
62720-47031			QUARTER GLASS RR/LH	1	168.10	25.00	126.07	Replace	Replace <i>✓ NEC</i>	No
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace <i>✓ NEC</i>	No
42611-47140		6505658	WHEEL, DISC	1	1,490.20	25.00	1,117.65	Replace	Replace <i>✓ R</i>	No
42602-47060		6505676	CAP SUB-ASSY, WHEEL	1	174.10	25.00	130.57	Replace	Replace <i>✓ Cont</i>	No
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace <i>R</i>	No
			PIXEL STICKER	1	60.00	0.00	60.00	Replace	Replace <i>✓ NEC</i>	No
TOTAL MATERIALS							5,526.03	5,526.00		
TOTAL MATERIALS(Discounted)							4,332.38	4,420.80		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									