



1094 Lower Delta Road Motorway Building Singapore 169205  
Main +65.6468 2200 | Fax +65.6273 5535

AXA Insurance  
8 SHENTON WAY  
#27-01, AXA TOWER  
SINGAPORE 068811

Attn To Motor Claims:

ESTIMATES

VEHICLE NO. : SBT3353C  
CHASSIS NO : RU11116302  
ENGINE NO : L15B4036305  
MAKE / MODEL : HONDA VEZEL - 1.5  
YEAR : 2016  
DATE OF ACCIDENT : 25/11/2017 @ 10:30HRS

YOUR INSURED VEHICLE NUMBER : SHC5911C

| <u>PARTS DISCRIPTION</u>                 | <u>QTY</u> | <u>List Price</u> | <u>Total List Price</u> |
|------------------------------------------|------------|-------------------|-------------------------|
| REAR END PANEL <i>Rp-plu</i>             | 1          | \$ 470.60         | \$ 470.60               |
| REAR BUMPER LOWER ASSY                   | 1          | \$ 762.70         | \$ 762.70               |
| REAR LH BUMPER UPPER <i>Rp</i>           | 1          | \$ 156.70         | \$ 156.70               |
| REAR RH BUMPER UPPER <i>Rp</i>           | 1          | \$ 156.70         | \$ 156.70               |
| REAR LH BUMPER RETAINER <i>all</i>       | 1          | \$ 18.50          | \$ 18.50                |
| REAR RH BUMPER RETAINER <i>all</i>       | 1          | \$ 18.50          | \$ 18.50                |
| REAR BUMPER CLIPS <i>all</i>             | 10         | \$ 3.00           | \$ 30.00                |
| REAR LH BUMPER LOWER REFLECTOR <i>yo</i> | 1          | \$ 148.40         | \$ 148.40               |
| REAR RH BUMPER LOWER REFLECTOR <i>yo</i> | 1          | \$ 148.40         | \$ 148.40               |
| REAR TAILGATE ASSY <i>bt</i>             | 1          | \$ 838.90         | \$ 838.90               |
| REAR RH TAILGATE LAMP ASSY <i>?</i>      | 1          | \$ 284.60         | \$ 284.60               |
| REAR LH TAILGATE LAMP ASSY <i>x</i>      | 1          | \$ 284.60         | \$ 284.60               |
| REAR TAILGATE "VEZEL" LOGO <i>all</i>    | 1          | \$ 42.90          | \$ 42.90                |
| REAR TAILGATE "H" LOGO <i>all</i>        | 1          | \$ 28.70          | \$ 28.70                |
| REAR RH TAILLAMP ASSY <i>x</i>           | 1          | \$ 419.10         | \$ 419.10               |
| REAR TAILGATE LOCK ASSY <i>bt</i>        | 1          | \$ 101.40         | \$ 101.40               |
| REAR TAILGATE CATCH ASSY <i>bt</i>       | 1          | \$ 34.70          | \$ 34.70                |
| REAR TAILGATE TRIM BOARD <i>?</i>        | 1          | \$ 183.40         | \$ 183.40               |
| REAR END PANEL TOP GARNISH <i>?</i>      | 1          | \$ 115.10         | \$ 115.10               |
| REAR FLOOR PANEL <i>x</i>                | 1          | \$ 862.30         | \$ 862.30               |
| Total                                    |            | \$                | 5,106.20                |
| Less 10%                                 |            | \$                | 510.62                  |
| Total Spare Part                         |            | \$                | 4,595.58                |

LABOUR CHARGES

TO SPRAY PAINT ON THE AFFECTED AREAS  
TO REPAIR, REMOVE & REPLACE ALL THE DAMAGE ITEMS

|              |                        |
|--------------|------------------------|
|              | \$ 1,800.00            |
|              | \$ 3,150.00 <i>800</i> |
| Total Labour | \$ 4,950.00            |
| SUB ToTal    | \$ 9,545.58            |

|             |              |
|-------------|--------------|
| GST @ 7%    | \$ 668.19    |
| Grand Total | \$ 10,213.78 |

Tony Kuan  
 Motor Claims  
 Motorway Car Care Centre Pte Ltd  
 TEL: 6571 9635  
 FAX : 6278 5535  
 EMAIL: klkuan@motorway.com.sg  
 WEBSITE: www.motorway.com.sg

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer<br/>           Signature:<br/>           Date:</p> |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

Tanpin 97495749  
 'wp'  
 4/12/17 @ 3pm  
 5 days  
 Linnipsum  
 Resurvey after repair.  
 sur@lkkauto.com