

Date : 03/12/2017

TO: **AIG Asia Pacific Insurance Pte Ltd**
AIG Building
78 Shenton Way #07-16
Singapore 079120

vic

Our Customer : Ng Sook Leng

Vehicle No : SLD6258X

Model : BMW X1 SDRIVE 201 LED NAV

Manufacture Year : 2016

Date of Accident : 01-12-17

Total Estimate Repair Days : 7

Total Pages : 2

Attn : Motor Claim Department

Fax : 6415 3727

Re: Repair Estimate For Third Party Claim against SBH59R

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Front bumper <i>Defered</i>	1		754.60 \$0.00	✓
2	Front bumper clip <i>~</i>	10		90 \$0.00	✓ 30
3	Front bumper side retainer RH <i>ne</i>	1		25 \$0.00	✓
4	Front bumper lower pad <i>at</i>	1		348.80 \$0.00	✓
5	Front bumper side garnish RH <i>at</i>	1		\$0.00	✓
6	Front bumper side garnish RH, sensor <i>eye</i>	1		382 \$0.00	✓
7	Front bumper side garnish top chrome RH <i>at</i>	1		\$0.00	✓
8	Headlamp RH <i>at</i>	1		3466.80 \$0.00	✓
9	Front fender RH <i>Pris</i>	1	\$725.80	831.60 \$0.00	+
10	Front fender wheel arch RH <i>ne ~</i>	1		204.20 \$0.00	+
11	Front fender wheel arch clip <i>ne ~</i>	8	\$153.22	72 \$0.00	+
12	Front sports rim RH <i>2</i>	1		1980 \$0.00	+
13	Front absorber RH <i>ne ~</i>	1		642 \$0.00	+
14	Front knuckle arm RH <i>ne ~</i>	1		576.80 \$0.00	+
15	Front knuckle arm bearing RH <i>ne ~</i>	1		612.40 \$0.00	+
16	Front lower arm RH <i>ne ~</i>	2		418.40 \$0.00	+
	Front sensor RH - corner <i>ne ~</i>	382			+
	Fog lamp RH <i>angled</i>	336.60			
			Sub Total	\$0.00	
			Less 10%	\$0.00	
			Sub-Total 1	\$0.00	
A.	Spare Parts (S/Nett)				
1	Front tyre RH <i>ne ~</i>	1	750		+
			Sub-total 2		
			Total for Spare Parts	\$0.00	
B.	Labour				
1	To check wiring.			\$90.00	50
2	Panel beating charges to remove and replace damaged parts & areas.			\$800.00	250
3	Spray painting all affected parts & areas.			\$800.00	400
4	To remove and replace front and rear undercarriage.			\$250.00	+
5	To check and align wheels with computerized wheel alignment.			\$150.00	+



Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel : 6636 9100 Fax : 6636 9113

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
6	To spray anti-rust undercoating.			\$120.00	X
			Total Labour	\$2,210.00	
			Total Repair Cost	\$2,210.00	

total: 5833.22

h/c: 4650

Redraw.
Claim

Yours faithfully,

Aun Teng
f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

Adrian Lj

05/12/17.

h/s 04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer