

ASS. REC. BY:

REF:

CS/FCL17022971/R1rb02

Special Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

From (Person):

CWS Lurene Jan

of

FCL

Date/Time: 04.12.2017 331pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SHD 2144P

Insured:

SHC 177M

at Workshop m/s

Prime Auto

Tel:

6861 0908

of

6 Banoi Place

Policy No:

Claim No:

D17011157MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 01.12.2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wpi'

05.12.2017 @ morning

H.O.D. Endorsement:

Date/Time:

04.12.2017 4pm

Person Contacted:

Alice

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHD 2144P - x

SHC 177M - NA / MS67141016852/b4

DCA: 02/09/14

Sent preli through email to Lurene

confirm LIS \$1350, 3 days

Red: \$471, 26%

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SHD 2144P
 at Workshop this: PRIME
 of: Bhai m
 Insured: FCI / up
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 2144P Yr Regn: 2015 May
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Truck / Prime Mover /
 Truck / Trailer or
 Make: TOYOTA PRIMS HYBRID 1.8 cc: 1797
 Colour: Brown A/C: _____ Insured / Std / NI / NA
 Sp. Reading: 299034 T. Radio: Insured / Std / NI / NA
 Eng. No: _____
 C/No: ZVW 300412645
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or
 Brake: Order / Jammed / Leaked / Burnt or
 Modl: 1.8 / S/Rim / STD A/Rim or
 Tyre Size: F: 185/65R15
 R: 185/65R15
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or GOODYEAR
 Front: _____ Rear: _____
 R/Bal: 5 mm R/Bal: 5 mm
 L/Bal: 5 mm L/Bal: 5 mm
 D.O.A: 01/14/17 D.O.A: 05/12/17
 Survey held at: PRIME AUTO
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 14 DEC 2017

Date/Time: File Pass to:

1) typist

Date/Time: File Return to:

2) _____

Report Format: TP

Lump Sum / 1356.00

Days Of Repair: 3

Resurvey No. of Trips: 1

Add Fee:

☐ Site Insp \$
☐ Inter. Insp \$
☐ Tech. Insp \$
☐ Pres. Insp \$

Survey Fee

Transportation

Food & Drink

Fuel

Other

100

50

50

24

224



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17022971/R1rb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 04-12-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 177M	Veh. Inspected	SHD 2144P
Policy No.		Coverage (\$)	0.00
Claim No.	D17011157MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	04/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	01/12/2017	Inspection Date	05/12/2017
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	04-12-2017	Our Ref No. D17011157MFSH
Accident Date	01-12-2017	Claim Type. Third Party
Insured Vehicle	SHC0177M	Third Party Vehicle. SHD2144P
Survey Location	5 BENOI PLACE	
Contact Person.	ALICE LEONG	
Contact No.	68610908/ 87819005	Fax No. 65152948
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PRIME AUTO CLAIMS SERVICE PTE. LTD.	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231361)



PRI Documents



Close X

PRI Header Details

Claim No	D17011157MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & PRI PTE LTI
Workshop Name	PRIME AUTO CLAIMS SERVICE PTE. LTD. (Contact Person : ALICE LEONG)	Survey Location & Contact Details	5 BENOI PLACE Mobile: 87819005 , Phone: 68610908 , Fax: EmailId: ALICELEONG@PRIMEAUTOCLAIMS.C		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0177M	TP Vehicle No	SHD21
PRI Recieved Date	04-12-2017 04:26:21 PM	Surveyor Appointed Date	04-12-2017 03:31:03 PM	Surveyor Accept Date	04-12-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	04-12-2017	Upload Survey Report *:	
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17011157MFSH

Our Ref: CS/FCI17022971/R1rb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 2144P

Please be informed that we had conducted the inspection of the above mentioned vehicle on 05/12/2017 at the premises of M/s PRIME AUTO and have the following to report:-

Workshop Estimate Amount	: S\$ <u>1,821.00</u>
Revised Estimate Amount	: S\$ <u>1,721.00</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at the rear portion.



Yours faithfully

RASUL
Automotive Assessor



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
5 Benoi Place Singapore 629926
Tel: 6861 0908 Fax: 6515 2948

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date: 01.12.2017

First Capital Insurance Ltd
36 Robinson Road #16-01
City House
Singapore 068877

Attn: Motor Claims Dept

RE: COST OF REPAIR TO VEHICLE SHD2144P TOYOTA PRIUS HYBRID 1.8L A (2014)

To Supply

1)	1pc	Rear bumper	\$	1,218.00 <i>PE</i>
2)	1pc	Rear bumper clip	\$	30.00 <i>an</i>
3)	1pc	Rear bumper right side retainer	\$	90.00 <i>an</i>
4)	1pc	Rear bumper left side retainer	\$	90.00 <i>an</i>

Sub total parts	\$	1,428.00
Less: 25% discount	\$	357.00
	\$	1,071.00

To Supply S.Nett Parts

1)	1pc	Rear bumper advertisement sticker	\$	100.00 <i>new</i>
-----	-----	-----------------------------------	----	-------------------

Sub total S.Nett Parts	\$	100.00
------------------------	----	--------

L/charges

1)	To remove & replace rear bumper, knock end panel. Adjust and align rear bumper.	\$	350.00 <i>300</i>
2)	To putty, respray painting rear bumper & end panel outer. To polish	\$	300.00 <i>250</i>

Sub total L/charges	\$	650.00
Estimated Grand Total	\$	1,821.00

*Resall
4p 90010068
3 days
45
05/12/17 @ 0910
Resurvey after repair*

Jmu



PRIME GROUP

Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

5 Benoi Place Singapore 629926

Tel: 6861 0908 Fax: 6515 2948

Date: 01.12.2017

First Capital Insurance Ltd

36 Robinson Road #16-01

City House

Singapore 068877

Attn: Motor Claims Dept

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RE: COST OF REPAIR TO VEHICLE SHD2144P TOYOTA PRIUS HYBRID 1.8L A (2014)

To Supply

1)	1pc	Rear bumper	\$	1,218.00	PE ✓
2)	1pc	Rear bumper clip	\$	30.00	✓
3)	1pc	Rear bumper right side retainer	\$	90.00	✓
4)	1pc	Rear bumper left side retainer	\$	90.00	✓

Sub total parts	\$	1,428.00
Less: 25% discount	\$	357.00
	\$	1,071.00 ✓

To Supply S.Nett Parts

1)	1pc	Rear bumper advertisement sticker	\$	100.00	neg ✓
-----	-----	-----------------------------------	----	--------	-------

Sub total S.Nett Parts \$ 100.00

L/charges

1)	To remove & replace rear bumper, knock end panel. Adjust and align rear bumper.	\$	350.00	300 ✓
2)	To putty, respray painting rear bumper & end panel outer. To polish	\$	300.00	250 ✓

Sub total L/charges	\$	650.00	580.00 ✓
Estimated Grand Total	\$	1,821.00	1721.00 ✓

Repair
4p 90010068
3 days
4s
05/12/17 0910
Dinner after repair

less: 20% LS - 344.20
1576.80
LS 1350/-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17022971/R1rbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 21-12-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 177M	Veh. Inspected	SHD 2144P	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17011157MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	04/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS HYBRID 1.8	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	ZVW300412645	Colour	BROWN	
Odometer	299034	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	GOODRIDE	5 mm	
L/H Front Tyre	185/65 R15	GOODRIDE	5 mm	
R/H Rear Tyre	185/65 R15	GOODRIDE	5 mm	
L/H Rear Tyre	185/65 R15	GOODRIDE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/12/2017	Inspection Date	05/12/2017	
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 2144P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	1,218.00	1,218.00
1	REAR BUMPER CLIP	NECESSARY	30.00	30.00
1	REAR BUMPER RIGHT SIDE RETAINER	NECESSARY	90.00	90.00
1	REAR BUMPER LEFT SIDE RETAINER	NECESSARY	90.00	90.00
	LESS 25% DISCOUNT		-357.00	-357.00
			1,071.00	1,071.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER ADVERTISEMENT STICKER (SN)	NECESSARY	100.00	100.00
			100.00	100.00
	<u>LABOUR</u>			
	TO REMOVE & REPLACE REAR BUMPER,KNOCK END PANEL,ADJUST AND ALIGN REAR BUMPER.		350.00	300.00
	TO PUTTY,RESPRAY PAINTING REAR BUMPER & END PANEL OUTER.TO POLISH.		300.00	250.00
			650.00	550.00
	GRAND TOTAL		1,821.00	1,721.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,350.00

Report Ref No. CS/FCI17022971/R1rbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.