

ASS. REC. BY:

REF:

CS/CTU7022973/Krbel

Special Instruction:

Surveyor  
Melimen

Kenneth

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTL

Date/Time:

04/12/2017 3:44pm

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFJ 777Y

Insured:

GW 3197S

at Workshop m/s

Lai Huat (Meng Kee)

Tel:

6453 8110

of

160 Sin ming Road #04-01

Policy No:

OMCVSN1617701701

Claim No:

SNM17D06901C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

01/12/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

05/12/2017 @ morning

H.O.D. Endorsement:

Date/Time:

04/12/2017 3:51pm

Person Contacted:

Jenny

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SFJ 777Y - X
	GW 3197S - X
11.45am. 5/11/18	Confirmed with Jenny via phone LIS \$3350 @ 6 days
	led: \$951.65, 22%.

ASS. REC. BY:

REF:

C721

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 11/27 Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SFJ MMYYr Regn: 01, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: HondaC.C. 1799Colour: White

A/C: Insured / Std / NI / NA

Sp. Reading: 165639

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: J14MRN0840PS2013F4Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: Continental 205/65R15R: Dayton

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mmR/Bal. 8 mmL/Bal. 9 mmL/Bal. 8 mmD.O.A. 11/12/17D.O.A. 5/12/17

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6/12/17 per to Catkins

RECEIVED 07 NOV 2018

Date/Time, File Pass to?

☐ : Prell. Report1) typist☒ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 6Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Survey Fee: 220

Transportation: \_\_\_\_\_

S + RS. \$ \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

220Report Format: TPLump Sum / L.B.I. (\$) 3350.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17022973/Krb	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 04-12-2017	
		Code : CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	GW 3197S	Veh. Inspected	SFJ 7777Y
Policy No.	DMCVSN1617701701	Coverage (\$)	0.00
Claim No.	SNM17D06901C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	04/12/2017
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	01/12/2017	Inspection Date	05/12/2017
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Dec 2017 Sendback Est	02 Dec 2017 11:21 S\$4,301.65	04 Dec 2017 15:44 Assign				New Assignment Cancel Case

MainReferenceClaim DetailsDocumentsShow All

CLAIM SUBFOLDER DETAILS

Insured:--, ID: --

Main Claimant:CHIA AH SAH, ID: S0286295F

Vehicle Reg. No.:SFJ7777Y

Claim Type:TP / SNM17D06901C02

Vehicle Reg. No. (Insured):GW3197S

Date of Loss:01/12/2017 16:00 - :59

Policy/Cover Note No.:DMCVSN1617701701

Policy No. (Claimant):17-MY008392-R03

Excess:S\$0.00

Repairer:Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110

Handling Insurer:China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]

Claimant's Insurer:Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111

Adjuster:LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/12/2017]

Adj Asg. Remarks:PLEASE ASSIST TO CONDUCT PRS AND REVERT WITH YOUR RECOMMENDATION

ASSOCIATED MAIL RECEIVED

View AllCompose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View AllSearch TasksCreate New TaskComplete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**LAI HUAT (MENG KEE)  
MOTOR PTE LTD  
SIN MING INDUSTRIAL  
ESTATE SECTOR A  
BLK 21 #01-58  
SINGAPORE 575679**

**Claim Reference:**  
**Assessment Number: LHMJ0551**  
**Version: LAI HUAT/4**  
**Date Calculated: 02/12/2017 03:06**

**Full Report - V1**  
**Registration: SFJ 7777Y**  
**Printed: 02/12/2017 11:06**

### Summary Information

#### Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Jenny Lim	Date of Incident:	01/12/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	TP-GW 3197S	Quote Due Date:	
Other Reference:	TP CLAIM	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

### Vehicle Details

#### Vehicle

Manufacturer:	*Honda
Model:	*Stream 1.8L
Sub Model:	
Model Sheet Number:	HAB 01
Registration:	SFJ 7777Y
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

#### Model Specs

FROM MODEL 1999	TWO COAT METALLIC
PREPARE OFF VEHICLE	

*Not Authored  
61/12/87  
Repair After Repair  
6 days*

### Vehicle Condition

#### Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	01/12/2017
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	01/12/2017 17:54
Date Of Accident	01/12/2017 16:20
Exact Location Of Accident	TOA PAYOH LORONG 4 (TOWARDS CENTRAL)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFJ7777Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHIA AH SAH
NRIC No	S0286295F
Email Address	CHIAAHSAH@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96651614
Alternative Phone No	OTHERS-96651614

### Vehicle Particulars

Manufacturer	HONDA
Model	STREAM-1.8 L (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	17-MY008392-R03
Cover Note Number	

### Driver

Name of Driver	CHIA YUNG MING DANIEL (XIE YONGMING DANIEL)
NRIC No	S7507177I
Date Of Birth	02/03/1975
Occupation	INDOOR
Date Of Driving Pass	16/07/1993
Driving Experience	24 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90904545
Fax Number	
Contact Number	
Email Address	DANIEL.CHIA@GECAS.COM

Address	BLK 224 BISHAN STREET 23 #13-129
Postcode	570224
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I was travelling along Toa Payoh Lorong 4 (towards Central) on 1/12/2017 at 4.20pm and my car (Vehicle A) was waiting to make a right turn (signal on) into the car park of Blk 81B. While Vehicle A was stationary and waiting for traffic to clear, Vehicle B failed to stop and drove right into the rear of my car (Vehicle A) resulting in an accident thus causing damages to the car.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GW3197S
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	MOHAMMAD SUFFIAN BIN ROSELI
NRIC/Passport Number	S9214522J
Contact Number	88181567
Address	BLK 188 BUKIT BATOK WEST AVENUE 6 #02-15
Postcode	650188
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name	
Phone Number	
Email Address	


**SKETCH PLAN**


**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time: - 1 DEC 2017


  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:  
 1/12/17

  
 Reporting Centre Personnel's Signature  
 Name: Deborah Lai  
 NRIC/FIN No.: S7332811Z



# Sketch Plan Pg. 2

## SKETCH PLAN




## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I was travelling along Toa Payoh Lor 4 (towards central) on 1 Dec'17 @ 4.20 pm and my car (Veh A) was waiting to make a right turn (signal on) into the carpark of BLK 81B;

While veh A was stationary and waiting for traffic to be clear, veh B fail to stop and drove right into the rear of my car (Veh A), resulting in an accident thus causing damage to the car.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time: - 1 DEC 2017

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: 5.50 pm 1 Dec'17

  
 Reporting Centre Personnel's Signature  
 Name: Deborah Lai  
 NRIC/FIN No.: S7332811Z

**REPUBLIC OF SINGAPORE DRIVING LICENCE**



Licence Number: **S75071771**  
 Name: **CHIA YUNG MING DANIEL  
 (XIE YONGMING DANIEL)**  
 Birth Date: **02 Mar 1975**  
 Issue Date: **14 Jul 2003**

000656932A

**REPUBLIC OF SINGAPORE**  
**IDENTITY CARD NO. S75071771**



Name: **CHIA YUNG MING DANIEL  
 (XIE YONGMING DANIEL)**  
 谢永明  
 Race: **CHINESE**  
 Date of birth: **02-03-1975** Sex: **M**  
 Country of birth: **SINGAPORE**

S75071771

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE: **16 Jul 1993**

NP 428A

Licence No: S75071771

3835121



NRIC No. **S75071771**



Date of issue: **02-02-2006**

Address: **APT BLK 224 BISHAN STREET 23  
 #13-129  
 SINGAPORE 570224**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	6295F

### Vehicle Details

Vehicle No.	SFJ7777Y
Vehicle to be Exported	Yes
Intended De-registration Date	01 Dec 2017
Vehicle Make	HONDA
Vehicle Model	STREAM 1.8L A
Primary Colour	Silver
Manufacturing Year	2007
Engine No.	R18A12801395
Chassis No.	JHMRN68408S201374
Maximum Power Output	103.0 kW (138 bhp)
Open Market Value	\$20,549.00
Original Registration Date	24 Jan 2008
First Registration Date	24 Jan 2008
Transfer Count	1
Actual ARF Paid	\$22,604.00

### Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	23 Jan 2018
PARF Rebate Amount	\$11,302.00

### Intended COE Rebate Details

COE Expiry Date	30 Nov 2027
COE Category	B - Car (1601cc & above)
COE Period(Years)	10
PQP Paid	\$50,168.00
COE Rebate Amount	\$50,154.00
<b>Total Rebate Amount</b>	<b>\$61,456.00</b>

The information contained herein is correct as at 01 Dec 2017

OK

# Thank you



Lai Mei Ling Deborah has successfully logged out.

Your last login date and time was 01 Dec 2017, 17:52:44.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

## Session Transaction History

<u>S/No.</u>	<u>Asset</u> <u>Type</u>	<u>Asset ID</u>	<u>Asset</u> <u>Owner ID</u>	<u>Transaction Type</u>	<u>Transaction</u> <u>Amount(S\$)</u>	<u>Log</u> <u>Date/Time</u>
1	Vehicle	GW3197S	-	18.32 Insurance Enquiry (GIRO Payment)	5.35	01 Dec 2017 / 17:53:29
2	Vehicle	SFJ7777Y	-	18.32 Insurance Enquiry (GIRO Payment)	5.35	01 Dec 2017 / 17:53:13

# 來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity  
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722  
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg  
UEN: 199407592C

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

--

Singapore

Claimant Insurer: Tokio Marine Insurance Singapore Ltd

## PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	69039
Policy No:		Date of Loss:	01/12/2017
Vehicle Reg. No.:	SFJ7777Y	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	CHIA YUNG MING DANIEL (XIE YONGMING DANIEL)		
Make/Model:	HONDA STREAM, 1.8 L (A)	Vehicle Reg. Date:	24/01/2008
Vehicle Colour:	SILVER		
Engine No:	R18A12801395	Chassis No:	JHMRN68408S201374
Odometer:	165639 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	12		

Description of Accident/Loss: I WAS TRAVELLING ALONG TOA PAYOH LORONG 4 (TOWARDS CENTRAL) ON 1/12/2017 AT 4.20PM AND MY CAR (VEHICLE A) WAS WAITING TO MAKE A RIGHT TURN (SIGNAL ON) INTO THE CAR PARK OF BLK 81B.

WHILE VEHICLE A WAS STATIONARY AND WAITING FOR TRAFFIC TO CLEAR, VEHICLE B FAILED TO STOP AND DROVE RIGHT INTO THE REAR OF MY CAR (VEHICLE A) RESULTING IN AN ACCIDENT THUS CAUSING DAMAGES TO THE CAR.

Present Location: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) / JASON TAN

COST OF CLAIMS	Amount
Parts	2,355.15
Miscellaneous Items	787.00
Labour	1,159.50
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	4,301.65
+ GST 7.00% (S\$)	301.12
Nett Amount (S\$)	4,602.77

This claim is handled by: JASON TAN

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 02 Dec 2017)

**Parts:** M1-MPV      HONDA STREAM 1.8 L (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** Lai Huat (Meng Kee) Motor Pte Ltd/SFJ7777Y/02/12/2017 11:21

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*BADGE "ODYSSEY"	0.00	0.00	rec *32.00 F ✓
2	1	NA	*BADGE HONDA	0.00	0.00	rec *20.00 F ✓
3	1	NA	*BOOT/TAILGATE LOCK	0.00	0.00	del *85.00 F ✓
4	1	NA	*BOOTLID/TAILGATE	0.00	0.00	bt *605.00 F ✓
5	1	NA	*L/R LAMP	0.00	0.00	cm *235.00 F ✓
6	1	NA	*LOWER TAILGATE TRIM	0.00	0.00	mtjcm *115.00 F ✓
7	1	NA	*LWR REAR SCREEN SEAL	0.00	0.00	rec *30.00 F ✓
8	1	NA	*REAR BUMPER	0.00	0.00	cm *396.00 F ✓
9	1	NA	*REAR SCREEN	0.00	0.00	shutfixed *550.00 F ✓
10	1	NA	*REAR WIPER BLADE	0.00	0.00	but *35.00 F ✓
11	1	NA	*TAILGATE OUTER GARNH	0.00	0.00	cm *125.00 F ✓
12	1	NA	*TOW HOOK COVER	0.00	0.00	mil *15.00 F ✓

F=Franchise part.

Sub Total (S\$)	2,243.00
+ Margin on L,N Items 5.00% (S\$)	112.15
<b>Total Parts (S\$)</b>	<b>2,355.15</b>

Lai Huat (Meng Kee) Motor Pte Ltd/SFJ7777Y/02/12/2017 11:21. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	AUDATEX FEE	42.00 ✓
2	1	REAR NUMBER PLATE	35.00 ✓
3	1	REVERSE SENSOR (4 PCS)	280.00 ✓
4	1	SUNDRY PARTS	100.00 ✓
5	1	TUFF COAT	40.00 ✓
6	1	UV FILM + INSTALL	250.00 ✓
7	1	WINDSCREEN SEALANT	40.00 ✓
Sub Total (S\$)			787.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	Total Paint Labour	New	473.80 ✓
2	Total Paint Materials	New	188.90 ✓
3	Total Panel/Mechanical Labour	New	496.80 ✓
Gross Labour Cost (S\$)			1,159.50

Lai Huat (Meng Kee) Motor Pte Ltd/SFJ7777Y/02/12/2017 11:21. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

# LAI HUAT (MENG KEE) MOTOR PTE LTD

Claim Reference:

Assessment Number: LHMJ0551



Version: LAI HUAT/4

Date Calculated: 02/12/2017 03:06

Full Report - V1

Registration: SFJ 7777Y

Printed: 02/12/2017 11:06



## Addresses

## Cost Summary

Total Labour	\$970.60
Total Paint/Material	\$188.90
Total Parts	\$2,355.15
Total of Additional Costs	\$787.00
Excess:	TBA
Grand Total Exc GST:	\$4,301.65
7 % GST:	\$301.12
Grand Total Inc GST:	\$4,602.77

## Repair Information

### LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR

Price/Dent = \$46.00/HR

### Repair /

### Guide Number Repair Details

		WU	Cost Price (\$)
NN	RENEW REAR NUMBER PLATE (REMOVED)	2.0	9.20
NN	RENEW REAR BUMPER (REMOVED)	2.0	9.20
NN	R + R L/TAILLAMP	5.0	23.00
NN	R + R TAILGATE	10.0	46.00
	INCLUDES: R + R TRIM AND GAS PRESSURE SPRING		
NN	RENEW TAILGATE (REMOVED)	57.0	262.20
	INCLUDES: R + R REAR SCREEN, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		
NN	TAILGATE OUTER GARNH R&R / NEW PARTS	2.0*	9.20
2711	REPAIR REAR PANEL	15 20.0*	92.00
3571	REPAIR L/R DRIP RAIL	8 10.0*	46.00

### LABOUR COST

#### Total Work Units

108.0

#### Corrosion Protection External Labour

0.0HRS

0.00

#### Corrosion Protection Internal Labour

0.0HRS

0.00

#### Sub Total

10.8HRS

\$496.80

#### Paint Labour

10.3HRS

\$473.80

#### Total Labour

21.1HRS

\$970.60

### PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$46.00/HR

### Guide Number Description

- TWO COAT METALLIC
- PREPARE OFF VEHICLE

WU

Cost Price (\$)



# LAI HUAT (MENG KEE) MOTOR PTE LTD

**Claim Reference:**

**Assessment Number: LHMJ0551**

**Version: LAI HUAT/4**

**Date Calculated: 02/12/2017 03:06**

**Full Report - V1**

**Registration: SFJ 7777Y**

**Printed: 02/12/2017 11:06**

2931	BOOTLID/TAILGATE NEW PART PAINTING	16.0	
2583	REAR BUMPER NEW PART PAINT K1R	12.0	
2711	REAR PANEL REPAIR PAINTING <50%	11.0	
3481	L/R WING SURFACE PAINT	7.0	
3482	R/R WING SURFACE PAINT	7.0	
1000	TOW HOOK COVER NEW PART PAINT	5.0*	✓
1000	TAILGATE OUTER GARNHNEW PART PAINT	15.0*	✓
<b>LABOUR COST - PAINT</b>			
<b>TIME(PAINT)</b>		<b>73.0</b>	
Preparation Main Work Plastic		5.0	
Preparation Main Work Metal		25.0	
Preparation Work Multi Layer Paint		0.0	
Total Work Units (10WU/HR)		103.0	
Total Paintwork Labour		10.3HRS	
<b>MATERIAL COST - PAINT</b>			<b>\$473.80</b>
<b>Cost Price</b>			
New Part Painting			\$45.92
New Part Painting - Plastic K1R			\$57.07
Material-Constant Main Work Metal			\$28.60
Surface-/Blend Paint			\$36.36
Repair Painting			\$11.95
Material-Const Main Work Plastic			\$9.00
Total Excluding Pearlescent Uplift			\$188.90
Pearlescent Uplift @ 0.0%			\$0.00
Total Paint Material Cost			\$188.90

## PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
3016	1	BADGE "ODYSSEY"			0% <i>AN</i> 32.00* ✓
3015	1	BADGE HONDA			0% <i>AN</i> 20.00* ✓
2977	1	BOOT/TAILGATE LOCK			0% <i>AN</i> 85.00* ✓
2931	1	BOOTLID/TAILGATE			0% <i>AN</i> 605.00* ✓
3281	1	L/R LAMP			0% <i>CM</i> 235.00* ✓
4907	1	LOWER TAILGATE TRIM			0% <i>mycm</i> 115.00* ✓
3171	1	LWR LOCK SUPPORT	91503SR3003		0% <i>AN</i> 0.00F X
3161	1	LWR REAR SCREEN SEAL			0% <i>AN</i> 30.00* ✓
3170	4	LWR RUBBER MOUNTING	91567SV4003		0% <i>AN</i> 0.00F X
2583	1	REAR BUMPER			0% <i>CM</i> 396.00* ✓
2702	1	REAR NUMBER PLATE	KNPL6		0% <i>AN</i> 0.00F X
3151	1	REAR SCREEN	USE SINGLE PARTS	<i>Shutter</i>	0% 550.00F ✓
3164	4	REAR SCREEN SPACER	73221SR4000		0% <i>AN</i> 0.00F X
3168	4	REAR SCREEN SUPPORTS	91563SV4003		0% <i>AN</i> 0.00F X
3227	1	REAR WIPER BLADE			0% <i>CM</i> 35.00* ✓
3172	1	RUBBER MOUNTING SET	04733SX0000		0% <i>AN</i> 0.00F X
1000	1	TAILGATE OUTER GARNH			0% <i>CM</i> 125.00* ✓
1000	1	TOW HOOK COVER			0% <i>AN</i> 15.00* ✓
f: OEM Parts				Saving	\$252.64
g: Original				Sub Total	\$2,243.00
h: Secondhand				Mark Up From Cost (5 %)	\$112.15
p: Parallel				Sundry Parts (Fixed)	\$0.00
x: Exchange				<b>Total Parts</b>	<b>\$2,355.15</b>

**THIS ASSESSMENT CONTAINS UNPRICED PARTS**

**NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER**

**Extras**

# LAI HUAT (MENG KEE) MOTOR PTE LTD

**Claim Reference:**

**Assessment Number: LHMJ0551**

**Version: LAI HUAT/4**

**Date Calculated: 02/12/2017 03:06**

**Full Report - V1**

**Registration: SFJ 7777Y**

**Printed: 02/12/2017 11:06**

Description	Betterment	Price
REVERSE SENSORS SPECIALIST 4PCS	0%	<i>nd</i> \$280.00 ✓
SUPPLY W/S SPECIALIST SEALANT		<i>nd</i> \$40.00 ✓
UV FILM + INSTALL SPECIALIST	0%	<i>nd</i> \$250.00 <i>200sn</i>
TUFF COAT SPECIALIST		\$40.00 ✓
AUDATEX FEE SPECIALIST	0%	\$42.00 ✓
REAR NUMBER PLATE SPECIALIST		<i>nd</i> \$35.00 ✓
SUNDRY PARTS SPECIALIST	0%	\$100.00
<b>Total Extras</b>		<b>\$787.00</b>

## Final Calculation

<b>Total Parts</b>		<b>\$2,355.15</b>
<b>Labour</b>		
Total Panel/Mechanical	<i>455.40</i> \$496.80	
Total Paintwork	\$473.80	
<b>Total Labour</b>	<i>450.80</i>	<b>\$970.60</b>
<b>Additional Costs</b>		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$787.00	
<b>Total of Additional Costs</b>		<b>\$787.00</b>
<b>Total Paint/Material Costs</b>		<b>\$188.90</b>
<b>Grand Total Excludes GST</b>		<b>\$4,301.65</b>
GST @ 7 %		<b>\$301.12</b>
<b>Grand Total Includes GST</b>		<b>\$4,602.77</b>

## Assessment Notes

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

**Janice Lee (LKKAUTO)**

---

**From:** Jenny Lim <jenny.lim@laihuat.com.sg>  
**Sent:** Friday, May 25, 2018 9:21 AM  
**To:** Kenneth Ho  
**Subject:** Finalisation - SFJ 7777Y / Honda Stream  
**Attachments:** SFJ 7777Y.pdf; IMG\_6970.jpg; IMG\_6971.jpg; IMG\_6972.jpg; IMG\_6973.jpg

Dear Sir

For your confirmation, please:

- Parts: \$2,243.00
- 5%: \$ 112.15
- SN: \$ 737.00
- L&P: \$1,118.10

Sub-total: \$4,210.25

LS -20%: (\$842.05) = \$3,368.20

**Lump sum: \$3350.00 / 12 days**

Supporting document and photographs are enclosed for your reference.

Thank you.

Kind regards.

Jenny Lim  
for LAI HUAT (MENG KEE) MOTOR PTE LTD  
160 Sin Ming Drive  
#04-01, #04-02 & #07-03  
Sin Ming Autocity  
Singapore 575722  
Tel: 64538110  
Fax: 64596267

**LAI HUAT (MENG KEE)  
MOTOR PTE LTD  
SIN MING INDUSTRIAL  
ESTATE SECTOR A  
BLK 21 #01-58  
SINGAPORE 575679**

**Claim Reference:**  
**Assessment Number: LHMJ0551**  
**Version: LAI HUAT/5**  
**Date Calculated: 10/01/2018 15:53**

**Full Report - V1**  
**Registration: SFJ 7777Y**  
**Printed: 10/01/2018 23:53**

---

**Summary Information**

**Claim**

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Jenny Lim	Date of Incident:	01/12/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	TP-GW 3197S	Quote Due Date:	
Other Reference:	TP CLAIM	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

---

**Vehicle Details**

**Vehicle**

Manufacturer:	*Honda
Model:	*Stream 1.8L
Sub Model:	
Model Sheet Number:	HAB 01
Registration:	SFJ 7777Y
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

**Model Specs**



FROM MODEL 1999	TWO COAT METALLIC
PREPARE OFF VEHICLE	

---

**Vehicle Condition**

**Vehicle Status**

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	01/12/2017
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

**LAI HUAT (MENG KEE) MOTOR PTE LTD****Full Report - V1****Claim Reference:****Assessment Number: LHMJ0551****Registration: SFJ 7777Y****Version: LAI HUAT/5****Printed: 10/01/2018 23:53****Date Calculated: 10/01/2018 15:53****Addresses****Cost Summary**

Total Labour	\$929.20
Total Paint/Material	\$188.90
Total Parts	\$2,355.15
Total of Additional Costs	\$737.00
Excess:	TBA
Grand Total Exc GST:	\$4,210.25
7 % GST:	\$294.72
Grand Total Inc GST:	\$4,504.97

**Repair Information****LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR  
Price/Dent = \$46.00/HR

**Repair /****Guide Number Repair Details**

		WU	Cost Price (\$)
NN	RENEW REAR NUMBER PLATE (REMOVED)	2.0	9.20
NN	RENEW REAR BUMPER (REMOVED)	2.0	9.20
NN	R + R L/TAILLAMP	5.0	23.00
NN	R + R TAILGATE	10.0	46.00
	INCLUDES: R + R TRIM AND GAS PRESSURE SPRING		
NN	RENEW TAILGATE (REMOVED)	57.0	262.20
	INCLUDES: R + R REAR SCREEN, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		
NN	TAILGATE OUTER GARNH R&R / NEW PARTS	2.0*	9.20
2711	REPAIR REAR PANEL	15.0*	69.00
3571	REPAIR L/R DRIP RAIL	6.0*	27.60

**LABOUR COST**

<b>Total Work Units</b>	<b>99.0</b>	
<b>Corrosion Protection External Labour</b>	<b>0.0HRS</b>	<b>0.00</b>
<b>Corrosion Protection Internal Labour</b>	<b>0.0HRS</b>	<b>0.00</b>
<b>Sub Total</b>	<b>9.9HRS</b>	<b>\$455.40</b>
<b>Paint Labour</b>	<b>10.3HRS</b>	<b>\$473.80</b>
<b>Total Labour</b>	<b>20.2HRS</b>	<b>\$929.20</b>

**PAINT WORK**

Time Basis 10 WU = 1 HR. Price = \$46.00/HR

**Guide Number Description**

	WU	Cost Price (\$)
- TWO COAT METALLIC		
- PREPARE OFF VEHICLE		

Police Station Of Origin:

Marine Parade N.P.C

300 Marine Parade Road SINGAPORE 449296

Tel No: 1800-4428999



T/20121207/4011

2 of 3

Report No. T/20121207/4011

### CONTINUATION OF REPORT

Driver			
Name	AZLI BIN ABDUL KADIR	ID No.	S7229566H
Related Vehicle	NIL	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL	Degree of Injury	NIL

**Brief Details. This report shall be signed by the informant.**

On the above mentioned date, time and location, while i was travelling along the said highway along the centre lane, my car had skidded due to the wet surface and i had collided with the center railling, there was no one injured, no traffic police attended to me at the point of time, i was advised by my insurance company to lodge a report for my own insurance claims.

Damages to my vehicle, scratches, dents on my front bumper and my headlights

**LAI HUAT (MENG KEE) MOTOR PTE LTD****Full Report - V1****Claim Reference:****Assessment Number: LHMJ0551****Registration: SFJ 7777Y****Version: LAI HUAT/5****Printed: 10/01/2018 23:53****Date Calculated: 10/01/2018 15:53**

<b>Description</b>		<b>Betterment</b>	<b>Price</b>
REVERSE SENSORS SPECIALIST 4PCS		0%	\$280.00
SUPPLY W/S SPECIALIST SEALANT			\$40.00
UV FILM + INSTALL SPECIALIST		0%	\$200.00
TUFF COAT SPECIALIST			\$40.00
AUDATEX FEE SPECIALIST		0%	\$42.00
REAR NUMBER PLATE SPECIALIST			\$35.00
SUNDRY PARTS SPECIALIST		0%	\$100.00
<b>Total Extras</b>			<b>\$737.00</b>

**Final Calculation**

<b>Total Parts</b>		<b>\$2,355.15</b>
<b>Labour</b>		
Total Panel/Mechanical	\$455.40	
Total Paintwork	\$473.80	
<b>Total Labour</b>		<b>\$929.20</b>
<b>Additional Costs</b>		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$737.00	
<b>Total of Additional Costs</b>		<b>\$737.00</b>
<b>Total Paint/Material Costs</b>		<b>\$188.90</b>
<b>Grand Total Excludes GST</b>		<b>\$4,210.25</b>
GST @ 7 %		\$294.72
<b>Grand Total Includes GST</b>		<b>\$4,504.97</b>

**Assessment Notes**

**Claim Reference:**  
**Assessment Number: LHMJ0551**  
**Version: LKKAUTOC/2**  
**Date Calculated: 25/05/2018 03:58**

**Full Report - V1**  
**Registration: SFJ 7777Y**  
**Printed: 25/05/2018 11:07**

## Summary Information

### Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	01/12/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	TP-GW 3197S	Quote Due Date:	
Other Reference:	TP CLAIM	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

### Vehicle Details

#### Vehicle

Manufacturer:	*Honda
Model:	*Stream 1.8L
Sub Model:	
Model Sheet Number:	HAB 01
Registration:	SFJ 7777Y
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

#### Model Specs

FROM MODEL 1999	TWO COAT METALLIC
PREPARE OFF VEHICLE	

### Vehicle Condition

#### Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	01/12/2017
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	



Claim Reference:



Assessment Number: LHMJ0551

Version: LKKAUTOC/2

Date Calculated: 25/05/2018 03:58

Registration: SFJ 7777Y

Printed: 25/05/2018 11:07

**Addresses****Cost Summary**

Total Labour	\$906.20
Total Paint/Material	\$188.90
Total Parts	\$2,355.15
Total of Additional Costs	\$737.00
Excess:	TBA
Grand Total Exc GST:	\$4,187.25
7 % GST:	\$293.11
Grand Total Inc GST:	\$4,480.36

**Repair Information****LABOUR**Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR  
Price/Dent = \$46.00/HR**Repair /****Guide Number Repair Details**

		WU	Cost Price (\$)
NN	RENEW REAR NUMBER PLATE (REMOVED)	2.0	9.20
NN	RENEW REAR BUMPER (REMOVED)	2.0	9.20
NN	R + R L/TAILLAMP	5.0	23.00
NN	R + R TAILGATE	10.0	46.00
	INCLUDES: R + R TRIM AND GAS PRESSURE SPRING		
NN	RENEW TAILGATE (REMOVED)	57.0	262.20
	INCLUDES: R + R REAR SCREEN, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		
NN	TAILGATE OUTER GARNH R&R / NEW PARTS	2.0*	9.20
2711	REPAIR REAR PANEL	15.0*	69.00
3571	REPAIR L/R DRIP RAIL	6.0*	27.60

**LABOUR COST**

Total Work Units	99.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	9.9HRS	\$455.40
Paint Labour	9.8HRS	\$450.80
Total Labour	19.7HRS	\$906.20

**PAINT WORK****Guide Number Description**

Time Basis 10 WU = 1 HR. Price = \$46.00/HR

		WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
2931	BOOTLID/TAILGATE NEW PART PAINTING	16.0	
2583	REAR BUMPER NEW PART PAINT K1R	12.0	

Claim Reference:

Full Report - V1

Assessment Number: LHMJ0551

Registration: SFJ 7777Y

Version: LKKAUTOC/2

Printed: 25/05/2018 11:07

Date Calculated: 25/05/2018 03:58

2711	REAR PANEL REPAIR PAINTING <50%	11.0	
3481	L/R WING SURFACE PAINT	7.0	
3482	R/R WING SURFACE PAINT	7.0	
1000	TOW HOOK COVER NEW PART PAINT	5.0*	
1000	TAILGATE OUTER GARNHNEW PART PAINT	10.0*	
<b>LABOUR COST - PAINT</b>			
	<b>TIME(PAINT)</b>	<b>68.0</b>	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	98.0	
	Total Paintwork Labour	9.8HRS	\$450.80
<b>MATERIAL COST - PAINT</b>			
			<b>Cost Price</b>
	New Part Painting		\$45.92
	New Part Painting - Plastic K1R		\$57.07
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$36.36
	Repair Painting		\$11.95
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$188.90
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$188.90

**PARTS**

					Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
3016	1	BADGE "ODYSSEY"			0%	32.00*
3015	1	BADGE HONDA			0%	20.00*
2977	1	BOOT/TAILGATE LOCK			0%	85.00*
2931	1	BOOTLID/TAILGATE			0%	605.00*
3281	1	L/R LAMP			0%	235.00*
4907	1	LOWER TAILGATE TRIM			0%	115.00*
3171	1	LWR LOCK SUPPORT			0%	0.00F
3161	1	LWR REAR SCREEN SEAL			0%	30.00*
3170	4	LWR RUBBER MOUNTING			0%	0.00F
2583	1	REAR BUMPER			0%	396.00*
2702	1	REAR NUMBER PLATE			0%	0.00F
3151	1	REAR SCREEN			0%	550.00F
3164	4	REAR SCREEN SPACER			0%	0.00F
3168	4	REAR SCREEN SUPPORTS			0%	0.00F
3227	1	REAR WIPER BLADE			0%	35.00*
3172	1	RUBBER MOUNTING SET			0%	0.00F
1000	1	TAILGATE OUTER GARNH			0%	125.00*
1000	1	TOW HOOK COVER			0%	15.00*
f: OEM Parts					Saving	\$252.64
g: Original					Sub Total	\$2,243.00
h: Secondhand					Mark Up From Cost (5 %)	\$112.15
p: Parallel					Sundry Parts (Fixed)	\$0.00
x: Exchange					<b>Total Parts</b>	<b>\$2,355.15</b>

THIS ASSESSMENT CONTAINS UNPRICED PARTS  
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

**Extras**

Description	Betterment	Price
-------------	------------	-------

REVERSE SENSORS	SPECIALIST	0%	\$280.00
4PCS			
SUPPLY W/S	SPECIALIST		\$40.00
SEALANT			
UV FILM + INSTALL	SPECIALIST	0%	\$200.00
TUFF COAT	SPECIALIST		\$40.00
AUDATEX FEE	SPECIALIST	0%	\$42.00
REAR NUMBER PLATE	SPECIALIST		\$35.00
SUNDRY PARTS	SPECIALIST	0%	\$100.00
<b>Total Extras</b>			<b>\$737.00</b>

**Final Calculation**

<b>Total Parts</b>	<b>\$2,355.15</b>
--------------------	-------------------

**Labour**

Total Panel/Mechanical	\$455.40
Total Paintwork	\$450.80

**Total Labour****\$906.20****Additional Costs**

Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$737.00

**Total of Additional Costs****\$737.00****Total Paint/Material Costs****\$188.90****Grand Total Excludes GST****\$4,187.25**

GST @ 7 %

**\$293.11****Grand Total Includes GST****\$4,480.36****Assessment Notes**

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Dec 2017 <a href="#">Sendback Est</a>	02 Dec 2017 11:21 <b>S\$4,301.65</b>	04 Dec 2017 15:44 <a href="#">Edit Adj Rpt</a>	<b>S\$3,350.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,350.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

MainReferenceClaim DetailsDocumentsShow All

CLAIM SUBFOLDER DETAILS

Insured: --, ID: --

Main Claimant: CHIA AH SAH, ID: S0286295F

Vehicle Reg. No.: SFJ7777Y

Date of Loss: 01/12/2017 16:00 - :59  
[118 Months and 7 Days From LTA Reg Date (Man Yr)]

Claim Type: TP / SNM17D06901C02

Policy/Cover Note No.: DMCVSN1617701701

Vehicle Reg. No. (Insured): GW3197S

Policy No. (Claimant): 17-MY008392-R03

Excess: S\$0.00

Repairer: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]

Claimant's Insurer: Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111

Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 13/12/2017]

Adj Asg. Remarks: PLEASE ASSIST TO CONDUCT PRS AND REVERT WITH YOUR RECOMMENDATION

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date

Priority

Type

Task Group

Subject

Handler

Assigned By

Completed On

Created On

Done?

No results.

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=dsp\_... 8/11/2018

## Claim Documents

SFJ7777Y (SNM17D06901C02)  
[GW3197S]  
TP  
CHIA AH SAH  
Dec 1 2017 4:00PM  
[--]  
Lai Huat (Meng Kee) Motor Pte Ltd

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	02/12/17 10:18	<b>Accident Statement</b>	Load HTM	
2	02/12/17 11:21	<b>Repairer Estimates</b>	Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	01/12/17 18:32	<b>Accident Scene</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	01/12/17 18:32	<b>Accident Scene</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	02/12/17 10:18	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	02/12/17 10:18	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	02/12/17 10:18	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	02/12/17 10:18	<b>Chassis Number</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	02/12/17 11:15	<b>Rear View Right</b>	Load JPG	<input checked="" type="checkbox"/>
8	02/12/17 11:15	<b>Rear View</b>	Load JPG	<input checked="" type="checkbox"/>
9	02/12/17 11:15	<b>Rear View Left</b>	Load JPG	<input checked="" type="checkbox"/>
10	02/12/17 11:15	<b>Chassis Number</b>	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/11/18 15:27	<b>General View</b>	Load PDF	
2	07/11/18 15:29	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
3	07/11/18 15:29	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
4	07/11/18 15:29	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
5	07/11/18 15:29	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	01/12/17 18:26	<b>Sketch Plan</b> [Linked Accident Report Documents]	Load TIF	
2	01/12/17 18:27	<b>Insurance Certificate</b> [Linked Accident Report Documents]	Load TIF	
3	01/12/17 18:27	<b>Driver NRIC and Driving Licence</b> [Linked Accident Report Documents]	Load TIF	
4	01/12/17 18:27	<b>Owner NRIC</b> [Linked Accident Report Documents]	Load TIF	
5	02/12/17 11:20	<b>E-filed GIA report</b>	Load PDF	
6	02/12/17 11:20	<b>Driver's NRIC + Driving License</b>	Load PDF	
7	02/12/17 11:20	<b>Certificate of Insurance</b>	Load PDF	
8	02/12/17 11:20	<b>Enquire PARF / COE Rebate for Registered Vehicle</b>	Load PDF	
9	02/12/17 11:20	<b>LTA Search</b>	Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT117022973/KRBE2

Date: 08/11/2018

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN1617701701

Claimant Vehicle  
No : SFJ7777YInsured Vehicle  
No : GW3197S

Date of Loss: 01/12/2017

Nature of Claim: TP

Claim  
No: SNM17D06901C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SFJ7777Y

Make &amp; Model: HONDA STREAM, 1.8 L (A)

Reg. Date: 24/01/2008 (Man. Year: 2007)

Colour: Metallic Silver

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: R18A12801395

Chassis No: JHMRN68408S201374

Odometer: 165639 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/65 R15

Front Left Side: Continental 9 mm

Front Right Side: Continental 9 mm

Rear Tyre Size: 205/65 R15

Rear Left Side: Dayton 8 mm

Rear Right Side: Dayton 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,355.15	2,355.15	0.00	0.00
Miscellaneous Items	787.00	737.00	50.00	6.35
Labour	1,159.50	1,095.10	64.40	5.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,301.65</b>	<b>4,187.25</b>	<b>114.40</b>	<b>2.66</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,350.00</b>		
<b>(S\$)</b>	<b>4,301.65</b>	<b>3,350.00</b>	<b>951.65</b>	<b>22.12</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>301.12</b>	<b>234.50</b>	<b>66.62</b>	<b>22.12</b>
<b>Nett Amount (S\$)</b>	<b>4,602.77</b>	<b>3,584.50</b>	<b>1,018.27</b>	<b>22.12</b>

## INSPECTION

Date of Assignment: 04/12/2017 Present Location:

Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)

Date Inspected: 05/12/2017 Inspected At:

Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)  
160 Sin Ming Drive #04-01, Sin Ming

AutoCity  
Singapore 575722

Estimated Period of Repair: 6.0 days

---

**Adjuster:** KENNETH KONG

**Manager:** Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Nov 2018)
Parts:	M1-MPV	HONDA STREAM 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFJ7777Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BADGE "ODYSSEY" (WCP)	Necessary	32.00 F	*32.00 F
2	1	NA	*BADGE HONDA (WCP)	Necessary	20.00 F	*20.00 F
3	1	NA	*BOOT/TAILGATE LOCK (WCP)	Dented	85.00 F	*85.00 F
4	1	NA	*BOOTLID/TAILGATE (WCP)	Bent	605.00 F	*605.00 F
5	1	NA	*L/R LAMP (WCP)	Cracked	235.00 F	*235.00 F
6	1	NA	*LOWER TAILGATE TRIM (WCP)	MTG Cracked	115.00 F	*115.00 F
7	1	NA	*LWR REAR SCREEN SEAL (WCP)	Necessary	30.00 F	*30.00 F
8	1	NA	*REAR BUMPER (WCP)	Cracked	396.00 F	*396.00 F
9	1	NA	*REAR SCREEN (WCP)	Shattered	550.00 F	*550.00 F
10	1	NA	*REAR WIPER BLADE (WCP)	Cut	35.00 F	*35.00 F
11	1	NA	*TAILGATE OUTER GARNH (WCP)	Cracked	125.00 F	*125.00 F
12	1	NA	*TOW HOOK COVER (WCP)	Missing	15.00 F	*15.00 F

F=Franchise part.

<b>Sub Total (S\$)</b>	<b>2,243.00</b>	<b>2,243.00</b>
<b>+ Margin on L,N Items 5.00/5.00% (S\$)</b>	<b>112.15</b>	<b>112.15</b>
<b>Total Parts (S\$)</b>	<b>2,355.15</b>	<b>2,355.15</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	AUDATEX FEE	42.00	42.00
2	1	REAR NUMBER PLATE (DENTED)	35.00	35.00
3	1	REVERSE SENSOR (4 PCS) (DENTED)	280.00	280.00
4	1	SUNDRY PARTS (NECESSARY)	100.00	100.00
5	1	TUFF COAT	40.00	40.00
6	1	UV FILM + INSTALL (NECESSARY)	250.00	200.00
7	1	WINDSCREEN SEALANT (NECESSARY))	40.00	40.00
Sub Total (S\$)			<b>787.00</b>	<b>737.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	Total Paint Labour	New	473.80	450.80
2	Total Paint Materials	New	188.90	188.90
3	Total Panel/Mechanical Labour	New	496.80	455.40
Gross Labour Cost (S\$)			<b>1,159.50</b>	<b>1,095.10</b>

Report was unsubmitted during this print-out.
---

&lt; END OF ESTIMATES &gt;