

ASS. REC. BY:

REF: CS/FCU 7022977 / Ktb02

Special Instruction:

Surveyor: Kiem Anh

ASSIGNMENT (Office)

From (Person): CWS May Chua of FCL Date/Time: 04.12.2017 330 pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKB 6110K Insured: SHH 27203

at Workshop m/s Complete vms Tel: 6455 0012

of 176 Sin Ming Ave #03-14

Policy No: Claim No: 017010823 MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 18/12/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS WPI 06.12.2017 H.O.D. Endorsement:

Date/Time: 04.12.2017 330 pm Person Contacted: Li Hui Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKB 6110K - CS/FCU 7022977 / Ktb02 Def: 22.12.16
	SHH 27203 - X
13/12-7:26pm	revert via preli advise.
1/3	11pm 8 205d Confirmed 4 eno.1 (Red: 5064.92:71%)

ASSIGNMENT

From Date 6/12/17

Estimated Cost:

CD TP WS / TP RES / CD RES / EVA / INV / MV

To inspect Vehicle No: SKB 6110K

at Workshop no: Complete Vms

of 176 Sin Ming Drive # 03-14

Insured

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value.

IDAO Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 04 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS up

Date Person Contacted:

Vehicle IN / OUT

Veh No.

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Colour

Sp. Reading

Eng. No.

C. No.

Gen. Cond. ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orMod: ☒ Nil / ☒ S. Rim / STD A/Rim or

Tyre Size

R.

☒ BS / ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R. Bal.

L. Bal.

D.O.A.

Survey held at

Des. of Damages: ☒ Frt / ☒ Rear / ☒ O/S / ☒ N/S / ☒ U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

7/12 File pass to Catherine

RECEIVED 05 MAR 2018

Date/Time File Pass to

5/3 Typist

Date/Time File Return to



Prel. Report



Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:



Site Insp. \$



Interview \$



Tech. Insp. \$



Clean up \$

Survey Fee

Transportation

Sub. Fee

Break

Total

Report Format: TP

Lum. Sum / I.B. R: 2050

150

50

50

21

271



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17022977/Ktb		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 04-12-2017		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 2720S	Veh. Inspected	SKB 6110K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17010823MFSH	Excess (\$)	0.00	
Assign From	CWS (MAY CHUA)	Assign Date	04/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	18/11/2017	Inspection Date		
Survey held at	COMPLETE VMS PTE LTD BLK 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	21-11-2017	Our Ref No. D17010823MFSH
Accident Date	18-11-2017	Claim Type. Third Party
Insured Vehicle	SHA2720S	Third Party Vehicle. SKB6110K
Survey Location	176 SIN MING DRIVE #03-14SIN MING AUTOCARE COMPLEX	
Contact Person.	LILY/LI HUI (TEL; 64539622)	
Contact No.	64550012/ 0	Fax No. 65540012
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	COMPLETE VMS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/230468)  PRI Documents  Close 	
---	--

PRI Header Details

Claim No	D17010823MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & CO
Workshop Name	COMPLETE VMS PTE LTD (Contact Person : LILY/LI HUI (TEL; 64539622))	Survey Location & Contact Details	176 SIN MING DRIVE #03-14SIN MING AUTOC Mobile: 0 , Phone: 64550012 , Fax: 6554001 EmailId: LIHUI@COMPLETEVMS.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA2720S	TP Vehicle No	SKB61
PRI Recieved Date	01-12-2017 08:26:11 PM	Surveyor Appointed Date	04-12-2017 03:26:25 PM	Surveyor Accept Date	04-12-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	04-12-2017	Upload Survey Report *:	
-----------------------------	---	----------------------	------------	-------------------------	---

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks



Not Authorised
6/12/17 8:2050h
Recovery After Pain
4 days

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

QUEK JOO HAI
60 JOON HIANG ROAD
SINGAPORE 548347

Attention : THE OWNER
Contact : 90613018

Estimate : ES006224

Date : 05/12/2017
Vehicle Num. : SKB6110K
Make/Model : HONDA FIT-2008
Chassis/Eng# : GE81021253/L15A1573412
Accident Date : 18/11/2017
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT DOOR L/H	<i>R</i> 797.60	<i>X</i>
2.	1	FRONT DOOR MIRROR L/H	<i>cm</i> 551.20	<i>✓</i>
3.	1	SIDE SKIRTING L/H	<i>sh</i> 425.00	<i>X</i>
4.	1	FRONT WHEEL BEARING L/H	<i>sh</i> 266.60	<i>X</i>
5.	1	FRONT SHOCK ABSORBER L/H	<i>sh</i> 516.00	<i>X</i>
6.	1	FRONT LOWER ARM L/H	<i>sh</i> 260.50	<i>X</i>
7.	1	FRONT KNUCKLE ARM L/H	<i>sh</i> 356.00	<i>X</i>
8.	1	REAR DOOR L/H	<i>pd/hay</i> 770.50	<i>✓</i>
9.	1	REAR DOOR FRAME STICKER L/H	<i>an</i> 50.00	<i>✓</i>
10.	1	FRONT DOOR FRAME STICKER L/H	<i>an</i> 45.00	<i>X</i>
11.	1	REAR FENDER L/H	<i>R</i> 685.00	<i>X</i>
12.	1	REAR WHEEL BEARING L/H	<i>an</i> 364.00	<i>X</i>
List Total S\$:			5,087.40	
20.00% Discount S\$:			1,017.48	
			4,069.92	
SPECIAL NETT ITEMS :				
1.	1	FRONT TIRE L/H	<i>sh</i> 185.00	<i>X</i>
Special Nett Total S\$:			185.00	
LABOUR :				
TRANSFER L/H FRONT DOOR COMPONENTS TO NEW DOOR			<i>an</i> 150.00	<i>X</i>
TRANSFER L/H REAR DOOR COMPONENTS TO NEW DOOR			150.00	<i>6cl</i>
RUST PROOFING TREATMENT			100.00	<i>3cl</i>
REMOVE & REINSTALL FRONT SUSPENSION L/H			<i>an</i> 250.00	<i>X</i>
COMPUTER WHEEL ALIGNMENT			120.00	<i>6cl</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

CONTINUE ! ...



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

QUEK JOO HAI
60 JOON HIANG ROAD
SINGAPORE 548347

Attention : THE OWNER
Contact : 90613018

Estimate : ES006224

Date : 05/12/2017
Vehicle Num : SKB6110K
Make/Model : HONDA FIT-2008
Chassis/Eng# : GE81021253/L15A1573412
Accident Date : 18/11/2017
Claim No :
Reference :
Policy No :

S/N	Quantity	Particular	Unit Price	Amount S\$
		SPRAY PAINT DAMAGED AREA AFFECTED		1,100.00
		CHANGE REAR WHEEL BEARING		90.00
		TO KNOCK AND STRAIGHTEN L/H DOOR PILLAR AND CHANGE ALL		900.00
		NECESSARY PARTS		
		Labour Total S\$:		2,860.00

SingDollars : Seven Thousand One Hundred Fourteen & Cents Ninety-Two Only

Total S\$: 7,114.92

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17022977/Ktbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 06-03-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 2720S	Veh. Inspected	SKB 6110K	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17010823MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	04/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	GE81021253	Colour	METALLIC BLACK	
Odometer	103395	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195/55 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	195/55 R15	BRIDGESTONE	5 mm	
L/H Rear Tyre	195/55 R15	BRIDGESTONE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/11/2017	Inspection Date	06/12/2017	
Survey held at	COMPLETE VMS PTE LTD BLK 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKB 6110K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT DOOR L/H	TO REPAIR SEE LABOUR	797.60	-
1	FRONT DOOR MIRROR L/H	CRACKED	551.20	551.20
1	SIDE SKIRTING L/H	SERVICEABLE	425.00	-
1	FRONT WHEEL BEARING L/H	SERVICEABLE	266.60	-
1	FRONT SHOCK ABSORBER L/H	SERVICEABLE	516.00	-
1	FRONT LOWER ARM L/H	SERVICEABLE	260.50	-
1	FRONT KNUCKLE ARM L/H	SERVICEABLE	356.00	-
1	REAR DOOR L/H	DENTED / WARPED	770.50	770.50
1	REAR DOOR FRAME STICKER L/H	NECESSARY	50.00	50.00
1	FRONT DOOR FRAME STICKER L/H	NOT NECESSARY	45.00	-
1	REAR FENDER L/H	TO REPAIR SEE LABOUR	685.00	-
1	REAR WHEEL BEARING L/H	NOT NECESSARY	364.00	-
	LESS 20% DISCOUNT		-1,017.48	-274.34
			4,069.92	1,097.36
<u>SPECIAL NETT ITEMS</u>				
1	FRONT TIRE L/H (SN)	SERVICEABLE	185.00	-
			185.00	-
<u>LABOUR</u>				
	TRANSFER L/H FRONT DOOR COMPONENTS TO NEW DOOR.	NOT NECESSARY	150.00	-
	TRANSFER L/H REAR DOOR COMPONENTS TO NEW DOOR.		150.00	60.00
	RUST PROOFING TREATMENT.		100.00	30.00
	REMOVE & REINSTALL FRONT SUSPENSION L/H.	NOT NECESSARY	250.00	-
	COMPUTER WHEEL ALIGNMENT.		120.00	60.00
	SPRAY PAINT DAMAGED AREA AFFECTED.		1,100.00	800.00
	CHANGE REAR WHEEL BEARING.	NOT NECESSARY	90.00	-

Report Ref No. CS/FCI17022977/Ktbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO KNOCK AND STRAIGHTEN L/H DOOR PILLAR AND CHANGE ALL NECESSARY PARTS.INCLUSIVE OF THE REPAIR OF FRONT DOOR L/H AND REAR FENDER L/H.		900.00	540.00
			2,860.00	1,490.00
GRAND TOTAL			7,114.92	2,587.36
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,050.00

Report Ref No. CS/FCI17022977/Ktbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.