

Wed 27/12 @ 10am  
SJR

SJS6680D

BMW Dealer

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



GST REG. NO : M2 - 0020081

ESTIMATE

Signature:  
Date:

04 DEC 2017

REC: 5.48pm

Estimate No. : b1 45045  
Date Estimated : 04/12/2017  
Prepared By : Han Kwan Yong

Page No. : 1 of 1

### - ESTIMATE REPAIR FOR -

Evelyn Chan Kah Eng  
75M Jalan Senang

Singapore 418400

- ACCOUNT - 40000

Cash Sales - Service  
Singapore

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------|------------|-------|---------|
| SJS6680D  | CX30056     | 27/08/2009 | 520iA | 0       |

#### DESCRIPTION

To replace rear bumper & attachment including to knock out rear left fender and dented area caused by the accident

1700 2,580.00

To respray rear bumper and rear left fender

1730 1,923.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

230 271.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Sundries.

80.00

Total Labour 1: 5,001.00

#### DESCRIPTION

# RR BUMPER LH MOUNT (M)  
# RR BUMPER W/PDC (-M-)

| QTY | PRIC     | VALUE    |
|-----|----------|----------|
| 1   | 141.65   | 141.65   |
| 1   | 1,465.40 | 1,465.40 |

Total Parts : 1,607.05

#### Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.  
Date & Time 27/12/17 @ 1645 Excess \$  
Surveyor's Name RASUL Sign

Surveyor's Tel 96010668 Authorised Yes / No

Authorised Date Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail

No. of Working Days Recommend 4-5 days

5 days

|                |   |          |
|----------------|---|----------|
| Labour 1       | : | 5,001.00 |
| Parts          | : | 1,607.05 |
| Labour 2       | : | 0.00     |
| Excess         | : | 0.00     |
| Total GST @ 7% | : | 462.56   |
| Grand Total    | : | 7,070.61 |

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## SUPPLEMENTARY

Estimate No. : b1 45045  
Date Estimated : 04/12/2017  
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -  
Evelyn Chan Kah Eng  
75M Jalan Senang

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

Singapore 418400

| REGN NO  | CHASSIS NO | REGN DATE  | MODEL | MILEAGE |
|----------|------------|------------|-------|---------|
| SJS6680D | CX30056    | 27/08/2009 | 520iA | 0       |

| DESCRIPTION | ORIGINAL PRICE | DISC. % | NETT |
|-------------|----------------|---------|------|
|-------------|----------------|---------|------|

| DESCRIPTION                          | UNIT PRICE | QTY  | DISC. % | NETT              |
|--------------------------------------|------------|------|---------|-------------------|
| # PLUG *                             | 1.20       | 4.00 |         | 4.80 <i>me</i>    |
| # RR LH LIGHT WHITE TURN INDICATOR * | 478.00     | 1.00 |         | 478.00 <i>scr</i> |

|                        |        |
|------------------------|--------|
| Total Labour :         |        |
| Total Parts :          | 482.80 |
| Total Labour & Parts : | 482.80 |