

REF:

CC3/ms617022994/Srbnz

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SKN 6231G

Policy No. 28692488 Rmy

Claims No. 539548


Sum Insured:

Excess: \$1500

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHC 4447H.

Yr Regn:

19/3/2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

c.c 1798

Colour

Maroon

A/C: Insured / Std / NI / NA

Sp. Reading

509745

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKN 364405758/98

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65R15

R:

"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Palken

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

1/12/2013

D.O.I.

4/12/2013

Survey held at

SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

SHC 4447H - PR3 / DBE 16006762 / Klyb392

DCA 070416 TAX/12/17/2007

SKN 6231G - X

Lick

MSIG

Confirm L/S \$1100, 2 days

Red: \$1708.40, 61%

RECEIVED 10 JAN 2010

Date/Time, File Pass to?



: Preli. Report

1) typist



: Final Report

Date/Time, File Return to?

2)

Report Format:

TP

Lump Sum / H.B.I: (\$

1100

Days Of Repair:

2

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

) \$ + RS. \$

) Photos

) Others

TOTAL

200  
10

210



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CC3/MSG17022994/Srb

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 05-12-2017



Code : MSG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKN 6231G	Veh. Inspected	SHC 4447H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	05/12/2017

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	01/12/2017	Inspection Date	04/12/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

## 5a. Remarks

--	--

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/12/2017 11:42
Date Of Accident	01/12/2017 16:30
Exact Location Of Accident	SLIP ROAD FROM PIE TOWARDS TPE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4447H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

### Driver

Name of Driver	MUHAMMAD NUR IMAN BIN MOHAMMED
NRIC No	S8016387H
Date Of Birth	09/06/1980
Occupation	OUTDOOR
Date Of Driving Pass	30/12/1999
Driving Experience	17 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OTHER - HIRER  
Vehicle Registration Number of Driver's Own Vehicle -  
-  
Insurance Company of Driver's Own Vehicle -  
-

### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
Weather Conditions CLEAR  
Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO  
Was any body injured in the Accident? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 1

### Details of Police Action

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

### Circumstances of Accident

I WAS STATIONARY ALONG THE SLIP ROAD FROM PIE TOWARDS TPE AS I WAS LOOKING OUT FOR THE ONCOMING TRAFFIC. SUDDENLY I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SKN6231G HAD COLLIDED ONTO THE REAR OF MY TAXI.

### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKN6231G  
Vehicle Make/Model/Colour  
Details Of Properties  
Name of Driver LAUW KHENG HUAT PETE  
NRIC/Passport Number S1269451B  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

### Details of Witness

Name  
Phone Number  
Email Address

TPE



A - SHC 4447 H

B = SKN 6231 G

new  
2/12/17

FROM  
PIE

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature:  
Date & Time:

Driver's Signature \_\_\_\_\_  
(If driver is not the policyholder)  
Date & Time: \_\_\_\_\_

Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type	Company
Owner ID	5369K
<b>Vehicle Details</b>	
Vehicle No.	SHC4447H
Vehicle to be Exported	Yes
Intended De-registration Date	05 Dec 2017
Vehicle Make	TOYOTA
Vehicle Model	PRIUS TAXI (SMRT)
Primary Colour	Maroon
Manufacturing Year	2014
Engine No.	2ZR5898536
Chassis No.	JTDKN36U405738148
Maximum Power Output	100.0 kW (134 bhp)
Open Market Value	\$33,120.00
Original Registration Date	19 Mar 2014
First Registration Date	19 Mar 2014
Transfer Count	0
Actual ARF Paid	\$8,368.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	18 Mar 2022
PARF Rebate Amount	\$6,276.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date	18 Mar 2022
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	8
PQP Paid	\$58,745.00
COE Rebate Amount	\$31,464.00
<b>Total Rebate Amount</b>	<b>\$37,740.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 05 Dec 2017

OK



Please read through the Privacy Statement, Terms of Use, and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 19 Nov 2017 at 12:12 AM



## SMRT Accident Vehicle Repair Estimates

mslg

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4447H  
 Ref. No : TAX/12/17/2007  
 Reg. Date : 19/03/2014  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS  
 Name of Driver : MUHANNAD NUR IMAN BIN MOHAMMED  
 Type of Accident : HEAD TO REAR  
 Date / Time of Accident : 01/12/2017 04:30:00 PM  
 Accident Reported Date / Time : 02/12/2017 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024093406  
 Special Instruction to ARC, if any :  
 TOWED \$50 / SKN6231G - MSIG - LKK  
 Prepared Date : 02/12/2017 11:56:45 AM



Sebastian.  
 4/12/2017.  
 - Long Term Repair.  
 - Question Mark Item  
 Photo.  
 - Photo After Paint.

LKK Auto Consultants hence notify  
 the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U405738148

Mileage : 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 338.00	0.00
Total Spray Painting Charges	: 558.00	0.00
Total Material Charges	: 896.54 1472.14	896.54
Other Charges	: 440.00	0.00
<b>TOTAL</b>	<b>: 2,232.54 2808.40</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 2,250.00</b>	<b>0.00</b>
No. of Repair Days	: 3.00	<del>0.00</del> 2 days
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 04/12/2017 10:41:46 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 04/12/2017 10:40:26 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

# Section D - Details of Repair Estimates

## Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	338.00	0.00 <del>200</del> /
<b>Total Labour</b>	<b>338.00</b>	<b>0.00</b>

## Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 <del>200</del> /
TO RESPRAY BUMPER BEAM	180.00 ?	0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>558.00</b>	<b>0.00</b>

## Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 ✓ 80
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 <del>30</del> /
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
<b>Total Other Costs</b>	<b>440.00</b>	<b>0.00</b>

# Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	30.00	321.02 ✓	Replace	Replace ✓ CRK	No
76891-47020		6505619	BUMPER LIP REAR	1	228.90	30.00	160.23	Replace	Replace X	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	30.00	143.99 ✓	Replace	Replace / DT	No
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	30.00	97.72	Replace	Replace 7 nh	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	30.00	97.72	Replace	Replace 7 nh	No
			SENSOR REVERSE	1	180.00	0.00	180.00 ✓	Replace	Replace ? dmy	No
			PIXEL STICKER	2	60.00	0.00	120.00 ✓	Replace	Replace ✓ wcc	No
TOTAL MATERIALS								1,120.68	1,120.68	
TOTAL MATERIALS(Discounted)								896.54	896.54	

## Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

6.12.17/11.49  
6.12.17/11.49


Camera (yes)

# SMRT Accident Vehicle Repair Estimates

4.12.17/15.

## Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4447H  
Ref. No : TAXI/12/17/2007  
Reg. Date : 19/03/2014  
Vehicle Type : TAXI  
Make : TOYOTA PRIUS  
Model : PRIUS  
Name of Driver : MUHANNAD NUR IMAN BIN MOHAMMED  
Type of Accident : HEAD TO REAR  
Date / Time of Accident : 01/12/2017 04:30:00 PM  
Accident Reported Date / Time : 02/12/2017 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by : Sebastian  
Vehicle is Towed Back? : No/Yes  
Towed Back Date/Time :  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024093406  
Special Instruction to ARC, if any :  
TOWED \$50 / SKN6231G - MSIG - LKK  
AFTER PAINT PHOTO, LUMP SUM REPAIR, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL  
SURVEYOR SEBASTIAN (LKK) & Email : sebastian.yong@lkkauto.com HP: 90036121  
Prepared Date : 02/12/2017 11:56:45 AM



to Fun

14.40 7/12/17 Pass

509745

1 1/4 1/2 3/4 1 1/4 1 3/4

509809km

Supplementary

to Refer to the Supplementary part 1/16

1 1/4 1/2 3/4 1 1/4 1 3/4

LEE SHENG AUTO PTE LTD

Vehicle Return Date: 07/12/2017

Vehicle Return Time: 13:14

SMRT staff sign: [Signature]

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN38U405738148

Mileage

0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	338.00	200.00
Total Spray Painting Charges	558.00	200.00
Total Material Charges	768.36	612.01
Other Charges	440.00	110.00
TOTAL	2,104.36	1,122.01
Lum Sum Total	2,100.00	1,100.00
No. of Repair Days	3.00	2.00
Prepared / Adjusted By		SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	04/12/2017 10:41:46 AM	04/12/2017 03:49:42 AM

*[Signature]*

*[Signature: LKK]*

Prepared / Adjusted Date :

Remarks :

Prepared Date : 04/12/2017 10:40:26 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : QN-1712-0216  
Quotation Date : 8/12  
Invoice Amount : 0.00

Invoice No :  
Invoice Date :  
Prepared Date : 12/4/2017 3:51:49 PM

## Section D - Details of Repair Estimates

### Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	338.00	200.00 /
<b>Total Labour</b>	<b>338.00</b>	<b>200.00</b>

### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY BUMPER BEAM	180.00	0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>558.00</b>	<b>200.00</b>

### Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	80.00 /
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 /
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
<b>Total Other Costs</b>	<b>440.00</b>	<b>110.00</b>

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
2159-17905		6505548	BUMPER REAR	1	458.60	30.00	321.02	Replace	Replace	No <input checked="" type="checkbox"/> CRK
6891-17020		6505619	BUMPER LIP REAR	0	228.90	30.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/> NN
2023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	30.00	143.99	Replace	Replace <input checked="" type="checkbox"/> S	No <input checked="" type="checkbox"/> DT
2010-17030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	30.00	97.72	Replace	Check	No <input checked="" type="checkbox"/> ) NN
2015-17050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	30.00	97.72	Replace	Check	No <input checked="" type="checkbox"/> ) NN
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace <input checked="" type="checkbox"/> S	No <input checked="" type="checkbox"/> DMG
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <input checked="" type="checkbox"/> NEC
TOTAL MATERIALS							960.45	765.01		
TOTAL MATERIALS(Discounted)							768.36	612.01		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

765.01 /  
 - 20%  
 612.01 /  
 + 200.00 /  
 + 310.00 /  
 -----  
 1122.01 /  
 45 \$1100/- /

Sebastian  
 11/12/2017

2808.40



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG17022994/SRBN2  
Date: 19/01/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 28692488QMY  
Claimant: SHC4447H Insured Vehicle No: SKN6231G  
Vehicle No: SHC4447H Nature of Claim: TP Claim No: 539548  
Date of Loss: 01/12/2017

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SHC4447H Engine No: 2ZR5898536  
Make & Model: TOYOTA PRIUS, 1.8 (A) Chassis No: JTDKN36U405738148  
Reg. Date: 19/03/2014 (Man. Year: 2014) Odometer: 509745 km  
Colour: Maroon  
Engine Capacity: 1798 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15  
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm  
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,472.40	765.01	707.39	48.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,336.00	510.00	826.00	61.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,808.40	1,275.01	1,533.39	54.60
Approved Total (Overridden) (S\$)		1,100.00		
Nett Amount (S\$)	2,808.40	1,100.00	1,708.40	60.83

## INSPECTION

Date of Assignment: 18/12/2017  
Date Inspected: 04/12/2017 Inspected At: SMRT Automotive Services Pte Ltd (Woodlands)  
60 Woodlands Industrial Park E4  
Singapore 757705

Estimated Period of Repair: 2.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jan 2018)
Parts:	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC4447H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER REAR (DISC 30%)	Cracked	458.60 F	*321.02 F
2	1		*BUMPER REINFORCEMENT REAR (DISC 30%)	Dented	205.70 F	*143.99 F
3	1		*SENSOR REVERSE (SN)	Damaged	180.00 F	*180.00 F
4	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
5	1		*BUMPER LIP REAR	Not Necessary	228.90 F	*- F
6	1		*ARM SUB-ASSY,RR BUMPER LH	Not Necessary	139.60 F	*- F
7	1		*ARM SUB-ASSY,RR BUMPER RH	Not Necessary	139.60 F	*- F
F=Franchise part.				Total Parts (S\$)	1,472.40	765.01

Report was unsubmitted during this print-out.

**Recommended Miscellaneous Items**

There are no new miscellaneous items selected.

**Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING & BODY WORK	New	338.00	200.00
2	SPRAY PAINT	New	558.00	200.00
3	TOWING CHARGE	New	80.00	80.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	-
5	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	30.00
6	TO REPLACE SUNDRY PARTS	New	100.00	-
7	TO WASH AND VACUUM	New	60.00	-
Gross Labour Cost (\$\$)			1,336.00	510.00

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;