

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.2 ANG MO KIO ST63 SINGAPORE 569111  
 TEL NO. 6287 6666 FAX NO. 6257 1330  
 CO/GST REG NO. 201019626G  
**SHD528D - TOKIO**

**AAD1712-002**

*Not Authored*  
*Resurvey B4 part 83021-18*

|                       |                          |
|-----------------------|--------------------------|
| Vehicle No.:          | <b>SHD528D - CANDY</b>   |
| Chassis No.:          | <b>VF1ABL15AUC283512</b> |
| Vehicle Make:         | <b>RENAULT</b>           |
| Vehicle Model:        | <b>LATITUDE</b>          |
| Date of Accident :    | <b>30.11.2017</b>        |
| Third Party Insurer : | <b>TOKIO</b>             |

|    |   | PART                            | LIST                        |
|----|---|---------------------------------|-----------------------------|
| 1  | 1 | BUMPER COVER FRT                | \$ <i>Bu/10M</i> 1,259.42 ✓ |
| 2  | 1 | BUMPER ABSORBER FRT             | \$ <i>Sm</i> 394.68 X       |
| 3  | 1 | BUMPER BEAM FRT                 | \$ <i>R</i> 914.08 X        |
| 4  | 1 | BUMPER SPOILER FRT              | \$ <i>Sm</i> 181.75 ✓       |
| 5  | 1 | BUMPER GRILLE LOWER FRT         | \$ <i>Sm</i> 266.80 X       |
| 6  | 1 | BUMPER FOG LAMP GRILLE RH       | \$ <i>Sm</i> 207.22 X       |
| 7  | 1 | BUMPER RETAINER FRT RH          | \$ <i>D/I</i> 151.41 ✓      |
| 8  | 1 | BUMPER SUPPORT FRT RH           | \$ <i>Sm</i> 123.88 X       |
| 9  | 1 | BUMPER RETAINER FRT LH          | \$ <i>Sm</i> 151.41 X       |
| 10 | 1 | BUMPER SUPPORT FRT LH           | \$ <i>Sm</i> 123.88 X       |
| 11 | 1 | HEADLAMP RH                     | \$ <i>Sm</i> 1,184.43 X     |
| 12 | 1 | HEADLAMP PANEL FRT RH           | \$ <i>R</i> 152.15 X        |
| 13 | 1 | FENDER PANEL FRT RH             | \$ <i>B</i> 783.83 ✓        |
| 14 | 1 | FENDER BRACKET FRT RH           | \$ <i>Sm</i> 13.02          |
| 15 | 1 | FENDER WHEELARCH FRT RH         | \$ <i>Sm</i> 278.84         |
| 16 | 1 | FENDER PANEL BRACKET FRT RH     | \$ <i>Sm</i> 177.41         |
| 17 | 1 | WIPER RESERVOIR                 | \$ <i>Sm</i> 348.25         |
| 18 | 1 | WIPER RESERVOIR NECK            | \$ <i>Sm</i> 136.11         |
| 19 | 1 | WIPER RESERVOIR MOTOR           | \$ <i>Sm</i> 270.06         |
| 20 | 1 | RADAITOR GRILLE                 | \$ <i>Sm</i> 1,707.78       |
| 21 | 1 | RADAITOR GRILLE BADGE 'RENAULT' | \$ <i>Sm</i> 273.36 X       |
| 22 | 1 | RADAITOR GRILLE FRAME           | \$ <i>Sm</i> 1,353.75       |
| 23 | 1 | FRAME FULL SUPPORT PANEL        | \$ <i>R</i> 615.90          |
| 24 | 1 | FRAME FULL SUPPORT BRACKET      | \$ <i>R</i> 89.79           |
| 25 | 1 | BONNET                          | \$ <i>R</i> 1,941.63        |
| 26 | 1 | DOOR MIRROR RH                  | \$ <i>Sm</i> 1,483.40       |
| 27 | 1 | DOOR MIRROR GLASS RH            | \$ <i>Sm</i> 242.33         |
| 28 | 1 | DOOR MIRROR BACK COVER RH       | \$ <i>Sm</i> 218.46         |
| 29 | 1 | DOOR MIRROR LAMP RH             | \$ <i>Sm</i> 194.18         |
| 30 | 1 | DOOR PANEL FRT RH               | \$ <i>R</i> 2,844.66        |

|              |           |                  |
|--------------|-----------|------------------|
| <b>TOTAL</b> | <b>\$</b> | <b>17,983.89</b> |
| <b>10%</b>   | <b>\$</b> | <b>1,798.39</b>  |

**TRANS-CAB AUTO SERVICES PTE LTD****AAD1712-002**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHD528D - TOKIO**

|    |           |
|----|-----------|
| \$ | 16,185.50 |
|----|-----------|

**Special Nett**

|    |      |                             |    |           |        |   |
|----|------|-----------------------------|----|-----------|--------|---|
| 1  | 1SET | FRONT BUMPER CLIP           | \$ | <i>na</i> | 66.00  | ✓ |
| 2  | 1SET | WHEELARCH CLIP RH           | \$ | <i>na</i> | 66.00  | X |
| 3  | 1    | TOW COVER FRT               | \$ | <i>na</i> | 14.50  | X |
| 4  | 1    | CAP HUB RH FRT              | \$ | <i>na</i> | 35.00  | ✓ |
| 5  | 1    | RIM RH FRT                  | \$ | <i>na</i> | 385.00 | X |
| 6  | 1    | TYRE RH FRT                 | \$ | <i>na</i> | 330.00 | X |
| 7  | 1    | DOOR SEAL CLIP FRT RH       | \$ | <i>na</i> | 4.68   | X |
| 8  | 1    | DOOR STICKER "Trans-cab"    | \$ | <i>na</i> | 80.00  | X |
| 9  | 1    | DOOR STICKER "Classic"      | \$ | <i>na</i> | 30.00  | X |
| 10 | 1SET | BUMPER SUPPORT FRT CLIP RH  | \$ | <i>na</i> | 9.80   | X |
| 11 | 1SET | BUMPER RETAINER FRT CLIP RH | \$ | <i>na</i> | 12.50  | X |

|                    |    |                  |
|--------------------|----|------------------|
| <b>TOTAL</b>       | \$ | <b>1,033.48</b>  |
| <b>TOTAL PARTS</b> | \$ | <b>17,218.98</b> |

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ *400*  
2,800.00

To Check Electrical Lighting Concerned.

\$ 170.00 *150*

Putty and spray painting of the affected portion.

\$ 3,000.00 *4400*

To rust-proofing of the affected areas.

\$ 170.00 *300*

To check steering geometry and computer wheel alignment

\$ 220.00 *800*

To transfer of tire, rim and on wheel balancing.

\$ *na* 170.00 X

To transfer of door fittings, attachment and perform water seepage test.

\$ *na* 170.00 X

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ *na* 380.00 X

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.

\$ *na* 170.00 X

**TRANS-CAB AUTO SERVICES PTE LTD****AAD1712-002**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHD528D - TOKIO**Towing fees \$ *in* 120.00 *X*To Remove And Refit Front W/Screen Glass To  
Facilitate Bodywork Repair. \$ *in* 170.00 *X*

|                       |           |                  |
|-----------------------|-----------|------------------|
| <b>TOTAL</b>          | <b>\$</b> | <b>7,540.00</b>  |
| <b>Over All Total</b> | <b>\$</b> | <b>24,758.98</b> |

**(PARTS BY PARTS) Repair Days**~~10 Days~~*2 days*LKK Auto Consultants hence notify  
the Repairer of the following:

- To reserve colour after spray painting
- To display damaged part (if any) for approval
- Parts price and labour/combination
- Third party survey is to be done by 3rd party
- No illegal modification is allowed
- Supplementary detail must be insured and  
is subject to final approval from insurance company

Acknowledged by Repairer:

Signature:

Date: