387117 REF: NC/	7015 17 12 12 1 WIN	
Sirreyor Kolvin	WC 17033013/Klrbnz	
	ASSIGNMENT	18
From: Date:	Veh No: SHB 4335	KE Yr Regn: 18 Jul 2515
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van /	
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or	
To Inspect Vehicle No:	Make: Hyunde	I40 00 /685
at Workshop m/s	Colour Blue	A/C: Insured / Std / NI / NA
of	Sp.Reading 7 6 0 7-78	T/Radio: Inseped / Std / NI / NA
Insured: ShB 771P	Eng/No:	
Policy No. 5017 128877 40 071216.	061217 C/No: KM HLI	8414A64074960
Claims No. MT/0972173-002	Gen. Cond: Good / Fair Poor / Bur	rnt
Sum Insured: Excess:	Steering: Inord6/ Jammed / Leake	ed / Burnt or
(Client's Record)	Brake: Inorder Jammed / Leake	ed / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD/3/Rim	or
20-10-1	Tyre Size; F: 2	05/60K16
(Policy Condition)	R:	٠, .
Remark: The veh had commenced its N/S	O/S BS / DUN / EXNOVA / GY / FS / LIZ	
repair at the time of inspection.	TOYO/YOKO or	Westlake
Bal. or Market Value:	~- Front	Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 7 mm	R/Balmm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. + mm	L/Balmm
Est Repairs: days Res.: Yes or No	D.O.A. 2/12/12	D.O.I. K/2/13
Lum Sum: % 3 Val.: Yes or No	Survey held at	(OGE (10749)
CA / REV / REP. / 24 HRS	Des. of Damages ; Frt / Rear / Of	S / N/S / U/C / Rooftop or
		~ Ms
Date: Person Contacted: Date / Time Action / Instruction	The U/C / Chassis frame / Bo	ody Structure affected due to collision.
SIB 4334E - CC4 /AXA130	DEFE / HERRES DEFE O	704B IN
SUB AIP - X	V61257 (M-3G-	4/5.
11/12/17 Cold 4/5 \$2900/ 2Pm.		
Red: \$54.86,16%	1 35%	
RECEIVED 1 2	DEG /	
DateTime. File Pass to? : Preli. Report	Days Of Repair: 2	
: Final Report	Resurvey No. of Trip:	Survey Fee:
Date/Time, File Return to?	Add Fee: : Site Insp (\$	Transportation:)S + RS,St
2)	: Interview (\$)S+R3,Si
Report Formet : 1P	: Tech. Invs (\$) Others
Report Format : IF Lump Sum / f.B.I: (\$ 2600)	: Weekend (\$) Unes 195
Comp Com / Ed. (C. P. 15	.vveekend (9	
		TOTAL



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





NTUC	INCOME INSURA	ANCE CO-OPERATIVE LTD	Ref: NS/INC1702300	03/K1rb	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556					
			Code: INC4	War and the second of the	
1.	TOTAL PROPERTY.	Policy Particulars	:- THIRD PARTY CLAIM	410 10015	
	Insured Veh.	SGB 771P	Veh. Inspected	SHB 4334E	
	Policy No.	5017428817-10	Coverage (\$)	0.00	
	Claim No.		Excess (\$)	0.00	
	Assign From		Assign Date 04/12/2017		
2.		Vehicle Part	iculars & Condition		
	Make & Model		c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer		Steering		
	Brakes		Modification		
	General				
3.		Condi	tions of Tyres		
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre		=	mm	
	L/H Rear Tyre			mm	
4.		Descript	tion of Damages		
5.		Gener	ral Information		
-	Accident Date	02/12/2017	Inspection Date	04/12/2017	
	Survey held at	COMFORTDELGRO ENGINE	ERING PTE LTD	West III for	
		59 LOYANG DRIVE SINGAPORE 508969			
5a.			Remarks		
	A)THE INSPECTI B)IN ACCORDAN	ON WAS CONDUCTED ON A"W CE TO YOUR INSTRUCTIONS,	VITHOUT PREJUDICE" BAS WE HAVE NOT AUTHORIS	IS. ED REPAIRS.	

eBaoTech								Gener	alClaim
Hello, NAC_PAYA_UBI_80	0601			A PARTICIPATION AND ADDRESS OF THE PARTICIPATION AND ADDRESS OF TH		Change Lar	nguage	· Change Password	• Log Out
My Desktop	Policy Query								
Notice of Loss	Policy No.				Date of Acci	dent	02/12	/2017 10:14	
	Vehicle No.(For Motor)	SGB771P							
					Search				
	Select Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
	5017428817-10	ANG THIAM PENG	51275627E	GPC	Third Party, Fire & Theft	SGB771P	SGB771P	07/12/2016	06/12/2017
				1	Continue				

TP Claims against NTUC Income: Follow-Through Survey

Date: 08/12/2017

1 MT/09		ä	The state of the s					
MT/09	20121212121	Ciaminant (Owner) Taxi Company)	Claimant Vehicle No.	Income Vehicle No	Date of Accident	Times of Assistant	1	
֡	4T/09666652-002	CONSCIONT TO ANCHORATED AS NOT THE		interest of the late.		Time of Accident	Estimate	Tentative renair cost
	700 7000	z	SHR 4977A	CIZEAZAC		10000		400
NAT/OU	AT/0065716.003	Н	10000	316.346		71:50	5 11 054 80	~
CO (1141	03/10-003	COMPORT INANSPORTATION PTE LTD	CHA 4247D	VI TARBO	and the state of t		DOLL DOLL .	2,730.00
AAT IAM	74047 000		0/157 WILE	TL 1455A	14/10/2017	19:10	\$ 7 A21 E0	
WII/03	MII/U9/1843-002	COMFORT TRANSPORTATION DTELTO	Cità Poster			2000	C'151'30 4	•
		MOUNT OF THE PARTY	D/4/0 AHC	SIM 2865X	30/11/2017	43.30		
1 MT/09	77173-002	COMEOST TRANSPORTATION DESCRIPTION			CONTRACTOR !	13:50	5 1.077.88	S
	200 000	7	CHR 4334F	CCD 2210	and to a decident			
- Astron	224.25.000	в	200000000	ATT ODE	05/15/201/	1.20	2 454 96	
WII/09,	700-9/57/60/11	COMFORT TRANSPORTATION PTE 1 Th	CLIC SPENE			0.00	00.404,00	-
The same of the same of		017 71 110 1110 1110	3/CC 300/E	GW 50/8	05/12/2017	16:35	40000	
MI/09	MI/0973066-001	4			ATOM/ATOM	10.33	4,656.54	0
	400 0000	I PANASPORIATION	SH 84845	CHAI 0777A	Ar les mass	1	-	
			200000000	WILLIAM ON LINE	05/17/201/	1:05	5 610.00	2000
							000000	300.00

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

and code of				
	ACCIDENT STATEMENT			
Date Of Report	02/12/2017 10:48			
Date Of Accident	02/12/2017 01:20			
Exact Location Of Accident	PIE TOWARDS CHANGI AIRPORT BEFORE JLN EUNOS EXIT			
Country/State of Loss	SINGAPORE			
	DETAILS OF OWN VEHICLE			
Vehicle Registration Number	SHB4334E			

DETAILS OF OWN VEHICLE					
Vehicle Registration Number	SHB4334E				
Insured/Policyholder					
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD				

Name Of Registered Owner 199303821R Co Reg No

FLEETSAFETY@CDGTAXI.COM.SG Email Address

Mobile Phone No

OFFICE-65508768 Alternative Phone No

Vehicle Particulars

HYUNDAI Manufacturer 140 Model

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

NO

TAXI Vehicle Category

Insurance Company

INDIA INTERNATIONAL INSURANCE PTE LTD Name of Insurance Company

THIRD PARTY FIRE AND/OR THEFT Type Of Coverage

YES Fleet Policy

MCOM0016 Policy Number

Cover Note Number

Driver

TEO CHIN CHYE Name of Driver S1374494G NRIC No

14/07/1959 Date Of Birth OUTDOOR Occupation 28/08/1980 Date Of Driving Pass

37 YEARS AND 3 MONTHS Driving Experience

MALE Gender

Mobile Number Fax Number Contact Number

NOEMAIL EMail Address

Address

703 07-125 PASIR RIS DRIVE 10

Postcode

510703

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO YES

Was any body injured in the Accident?

YES

Was any other material or property damaged? I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SGB771P

Vehicle Make/Model/Colour

Details Of Properties

ANG YOCK SENG

NRIC/Passport Number

S8708695Z

Contact Number

Name of Driver

91719220

Address

Postcode

Insurance Company Name

Nature Of Damage

FRT RHT

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name

TEO CHIN CHYE

Approximate Age

58

Injuries Sustain

NECK, BACK, LEGS

Injured person in which vehicle?

SHB4334E

Were seat belts worn?


YES

Was injured conveyed to hospital by ambulance?

NO

Address

Postcode



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT	
As seen in the video, while tra	velling on PIE
	V
in the direction towards change Air	roit, I stopped my
taxi when I paw the car in front	
J/n Eunos exit.	
It was under such situation I fe	et a jarle and
	0
impact when car B(SSB 771P).	hit into the rear
7777	
of my texis cousing damage to.	<i>t</i>
The state of the s	
The first of car B was dond.	***
7 0	
of took down particulars of the	liver B.
283	
while my passenger on boord was	rat injured, I felt
Pains on my less and & intended	to per adoctor.
DECLARATION (/ /	

I/We declare the foregoing particulars are true in every respect.

CO REG NO-199303821R
Policyholder's Signature

Driver

Date & Time:

Driver's Signature (If driver is not the policyholder)

Date & Time:

Lim Ee Soon CSO

Reporting Centre Personnel's Signature Name: NRIC/FIN No :

Sketch Plan Pg. 2

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims:
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (Iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LILL CO. REG. NO. 199303821R


21R


217


Lim Ee Soon

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature Name: NRIC/FIN No.:











A mambar of ComfortDelcro

Date/Time: 04.12.2017 08:25

ComfortDelGro Engineering Pta Ltd

Page : 1

JC NO.305094154 JOB CARD Sales Order: ARC Repair TP(CLSO)1 Team: REGN NO: SHB4334E MILEAGE ISTOMER COMFORT TRANSPORTATION PTE LTD MAKE: HYUNDAI FUEL R/MS 7010045 E.....F STOMER NO. 383 SIN MING DRIVE MODEL 1-40 02.12.2017 02:20 DRESS Singapore SINGAPORE 575717 65508755 TARGET DATE YR OF MANUG. 2015 (0) L. (R) (P) COMPLETION DATE/TIME: CHASSIS CODE 41UMGU074960 SCOUNT CARD NO.

JOB DESCRIPTION

Accident Date: 02.12.2017

NATURE: 3P 02.12.17

S/NO

LABOR CODE

DESCRIPTION

HECKED & PASSED OUT BY:	
SERVICE ADVISOR	CUSTOMER'S SIGNATURE
iowledgement Slip	Exit Pass
e: lo.: SHB4334E CHIANG	Vehicle No.: SHB4334E
ie of Service Advisor Signature/Date a returned to Service Reception upon collection	Name of Service Advisor Date To be kept by Security Guard

LEC

COMFORTDELGRO ENGINEERING PTE LTD REPAIR ESTIMATE*

VEHICLE NO

: SHB 4334E

MAKE

DATE 12/2/2017 10:45

Chara

Qty	: HYUNDAI i40 Parts Description/ Labour	Type	Unit Price	Amount	
7-1	Rear Bumper / Idal			\$ 603.60	
	~ "^		AL OL	\$ 504.35	١,
	Rear Bumper Reinforcement Rear Bumper Reinforcement Bracket (LH/RH)	CHUBY	\$ KHX3 180.00	\$ 360.00	18
	Rear Bumper Sponge			\$ 143.40	
	Rear Rumper Under Cover			\$ 225.00	
	Rear Bumper Reflector Lamp (LH)			\$ 32.00	
	Poor Rumper Clins 10 ncs			\$ 22.00	
	Full a cost Ding Insulator (LH)			\$ 58.55	
	Exhaust Silencer (LH)			\$ 954.00	
				\$ 58.55	
	Exhaust Pipe Hanger (LH) \$ 1130.50			Bother Sections	
	Exhand SUB TOTAL			\$ 2,961.45	1
	LESS 20%	1		\$ 592.29	
	DISCOUNTED TOTAL	1		\$ 2,369.16	
	Rear Bumper Reverse Sensor × **			\$ 135.70	N
	Rear Bumper Advertisement Logo / ^			\$ 50.00	N
	Rear Fender Advertisement Logo (LH/RH)	1	\$ 100.00	\$ 200.00	N
				\$ 385.70	1
	Labour Charge			\$ 350.00	2
	Panel Beating			\$ 200.00	1
	Spray Painting Charge			\$ 30.00	
	Wiring Charge			\$ 30.00	
	Remove/Refix Reverse Sensor				
	TOTAL LABOUR	3		\$ 700.00	
	ESTIMATE TOTA	L ×6		\$ 3,454.86	
		apper)		4359.26	
	Kalin ICKIV () A 4/12/17 1110hs. 2 Poys 4 S A Hu Repair philo	1/2/	# 1 of Consultants	s hence notify	Ť
	Railin	(-1		stray starting	
	4/12/17 111045.		 Dam Livings are subject to The diparty survey is child 	o common soon	nele
	2 Pays		Na Jegal mo incarenza	0 KAR2	
	1/0		Supplementary at militia subject to final approva	ust the resurveyed and	
	4, 11				any
	A He Repair phin		Acknowledged by Repairer		
	F1 11 1 1 1 1		Signature: Date:		
		1 1	2001		

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING

Our Job Ref No 305094154 ComfortDetGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156 05/12/17 FINALIZATION FORM Fax: LKK Attn : 02/12/17 Vehicle Reg No. : SHB4334E The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-SGB771P NTUC The repair job shall bill to: The finalized amount shall be: Spare Parts after List discount (a) (b) Labour Charges Total for Part-By-Part Repair Cost (c.) Lumpsum Repair (if applicable) 20% Total for Lumpsum repair cost after Less: \$2,900.00 Final Lumpsum Repair cost working days. Estimated normal period for repairs: 3. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 4. working days We confirm the estimates and Thank you for your assistance. 5. finalized amount Signature: Signature: CHIANG Name 11/12/17 : 62148314 Tel 65468156 Fax For Official Use Only Document Confirm By Remarks Attached Amount Item (Signature) Yes or No YES Rental Rate P/Day N Loss of Income Paid Survey Fees LTA Search Fee Medical Fees (on behalf of driver, if applicable) Overrun Remarks:



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315



Thatcham escribe

Reg. No: 52983356E GST Reg. No. 20-0405911-H

NTUC INCOME INSU	RANCE CO-OPERATIVE LTD	Ref: NS/INC17023003/K1rbn2		
73 BRAS BASAH ROA #05-01 NTUC TRADE 189556	AD UNION HOUSESINGAPORE	Date: 21-12-2017 Code: INC4		
	Policy Particulars	:- THIRD PARTY CLAIM	V	
Insured Veh.	SGB 771P	Veh. Inspected	SHB 4334E	
Policy No.	5017428817-10	Coverage (\$)	0.00	
Claim No.	MT/0972173-002	Excess (\$)	0.00	
Assign From		Assign Date	04/12/2017	
	Vehicle Parti	iculars & Condition		
Make & Model	HYUNDAI 140	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KMHLB41UMGU074960	Colour	BLUE	
Odometer	360738	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3.	Condit	tions of Tyres		
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	7 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	7 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	7 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	7 mm	
4.	Descript	ion of Damages		
THE VEHICLE S	USTAINED DAMAGES AT THE RI DETAILS.	EAR N/S PORTION.		
5.		al Information		
Accident Date	02/12/2017	Inspection Date	04/12/2017	
Survey held at	COMFORTDELGRO ENGINEE	ERING PTE LTD		
1.00	59 LOYANG DRIVE SINGAPORE 508969			
5a.		Remarks		
A)THE INSPECT B)IN ACCORDA	ION WAS CONDUCTED ON A"W NCE TO YOUR INSTRUCTIONS,	WE HAVE NOT AUTHORIS	SIS. SED REPAIRS.	
5b.		e Days of Repair		
ESTIMATED NO	RMAL PERIOD FOR REPAIR:	2 Working Day	ys	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 4334E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	603.60	603.60
1	REAR BUMPER REINFORCEMENT	CRACKED	504.35	504.35
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$180.00	N/S BENT / O/S SERVICEABLE	360.00	180.00
1	REAR BUMPER SPONGE	TORN	143.40	143.40
1	REAR BUMPER UNDER COVER	CRACKED	225.00	225.00
1	REAR BUMPER REFLECTOR LAMP (LH)	SERVICEABLE	32.00	9.5
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	EXHAUST PIPE INSULATOR (LH)	SERVICEABLE	58.55	10
1	EXHAUST SILENCER (LH)	BENT	954.00	954.00
1	EXHAUST PIPE HANGER (LH)	SERVICEABLE	58.55	3.0
1	EXHAUST CENTRE	BENT	1,130.50	1,130.50
	LESS 20% DISCOUNT		-818.39	-752.57
			3,273.56	3,010.28
	SPECIAL NETT ITEMS			
1	REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	135.70	
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
			385.70	250.00
	LABOUR			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		500.00	200.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		200.00	180.00
	-		8-	
	-			
	-		700.00	380.00
	GRAND TOTAL		4.359.26	

Report Ref No. NS/INC17023003/K1rbn2





RECOMMENDED COST OF LUMP SUM REPAIRS	2,900.00
(TO ITS PRE-ACCIDENT CONDITION)	
(CONFIRMED)	

Report Ref No. NS/INC17023003/K1rbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report,

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.