REF: ALL



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

		STATE OF THE PROPERTY OF THE PARTY OF THE PA	nationale Des Experis En Autom	
AIG	ASIA PACIFIC INS	SURANCE PTE LTD	Ref : CC6/LCR17023	3024/Uza3
	HENTON WAY #0 RTIS BUILDINGSI	8-16 NGAPORE 079120	Date: 05-12-2017 Code: LCR	
1.		Policy Particu	lars :- THIRD PARTY CLAI	M
	Insured Veh.	SLE 7405B	Veh. Inspected	SGG 2704U
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	05/12/2017
2.	Walter March 200	Vehicle F	Particulars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	(4):	Steering	
	Brakes		Modification	
	General			
3.		Co	nditions of Tyres	TWEIS NEEDS
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre		21	mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.		Desc	ription of Damag ₃s	
5.	Salas III.	Go	neral Information	
J.	Accident Date	02/12/2017	Inspection Date	05/12/2017
	Survey held at	ABWIN SERVICE PTE LTD		O BOWN OFF AND WALLEY
	Survey field at	No. 8 KAKI BUKIT AVENU	*	
		#07-48 PREMIER@KAKI E SINGAPORE 415875		
5a.			Remarks	50 p. 80 P. C. S
	A)THE INSPECTION	ON WAS CONDUCTED ON A	A"WITHOUT PREJUDICE" BAS NS, WE HAVE NOT AUTHORIS	SIS. SED REPAIRS.

Please arrange to survey vehicle at 8 KAKI BUKIT AVENUE 4 - GATE 2 #07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875

Date

: 06/12/2017

TP Vehicle No. : SLE-7405-B

To

: AIG ASIA PACIFIC INSURANCE PTE LTD

Attn

: Motor Claim Department

Owner

: I CAB

TOKIO MARINE INSURANCE SINGAPORE LTD : 17-MG000683-R02

Certificate No. Vehicle No.

: SGG-2704-U

Make & Model : TOYOTA CAMRY 2.4 (A)

LINDA LIAO

ABWIN SERVICE PTE LTD

DID: 67139417

Fax: 67139415 HP: 97519596

Accident Date: 02/12/2017

#### ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
List Iten	1	L	
1	FRONT BUMPER	\$595.70	
2	FRONT BUMPER RETAINER RH & LH	Ner \$113.60	
1	FRONT BUMPER REINFORCEMENT	A 1 \$350.60	<b>&amp;</b>
1	FRONT BUMPER SPONGE	n - \$120.60	₹
1	FRONT BUMPER LOWER GRIEEL	مر \$125.00	8
1	FRONT BUMPER FOG LAMP RH	A7 \$250.70	×
1	FRONT BUMPER FOG LAMP LH	<b>11</b> \$250.70	4
10	FRONT BUMPER CLIPS	Ne \$50.00	
1	RH HEADLAMP	M \$2,550.00	N
1	LH HEADLAMP	A A \$2,550.00	a
1	BONNET	1 1 \$1,216.70	X
1	BONENT LOGO	11 \$65.20	d
1	BONNET GRILLE	11(cm \$455.60	a
1	AIR CON CONDENSER	17 \$1,440.70	V
1	AIR CON COMPRESSOR	17 \$1,934.50	$\triangle$
1	STEERING RACK AND PINON	11 \$2,418.80	火
1	FRONT BRRAKE DISC	7 n \$194.15	Ν
1	FRONT BRACKE PAD	A 1 \$195.75	X
1	ENGINE MOUNT FRONT	11 \$350.60	U,
1	EINGINE MOUNT LH	11 \$363.10	d
1	EINGINE MOUNT RH	1 \$326.10	X
1	ENGINE MOUNT TOP	17 \$205.30	d
2	FRONT LOWER ARM BUSH	17 \$130.00	X
2	REAR LOWER ARM BUSH	√ ↑ \$130.00	X
2	FRONT SHOCK ABSORBER	1 1 \$723.80	X
2	REAR SHOCK ABSORBER	N1 \$756.80	d
	Sub Total	\$17,864.00	68.1
	Discount 25% on Parts	(\$4,466.00) \$13,398.00	-1211



LINDA LIAO

ABWIN SERVICE PTE LTD

DID: 67139417 Fax: 67139415

HP: 97519596

Date TP Vehicle No. : SLE-7405-B

: 06/12/2017

To

: AIG ASIA PACIFIC INSURANCE PTE LTD

Attn

: Motor Claim Department

Owner

: 1 CAB

TOKIO MARINE INSURANCE SINGAPORE LTD

Certificate No. : 17-MG000683-R02

Vehicle No.

: SGG-2704-U

Make & Model : TOYOTA CAMRY 2.4 (A)

Accident Date: 02/12/2017

#### ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
Special	Nett	8	1004
1	FRONT NUMBER PLATE & CASING	\$45.00	40
	Sub Total	\$45.00	
Labour	& Misc		27-
	TO STRAIGHTEN AND PANEL BEAT ACCIDNET AREAS	\$1,500.00	^
	TO SPRAY PAINT ON AFFECTED AREAS	\$1,500.00	
	TO CHECK ALL NECCESSARY WIRINGS	\$150.00	30
	TO VACUUM AND TOP UP AIR-CON GAS	A1 \$150.00	X
	TO WHEEL ALIGNMENT AND BALANCING	17 \$150.00	a
	TO CHECK AND CONDUCT UNDERCARRIAGE SYSTEM	11 \$350.00	$\alpha$
	Sub Total	\$3,800.00	
	Sub Total	\$17,243.00	
	GST 7%	\$1,207.01	
	Total	\$18,450.01	

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- . Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type	Business	
Owner ID	1738X	
Vehicle Details		
Vehicle No.	SGG2704U	
Vehicle to be Exported	No	
Intended De-registration Date	05 Dec 2017	
Vehicle Make	TOYOTA	
Vehicle Model	CAMRY 2.4	
Primary Colour	Silver	
Manufacturing Year	2006	
Engine No.	2AZ3234284	
Chassis No.	MR053BK3005029407	
Maximum Power Output	112.0 kW (150 bhp)	
Open Market Value	\$29,681.00	
Original Registration Date	08 May 2006	
First Registration Date	08 May 2006	
Transfer Count	3	
Actual ARF Paid	\$32,650.00	
Intended PARF Rebate Details		
PARF Eligibility	Forfeited	
PARF Eligibility Expiry Date		
PARF Rebate Amount	\$0.00	
Intended COE Rebate Details		
COE Expiry Date	07 May 2026	
COE Category	B - Car (1601cc & above)	
COE Period(Years)	10	
PQP Paid	\$46,048.00	
COE Rebate Amount	\$38,781.00	
Total Rebate Amount	\$38,781.00	

The information contained herein is correct as at 05 Dec 2017



### Joy Irene (LKKAuto)

From:

Zavver (LKKAuto)

Sent:

Tuesday, 9 January 2018 6:27 PM

To:

Linda Liao; Ivan Teo

Cc:

Admin A; Vivian Lau (LKKAuto); Hsiao Tong (LKKAuto)

Subject:

RE: Re: SGG2704U Against SLE7405B Accident on 02/12/2017 \*\*\* LKK REF -

CC6/LCR17023024/Uza3

Attachments:

our isured sketch plan.pdf

Dear Linda,

Attached is our insured sketch plan and below is police report.

Our insured reported that your client rear ended him multiple times.

Please forward us proof / evidence / video for our review. Thanks.

Hospital/Clinic	NIL	9	Class Drivin Licen Expin	g	Class: N Date of E
Date Treatment	NIL		Date Discharge	NIL	
	ted Medical Leave	NIL	Degree of Injury	NIL	

#### Brief Details.

On 02/12/2017 at about 1315hrs, I was travelling along Lentor Ave towards Ang Mo Kio vehicle, SLE7405B (V1) and I was carrying a passenger in that point of time. I wish to st no vehicle on lane 3 as such I made a check on my rear and side mirrors for oncoming v I then spotted one vehicle, SGG2704U (V2) from afar, about 10-15metres away from afa signalled left and made a lane change to lane 3. The driver of V2 then caught up with micontinuously at me as such I slowed down my vehicle and asked passenger for permissi my vehicle when the driver of V2 hit onto the rear of my vehicle. The impact was great a my vehicle to surge forward and the driver of V2 hit onto the rear of my vehicle again. The then reversed and hit onto the rear of my vehicle continuously for about more than 4 times.

Both drivers got out of the vehicles. My passenger was in a rush as both drivers took do number. The driver of V2 then approached me and asked me "Now shiok is it?" and he is nothing happened to your car" and "You are done". The driver of V2 then drove off within any details.

I do have a front in-built camera in my vehicle. The rear portion of my vehicle were serio have reported the matter to Uber and called for Police who attended to me vide F/20171 pains on my neck and back as such I will be proceeding to see a doctor to get treated.

Zayer | Case Handler

#### LKK Auto Consultants Pte Ltd

Phone: 6841 2409, email: <u>zayyer@lkkauto.com</u> fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto)

Sent: Tuesday, 9 January, 2018 5:58 PM

To: Linda Liao lindaliao@abwin.com.sg>; Ivan Teo <ivanteo@abwin.com.sg>; Zayyer (LKKAuto)

<zayyer@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; Hsiao Tong (LKKAuto)

<chewht@lkkauto.com>

Subject: RE: Re: SGG2704U Against SLE7405B Accident on 02/12/2017 \*\*\* LKK REF - CC6/LCR17023024/Uza3

Dear Linda,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Dear Zayyer,

For your information and necessarily action please.

To check availability of the case handler, you may contact the undersigned.

"Wishes you a Merry Christmas & Happy New Year 2018"

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: <u>ShirleyHiew@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Linda Liao [mailto:lindaliao@abwin.com.sg]

Sent: Tuesday, 9 January 2018 4:17 PM
To: Admin A <a href="mailto:admin-a@lkkauto.com">admin-a@lkkauto.com</a>
Cc: Ivan Teo <a href="mailto:ivanteo@abwin.com.sg">ivanteo@abwin.com.sg</a>

Subject: RE: Re: SGG2704U Against SLE7405B Accident on 02/12/2017

Dear Lkk

Please refer to attached document for your action.

Thank you Regards



Abwin Service Pte Ltd No. 8 Kaki Bukit Avenue 4 #07-48 Premier@Kaki Bukit Gate 2 Singapore 415875

#### Linda Liao

Motor Claim Executive

DID +65 6713 9417 HP:9751 9596

T +65 6713 9400 | F +65 6713 9415

Website | Facebook | LinkedIn

Looking to start a new business soon? Find out how we can provide you with a complete vehicle ownership solution and much more!

Click here to view our listing >>



From: Linda Liao

Sent: Wednesday, 6 December, 2017 5:01 PM

To: Admin A <admin-a@lkkauto.com>
Cc: Ivan Teo <ivanteo@abwin.com.sg>

Subject: Re: SGG2704U Against SLE7405B Accident on 02/12/2017

Dear Lkk

Please advise the liability as soon as possible.

Thank you Regards

# **ABWIN**

Abwin Service Pte Ltd No. 8 Kaki Bukit Avenue 4 #07-48 Premier@Kaki Bukit Gate 2 Singapore 415875

#### Linda Liao

Motor Claim Executive DID +65 6713 9417 HP:9751 9596 T +65 6713 9400 | F +65 6713 9415

Website | Facebook | LinkedIn

Looking to start a new business soon? Find out how we can provide you with a complete vehicle ownership solution and much more!

Click here to view our listing >>



#### Joy Irene (LKKAuto)

From:

Joy Irene (LKKAuto)

Sent:

Friday, 7 September 2018 1:43 PM

To:

'Chong, Joee'

Cc:

Admin A

Subject:

LCR SLE 7405B AND SGG 2704U ON 02.12.2017

AIG: 6862298171SG

LKK: CC6/LCR17023024/Uja3

Dear Joee,

We refer to the subject.

We were informed by TP repairer that their client did not send his vehicle for repair.

In view of this, we will proceed to submit our wp report in Merimen.

Thank you.

Best Regards, Joy Irene | Case Handler LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: joyirene@lkkauto.com| Fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

# ...CLAIM SUBFOLDER...(Pending for Survey Report) Revoked / No settlement

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj	Submitted	Ins Auth'ed	Status	
Main	05 Dec 2017 Edit Reg		05 Dec 2017 00:00 Edit Adj Rpt	S\$1,000.00 Edit Estimate	1 1 2 2 2 2	t,000.00 ew Rpt		Pending for Report Cancel Ca	energen stærn
	Main	R	eference	Claim	Details		Documents	. 1	Show All
CLAIM S	JBFOLDER DI	ETAILS				[Created I	by adjuster]		
Insured:	LCRF PTE	LTD, Co. Reg. 1	No.; 201624597K						
Main Claimant:	I CAB,	Co. Reg. No.: 533	11738X						
Vehicle Re No.:	Date of Loss: [138 Months and 24 Days From LTA Reg Date					te (Man Yr)]			
Cialm Type	TP / 686	2298171SG			y/Cover No.:	099995059 (Comprehensive)			
Vehicle Re No. (Insured):	SLE7405	в			y No. mant):	17-MG000683-R02			
				Exce	\$SI				
Repairer:	Abwin Se	rvice Pte Ltd (H	Q) No. 8 Kaki Bukit	Avenue 4, #07-4	8 Premie	r@Kaki Bukit	Gate 2, 415875	Kaki Bukit - Tel:	6713 9400
Handling Insurer:	AIG Asia	Pacific Insuranc	e Pte. Ltd. (Expre	ss) - Tel: 65-641	9-3000	., [Handled b	y Chong, Joee]		
Claimant's Insurer:	Tokio Ma	rine Insurance S	ingapore Ltd (HQ	) - Tel: 6221 611	1				
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [Han	dled by P	MARCUS CHU	JA] [Final R	pt due 14/12	/2017]
ASSOCIA	TED MAIL RE	CEIVED					Vie	w All   Compr	se Case Mai
<ul> <li>AIG_SG</li> </ul>	(06/12/2017)	: Confirmation o	f OI vehicle numb	er					
ALL ASS	OCIATED TAS	кѕ⊟			[3)	View All   S	earch Tasks   C	reate New Task	Complete
Due Dat		Type Task	Group Subjec	t Handler	Assign	ned By	Completed On	Created C	n Done

Merimen e-Claims Page 1 of 2

#### Claim Documents

Ass	essment Reports		1 per	page V	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	I put	Thumbnail	-
1	07/12/17 12:05	Accident Statement From:SC - Reg. No. SLE74058, Claimant: LCRF PTE LTD	0	Load HTM	
Pho	otos/Images		3 per	page 🔻	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/12/17 13:54	Odometer Reading	0	Load JPG	V
2	05/12/17 13:54	General View	0	Load JPG	V
3	05/12/17 13:54	Chassis Number	0	Load JPG	V
4	05/12/17 13:54	General View	0	Load JPG	V
5	05/12/17 13:54	General View	0	Load JPG	V
6	05/12/17 13:54	General View	0	Load JPG	V
7	05/12/17 13:54	General View	0	Load JPG	V
8	05/12/17 13:54	General View	0	Load 3PG	V
9	05/12/17 13:54	General View	0	Load JPG	V
10	05/12/17 13:54	General View	0	Load JPG	V
11	05/12/17 13:54	General View	0	Load JPG	V
12	05/12/17 13:54	General View	0	Load JPG	V
13	05/12/17 13:54	General View	0	Load JPG	V
14	05/12/17 13:54	General View	0	Load JPG	[Z]
15	05/12/17 13:54	General View	0	Load JPG	V
16	05/12/17 13:54	General View	0	Load JPG	V
17	05/12/17 13:54	General View	0	Load JPG	V
18	05/12/17 13:54	General View	0	Load JPG	V
19	05/12/17 13:54	General View	0	Load JPG	V
20.	05/12/17 13:54	General View	0	Load JPG	V
21	05/12/17 13:54	General View	0	Load JPG	V
22	05/12/17 13:54	General View	0	Load JPG	V
23	05/12/17 13:54	General View	0	Load 3PG	V
Doc	umentation		1 per	page 🔻	V
Νo	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/12/17 10:44 07/09/18 13:55	TP GIA REPORT	0	Load PDF	

#### **Documents Checklist**

	(44)4.43	Save	Print
There are no document checklists configured.			

Merimen e-Claims Page 2 of 2

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR17023024/UJA3Q2

12/09/2018 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Claimant Vehicle SGG2704U

0999995059 Policy No:

No:

Insured Vehicle No: SLE7405B

Nature of Claim: TP Date of Loss: 02/12/2017 Claim No: 6862298171SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SGG2704U Reg No:

Make & Model: TOYOTA CAMRY, 2.4 (A) Engine No: 2AZ3234284

Reg. Date: 08/05/2006 (Man. Year. 2006) Chassis No: MR053BK3005029407

Colour Odometer: 369872 km

Engine Capacity: 2362 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,443.00	609.47	12,833.53	95.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,800.00	650.00	3,150.00	82.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,243.00	1,259.47	15,983.53	92.70
Approved Total (Overridden) (S\$)		1,000.00		
(S\$)	17,243.00	1,000.00	16,243.00	94.20
+ GST 7.00/7.00% (S\$)	1,207.01	70.00	1,137.01	94.20
Nett Amount (S\$)	18,450.01	1,070.00	17,380.01	94.20
Global Sum S	Settlement (S\$)	0.00		

INSPECTION

Date of Assignment: 05/12/2017

Date Inspected: 05/12/2017 Inspected At: Abwin Service Pte Ltd (HQ)

No. 8 Kaki Bukit Avenue 4, #07-48

Premier@Kaki Bukit Gate 2

Singapore 415875

Estimated Period of Repair: 2.0 days Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

# Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*FRONT BUMPER	Dented / Torn	595.70 FL	*595.70 FL
2		*FRONT BUMPER RETAINER RH & LH	Necessary	113.60 FL	*113.60 FL
1		*FRONT BUMPER REINFORCEMENT	Not Necessary	350.60 FL	*-FL
1		*FRONT BUMPER SPONGE	Not Necessary	120.60 FL	*-FL
1		*FRONT BUMPER LOWER PANEL	Not Necessary	125.00 FL	*-FL
1		*FRONT BUMPER FOG LAMP RH	Not Necessary	250.70 FL	*-FL
1		*FRONT BUMPER FOG LAMP LH	Not Necessary	250.70 FL	*-FL
10		*FRONT BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
1		*RH HEADLAMP	Not Necessary	2,550.00 FL	*- FL
1		*LH HEADLAMP	Not Necessary	2,550.00 FL	*-FL
1		*BONNET	Not Necessary	1,216.70 FL	*-FL
1		*BONNET LOGO	Not Necessary	65.20 FL	*-FL
1		*BONNET GRILLE (CRACKED)	Not Consistent With The Impact	455.60 FL	*-FL
1		*AIR CON CONDENSER	Not Necessary	1,440.70 FL	*-FL
1		*AIR CON COMPRESSOR	Not Necessary	1,934.50 FL	*-FL
1		*STEERING RACK AND PINION	Not Necessary	2,418.80 FL	*-FL
1		*FRONT BRAKE DISC	Not Necessary	194.15 FL	*-FL
1		*FRONT BRACKE PAD	Not Necessary	195.75 FL	*-FL
1		*ENGINE MOUNT FRONT	Not Necessary	350.60 FL	*-FL
1		*ENGINE MOUNT LH	Not Necessary	363.10 FL	*-FL
1		*ENGINE MOUNT RH	Not Necessary	326.10 FL	*-FL
1		*ENGINE MOUNT TOP	Not Necessary	205.30 FL	*-FL
2		*FRONT LOWER ARM BUSH	Not Necessary	130.00 FL	*-FL
2		*REAR LOWER ARM BUSH	Not Necessary	130.00 FL	*-FL
2		*FRONT SHOCK ABSORBER	Not Necessary	723.80 FL	*-FL
2		*REAR SHOCK ABSORBER	Not Necessary	756.80 FL	*-FL
1		*FRONT NUMBER PLATE & CASING	Bent	45.00 FS	*40.00 FS
enchise	part. S=Spc	Nett. L=ListItemDisc.		47.000.00	700.00
		ver manager	그는 그 그 그 그		799.30
		- List item Disco	unt on L Items 25.00/25.00% (S\$)	4,466.00	189,83
			Total Parts (S\$)	13,443.00	609.47
	1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	*FRONT BUMPER RETAINER RH & LH *FRONT BUMPER REINFORCEMENT *FRONT BUMPER SPONGE  *FRONT BUMPER LOWER PANEL *FRONT BUMPER FOG LAMP RH  *FRONT BUMPER FOG LAMP LH *FRONT BUMPER CLIPS  *RH HEADLAMP *LH HEADLAMP  *BONNET  *BONNET LOGO  *BONNET GRILLE (CRACKED) *AIR CON CONDENSER  *AIR CON COMPRESSOR  *STEERING RACK AND PINION  *FRONT BRAKE DISC *FRONT BRAKE DISC  *FRONT BRACKE PAD  *ENGINE MOUNT FRONT *ENGINE MOUNT LH  *ENGINE MOUNT TOP  *FRONT LOWER ARM BUSH *FRONT SHOCK ABSORBER  *REAR LOWER ARM BUSH *FRONT NUMBER PLATE & CASING anchise part. S=SpcNett. L=ListItemDisc.	**FRONT BUMPER Dented / Torn  Dented / Torn  PRONT BUMPER RETAINER RH & LH Necessary  **FRONT BUMPER REINFORCEMENT Not Necessary  Not Necessary  **FRONT BUMPER SPONGE Not Necessary  **FRONT BUMPER FOG LAMP RH Not Necessary  **FRONT BUMPER FOG LAMP RH Not Necessary  **FRONT BUMPER FOG LAMP LH Not Necessary  **FRONT BUMPER CLIPS Necessary  **Necessary  **TRONT BUMPER CLIPS Necessary  **Necessary  **TRONT BUMPER CLIPS Necessary  **Not Necessary  **STEERING RACK AND PINION Not Necessary  **STEERING RACK AND PINION Not Necessary  **STEERING RACK AND PINION Not Necessary  **STEERING MOUNT FRONT Not Necessary  **STEERING MOUNT FRONT Not Necessary  **STENGINE MOUNT FRONT Not Necessary  **STENGINE MOUNT FRONT Not Necessary  **STENGINE MOUNT RH NOT NECESSAR	FRONT BUMPER

Adjuster Report Page 4 of 4

### Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	New	1,500.00	320.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	1,500.00	300.00
3	TO CHECK ALL NECESSARY WIRINGS	New	150.00	30.00
4	TO VACUUM AND TOP UP AIR-CON GAS	New	150.00	0.00
5	TO WHEEL ALIGNMENT AND BALANCING	New	150.00	0.00
6	TO CHECK AND CONDUCT UNDERCARRIAGE SYSTEM	New	350.00	0.00
	Gross Lab	our Cost (S\$)	3,800.00	650.00
	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >