

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 4496K

DATE 4/12/2017 12:33

MAKE :

MODEL : HYUNDAI SONATA

LKK/Kahrin

L/Sum

Like

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid ✓			\$ 1,349.50
	Boot Lid Rubber ✕			\$ 110.90
	Boot Lid Lock Upper ✕			\$ 132.10
	Boot Lid Lock Lower ✕			\$ 30.30
	Boot Lid Sonata Plate —			\$ 43.60
	Boot Lid Hyundai Plate —			\$ 24.20
	Boot Lid 'H' Emblem —			\$ 26.10
	Boot Lid CRDI Plate —			\$ 22.70
	Boot Lid Lamp (LH/RH) —		\$ 230.20	\$ 460.40
	Rear Bumper —			\$ 578.40
	Rear Bumper Reinforcement —			\$ 483.30
	Rear Bumper Clip —			\$ 22.00
	Rear Bumper Sponge —			\$ 137.40
	Rear Bumper Under Cover ?			\$ 185.80
	Rear Bumper Protector (LH/RH) ✓		\$ 38.00	\$ 76.00
	Tail Lamp (LH/RH) ?		\$ 344.00	\$ 688.00
	Rear Panel ✕ Repair			\$ 391.80
	Rear Panel Garnish —			\$ 95.80
	SUB TOTAL			\$ 4,858.30
	LESS 20%			\$ 971.66
	DISCOUNTED TOTAL			\$ 3,886.64
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00
	Rear No. Plate —			\$ 25.00
	Rear Bumper Reverse Sensor ✕			\$ 135.70
				\$ 190.70
	Labour Charge			
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 1,670.00
	ESTIMATE TOTAL			\$ 5,747.34
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

SUB TOTAL

LESS 20%

DISCOUNTED TOTAL

Boot Lid Comfort Logo & Tel No. Sticker

Rear No. Plate

Rear Bumper Reverse Sensor ✕

Labour Charge

Panel Beating

Spray Painting Charge

Wiring Charge

Tuff Kote

Remove/Refix Reverse Sensor

TOTAL LABOUR

ESTIMATE TOTAL

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.