

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 2010196262G

SHD914Y - AIG**AAD1711-315***Not Authored*
Recovery B4 part 82928.18

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD914Y - CANDY

VF1ABL15AUC283249

RENAULT

LATITUDE

28.11.2017

AIG

		PART		LIST
1	1	BUMPER COVER FRT	\$	<i>Br</i> 1,259.42 ✓
2	1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68 X
3	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08 X
4	1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75 X
5	1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80 X
6	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sn</i> 207.22 X
7	1	BUMPER RETAINER FRT LH	\$	<i>Dir</i> 151.41 ✓
8	1	BUMPER BRACKET FRT LH	\$	<i>R</i> 181.75 X
9	1	HEADLAMP LH	\$	<i>Sn</i> 1,184.43 X
10	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15 X
11	1	FENDER PANEL FRT LH	\$	<i>R</i> 783.83 ✓
12	1	FENDER INSULATOR LH	\$	<i>Sn</i> 130.84
13	1	FENDER BRACKET FRT LH	\$	<i>R</i> 34.14
14	1	WHEELARCH FRT LH	\$	<i>Sn</i> 278.84
15	1	RADAITOR GRILLE	\$	<i>Sn</i> 1,707.78
16	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i> 173.36
17	1	RADAITOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75
18	1	FRAME FULL SUPPORT PANEL	\$	<i>R</i> 615.90
19	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79
20	1	BONNET	\$	<i>R</i> 1,941.63
21	1	DOOR PANEL FRT LH	\$	<i>R</i> 2,844.66
22	1	DOOR HINGE UPPER LH	\$	<i>R</i> 274.50
23	1	DOOR HINGE LOWER LH	\$	<i>R</i> 300.55
24	1	DOOR MOULDING FRT LH	\$	<i>Sn</i> 176.82
25	1	DOOR MIRROR LH	\$	<i>Sn</i> 1,483.40
26	1	DOOR MIRROR GLASS LH	\$	<i>Sn</i> 148.20
27	1	DOOR MIRROR BACK COVER LH	\$	<i>Sn</i> 218.46
28	1	DOOR WHETHERSTRIP FRT LH	\$	<i>Sn</i> 474.21
29	1	DOOR SEAL FRT LH	\$	<i>Sn</i> 68.67
30	1	ROCKER PANEL OUTER LH	\$	<i>R</i> 987.49

TOTAL	\$	18,980.52
10%	\$	1,898.05
	\$	17,082.47

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 2010196262G

SHD914Y - AIG**AAD1711-315****Specical Nett**

1	1SET	WHEELARCH CLIP FRT LH	\$	<i>nn</i> 66.00 X
2	1SET	FRONT BUMPER CLIP	\$	<i>nn</i> 66.00 ✓
3	1	RIM LH FRT	\$	<i>nn</i> 385.00 X
4	1	TYRE LH FRT	\$	<i>nn</i> 330.00 X
5	1	DOOR STICKER "Trans-cab"	\$	<i>nn</i> 80.00 X
6	1	DOOR STICKER "Classic"	\$	<i>nn</i> 30.00 X
7	1	DOOR STICKER "6555-3333"	\$	<i>nn</i> 80.00 X

TOTAL	\$	1,037.00
TOTAL PARTS	\$	18,119.47

To Check Electrical Lighting Concerned.	\$	170.00 <i>15/</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,800.00 <i>400/</i>
Putty and spray painting of the affected portion.	\$	3,000.00 <i>440/</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 170.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 X
Towing fees	\$	<i>nn</i> 120.00 X
To rust-proofing of the affected areas.	\$	170.00 <i>30/</i>

(PARTS BY PARTS) Repair Days

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL	\$	7,160.00
Over All Total	\$	25,279.47

10 Days*2 days*