




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CT117023034/K1pb3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 05-12-2017	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKK 4061J	Veh. Inspected	SHD 4513U	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	05/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/12/2017	Inspection Date	04/12/2017	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO 305094341

MEMER
COMFORT TRANSPORTATION PTE LTD
7010045
MEMER NO
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755

REGN NO SHD4513U	MILEAGE
MAKE HYUNDAI	FUEL E.....1/2.....F
MODEL SONATA	DATE/TIME IN 02.12.2017 19:05
YR OF MANU 11.10.2012	TARGET DATE
CHASSIS CODE KMHET41VMCA830442	COMPLETION DATE/TIME:

CHINA

UNT CARD NO:

JOB DESCRIPTION

Accident Date: 02.12.2017
ATURE: 3P 02.12.2017

NO	LABOR CODE	DESCRIPTION
----	------------	-------------

KEYED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

to: SHD4513U LKE/KALVIN

Vehicle No.: SHD4513U

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard

Our Job Ref No 305094341
Date 07/12/17

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508669
Fax: 6548 8158

FINALIZATION FORM

To LKK
Attn : Mr KALVIN ANG
Vehicle Reg No. SHD4513U CTPL

Fax :


02.12.17


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA -- SKK4061J
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$650.00
Final Lumpsum Repair cost \$650.00

3. Estimated normal period for repairs: 3 working days
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature: 
Name : LIM KWOK ENG
Tel : 62148316
Fax : 65468156

Signature: 
Name : KALVIN ANG
Date : 8/12/17

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 4513U

MAKE :

MODEL : HYUNDAI SONATA

DATE 4/12/2017 13:01

Lee/Kalvin
LeeJL Sum
CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid Sonata Plate — <i>all</i>			\$ 43.60
	Boot Lid Hyundai Plate — <i>all</i>			\$ 24.20
	Boot Lid 'H' Emblem — <i>all</i>			\$ 26.10
	Boot Lid CRDI Plate — <i>all</i>			\$ 22.70
	Rear Bumper <i>+ repair</i>			\$ 578.40
	Rear Bumper Reinforcement <i>Ken</i>			\$ 483.30
	Rear Bumper Clip <i>X</i>			\$ 22.00
	Rear Bumper Sponge <i>Ken</i>			\$ 137.40
	Rear Bumper Under Cover <i>Ken</i>			\$ 185.80
	Rear Bumper Protector (LH/RH) <i>X repair</i>		\$ 38.00	\$ 76.00
	Rear Panel <i>X su</i>			\$ 391.80
	Rear Panel Garnish <i>X su</i>			\$ 95.80
	<i>Rec Bootlid X repair</i>			
	SUB TOTAL			\$ 2,087.10
	LESS 20%			\$ 417.42
	DISCOUNTED TOTAL			\$ 1,669.68
	Boot Lid Comfort Logo & Tel No. Sticker — <i>all</i>			\$ 30.00
	Rear Bumper Reverse Sensor <i>X</i> <i>all</i>			\$ 135.70
	Rear Bumper Rubber Mat — <i>all</i>			\$ 50.00
				\$ 215.70
	Labour Charge			
	Panel Beating- Repair bootlid			\$ 560.00 <i>300</i>
	Spray Painting Charge			\$ 400.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 1,180.00
	ESTIMATE TOTAL			\$ 3,065.38
	<i>Kalvin Lee</i>			
	<i>U 4/12/17 1445h</i>			
	<i>3 Days</i>			
	<i>U/S</i>			
	<i>After Repair ph</i>			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTII7023034/K1pb3

Date: 05.12.2017

The Motor Claim Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD4513U


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 04.12.2017 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	3,065.38
Revised Estimate Amount	: S\$	833.28
"Check" Items Amount	: S\$	645.20
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 4513U

DATE 4/12/2017 13:01

MAKE :

MODEL : HYUNDAI SONATA

Like/Kalvin

L/Sun

CHINA

Like

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid Sonata Plate ✓			\$ 43.60	
	Boot Lid Hyundai Plate ✓			\$ 24.20	
	Boot Lid 'H' Emblem ✓			\$ 26.10	
	Boot Lid CRDI Plate ✓			\$ 22.70	
	Rear Bumper X repair			\$ 578.40	
	Rear Bumper Reinforcement ?			\$ 483.30	
	Rear Bumper Clip X			\$ 22.00	
	Rear Bumper Sponge ?			\$ 137.40	
	Rear Bumper Under Cover ?			\$ 185.80	
	Rear Bumper Protector (LH/RH) X repair		\$ 38.00	\$ 76.00	
	Rear Panel X			\$ 391.80	
	Rear Panel Garnish X			\$ 95.80	
	Rear Boot Lid X repair				
	SUB TOTAL			\$ 2,087.10	
	LESS 20%			\$ 417.42	
	DISCOUNTED TOTAL			\$ 1,669.68	
	Boot Lid Comfort Logo & Tel No. Sticker ✓			\$ 30.00	Nett
	Rear Bumper Reverse Sensor X			\$ 135.70	Nett
	Rear Bumper Rubber Mat ✓			\$ 50.00	Nett
				\$ 215.70	
	Labour Charge				
	Panel Beating- Repair bootlid			\$ 560.00	
	Spray Painting Charge			\$ 400.00	360
	Wiring Charge			\$ 50.00	X
	Tuff Kote			\$ 50.00	X
	Remove/Refix Reverse Sensor			\$ 120.00	X
	TOTAL LABOUR			\$ 1,180.00	
	ESTIMATE TOTAL			\$ 3,065.38	
	<p>Like/Kalvin 10/11/17</p> <p>U 4/12/17 1445h</p> <p>3 Days</p> <p>L/S</p> <p>After Repair plz</p> <p>Like/Kalvin 10/11/17</p> <p>U 4/12/17 1445h</p> <p>3 Days</p> <p>L/S</p> <p>After Repair plz</p>				
	<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

Shu Pei (LKKAuto)

From: Jowyn Tay <jowyn.tay@sg.cntaiping.com>
Sent: Wednesday, 6 December, 2017 6:36 PM
To: Shu Pei (LKKAuto); Hsiao Tong (LKKAuto)
Cc: Alfred Toh; Admin A; Zaini (LKK Auto); Jowyn Tay
Subject: RE: Direct Settlement - Accident Involving SKK4061J(SNM17D06919/C02/1/LKKDS) and SHD4513U (TP : LKK REF - CC3/CTI17023034/K1pb3) on 02.12.2017
Attachments: SNM17D06919C02 20171206-TO INSD-APPT LKK AS SETTLEMENT AGENT.pdf; MCC417159495-SKK4061J.pdf

Importance: High

Dear Hsiao Tong &/or Shu Pei,

Please refer to both attachments.

Thank you.

Regards,

Jowyn Tay

Deputy Claims Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6174
Fax: 6224 7175 / 6224 7478
Email: claimsdept@sg.cntaiping.com
jowyn.tay@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Tuesday, 5 December, 2017 7:46 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Alfred Toh <alfred.toh@sg.cntaiping.com>; Jowyn Tay <jowyn.tay@sg.cntaiping.com>; Joel Goh <joel.goh@sg.cntaiping.com>; Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Zaini (LKK Auto) <Zaini@lkkauto.com>
Subject: Direct Settlement - Accident Involving SKK4061J(CTI - TBA) and SHD4513U (TP : LKK REF - CC3/CTI17023034/K1pb3) on 02.12.2017

WITHOUT PREJUDICE

Dear Jowyn,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHD 4513U at M/s ComfortDelGro Engineering Pte Ltd (Loyang).

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- TP's GIA report
- Police report
- Estimated cost of repair
- Preliminary advice

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank You.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

91k 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079908
Tel: 6389 8111 Fax: 6222 1033
Website: www.ctg.com.sg
Co. Reg. No. 200208384E

Our Reference: **SNM17D06919/C02/1**

Date : **06 DECEMBER 2017**

via Ordinary & Registered Mail

**ZHANG QI
12 ADIS ROAD
#06-20 ADIS VILLA
SINGAPORE 229976**

Dear Sir / Madam

**ACCIDENT INVOLVING SKK4061J AND SHD4513U ON 02 DECEMBER 2017
ALONG SERANGOON ROAD**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHD4513U**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,

Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd
Attn : HSHAO TONG
Ref : CC3/CT117023034/K1pb3
Contact No : 67423197
via Email : chewht@lkkauto.com

CC : Agent - (BR0070A) - IPP FINANCIAL ADVISERS PTE LTD

F01/LKKDS-2013

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Friday, 29 December, 2017 3:13 PM
To: 'williamtan@cdge.com.sg'; 'catherinekoh@cdge.com.sg'
Subject: Your Ref: T 1217/ SHD4513U/ WT(st) *Our Ref: CC3/CTI17023034/K1pb3
[ACCIDENT INVOLVING SKK 4061J(CHINA TAIPING)/ SHD 4513U/ OTHERS ON 02/12/2017]

Your Ref: **T 1217/ SHD4513U/ WT(st)**
Our Ref: CC3/CTI17023034/K1pb3

Without Prejudice

Dear Sirs/Madam,

ACCIDENT INVOLVING SKK 4061J(CHINA TAIPING)/ SHD 4513U/ OTHERS ON 02/12/2017

We refer to the above matter.

We propose settlement at a global sum of **S1,210.00(all-in)**.

Please confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

"Wishes you a Merry Christmas & Happy New Year 2018"

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From: William Tan Thoo Seng <williamtan@cdge.com.sg>
Sent: Tuesday, 2 January, 2018 9:13 AM
To: Hsiao Tong (LKKAuto)
Subject: Re: Your Ref: T 1217/ SHD4513U/ WT(st) *Our Ref: CC3/CTI17023034/K1pb3 [ACCIDENT INVOLVING SKK 4061J(CHINA TAIPING)/ SHD 4513U/ OTHERS ON 02/12/2017]

Without Prejudice.

Dear Ms Hsiao Tong

We are glad to accept your offer. Kindly forward your D.V. and payment to CDGE.

Thank you.

Best Regards
William Tan
Claims Department | ComfortDelgro Engineering Pte Ltd
Off : 62148737 | Fax : 62141843

From: "Hsiao Tong (LKKAuto)" <chewht@lkkauto.com>
To: "williamtan@cdge.com.sg" <williamtan@cdge.com.sg>, "catherinekoh@cdge.com.sg" <catherinekoh@cdge.com.sg>
Date: 29/12/2017 03:13 PM
Subject: Your Ref: T 1217/ SHD4513U/ WT(st) *Our Ref: CC3/CTI17023034/K1pb3 [ACCIDENT INVOLVING SKK 4061J(CHINA TAIPING)/ SHD 4513U/ OTHERS ON 02/12/2017]

Your Ref: **T 1217/ SHD4513U/ WT(st)**
Our Ref: CC3/CTI17023034/K1pb3

Without Prejudice

Dear Sirs/Madam,

ACCIDENT INVOLVING SKK 4061J(CHINA TAIPING)/ SHD 4513U/ OTHERS ON 02/12/2017

We refer to the above matter.

We propose settlement at a global sum of **\$1,210.00(all-in)**.

Please confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

"Wishes you a Merry Christmas & Happy New Year 2018"

Best Regards,
Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Our Ref : T 1217 / SHD4513U /WT(st)
Your Ref : _____
Date : 12-Dec-17

CDGE Taxi Claims Dept
59 Loyang Drive 4th Flr
Singapore 508969

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6383 6280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 13850648W

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 609286

Ubi
320 Ubi Road 3
Singapore 408649

Senoko
24 Senoko Loop
Singapore 758156

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

Yishun
Yishun Industrial Park A
Singapore 768732

CHINA INSURANCE CO LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

Attn : Motor Claims Department

WITHOUT PREJUDICE

Dear Sir

ACCIDENT INVOLVING OUR TAXI SHD4513U YOUR INSURED SKK4061J
AND OTHER SHD6799Z ON 02.12.17

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No : SHD4513U which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving SKK4061J we are submitting these claims for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$	695.50
2	<u>4.5</u> days Loss of Rental @ \$ <u>98.25</u> per day	\$	<u>442.13</u>
3	Survey Report Fees (Surveyed by M/s LKK)	\$	-
4	LTA Search Fees	\$	5.35
5	GIA / Police Report Fees	\$	-
6	Towing / Medical / Transportation Fees	\$	-
Sub Total :		\$	1,142.98

HIRER'S CLAIM

7	<u>4.5</u> days Loss of Income @ \$ <u>80.00</u> per days	\$	360.00
Total Claims :		\$	1,502.98

We enclosed herewith the following documents to support the claims: -

- a) Original repair bill and photostat photographs : 5 pcs.
b) LTA search slip/s of : SKK4061J
c) GIA / Police report/s of : SHD4513U
d) Letter of authority from owner / hirer / operator
() Traffic Compound () Towing/Medical bill/receipts () Certificate of Insurance
(X) Photograph/s of Accident Scene (x) Downtime/Mileage record (x) Rental Rate letter

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully
William Tan

Deputy Manager
CDGE Claims Department

Tel: 6214 8737 Fax: 6214 1843 Email : williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.

A member of

COMFORTDELGRO





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/CTI17023034/K1pb3

11 DECEMBER 2017

ZHANG QI
12 ADIS ROAD
#06-20
SINGAPORE 229976

Dear Sir/Madam,

ACCIDENT INVOLVING SKK 4061J/ SHD 4513U/ OTHERS ON 02/12/2017

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, China Taiping Insurance (Singapore) Pte Ltd to deal with the third party claim against your policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG
Case Handler
DID: 6742 3197
FAX: 6741 4108
EMAIL: chewht@lkkauto.com

c.c. *China Taiping Insurance (Singapore) Pte Ltd*
(Motor Claims Dept)

LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING
ALONGSONATA SHD4513U , SKK 4061 J , SHD679... ON 02-Dec-17 17:05
SERANGOON RD TWDS LAVENDER ST NEAR DESKER RD

I / We

CHEONG TAI ZEAN

(Hirer) NRIC No.:

S1687807C

and/or

(Relief) NRIC No.:

Taxi Number

SHD4513U

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

03-Dec-2017

Name of Hirer

CHEONG TAI ZEAN

Hirer NRIC

S1687807C

Signature :



Address

106B PUNGGOL FIELD #15-530
822106

Contact No.

97695530

MOTOR CLAIMS DISCHARGE VOUCHER

Policy No : DMPCSN1602491701 Claim No : SNMI7D06919/C02/1/LKKDS

Claimant : COMFORT TRANSPORTATION PTE LTD

Amount : S\$1,210.00
Singapore Dollars ONE THOUSAND TWO HUNDRED TEN Only

I/We agree to accept the above mentioned amount to be paid to me/us in full & final settlement of all claims, costs & disbursements for injuries / damages sustained by me/us through an accident involving

Claimant Vehicle No. : SHD4513U

Insured Vehicle No. : SKK4061J

Date of Loss : 02/12/2017

Place of Accident : SERANGOON ROAD TOWARDS LAVENDER ST NEAR DESKER ROAD

IN CONSIDERATION of the payment made to me/us of the aforementioned sum by CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD., I/We agree absolutely to discharge CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. and/or

Insured Name : ZHANG QI

Driver Name : ZHANG QI

from all claims, present or future in respect of all loss, injury or damage sustained by me/us arising out of the said accident.

I acknowledge that this payment is made without admission of liability on the part of CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

(1) Global Sum	S\$ 1,210.00
	=====
TOTAL	S\$ 1,210.00
	=====

CLAIMS DEPARTMENT
COMFORTDELGRO ENGINEERING PTE LTD

391 YONG DRIVE

SINGAPORE 610005

Claimant Name : _____ NRIC No : _____

Signature :  Date : 3/1/18

The contents of this document apply to vehicle damages only.
All personal injuries and damages arising therefrom are excluded
from the ambit and application of this document.

Please forward your cheque made payable to:
COMFORTDELGRO ENGINEERING PTE LTD

GST REG. NO. M2-8921817-3

TAX INVOICE

8010012

CHINA TAIPING INSURANCE CO(S) PTE L
SPRINGLEAF TOWER

3 ANSON ROAD #16-00
SINGAPORE 079909

CONTACT NO: 62222366

VEHICLE NO
SHD4513U

MAKE
HYUNDAI

MODEL
SONATA

DATE OF REG
11.10.2012

CHASSIS CODE
KMHE41VMCA830442

INV. NO/DATE
91345508 11.12.2017

JOB NO.
305094341

ODOMETER READING

JOB TYPE

Description : 3P 02.12.2017

Invoice for Lump Sum Repair

Total Lump Sum Repair Amt	650.00
Add GST @ 7.000 %	45.50
Total Invoice amount	695.50

Issued by : CHEWBEELENG 11.12.2017 09:31:39
Repair Type : CLSO/57/57
Payment Type/Term : /Credit 30 days

ComfortDelGro Engineering Pte Ltd
Member of COMFORTDELGRO

Head Office:
5 Braddell Road
Singapore 119701

Please note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.

Our Ref: CT17120054

Date: 11 December 2017



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON	02/12/2017 @ 17:05 hrs
ALONG	SERANGOON RD TWDS LAVENDER ST NEAR DESKER RD
INVOLVING	SKK 4061 J, SHD6799Z

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHD4513U** (the "Taxi"). The Taxi was hired to **CHEONG TAI ZEAN IC NO S1687807C** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$98.25** per day (inclusive of GST).

Please be advised that the Taxi was insured with **India International Insurance Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Executive, Fleet Safety

This is a computer generated letter. No signature is required.

SHD 145134

DATE	NAME OF DRIVER	MILEAGE READING						MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)		DATE
		5	6	0	1	5	P		FROM	TO	
27/11/17	Cyrena	5	6	0	1	5	P	235	0615	1800	
28/11/17	Cyrena	5	6	0	5	1	3	354	0115	2110	
29/11/17	Cyrena	5	6	0	7	6	7	252	0615	2010	
20/11/17	Cyrena	5	6	1	0	7	7	310	0615	2050	
01/12/17	Cyrena	5	6	1	3	9	9	322	0615	2120	
01/12/17	Cyrena	5	6	1	7	1	8	319	0615	1900	
02/12/17	Cyrena	5	6	1	7	1	8	319	1905	-	
02.12.17	ACCIDENT							14	1905	-	
06.12.17	REPAIR							001	1030	-	

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SKK4061J	02 Dec 2017 / 17:05:00	Successful	C01	CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

[Previous](#) [OK](#)

SHDA5734



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI17023034/K1pb3q2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Date : 12-01-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKK 4061J	Veh. Inspected	SHD 4513U	
Policy No.	DMPCSN1602491701	Coverage (\$)	0.00	
Claim No.	SNM17D06919/C02/1/LKKDS	Excess (\$)	0.00	
Assign From		Assign Date	04/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI SONATA	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	KMHET41VMCA830442	Colour	BLUE	
Odometer	561719	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	MAXXIS	7 mm	
L/H Front Tyre	215/60 R16	MAXXIS	7 mm	
R/H Rear Tyre	215/60 R16	MAXXIS	7 mm	
L/H Rear Tyre	215/60 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/12/2017	Inspection Date	04/12/2017	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4513U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOT LID SONATA PLATE	NECESSARY	43.60	43.60
1	BOOT LID HYUNDAI PLATE	NECESSARY	24.20	24.20
1	BOOT LID 'H' EMBLME	NECESSARY	26.10	26.10
1	BOOT LID CRDI PLATE	NECESSARY	22.70	22.70
1	REAR BUMPER	TO REPAIR SEE LABOUR	578.40	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	483.30	-
1	REAR BUMPER CLIP	NOT NECESSARY	22.00	-
1	REAR BUMPER SPONGE	SERVICEABLE	137.40	-
1	REAR BUMPER UNDER COVER	SERVICEABLE	185.80	-
2	REAR BUMPER PROTECTOR (LH/RH) @\$38.00	TO REPAIR SEE LABOUR	76.00	-
1	REAR PANEL	SERVICEABLE	391.80	-
1	REAR PANEL GARNISH	SERVICEABLE	95.80	-
1	REAR BOOTLID (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-417.42	-23.32
			1,669.68	93.28
<u>SPECIAL NETT ITEMS</u>				
1	BOOT LID COMFORT LOGO & TEL NO.STICKER (SN)	NECESSARY	30.00	30.00
1	REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	135.70	-
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
			215.70	80.00
<u>LABOUR</u>				
	PANEL BEATING INCLUSIVE OF THE REPAIR OF REAR BUMPER ,REAR BUMPER PROTECTOR (LH/RH) AND REAR BOOTLID.		560.00	300.00
1	SPRAY PAINTING CHARGE .		400.00	360.00
	WIRING CHARGE .	NOT NECESSARY	50.00	-
	TUFF KOTE .	NOT NECESSARY	50.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE/REFIX REVERSE SENSOR.	NOT NECESSARY	120.00	-
			1,180.00	660.00
GRAND TOTAL			3,065.38	833.28
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				650.00

Report Ref No. CC3/CT117023034/K1pb3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.