

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 4513U

DATE 4/12/2017 13:01

MAKE :

MODEL : HYUNDAI SONATA

LKK/Kalvin

L/Sun

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid Sonata Plate ✓			\$ 43.60	
	Boot Lid Hyundai Plate ✓			\$ 24.20	
	Boot Lid 'H' Emblem ✓			\$ 26.10	
	Boot Lid CRDI Plate ✓			\$ 22.70	
	Rear Bumper ✕ repair			\$ 578.40	
	Rear Bumper Reinforcement ?			\$ 483.30	
	Rear Bumper Clip ✕			\$ 22.00	
	Rear Bumper Sponge ?			\$ 137.40	
	Rear Bumper Under Cover ?			\$ 185.80	
	Rear Bumper Protector (LH/RH) ✕ repair		\$ 38.00	\$ 76.00	
	Rear Panel ✕			\$ 391.80	
	Rear Panel Garnish ✕			\$ 95.80	
	Rear Boot lid ✕ repair				
	SUB TOTAL			\$ 2,087.10	
	LESS 20%			\$ 417.42	
	DISCOUNTED TOTAL			\$ 1,669.68	
	Boot Lid Comfort Logo & Tel No. Sticker ✓			\$ 30.00	Nett
	Rear Bumper Reverse Sensor ✕			\$ 135.70	Nett
	Rear Bumper Rubber Mat ✓			\$ 50.00	Nett
				\$ 215.70	
	Labour Charge			300	
	Panel Beating- Repair bootlid			\$ 560.00	
	Spray Painting Charge			\$ 400.00	360
	Wiring Charge			\$ 50.00	✕
	Tuff Kote			\$ 50.00	✕
	Remove/Refix Reverse Sensor			\$ 120.00	✕
	TOTAL LABOUR			\$ 1,180.00	
	ESTIMATE TOTAL			\$ 3,065.38	
	Kalvin 10/11/17				
	U 4/12/17 1445h				
	3 Days				
	L/S				
	After Repair photo				
	LKK Kur : Do not notify the Repairer the following:				
	• To resurvey the car after spray painting				
	• To display damaged parts during resurvey				
	• Parts prices are subject to confirmation				
	• Third party survey is on a "Without Prejudice" basis				
	• No illegal modification(s) is allowed				
	• Supplementary cost(s) must be resurveyed and is subject to final approval from insurance company				
	Acknowledged by Repairer				
	Signature:				
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				