

ASS. RES. BY:

REF: CS/FCI17023038/M1rb01

Special Instruction:

Surveyor:
CWS

MA

ASSIGNMENT (Office)

From (Person):

Lurene Jaw

of

FCI

Date/Time: 10:26 am @ 5/12/17

Estimated Cost:

Bill to:

OD ☒ TP/WS+TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 3254Z

Insured:

SHC 0860Z

at Workshop m/s

Chunni Motor (AMK)

Tel:

65425119

of

AMK AutoPoint #01-05/06

Policy No:

Claim No:

D1701152MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 1/12/17

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

9:20 am @ 5/12/17

Person Contacted:

Lynn


Vehicle ☒ IN/OUT

Date/Time	Action/Instruction
	(✓) Estimate
	SHD 3254Z - CC3/AIG10008435/DN1jp2
	SHC 0860Z - X
	Submit L/S \$17,100.00, 12 days
	Red: \$1802314, 51%.

D.O.A: 30h4/2010

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s CHUNNI
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 30047 Yr Regn: JUL 2016
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: HYUN 140 C.C. 1600
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 85634 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KMHUB41UM6U 09187
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/60/R16
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or HANKOOK

Front	Rear
R/Bal. <u>7</u> mm	R/Bal. <u>7</u> mm
L/Bal. <u>7</u> mm	L/Bal. <u>7</u> mm
D.O.A. <u>1/12/2017</u>	D.O.I. <u>5/12/2017</u>

Survey held at _____
 Des. of Damages: FR Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 1 JUL 2017

Date/Time. File Pass to? ☐ : Preli. Report

1) typist ☒ : Final Report

Date/Time. File Return to?

2)

Days Of Repair: 12

Resurvey No. of Trip: 1

Survey Fee:

Transportation.

) S + RS. Si

) Photos

) Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format : TR

Lump Sum / L.B.I: (\$ 17,100.00)

29 X 15
170 + 375
50
50
86
731




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17023038/M1rb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 05-12-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 860Z	Veh. Inspected	SHD 3254Z
Policy No.		Coverage (\$)	0.00
Claim No.	D17011152MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	05/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	01/12/2017	Inspection Date	05/12/2017
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C

GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	04-12-2017	Our Ref No. D17011152MFSH
Accident Date	01-12-2017	Claim Type. Third Party
Insured Vehicle	SHC0860Z	Third Party Vehicle. SHD3254Z
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06	
Contact Person.	LYNN OR IRENE	
Contact No.	64836016/ 65425119	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231367)



PRI Documents



Close X

PRI Header Details

Claim No	D17011152MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & CHUNNI M
Workshop Name	CHUNNI MOTOR WORK PTE LTD (Contact Person : LYNN OR IRENE)	Survey Location & Contact Details	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06 Mobile: 65425119 , Phone: 64836016 , Fax: 0 EmailId: CHUNNIMOTOR@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0860Z	TP Vehicle No	SHD3254Z
PRI Recieved Date	04-12-2017 04:16:33 PM	Surveyor Appointed Date	05-12-2017 10:25:23 AM	Surveyor Accept Date	05-12-2017 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	05-12-2017	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

[Upload Multiple Documents](#)

File Name

Action

Surveyor Job Remarks

Remarks

MCD617158864 / ComfortDelGro Engineering Pte Ltd - Loyang
ENTRY DATE & TIME: 02/12/2017 00:40

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 02/12/2017 09:40
Date Of Accident 01/12/2017 17:15
Exact Location Of Accident ECP >CHANGI AIRPORT B4 TANJONG KATONG RD EXIT
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHD3254Z
Insured/Policyholder
Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
Co Reg No 199303821R
Email Address FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No
Alternative Phone No OFFICE-85508768
Vehicle Particulars
Manufacturer HYUNDAI
Model I40
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own Insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category TAXI
Insurance Company
Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
Fleet Policy YES
Policy Number MCOM0016
Cover Note Number
Driver
Name of Driver LEE CHEE KWONG
NRIC No S1191008D
Date Of Birth 08/12/1956
Occupation OUTDOOR
Date Of Driving Pass 20/12/1975
Driving Experience 41 YEARS AND 11 MONTHS
Gender MALE
Mobile Number
Fax Number
Contact Number
EMail Address NOEMAIL

Address 396 YISHUN AVENUE 6 #03-1142
 Postcode S760396
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLS SEE ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: -
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHC860Z
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage FRT
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJG4308G

Vehicle Make/Model/Colour**Details Of Properties****Name of Driver** PARRIS ANG HOCK HENG**NRIC/Passport Number** S1545133E**Contact Number** 97300809**Address****Postcode****Insurance Company Name****Nature Of Damage** REAR**No. Of Passenger (Including Driver)****Details of Witness****Name****Phone Number****Email Address****DETAILS OF OTHER VEHICLE PROPERTY 3****Vehicle Registration Number** SHC5126C**Vehicle Make/Model/Colour****Details Of Properties****Name of Driver** KEVIN KOH**NRIC/Passport Number** S 14148888**Contact Number** 94501551**Address****Postcode****Insurance Company Name****Nature Of Damage** WHOLE LEFT SIDE**No. Of Passenger (Including Driver)****Details of Witness****Name****Phone Number****Email Address****DETAILS OF INJURED PERSON 1****Name** LEE CHEE KWONG**Approximate Age** 61**Injuries Sustain** BACK & NECK**Injured person in which vehicle?** SHD3254Z**Were seat belts worn?** YES**Was Injured conveyed to hospital by ambulance?** NO**Address** 396 YISHUN AVENUE 6 #03-1142**Postcode** 760396

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 02.12.2017 @ 09:45 Hrs

Reporting Centre Personnel's Signature
Name: *Rubbini*
NRIC/FIN No.:

SKETCH PLAN



A - SHD 3254Z.
 B - SHC 860Z. (CTPL)
 C - SJG 4308G.
 D - SHC 5126C. (TR)

Along ECP Towards Changi Airport Before Tanjong Katong Road Exit.

Describe Circumstances of the Accident

On 01/12/2017 @ about 17:15hrs, my taxi (A) (SHD 3254Z) was travelling.
along ECP towards Changi Airport before Tanjong Katong Road Exit with one
male passengers on board.
I saw in front of my vehicles slowing down and stopped, So I follow too.
Out of sudden, there was a loud impact coming from the rear portion and
caused my taxi (A), to lose control and surge forward, and colliding onto veh (C)
(SJG 4308G) rear portion. Following the accident, I came down to check the
vehicle and came to know that veh (D) (SHC 5126C) hit my taxi rear right
portion. I assessed the damages to my taxi (A) and come to know that there
were 4 vehicles involved in the chain accident.
No one was conveyed by the ambulance.
The parties involved in the accident are:
A - SHD 3254Z.
B - SHC 860Z (CTPL). Male driver.
C - SJG 4308G. Mr. Ang Hock Heng Parris. NRIC : S 1545133E. Hp : 9730 0809.
D - SHD 5126C (TR) : Mr. Kevin Koh. NRIC : S 1414868Z. Hp : 9450 1551.
No injury in this accident. I suffered pain behind the back and neck.

Declaration

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
 CO. REG. NO. 199303821R

policyholder's Signature
 Date & Time

Driver's Signature (If driver is not the policyholder)
 Date & Time 02.12.2017 @ 09:45 Hrs

Reporting Centre Personnel's Signature
 Name : Rubbini
 NRIC/FIN No : -

1100

FAX : 6542 6039 FCI

dis
X.NH
~~2~~ monthly
trade
turn
BT
Jue
Zarc
Zur
MC
JVC
crack men
MC
the
turn
on ~~900~~
SRU
BT ✓
SRU X
the

Nett
Nett

200 ~~180~~
180.
30
—
100%
✓

SHD 3254Z

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid			\$ 1,681.40	bot
	Boot Lid Rubber			\$ 115.80	dis
	Boot Lid Lock Upper			\$ 137.90	bot
	Boot Lid Lock Lower			\$ X 31.70	R
	Boot Lid 'H' Emblem			\$ - 27.20	MC
	Boot Lid CRDI Plate			\$ - 41.00	MC
	Boot Lid Lamp (LH/RH)		\$ 556.80	\$ 1,113.60	one
	Boot Lid Trimboard			\$ X 172.70	one
	Boot Lid Trimboard Clips (10pcs)			\$ - 11.00	MC
	Bootlid Moulding			\$ X 85.00	one
	Bootlid i40 Emblem			\$ - 41.00	MC
	Bootlid Lower Garnish			\$ X 398.00	one
	Rear Bumper			\$ - 603.60	def
	Rear Bumper Reinforcement			\$ 7 504.35	broken
	Rear Bumper Reinforcement Bracket (LH/RH)		\$ 180.00	\$ 7 360.00	br
	Rear Bumper Clip 10 pcs			\$ - 22.00	MC
	Rear Bumper Bracket		\$ 49.00	\$ - 98.00	dis
	Rear Bumper Sponge			\$ 7 143.40	atom
	Rear Bumper Under Cover			\$ - 225.00	def
	Rear Bumper Reflector Lamp (LH)			\$ X 32.00	one
	Tail Lamp (LH/RH)		\$ 565.60	\$ 1,131.20	one
	Rear Panel			\$ 7 592.30	broken
	Rear Panel Garnish			\$ X 57.70	one
	Rear Panel Lower Panel			\$ 7 495.50	one
	Exhaust Pipe Insulator		\$? (58.55)	\$ X 117.10	one
	Exhaust Silencer		\$ (954.00)	\$ 1,908.00	one
	Exhaust Pipe Hanger		\$ 58.55	\$ X 117.10	one
	Exhaust Pipe Centre			\$ 7 1,150.30	MC
	Rear Fender With Housing (RH) fender only.			\$ 4,736.80	bot.
	Rear Fender Inner Lining (RH)			\$ - 164.40	dis
	Rear Windscreen Moulding			\$ - 60.00	MC
	Rear Door (RH)			\$ 1,351.10	R.
	Rocker Panel Outer Garnish (RH)			\$ - 483.60	def
	Rear Tyre Rim (RH)			\$ - 351.90	bot.
	Rear Wheel Hup-Cap (RH)			\$ - 150.70	dis
	Rear Wheelbearing ING & Hub			\$ 7 401.40	one
	Rear Trailing Arm (RH)			\$ 7 120.00	distributed
	Rear Assist (RH)			\$ 7 120.00	distributed
	Rear Shock Absorber (RH)			\$ 7 342.20	distributed
	Rear Shock Absorber Mounting (RH)			\$ 7 57.70	one
	Rear Crossmember			\$ 7 1,190.00	MC
	Stabilizer Bar			\$ X 204.60	br
	Stabilizer Link			\$ 7 68.15	br
	Rear Upper Arm (RH)			\$ 7 335.75	distributed
	Rear Lower Arm (RH)			\$ 7 204.35	distributed
	Rear Knuckle Arm (RH)			\$ 7 574.80	MC
	SUB TOTAL			\$ 22,331.30	
	LESS 20%			\$ 4,466.26	
	DISCOUNTED TOTAL			\$ 17,865.04	

SHD 3254Z

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00	Nett Nett
	Boot Lid Advertisement Logo			\$ 100.00	Nett Nett
	Rear No. Plate			\$ 25.00	Nett Nett
	Rear Bumper Reverse Sensor			\$ 135.70	Nett Nett
	Rear Bumper Advertisement Logo			\$ 50.00	Nett Nett
	Rear Bumper Rubber Mat			\$ 50.00	Nett Nett
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00	Nett Nett
	Rear Windscreen Scalant			\$ 46.00	Nett Nett
	Rear Door Advertisement Logo (RH)			\$ 100.00	Nett Nett
	Rear Door Comfortdelgro & Apps Sticker (RH)			\$ 80.00	Nett Nett
	Rear Tyre (RH)			\$ 216.00	Nett Nett
				172.80	
				\$ 1,032.70	
	Labour Charge				
	Panel Beating			\$ 2,000.00	1400
	Spray Painting Charge			\$ 1,400.00	1000
	Wiring Charge			\$ 50.00	30
	Tuff Kote			\$ 100.00	40
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	60
	Remove/Refix Rear Windscreen Glass			\$ 120.00	100
	Remove/Refix Reverse Sensor			\$ 120.00	60
	Remove/Refix Undercarriage (RR)			\$ 400.00	300
	Remove/Refix Exhaust Pipe			\$ 360.00	100
	Transfer of Door			\$ 120.00	X
	Rear Wheel Alignment			\$ 120.00	20
	TOTAL LABOUR			\$ 4,940.00	
	ESTIMATE TOTAL			\$ 35,123.14	
<p>Not Authorised HS Repur After Paint Done LCC Auto (MA) 3/12/2017 12 working days</p>					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17023038/M1rbe2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 01-03-2018	
			Code : FCI2	
1. Policy Particulars - THIRD PARTY CLAIM				
Insured Veh.	SHC 860Z	Veh. Inspected	SHD 3254Z	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17011152MFSH	Excess (\$)	0.00	
Assign From	LURENE JAW	Assign Date	05/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMGU091895	Colour	BLUE	
Odometer	85634	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	HANKOOK	7 mm	
L/H Front Tyre	205/60 R16	HANKOOK	7 mm	
R/H Rear Tyre	205/60 R16	HANKOOK	7 mm	
L/H Rear Tyre	205/60 R16	HANKOOK	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/12/2017	Inspection Date	05/12/2017	
Survey held at	ANG MO KIO AUTOPOINT #01-05/06			
Repairer	CHUNNI MOTOR WORK PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3254Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	RADIATOR GRILLE	DISTORTED	1,480.00	1,480.00
1	RADIATOR GRILLE H EMBLEM	NOT NECESSARY	290.80	-
1	RADIATOR GRILLE CHROME MOULDING	NOT NECESSARY	395.50	-
1	FRONT BUMPER COVER	MTG CRACKED	1,052.20	1,052.20
1	FRONT BUMPER SPONGE	TORN	142.20	142.20
1	FRONT BUMPER REINFORCEMENT	BENT	526.10	526.10
2	FRONT BUMPER BRACKET (TOP) (LH/RH) @\$22.40	SERVICEABLE	44.80	-
2	FRONT BUMPER BRACKET (LH/RH) @\$24.60	SERVICEABLE	49.20	-
2	FRONT BUMPER RETAINER MOUNTING @\$9.20	SERVICEABLE	18.40	-
1	HEADLAMP SUPPORT TOP COVER	SERVICEABLE	398.00	-
1	HEADLAMP SUPPORT PANEL ASSY	SERVICEABLE	1,067.50	-
2	HEADLAMP (LH/RH) @\$1388.00	MTG CRACKED	2,776.00	2,776.00
1	RADIATOR	SERVICEABLE	850.20	-
1	RADIATOR FAN BLADE, COWLING, MOTOR ASSY	SERVICEABLE	792.95	-
2	RADIATOR BRACKET (LH/RH) @\$6.50	SERVICEABLE	13.00	-
2	RADIATOR GUARD @\$35.00	TORN	70.00	70.00
2	HORN UNIT (LH/RH) @\$86.75	SERVICEABLE	173.50	-
1	AIRCON CONDENSER	BENT	1,137.35	1,137.35
1	INTER COOLER	SERVICEABLE	921.90	-
2	INTER COOLER MOUNTING	SERVICEABLE	25.90	-
1	BOOT LID	BENT	1,681.40	1,681.40
1	BOOT LID RUBBER	DISTORTED	115.80	115.80
1	BOOT LID LOCK UPPER	BENT	137.90	137.90
1	BOOT LID LOCK LOWER	TO REPAIR SEE LABOUR	31.70	-
1	BOOT LID 'H' EMBLEM	NECESSARY	27.20	27.20
1	BOOT LID CRDI PLATE	NECESSARY	41.00	41.00
2	BOOT LID LAMP (LH/RH) @\$556.80	SERVICEABLE	1,113.60	-
1	BOOT LID TRIMBOARD	SERVICEABLE	172.70	-
10	BOOT LID TRIMBOARD CLIPS	NECESSARY	11.00	11.00
1	BOOTLID MOULDING	SERVICEABLE	85.00	-

Report Ref No. CS/FCI17023038/M1rbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOTKUD I40 EMBLEM	NECESSARY	41.00	41.00
1	BOOTLID LOWER GARNISH	SERVICEABLE	398.00	-
1	REAR BUMPER	DEFORMED	603.60	603.60
1	REAR BUMPER REINFORCEMENT	BROKEN	504.35	504.35
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$180.00	BENT	360.00	360.00
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
2	REAR BUMPER BRACKET @\$49.00	DISTORTED	98.00	98.00
1	REAR BUMPER SPONGE	TORN	143.40	143.40
1	REAR BUMPER UNDER COVER	DEFORMED	225.00	225.00
1	REAR BUMPER REFLECTOR LAMP (LH)	SERVICEABLE	32.00	-
2	TAIL LAMP (LH/RH) @\$565.60	CRACKED	1,131.20	1,131.20
1	REAR PANEL	DENTED	592.30	592.30
1	REAR PANEL GARNISH	SERVICEABLE	57.70	-
1	REAR PANEL LOWER PANEL	SERVICEABLE	495.50	-
2	EXHAUST PIPE INSULATOR @\$58.55	SERVICEABLE	117.10	-
2	EXHAUST SILENCER @\$954.00	NOT NECESSARY	1,908.00	-
2	EXHAUST PIPE HANGER @\$58.55	SERVICEABLE	117.10	-
1	EXHAUST PIPE CENTRE	NOT NECESSARY	1,150.30	-
1	REAR FENDER WITH HOUSING (RH)	BENT	4,736.80	4,736.80
1	REAR FENDER INNER LINING (RH)	DISTORTED	164.40	164.40
1	REAR WINDSCREEN MOULDING	NECESSARY	60.00	60.00
1	REAR DOOR (RH)	TO REPAIR SEE LABOUR	1,351.10	-
1	ROCKER PANEL OUTER GARNISH (RH)	DEFORMED	483.60	483.60
1	REAR TYRE RIM (RH)	BENT	351.90	351.90
1	REAR WHEEL HUP-CAP (RH)	DISTORTED	150.70	150.70
1	REAR WHEELBEARING ING & HUB	DAMAGED	401.40	401.40
1	REAR TRAILING ARM (RH)	DISTORTED	120.00	120.00
1	REAR ASSIST (RH)	DISTORTED	120.00	120.00
1	REAR SHOCK ABSORBER (RH)	DISTORTED	342.20	342.20
1	REAR SHOCK ABSORBER MOUNTING (RH)	SERVICEABLE	57.70	-
1	REAR CROSSMEMBER	NOT NECESSARY	1,190.00	-
1	STABILIZER BAR	BENT	204.60	204.60

Report Ref No. CS/FCI17023038/M1rbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	STABILIZER LINK	BENT	68.15	68.15
1	REAR UPPER ARM (RH)	DISTORTED	335.75	335.75
1	REAR LOWER ARM (RH)	DISTORTED	204.35	204.35
1	REAR KNUCKLE ARM (RH)	NOT NECESSARY	574.80	-
	LESS 20% DISCOUNT		-6,911.36	-4,132.57
			27,645.44	16,530.28
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN) }	DISTORTED	25.00	40.00
1	FRONT NO PLATE TRIM COVER (SN) }		30.00	-
1	BOOT LID COMFORT LOGO & TEL NO. STICKER (SN)	NECESSARY	30.00	30.00
1	BOOT LID ADVERTISEMENT LOGO (SN)	NECESSARY	100.00	100.00
1	REAR NO. PLATE (SN)	DISTORTED	25.00	25.00
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	135.70	135.70
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR DOOR ADVERTISEMENT LOGO (RH) (SN)	NECESSARY	100.00	100.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (RH) (SN)	NECESSARY	80.00	80.00
1	REAR TYRE (RH) (SN) (80%)	CUT	216.00	172.80
			1,087.70	1,029.50
	LABOUR			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF BOOT LID LOCK LOWER AND REAR DOOR (RH).		3,000.00	1,600.00
	SPRAY PAINTING CHARGE.		1,600.00	1,180.00
	WIRING CHARGE.		100.00	60.00
	TOWING CHARGE.		50.00	50.00
	REMOVE/REFIX AIRCON & REFILL GAS.		150.00	100.00
	TUFF KOTE.		100.00	40.00
	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.		150.00	60.00
	REMOVE / REFIX REAR WINDSCREEN GLASS.		120.00	100.00

Report Ref No. CS/FCI17023038/M1rbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate @ Workshop (\$)	Our Advice (\$)
	REMOVE / REFIX REVERSE SENSOR.	NOT NECESSARY	120.00	60.00
	REMOVE / REFIX UNDERCARRIAGE (RR)		400.00	350.00
	REMOVE / REFIX EXHAUST PIPE.		360.00	100.00
	TRANSFER OF DOOR.		120.00	-
	REAR WHEEL ALIGNMENT.		120.00	80.00
			6,390.00	3,780.00
GRAND TOTAL			35,123.14	21,339.78

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			17,100.00
---	--	--	-----------

Report Ref No. CS/FCI17023038/M1rbe2

MA CHIN FOOK

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.