

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

4-Dec-17

GBE

65446671

ESTIMATE REPAIR BILL FOR HYUNDAI I30A REGN NO: SHD 1662 S

S/NETT

1 pc	Rear n/s fender sticker	\$	60.00	✓
	Sundry	\$	50.00	20
	To check wheel alignment	\$	80.00	X
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear n/s fender, rear bumper	\$	700.00	200
	To putty and spray painting on rear n/s fender, rear bumper	\$	400.00	360
	To apply rustproofing on the repaired and replaced panels.	\$	120.00	X
		\$	1,410.00	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Calvin (LKK)
4/12/17 1320hrs
2 Days.
PP
After Repair photo.

LKK Auto Components will notify the Repairer of the following:

- To reserve, before any spray painting
- To display damaged parts during a survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal or unsafe repairs allowed
- Supplementary items must be reserved and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: