

11/09/2001

ASS. REC. BY:

REF: CS3/17014486 / MIGB-1

Special Instruction:

SURVIVOR:

MA

## ASSIGNMENT (Office)

From (Person):

Gabriel Wae

of

TH

Date/Time:

05.12.2017

Estimated Cost:

Bill to:

OD / PP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD 8763 R

Insured:

SH 9512M

at Workshop m/s

L SOON AUTO

Tel:

64521513

of

Bik 10 AMK Ind Park 2A #03-18

Policy No:

Claim No:

Sum Insured:

Excess:

D.O.A.

20072017

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time:

26072017 6:11pm

Person Contacted:

Mrs Lee

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLD 8763 R - X
	SH 9512M - CS3 / AXA 13014331 / Y83C3
	45 \$ 2600 , 6 day.
	C Red: 2052.08 , 89 %.

D.A: 050313

RECEIVED 05 DEC 2017



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III17014486/M1gb-1

64 CECIL STREET  
#05-02 IOB BUILDING SINGAPORE 049711

Date : 05-12-2017



Code : III2

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SH 9512M	Veh. Inspected	SLD 8763R
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	GABRIEL WEE	Assign Date	05/12/2017

**2. Vehicle Particulars & Condition**

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

**4. Description of Damages**

--

**5. General Information**

Accident Date	20/07/2017	Inspection Date	05/12/2017
Survey held at	L SOON AUTO SERVICES 10 ANG MO KIO INDUSTRIAL PARK 2A #03-18 AMK AUTO POINT SINGAPORE 568407		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**Catherine Chong (LKK Auto)**

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Wednesday, 26 July, 2017 4:18 PM  
**To:** Prestina Moh; assignments@lkkauto.com  
**Cc:** Sherini Pillai  
**Subject:** RE: NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY  
WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-  
ACTION PROTOCOL FOR NIMA CASES  
20170726160159.pdf; shd7161g\_20170726160155.pdf  
**Attachments:**

Dear Sir / Mdm

**This Pre-Repair Survey is on Without Prejudice Basis.**

THIRD PARTY VEHICLE NO. : SLD8763R  
III INSURED VEHICLE NO. : SH9512M  
DATE OF LOSS : 20/07/17

We acknowledge receipt of your email.

**In compliance to Pre-Action Protocol for NIMA cases, we note that**

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by **Sherini**.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

**\*\*We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

**\*\*Surveyor kindly upload this assignment to Merimen.**

Thank You.

*Best Regards,*

**Gabriel Wee**

Motor Claims Dept.

**India International Insurance Pte Ltd**

64 Cecil Street #04/#05 10B Building

Singapore 049711

Tel : 63476100, Ext-248, Fax : 62244174

e-mail: [Gabriel@iii.com.sg](mailto:Gabriel@iii.com.sg)

**From:** Prestina Moh [mailto:[prestinaMoh@visionlawllc.com](mailto:prestinaMoh@visionlawllc.com)]

**Sent:** Wednesday, 26 July, 2017 4:07 PM

**To:** Motor Claim - III <motorclaim@iii.com.sg>

**Subject:** RE: NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS  
PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

Dear Sir,

Please see attached our reply letter of even date.

Regards,

*Prestina Moh (Secretary)*

Vision Law LLC  
133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413  
Tel: 6534-2811 (Ext. 146)  
Fax: 6535-6802

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

Sent: Wednesday, 26 July, 2017 3:34 PM

To: Prestina Moh

Subject: RE: NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS  
PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

*Best Regards,*

**Gabriel Wee**

Motor Claims Dept.  
India International Insurance Pte Ltd  
64 Cecil Street #04/#05 IOB Building  
Singapore 049711  
Tel : 63476100, Ext-248, Fax : 62244174  
e-mail: [Gabriel@iii.com.sg](mailto:Gabriel@iii.com.sg)

From: Prestina Moh [<mailto:prestinaMoh@visionlawllc.com>]

Sent: Wednesday, 26 July, 2017 3:20 PM

To: Motor Claim - III <[motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)>

Subject: NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS  
PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

**IMMEDIATE ATTENTION**

WITHOUT PREJUDICE  
OUR REF: SLD 8763 R

Dear Sir,

Please find attached our letter of even date which is self-explanatory.

Regards,

*Prestina Moh (Secretary)*

Vision Law LLC  
133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413  
Tel: 6534-2811 (Ext. 146)  
Fax: 6535-6802

---

VISION LAW LLC  
Advocates & Solicitors  
(Incorporated with limited liability)  
Unique Entity No. 200721148H  
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413  
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

---

**DISCLAIMER:**

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

---

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this

# VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths  
Agents for Trade Marks

(Incorporated with limited liability)

Unique Entity Number: 200721148H

## ✓ HEAD OFFICE

133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413

Branch: 490 Toa Payoh Lorong 6  
#03-11 HDB Hub  
Singapore 310490

## ✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)  
FAX : (65) 65356802 (General)  
✓ : (65) 65355905 (Litigation)  
E-mail : yvonne@visionlawllc.com

## BRANCH

TEL : (65) 63580703  
FAX : (65) 63580448 (Conveyancing)

ERIC NG CHING BOON  
RAYNEY WONG KENG LEONG  
AUDREY WONG SU-HSIEN  
PAUL YAP TAI SAN  
ANJALI D'D MURHANDY  
SEGA PARAM  
TIWARY ANURADHA  
SHARON PARWANI  
ONG BOCK KEE  
DIANE ANG KIM NOI  
RAVENDRA KRISHNASAMY  
ROCHE ENG KENG LOON  
TAY HAO RAN  
JANICE HAN JIA LIN

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - PLEASE REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: SLD 8763 R (PM)  
Your Ref: SH 9512 M

26 July 2017

INDIA INTERNATIONAL INSURANCE PTE LTD  
64 Cecil Street  
#04/#05 IOB Building  
Singapore 049711  
[Attention : Motor Claim Department]

BY FAX 6225 7743 & EMAIL

Dear Sirs,

ACCIDENT INVOLVING MOTOR VEHICLE SLD 8763 R AND SH 9512 M ON 20 JULY 2017 ALONG  
BISHAN ROAD (NEXT TO BISHAN MRT) AT ABOUT 0800 HOURS  
(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS  
PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

We refer to your email of even date informing that you wish to conduct a pre-repair survey and your List  
of Surveyors.

Under the circumstances, no Single Joint Expert has been agreed for this matter.

Please be informed that the said vehicle can be inspected at:

L SOON AUTO SERVICES  
No. 10 Ang Mo Kio Industrial Park 2A  
#03-18 AMK Autopoint  
Singapore 568047  
Mrs Lee @ 64821513 (To call before going)

Contact:

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening  
Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further  
reference to you.

Yours faithfully

ANJALI M  
(HEAD OFFICE)

cc: SLD 8763 R - By fax: 65562590 only

## FOR SURVEYOR

Please initial here after completion of pre-repair  
inspection. Thank you.

Appointed surveyor  
(Name & Signature)

Date & Time of Inspection :

CONFIDENTIALITY  
THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE  
OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or use of this  
communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its  
return



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 20/07/2017 15:33  
Date Of Accident 20/07/2017 08:00  
Exact Location Of Accident BISHAN RD(NEXT TO BISHAN MRT)  
Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SLD8763R  
Insured/Policyholder  
Name Of Registered Owner BAY CHEE WEE 95377390  
NRIC No S7518502B  
Email Address TINA\_0659@HOTMAIL.COM  
Mobile Phone No (LOCAL) +65-98521235  
Alternative Phone No OFFICE-98521235  
Vehicle Particulars  
Manufacturer SUBARU  
Model IMPREZA 4DR 2.0R-S AWD 4AT ABS  
Exact Purpose for which vehicle was being used at time of accident  
Are you claiming under your own insurance policy for repair to your vehicle? NO  
If No, Please state action to be taken THIRD PARTY  
Vehicle Category PRIVATE CAR  
Insurance Company  
Name of Insurance Company AXA INSURANCE PTE LTD  
Type Of Coverage COMPREHENSIVE  
Fleet Policy NO  
Policy Number GA206990  
Cover Note Number 26/05/2017-04/06/2018  
Driver  
Name of Driver LU XIAO LAN  
NRIC No S7762264J  
Date Of Birth 10/01/1977  
Occupation INDOOR  
Date Of Driving Pass 07/01/2014  
Driving Experience 3 YEARS AND 6 MONTHS  
Gender FEMALE  
Mobile Number  
Fax Number  
Contact Number  
EMail Address NOEMAIL



**SKETCH PLAN**

**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)  
I understand, acknowledge, agree and consent that:  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



A: SLB 8763 R  
B: SH 4512 M

CAT

Hua-MK MA

**L Soon Auto Services**  
**No.10 Ang Mo Kio Industrial Park 2A**  
**#03-18 Ang Mo Kio Auto Point**  
**Singapore 568047**  
**Tel: 6482 1513 Fax: 6556 2590**

**SLD8763R Subaru Impreza**

No	Qty	Parts Description	Estimated Parts Price
1	1	Front left fender	\$ 1,295.10 X R
2	1	Front left fender inner cowling	\$ 108.20 X R
3	1	Front left fender lamp	\$ 88.70 X R
4	1	Front power steering rack and pinion assy	\$ 3,605.20 X R
5	1	Front left door	\$ 922.40 X R
6	1	Front left door lock	\$ 248.60 X R
7	1	Front left door lock catch	\$ 62.40 X R
8	1	Front left door weatherstrip	\$ 182.20 X R
9	1	Front left door regulator with motor	\$ 350.10 X R
10	1	Front left door outer handle	\$ 195.40 X R
11	2	Front left door hinges	\$ 106.20 X R
12	1	Front left door checker linkage	\$ 138.50 X R
13	1	Front left suspension assy	\$ 1,280.70 X R
14	1	Front left brake disc housing	\$ 88.50 X R
15	1	Front stabilizer bar	\$ 320.10 X R
16	1	Front left lower arm	\$ 389.50 X R
17	1	Front left knuckle arm	\$ 436.20 X R
18	1	Front left wheel hub bearing	\$ 354.30 X R
19	1	Front left brake disc	\$ 251.50 X R
20	1	Front left stabilizer link	\$ 191.70 X R
			\$ 10,615.50
Less 20%			\$ 2,123.10
			\$ 8,492.40

Special Nett Items

1	6	Front left fender inner cowling clips	NW \$ 30.00 X
2	1	Left side skirting	R \$ 1,200.00 X R
3	1	Left side skirting sealant	W \$ 60.00
4	12	Left side skirting clips	W \$ 50.00
5	1	Front left sport rim	W \$ 750.00 X R
6	1	Front left tyre	W \$ 300.00 X
			\$ 2,390.00

**Total parts****\$ 10,882.40**

2600k  
 6w days  
 Confirmed

**L Soon Auto Services**  
**No.10 Ang Mo Kio Industrial Park 2A**  
**#03-18 Ang Mo Kio Auto Point**  
**Singapore 568047**  
**Tel: 6482 1513 Fax: 6556 2590**

**SLD8763R Subaru Impreza****No Qty Parts Description**

1	1	Rear bumper assy
2	1	Rear left door
3	2	Rear left door hinges
4	1	Rear left door checker linkage
5	1	Rear left door outer handle
6	1	Rear left door weatherstrip
7	1	Rear left door regulator with motor
8	1	Rear left fender
9	1	Rear left suspension assy
10	1	Rear left lower arm carrier
11	1	Rear left wheel hub bearing
12	1	Rear left trailing arm
13	1	Rear left idle arm
14	1	Rear left idle link
15	1	Rear stabilizer bar

Less 20%

**Estimated  
Parts Price**

\$	1,252.30	X	mc
\$	922.60	X	A
\$	106.20	X	
\$	138.50	X	
\$	195.40	X	
\$	182.20	X	
\$	350.10	X	
\$	1,472.30	X	
\$	889.50	X	mc
\$	442.30	X	
\$	251.80	X	
\$	284.90	X	
\$	242.30	X	
\$	262.50	X	
\$	280.10	X	
\$	7,273.00		
\$	1,454.60		
\$	5,818.40		

Special Nett Items

1	1	Rear left sport rim
2	1	Rear left tyre
3	10	Rear bumper clips
4	1	Rear windscreen glass sealant

\$	750.00	X	mc
\$	300.00	X	mc
\$	40.00	X	mc
\$	80.00	X	N/N
\$	1,170.00		

**Total parts****\$ 6,988.40**

**L Soon Auto Services**  
**No.10 Ang Mo Kio Industrial Park 2A**  
**#03-18 Ang Mo Kio Auto Point**  
**Singapore 568047**  
**Tel: 6482 1513 Fax: 6556 2590**

**SLD8763R Subaru Impreza**

No	Description	Labour Charges
① 1	Labour for panel beating, cut, weld, straighten front left affected area and replace front left damaged parts.	\$ 800.00 600
② 2	To putty and spray painting front left portion.	\$ 800.00 800
3	To check wiring and focus front headlamp.	\$ 50.00 X
④ 4	To remove and install front left door lock mechanism.	\$ 80.00 60
5	To check door central locking for function.	\$ 80.00 X
⑤ 6	To transfer front left door glass to new door.	\$ 80.00
7	To apply anti rust proofing to front left affected area.	\$ 80.00 40
8	To balance front left wheel.	\$ 20 50.00 ✓
9	To conduct four wheel alignment.	\$ 120.00 60
10	To remove and install front power steering rack and pinion assy.	\$ 160.00 X
11	To remove and install front left undercarriage parts.	\$ 300.00 X
① 12	Labour for panel beating, cut, weld, straighten rear left affected area and replace rear left damaged parts.	\$ 800.00 X
② 13	To putty and spray painting rear and rear left affected portion.	\$ 800.00 X
14	To remove and install rear left door lock mechanism.	\$ 80.00 X
15	To apply anti rust proofing to rear left affected area.	\$ 80.00 20
16	To transfer rear left door glass to new door.	\$ 80.00 ✓
17	To remove and install rear left undercarriage parts.	\$ 300.00 X
18	To balance rear left wheel.	\$ 50.00 20
19	To remove and install rear fuel tank to facilitate the repair.	\$ 180.00 X
20	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00 X
21	Towing service.	\$ 140.00 X

**Total labour : \$ 5,250.00**

**Total parts : \$ 17,870.80**

**Total labour : \$ 5,250.00**

**Total repair cost : \$ 23,120.80**

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Jul 2017 <a href="#">Edit Reg</a>		05 Dec 2017 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$2,600.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,600.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

<b>Insured:</b>	-, Co. Reg. No.: -		
<b>Main Claimant:</b>	BAY CHEE WEE, ID: S7518502B		
<b>Vehicle Reg. No.:</b>	SLD8763R	<b>Date of Loss:</b>	20/07/2017 08:00 - :59
<b>Claim Type:</b>	TP / MCT17070722	<b>Policy/Cover Note No.:</b>	MCOM0015
<b>Vehicle Reg. No. (Insured):</b>	SH9512M	<b>Policy No. (Claimant):</b>	
	<b>Excess:</b>		
<b>Repairer:</b>	L Soon Auto Services (HQ) 10 Ang Mo Kio Industrial Park 2A, #03-18 AMK Auto Point, 568407 Ang Mo Kio - Tel: 6482 1513 / 9832 8361		
<b>Handling Insurer:</b>	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]		
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 07/12/2017]		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.







































**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SLD8763R (MCT17070722)**  
[SH9512M]

TP  
BAY CHEE WEE  
Jul 20 2017 8:00AM  
[-]  
L Soon Auto Services

Upload Documents			Upload Photos			Compose New Letter			View Use Viewer		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
2	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
3	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
4	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
5	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
6	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
7	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
8	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
9	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
10	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
11	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
12	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
13	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
14	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
15	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
16	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
17	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
18	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
19	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
20	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
21	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
22	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
23	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
24	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
25	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
26	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
27	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
28	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
29	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
30	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
31	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
32	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
33	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
34	28/07/17 14:34	General View						 Load JPG	<input checked="" type="checkbox"/>		
Documentation									1 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	16/09/17 13:10	Email from Insurance						 Load PDF			
2	16/09/17 13:10	LAWYER LETTER						 Load PDF			
3	07/12/17 16:08	PRS INVOICE						 Load PDF			
No	Finalized On	India International Insurance Pte Ltd (HQ)						Thumbnail	Print		
1	31/07/17 08:32	Singapore Accident Statement						 Load PDF			

## Documents Checklist

**DOCUMENTS CHECKLIST**[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III17014486/M1GBS2-1

Date: 07/12/2017

## REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SLD8763R	Insured Vehicle No :	SH9512M
Date of Loss:	20/07/2017	Nature of Claim:	TP
		Claim No:	MCT17070722

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLD8763R	Engine No:	EJ20D558395
Make & Model:	SUBARU IMPREZA, 2.0 4DR (A)	Chassis No:	JF1GE7KS59G002089
Reg. Date:	05/12/2009 (Man. Year: 2008)	Odometer:	99614 km
Colour:	Blue		
Engine Capacity:	1994 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	Dunlop 8 mm	Rear Right Side:	Dunlop 8 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	17,870.80	1,627.12	16,243.68	90.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,250.00	1,620.00	3,630.00	69.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,120.80	3,247.12	19,873.68	85.96
Approved Total (Overridden) (S\$)		2,600.00		
(S\$)	23,120.80	2,600.00	20,520.80	88.75
+ GST 7.00/7.00% (S\$)	1,618.46	182.00	1,436.46	88.75
Nett Amount (S\$)	24,739.26	2,782.00	21,957.26	88.75

## INSPECTION

Date of Assignment: 05/12/2017

Date Inspected: 27/07/2017 Inspected At:

L Soon Auto Services (HQ)  
10 Ang Mo Kio Industrial Park 2A, #03-18  
AMK Auto Point  
Singapore 568407

Estimated Period of Repair: 6.0 days

Adjuster: MA CHIN FOOK

Manager: LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 07 Dec 2017)
<b>Parts:</b> 143	SUBARU IMPREZA 2.0 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLD8763R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT LEFT FENDER	Repair	1,295.10 FL	*- FL
2	1	*FRONT LEFT FENDER INNER COWLING	Serviceable	108.20 FL	*- FL
3	1	*FRONT LEFT FENDER LAMP	Serviceable	88.70 FL	*- FL
4	1	*FRONT POWER STEERING RACK AND PINION ASSY	Serviceable	3,605.20 FL	*- FL
5	1	*FRONT LEFT DOOR	Dented	922.40 FL	*922.40 FL
6	1	*FRONT LEFT DOOR LOCK	Serviceable	248.60 FL	*- FL
7	1	*FRONT LEFT DOOR LOCK CATCH	Serviceable	62.40 FL	*- FL
8	1	*FRONT LEFT DOOR WEATHERSTRIP	Necessary	182.20 FL	*182.20 FL
9	1	*FRONT LEFT DOOR REGULATOR WITH MOTOR	Serviceable	350.10 FL	*- FL
10	1	*FRONT LEFT DOOR OUTER HANDLE	Serviceable	195.40 FL	*- FL
11	2	*FRONT LEFT DOOR HINGES	Serviceable	106.20 FL	*- FL
12	1	*FRONT LEFT DOOR CHECKER LINKAGE	Serviceable	138.50 FL	*- FL
13	1	*FRONT LEFT SUSPENSION ASSY	Serviceable	1,280.70 FL	*- FL
14	1	*FRONT LEFT BRAKE DISC HOUSING	Serviceable	88.50 FL	*- FL
15	1	*FRONT STABILIZER BAR	Serviceable	320.10 FL	*- FL
16	1	*FRONT LEFT LOWER ARM	Serviceable	389.50 FL	*- FL
17	1	*FRONT LEFT KNUCKLE ARM	Serviceable	436.20 FL	*- FL
18	1	*FRONT LEFT WHEEL HUB BEARING	Bent	354.30 FL	*354.30 FL
19	1	*FRONT LEFT BRACKE DISC	Serviceable	251.50 FL	*- FL
20	1	*FRONT LEFT STABILIZER LINK	Serviceable	191.70 FL	*- FL
21	6	*FRONT LEFT FENDER INNER COWLING CLIPS	Not Necessary	30.00 FS	*- FS
22	1	*LEFT SIDE SKIRTING	Repair	1,200.00 FS	*- FS
23	1	*LEFT SIDE SKIRTING SEALANT	Necessary	60.00 FS	*60.00 FS
24	1	*LEFT SIDE SKIRTING CLIP	Necessary	50.00 FS	*50.00 FS
		12pcs			
25	1	*FRONT LEFT SPORT RIM	Cut	750.00 FS	*350.00 FS
26	1	*FRONT LEFT TYRE	Serviceable	300.00 FS	*- FS
27	1	*REAR BUMPER ASSY	Serviceable	1,252.30 FL	*- FL
28	1	*REAR LEFT DOOR	Repair	922.60 FL	*- FL
29	2	*REAR LEFT DOOR HINGES	Serviceable	106.20 FL	*- FL
30	1	*REAR LEFT DOOR CHECKER LINKAGE	Serviceable	138.50 FL	*- FL
31	1	*REAR LEFT DOOR OUTER HANDLE	Serviceable	195.40 FL	*- FL
32	1	*REAR LEFT DOOR WEATHERSTRIP	Serviceable	182.20 FL	*- FL
33	1	*REAR LEFT DOOR REGULATOR WITH MOTOR	Serviceable	350.10 FL	*- FL
34	1	*REAR LEFT FENDER	Serviceable	1,472.30 FL	*- FL
35	1	*REAR LEFT SUSPENSION ASSY	Serviceable	889.50 FL	*- FL
36	1	*REAR LEFT LOWER ARM CARRIER	Serviceable	442.30 FL	*- FL
37	1	*REAR LEFT WHEEL HUB BEARING	Serviceable	251.80 FL	*- FL
38	1	*REAR LEFT TRAILING ARM	Serviceable	284.90 FL	*- FL
39	1	*REAR LEFT IDLE ARM	Serviceable	242.30 FL	*- FL
40	1	*REAR LEFT IDLE LINK	Serviceable	262.50 FL	*- FL
41	1	*REAR STABILIZER BAR	Serviceable	280.10 FL	*- FL
42	1	*REAR LEFT SPORT RIM	Serviceable	750.00 FS	*- FS
43	1	*REAR LEFT TYRE	Serviceable	300.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
44	10	*REAR BUMPER CLIPS	Not Necessary	40.00 FS	*- FS
45	1	*REAR WINDSCREEN GLASS SEALANT	Not Necessary	80.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.					
Sub Total (S\$)				21,448.50	1,918.90
- List Item Discount on L Items 20.00/20.00% (S\$)				3,577.70	291.78
Total Parts (S\$)				17,870.80	1,627.12

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT LEFT AFFECTED AREA AND REPLACE FRONT LEFT DAMAGED PARTS. }	New	800.00	600.00
2	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN REAR LEFT AFFECTED AREA AND REPLACE REAR LEFT DAMAGED PARTS. }	New	800.00	0.00
3	TO PUTTY AND SPRAY PAINTING FRONT LEFT PORTION. }	New	800.00	800.00
4	TO PUTTY AND SPRAY PAINTING REAR AND REAR LEFT AFFECTED PORTION. }	New	800.00	0.00
5	TO CHECK WIRING AND FOCUS FRONT HEADLAMP.	New	50.00	0.00
6	TO REMOVE AND INSTALL FRONT LEFT DOOR LOCK MECHANISM. }	New	80.00	60.00
7	TO TRANSFER FRONT LEFT DOOR GLASS TO NEW DOOR. }	New	80.00	0.00
8	TO CHECK DOOR CENTRAL LOCKING FOR FUNCTION.	New	80.00	0.00
9	TO APPLY ANTI RUST PROOFING TO FRONT LEFT AFFECTED AREA.	New	80.00	40.00
10	TO BALANCE FRONT LEFT WHEEL.	New	50.00	20.00
11	TO CONDUCT FOUR WHEEL ALIGNMENT.	New	120.00	60.00
12	TO REMOVE AND INSTALL FRONT POWER STEERING RACK PINION ASSY.	New	160.00	0.00
13	TO REMOVE AND INSTALL FRONT LEFT UNDERCARRIAGE PARTS.	New	300.00	0.00
14	TO REMOVE AND INSTALL REAR LEFT DOOR LOCK MECHANISM.	New	80.00	0.00
15	TO APPLY ANTI RUST PROOFING TO REAR LEFT AFFECTED AREA.	New	80.00	20.00
16	TO TRANSFER REAR LEFT DOOR GLASS TO NEW DOOR.	New	80.00	0.00
17	TO REMOVE AND INSTALL REAR LEFT UNDERCARRIAGE PARTS.	New	300.00	0.00
18	TO BALANCE REAR LEFT WHEEL.	New	50.00	20.00
19	TO REMOVE AND INSTALL REAR FUEL TANK TO FACILITATE THE REPAIR.	New	180.00	0.00
20	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR.	New	140.00	0.00
21	TOWING SERVICE.	New	140.00	0.00
Gross Labour Cost (\$\$)			5,250.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >