

ESTIMATE FOR SLE5688P

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Technologies Creation Pte Ltd

22 Sin Ming Lane #06-85/86 Midview City Singapore 573969

Vehicle & Document Information

WIP No 19300

Reg No/Reg Date

SLE5688P / 26/09/2016

/--- O- /- /- /

Date In/Mileage

Chassis No

WDD2221622A262686

Engine No

27682430380927

Make/Model

MB/MB S 320 L SEDAN (V222)

Colour/Trim 027 775 Iridium Sil/ 048 808 Leather Cry

1.00

1.00

1.00

1.00

1.00

1.00

1.00

1.00

1.00

1.00

1.00

Date/Time Printed CSE Operator Terms Account No **CRDVCH** 350 / Eric Lee Ming Hui WCV26899 04/12/2017/ 14:31 EL Description of Goods / Services

POLICY NO/ACC DATE : GA267833/1 3-12-17 4-12-17 // TBC

DRIVE IN/EXCESS DATE IN/DATE SURVEY:

BY/AUTHRIZED ON

A BPILAB USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT

A BPIRES

M BPNSUN

RESPRAY LH/ FRONT FENDER, LH/ FRONT DOOR, LH/ REAR DOOR,

LH/ REAR FENDER, REAR BUMPER. A BPILAB

PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH

BODY PANELS AND REFINISH. A BPILAB

REMOVE & TRANSFER 2X DOOR MECHANICAL & ELETRICAL INSTALL

TO NEW DOOR.NETT

TRANSFER 2X RIM AND BALANCING TYRE, `NE-Ŧ1

PURCHASE ORDER NO:

LEFT FRONT FENDER

Confirmed & accepted by

A BPILAB TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT

LEFT FRONT WHEEL HOUSE COVERING REAR BUMPER LEFT CHROME TRIM REAR BUMPER RIGHT CHROME TRIM LH/ FRONT FENDER CHROME MOULDING LH/ FRONT DOOR CHROME MOULDING М LH/ REAR DOOR CHROME MOULDING М

М LEFT WING MIRROR FRAME LH/ FRONT DOOR М

LH/ FRONT DOOR SELF-ADHESIVE TRIM LH/ FRONT DOOR SELF-ADHESIVE TRIM Qty Unit Price

Disc% Amount

H / 1207.15 **DE** 208.91

106.59 106.59 S4/64.69

sel 147.78 147.78 **%** 🌠 967.40

F4 2795.06 nec - 6.14 15.58

Eric Lee Ming Hui

DID: 6771 4336 HP: 9181 7717 Email: eric.lee@cyclecarriage.com.sg Cycle & Carriage Industries Pte Ltd Customer Service Centre - Pandan Loop

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg

1207.15 00.00

208.91 00.00

106.59 00.00

106.59 00.00

64.69 00.00

147.78 00.00

967.40 00.00

6.14 00.00

15.58 00.00

2795.06 00.00

00.00

147.78

the removal of the windscreen.



ESTIMATE FOR SLE5688P

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Technologies Creation Pte Ltd

22 Sin Ming Lane #06-85/86 Midview City Singapore 573969

Vehicle & Document Information

WIP No 19300

Reg No/Reg Date

SLE5688P / 26/09/2016

Date In/Mileage

Chassis No

1 0 1 1 1 1 WDD2221622A262686

Engine No

27682430380927

Make/Model

MB/MB S 320 L SEDAN (V222)

C+1 / O40 000 L-

			Colour/Trim	02/ //5 Irio	11um 511/ 048	808 Leather Cry
Account No Terms	Date/Time Printed	CSE	Operator			
WCV26899 CRDVCH	04/12/2017/ 14:31	EL	350 / Eric Lee	Ming Hui		
	Description of Goods	/ Services		Qty	Unit Price D	isc% Amount
the Repairer of To resurvey befo To display damage Parts prices are: Third party surve No illegal modifice Supplementary if	ATHERSTRIP F-ADHESIVE TRIM F-ADHESIVE TRIM F-ADHESIVE TRIM EEL EL Sultants hence notify f the following: re/after spray pathting ged part(s) during meuryey subject to confirmation by is on a "Without Prejudice" basis cation(s) is allowed tem(s) must be resurveyed and approval from Insurance Company	Ema Cyc	TX(088-	1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	3501.77 0 272.55 0 15.58 0 6.14 0 768.77 0 788.73 0	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00

Confirmed & accepted by

Nett

22.139.76

7% GST on 22139.76

1549.78

Total Payable

23,689.54

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg

the removal of the windscreen.