

## **ESTIMATE FOR SLE5688P**

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Technologies Creation Pte Ltd

C/O AXA INSURANCE PTE LTD MOTOR CLAIM DEPARTMENT 8 SHENTON WAY #24-01 SINGAPORE 068811

Vehicle & Document Information

19300

Reg No/Reg Date SLE5688P

Date In/Mileage

05/12/2017/--17137 WDD2221622A262686 Chassis No

Engine No 27682430380927

Make/Model MB/MB S 320 L SEDAN (V222)

027 775 Iridium Sil/ 048 808 Leather Cry

/ 26/09/2016

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	03/01/2018/ 16:24	EL	350 / Eric Lee Ming Hui
100		Description of Good	s / Service	es Oty Unit Price Disc% Amount

Colour/Trim

WIP No

MOUNTING RAIL 00.00 10.71 NOT AN OFFICIA



Confirmed & accepted by

Nett

17.64

7% GST on

17.64

1.23

Total Payable

18.87

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg





## **ESTIMATE FOR SLE5688P**

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Technologies Creation Pte Ltd

C/O AXA INSURANCE PTE LTD MOTOR CLAIM DEPARTMENT 8 SHENTON WAY #24-01 SINGAPORE 068811

Vehicle & Document Information

WIP No 19300

Reg No/Reg Date

/ 26/09/2016 **SLE5688P** 

Date In/Mileage

05/12/2017/--17137

Chassis No

WDD2221622A262686

Engine No

27682430380927

Make/Model

MB/MB S 320 L SEDAN (V222)

Colour/Trim

027 775 Iridium Sil/ 048 808 Leather Cry

Account No	Terms	Date/Time Printed	CSE	Operator					
CSI00001	Cash	03/01/2018/ 16:2	4 EL	350 / Eric	Lee Ming Hu	i			20-20-00-00-00-00-00-00-00-00-00-00-00-0
		Description of G	oods / Services			Qty	Unit Price	Disc%	Amount
DRIVE IN	ÆXCESS DATE SURVE	GA267833/1 : 4-12-17 // :Y: 5-12-17 // : 5-12-17 //	RASUL - LKK /					WV	OICE
A BPILAB USING ST	AR DIAGNOS	STIC TO CHECK ON CO	.,			ر) د			480.00
A BPIRES RESPRAY	LH/ FRONT	FENDER, LH/ FRONT	DOOR, LH/ REAF	R DOOR,					3000.00
A BPILAB PANEL BE		REPAIR AFFECTED ARE	EAS, REMOVE AND	D. REPLACE WITH	NEW				3840.00
A BPILAB	TRANSFER	2X DOOR MECHANICAL	_ & ELETRICAL :	INSTALL				-	1200.00
S BPNSUB TRANSFER	& INSTALL BALANCING	. 2 PCS TYRE ONTO 1 & NEW VALVE HEAD	RIM-(RUNFLAT)						60.00
A BPILAB	-								540.00
X LEFT FROI		ICT WHEEL ALIGNMENT	I.NEII		1	1.00	1207.15	00.00	1207.15
	JSE COVERI	NG				1.00	208.91		208.91
X REAR BUMI	PER LEFT C	HROME TRIM			1	1.00	106.59	00.00	106.59
		CHROME TRIM			1	1.00	106.59		106.59
		HROME MOULDING				1.00		00.00	64.69
• .		OME MOULDING				.00	147.78		147.78
,		ME MOULDING				.00	147.78		147.78
X LH/ FRON						1.00	2795.06		2795.06
		F-ADHESIVE TRIM				.00		00.00	6.14
X LH/ FRON	DOOR SEL	F-ADHESIVE TRIM			1	1.00	15.58	00.00	15.58
Confirmed &	accented by								

Confirmed & accepted by

**Finalization** 

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg





## **ESTIMATE FOR SLE5688P**

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Technologies Creation Pte Ltd

C/O AXA INSURANCE PTE LTD MOTOR CLAIM DEPARTMENT 8 SHENTON WAY #24-01 SINGAPORE 068811

Vehicle & Document Information

19300

Reg No/Reg Date SLE5688P / 26/09/2016

Date In/Mileage 05/12/2017/--17137

Chassis No WDD2221622A262686

27682430380927 Engine No

Make/Model MB/MB S 320 L SEDAN (V222)

					Colour/Trim	027	775 Irio	lium Sil/ C	48 808 Le	eather Cry
Account No	Terms	Date/Time Printed	1 0	SE	Operator					
CS100001	Cash	03/01/2018/ 10	5:24 E	L	350 / Eric	Lee Ming	Hui			
***		Description of	of Goods / Se	rvices			Qty	Unit Price	Disc%	Amount
X LH/ REAR X LH/ REAR X LH/ REAR	DOOR WEA DOOR WEA DOOR SELI DOOR SELI DISK WHI RAIL	THERSTRIP F-ADHESIVE TRIM F-ADHESIVE TRIM EEL	AN S		FFIC	AL	1.00 1.00 1.00 1.00 1.00 1.00	272.55 3501.77 272.55 15.58 6.14 768.77 10.71 6.93	00.00 00.00 00.00 00.00 00.00 00.00	272.5 3501.7 272.5 15.5 6.1 768.7 10.7 6.9

WIP No

**Finalization** 

Confirmed & accepted by

Nett

18,781.27

7% GST on 18781.27

1314.69

Total Payable

20,095.96

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg



the removal of the windscreen.