

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

4-Dec-17

## ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) WAGON REGN NO: SHD 1485 L

1 pc	Rear o/s fender ✓	\$	1,575.23
		\$	1,575.23
	Less 20%	\$	315.05
		\$	1,260.18
<b>S/NETT</b>			
1 pc	Rear o/s fender sticker	\$	60.00 ✓
1 set	o/s door sticker	\$	100.00 ✓
	Sundry	\$	<del>50.00</del> 20
	To check wheel alignment	\$	<del>80.00</del> X
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the rear o/s door	\$	<del>500.00</del> 400
	To putty and spray painting on the rear bumper, rear o/s fender, rear o/s door	\$	<del>600.00</del> 500
	To apply rustproofing on the repaired and replaced panels	\$	<del>150.00</del> 20
<b>Total</b>		\$	2,800.18

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

Ka/ur c/c/c/c  
4/12/17 13304  
4 Days  
PIP  
Before Paint photo

LKK Auto Parts hereby notify the Repairer of the following:

- To resurvey before enter spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is in an "Out of Pre-Price" form
- No illegal modification(s) allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: