

CITYCAB PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHC 7439L

MAKE :

MODEL : HYUNDAI SONATA

AIG-LKK

DATE 12/2/2017 10:39

REAR

F2

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid ✓			\$ 1,349.50
	Boot Lid Rubber ✕			\$ 110.90
	Boot Lid Lock Upper 1			\$ 132.10
	Boot Lid Lock Lower 1			\$ 30.30
	Boot Lid Sonata Plate ✓			\$ 43.60
	Boot Lid Hyundai Plate ✓			\$ 24.20
	Boot Lid 'H' Emblem ✓			\$ 26.10
	Boot Lid CRDI Plate ✓			\$ 22.70
	Boot Lid Lamp (RH) ✓			\$ 230.20
	Rear Bumper ✓			\$ 578.40
	Rear Bumper Reinforcement ✓			\$ 483.30
	Rear Bumper Clip ✓			\$ 22.00
	Rear Bumper Sponge ✓			\$ 137.40
	Rear Bumper Under Cover 1			\$ 185.80
	Rear Bumper Protector (RH) ✓			\$ 38.00
	Tail Lamp (RH) ✓			\$ 344.00
	Rear Panel ✕ repair			\$ 391.80
	Rear Panel Garnish 1			\$ 95.80
	Rear Fender (RH) ✕ repair			\$ 1,935.90
	Rear Fender Inner Lining (RH) 1			\$ 74.10
	SUB TOTAL			\$ 6,256.10
	LESS 20%			\$ 1,251.22
	DISCOUNTED TOTAL			\$ 5,004.88
	Boot Lid Comfort Logo & Tel No. Sticker ✓			\$ 30.00
	Boot Lid Advertisement Logo ✓			\$ 100.00
	Rear Bumper Advertisement Logo ✓			\$ 50.00
	Rear Bumper Reverse Sensor ✓			\$ 135.70
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00
	Labour Charge			\$ 515.70
	Panel Beating			\$ 1,200.00
	Spray Painting Charge			\$ 800.00
	Wiring Charge			\$ 30.00
	Tuff Kote			\$ 50.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Towing Fee -			
	TOTAL LABOUR			\$ 2,470.00
	ESTIMATE TOTAL			\$ 7,990.58

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.