

ASS. REC. BY:

REF:

CS/FCL17023054/ATB

Special Instruction:

Surveyor:

Adnan

ASSIGNMENT (Office)

From (Person):

CWS Sereh Ler

of

FCL

Date/Time:

05/12/2017 12:41 pm

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGL 3200Z

Insured:

SHA 7519A

at Workshop m/s

Hua Meng

Tel:

6746 5519

of

Sik 1 Kaki Bukit Ave 6 #01-61

Policy No:

Claim No:

D17011178MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

01/12/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time:

05/12/2017 11:5 pm

Person Contacted:

June

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SGL 3200Z - x

SHA 7519A - NA / INC (500) 2831 / (R)2

DUP: 12/15

lump sum \$7900- (Red: 1726.40 (59%))

ASSIGNMENT

From: _____ Date: 05/12/017
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SGL 3200Z
 at Workshop/mis: Hua Meng
 of: Blk 1 Kaki Bukit Ave 6 #01-61
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Van No: SGL 3200Z . Yr Regn: 2006 Sept.
 Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Altis. cc: 1598
 Colour: Silver. A/C: Insured / Std / NI / NA
 Sp. Reading: 195307 . T/Radio: Insured / Std / NI / NA
 Eng No: _____
 Cr No: MROS3ZEC107130734
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: Nil / Si/Rim / STD A/Rim or _____
 Tyre Size: F: 185/70 R14
 R: 185/70 R14
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Fulker.

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % \$ Val: Yes or No
 CA / REV / REP. / 24 HRS NO
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

N/S	O/S

Front: _____ Rear: _____
 R.Bal. 06 mm R.Bal. 06 mm
 L.Bal. 06 mm L.Bal. 06 mm
 D.O.A _____ D.O.I 05/12/17.
 Survey held at: Hua Meng
 Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction
TP 1st Cap.
COE Expiry: 2021 Sept.
MV: 28K
PV: 20K
Nett: 8K
 RECEIVED 25 MAR 2018

Days Of Repair: 11
 Resurvey No. of Trip: 1
 Add Fee: Site Insp \$
 Interview \$
 Technician \$
 Weekend \$
 Report Format: TP
 Lump Sum / I.B.F: 7900
 Survey Fee: _____
 Transportation: _____
 Total: _____
 8X15 = 120
 170 + 120 = 290
 50 + 50 = 100
 151
26/3/18
591



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17023054/Atb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 05-12-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 7519A	Veh. Inspected	SGL 3200Z
Policy No.		Coverage (\$)	0.00
Claim No.	D17011178MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	05/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	01/12/2017	Inspection Date	05/12/2017
Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MOTOR SURVEY ASSIGNMENT

Date	04-12-2017	Our Ref No. D17011178MFSH
Accident Date	01-12-2017	Claim Type. Third Party
Insured Vehicle	SHA7519A	Third Party Vehicle. SGL3200Z
Survey Location	AUTOBAY@KAKIBUKIT 1 KAKI BUKIT AVENUE 6BLK C #01-61/01-34	
Contact Person.	JUNE	
Contact No.	67465519/ 0	Fax No. 67434896
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUA MENG SPRAY PAINTING WORKSHOP	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231418)



PRI Documents



Close X

PRI Header Details

Claim No	D17011178MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & HU WORKS
Workshop Name	HUA MENG SPRAY PAINTING WORKSHOP (Contact Person : JUNE)	Survey Location & Contact Details	AUTOBAY@KAKIBUKIT 1 KAKI BUKIT AVENUE Mobile: 0 , Phone: 67465519 , Fax: 6743489 EmailId: HUAMENG@LIVE.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY Q		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA7519A	TP Vehicle No	SGL321
PRI Recieved Date	04-12-2017 08:25:39 PM	Surveyor Appointed Date	05-12-2017 12:41:52 PM	Surveyor Accept Date	05-12-

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	05-12-2017	Upload Survey Report *:	<input type="text"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	----------------------

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/12/2017 12:19
Date Of Accident	01/12/2017 10:15
Exact Location Of Accident	FILTER LANE OF ADAM ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGL3200Z
Insured/Policyholder	
Name Of Registered Owner	SHILOH CASKET SERVICES
Co Reg No	53354681L
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-97606693

Vehicle Particulars

Manufacturer	TOYOTA
Model	ALTIS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5088145765
Cover Note Number	

Driver

Name of Driver	DHUSHENDRAN S/O BALAKRISHNAM
NRIC No	S8224633I
Date Of Birth	12/08/1982
Occupation	INDOOR
Date Of Driving Pass	30/08/2007
Driving Experience	10 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98892253
Fax Number	
Contact Number	
EMAIL Address	NOEMAIL

Address BLK 609 BUKIT PANJANG RING ROAD #03-908
 Postcode 670609
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name EUNOS NPP
 Police Station Address ROAD: 629 BEDOK RESERVOIR ROAD #01-1620 , POSTCODE: 470629 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT: T/20171201/2102.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHA7519A
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Name of Driver LUA CHIEN PIN
 NRIC/Passport Number S7811525D
 Contact Number 92356655
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name

Signature

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKZ412C
Vehicle Make/Model/Colour
Details Of Properties VEHICLE C
Name of Driver
NRIC/Passport Number
Contact Number 91555838
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

DETAILS OF INJURED PERSON 1

Name DHUSHENDRAN S/O BALAKRISHNAM
Approximate Age
Injuries Sustain
Injured person in which vehicle? SGL3200Z
Were seat belts worn?
Was injured conveyed to hospital by ambulance?
Address
Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20171201/2102

1 of 3

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

Report No. T/20171201/2102

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/12/2017 15:27	Vide Report No.:	Station Diary No.: 34
--	------------------	--------------------------

Informant's Particulars

Name of Informant: DHUSHENDRAN S/O BALAKRISHNAM		Address: APT BLK 609 BUKIT PANJANG RING ROAD #03-908 SINGAPORE 670609	
ID Type / ID No.: NRIC NO / S8224633I		Contact No.: Home/Office: Mobile: 98892253	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 35	Date of Birth: 12/08/1982	Type of Informant: Driver
Race: Indian		Language:	Institution / School Name:
Occupation: UBER DRIVER		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 01/12/2017 10:15	Type of Location: Straight Road
Location: Along Road 1 ADAM ROAD PAN ISLAND EXPRESSWAY Adam Rd entering PIE				
Weather: Sunny		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGL3200Z	Car	TOYOTA	Altis	Grey	Slightly Damaged	0
SHA7519A	Car	HYUNDAI		Blue	Slightly Damaged	0
SKZ412C	Car	HONDA	Odyssey	Purple	Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20171201/2102

2 of 3

Report No. T/20171201/2102

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	DHUSHENDRAN S/O BALAKRISHNAM	ID No	S8224633I
Related Vehicle	SGL3200Z (Car)	Contact No	98892253
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	01/12/2017	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	LUA CHIEN PIN	ID No	S7811525D
Related Vehicle	SHA7519A (Car)	Contact No	92356855
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 01/12/2017 at about 1015hrs, I was driving my grey coloured Toyota Altis (bearing registration number SGL3200Z) along the slip road from Adam Rd entering the Pan Island Expressway. While driving at a slow speed, suddenly there was an impact from the rear. I came to know that a blue coloured ComfortDelgro taxi (bearing registration number SHA7519A) had collided into the rear of my vehicle. Due to the impact, I was not able to react in time, and the front of my vehicle had collided into the rear of the purple coloured Honda Odyssey (bearing registration number SKZ412C) which was in front of me. It was a chain collision.

Due to the impact, the rear bumper of my vehicle was greatly dented in, there was a huge crack on my front bumper and the bonnet of my vehicle was greatly bent upwards. Ambulance arrived shortly, and I was conveyed to Ng Teng Fong Hospital to seek for medical treatment. I complaint of pain in the lower back, and whiplash at my neck. I was then given 3 days MC.



**SINGAPORE
POLICE FORCE**



T/20171201/2102

3 of 3

Report No. T/20171201/2102

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 2 MUHAMMAD NAQIB BIN ABDUL-RAZAK	Signature Of Informant
Signature Of Interpreter: Not applicable	Date/Time: 01/12/2017 16:27
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt ONG YONG HOCK Contact No : 65476438	Classification Of Case:


Authentication Stamp
SP-10

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Business
Owner ID	4681L
Vehicle Details	
Vehicle No.	SGL3200Z
Vehicle to be Exported	Yes
Intended De-registration Date	05 Dec 2017
Vehicle Make	TOYOTA
Vehicle Model	COROLLA ALTIS 1.6 AUTO
Primary Colour	Silver
Manufacturing Year	2006
Engine No.	3Z24601519
Chassis No.	MR053ZEC107130734
Maximum Power Output	81.0 kW (108 bhp)
Open Market Value	\$15,498.00
Original Registration Date	12 Sep 2006
First Registration Date	12 Sep 2006
Transfer Count	3
Actual ARF Paid	\$13,459.00
Intended PARF Rebate Details	
PARF Eligibility	Forfeited
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	11 Sep 2021
COE Category	A - Car (1600cc & below)
COE Period(Years)	5
PQP Paid	\$26,670.00
COE Rebate Amount	\$20,091.00
Total Rebate Amount	\$20,091.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 05 Dec 2017

OK


 Username / Email Add
 password
 Connect
 Sign Up New Account
 Forgot Password

toyota altis

Price Range

Depreciation

> 10 year()

Vehicle Type



Advanced Search

Used Car Comparison

— Comparing 4 Vehicles —

Toyota Corolla Altis 1.6A (COE till 06/2021)



Add to Shortlist

Toyota Corolla Altis 1.6A (COE till 06/2021)



Add to Shortlist

Toyota Corolla Altis 1.6A (COE till 11/2021)



Add to Shortlist

Toyota Corolla Altis 1.6A (COE till 12/2021)



Add to Shortlist

Clear All

Add all to Shortlist

Back to search result

CAR DETAILS

Price	\$26,900	\$28,800	\$28,800	\$29,500
Instalment	N.A.	N.A.	N.A.	N.A.
Registration Date	26-Jul-2006	10-Jul-2006	17-Nov-2006	14-Dec-2006
Manufactured	2006	2006	2006	2006
Mileage	88,285 km	135,219 km	-	-
Transmission	Auto	Auto	Auto	Auto
Engine Cap	1,598 cc	1,598 cc	1,598 cc	1,598 cc
Road Tax	\$816 /yr	\$816 /yr	\$816 /yr	\$816 /yr
Power	81.0 kW (108 bhp)	81.0 kW (108 bhp)	81.0 kW (108 bhp)	81.0 kW (108 bhp)
Curb Weight	1,115 kg	1,115 kg	1,115 kg	1,115 kg
Features	1.6L VVT-i DOHC Engine, Four Speed Auto Transmission Gearbox, Climate Aircon Control, Dual Airbags.	Durable And Reliable 1.6L DOHC 16 Valves 4 Cylinders VVT-i Engine, 4 Speed Auto, Climatic Control Aircon, Dual SRS Airbags, ABS.	Airbags, ABS, Reliable And Fuel Efficient 1.6L VVT1 Engine, Climate Control Aircon, Multi Function Steering.	SRS Airbags, ABS, Refi Efficient 1.6L VVT1 Eni Control Aircon, Multi F \$2500 Drive Away.
Accessories	Leather Seats, Sports Rims, Retractable Side Mirror, Reverse Sensors, Factory Fitted Audio System.	Leather Seats, Sports Rims, Original Toyota Audio Systems, Retractable Side Mirrors, Reverse Sensors, Etc.	Leather Seats, Sports Rims, Audio System.	Leather Seats, Sports System.
Description	1 Ownership, 100% Accident Free, Fully Serviced By Borneo Motors Since First Day Till Now. It Is Affordable For Everyone Very Low Depreciation Per Day Only \$20, Great Fuel Efficiency Car, Platinum Auto Being Awarded Premium Dealer For 5 Year By sgCarMart, Peace Of Mind Buy Car From Our Company, Please Call For Viewing Before It's Gone.	Up To 90% Loan! No Hidden Cost! No Gimmicks! Fuel Economy Yet Powerful Drive And Durability, Beautiful Condition. Call Now!	Elegant Black, Low Fuel Consumption, Low Maintenance Cost, Drive Away With Minimum Down Payment, Flexible In-house Loan Packages Available, Very Well Maintained.	Elegant Beige, Flexible Packages Available, Lc Cost, Low Fuel Consur Maintained.
COE	\$23,227	\$23,227	\$25,821	\$25,636
OHV	\$15,950	\$15,950	\$15,498	\$15,355
ARF	\$17,545	\$17,545	\$17,048	\$16,891
Depreciation	\$7,540 /yr	\$8,070 /yr	\$7,290 /yr	\$7,330 /yr
No. of Owners	1	2	2	2
Type of Vehicle	Sedan	Sedan	Sedan	Sedan
Category	COE Car, Consignment Car, Low Mileage Car	COE Car	COE Car	COE Car
Availability	Available	Available	Available	Available
Remarks	COE expiry date 2021-12-13	COE expiry date 2021-12-13	COE expiry date 2021-12-13	COE expiry date 2021-12-13

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

SHILOH CASKET SERVICES
22 SIN MING LANE
#06-76 MIDVIEW CITY
S 573969

TP 1st Cap
Dorise

Date :02.01.2018
Vehicle no :SGL 3200 Z
Make/Model :TOYOTA ALTIS
Accident date :01.12.2017

No	Description	Qty	Amount (\$)
<u>List Items</u>			
1	Rear windscreen rubber <i>new</i>	1	\$ 53.8 ✓
2	Rear boot lid <i>Dented</i>	1	\$ 845.3 ✓
3	Rear boot lid hinges @ \$56.40 <i>Bent</i>	2	\$ 112.8 ✓
4	Rear boot lid upper lock <i>Damaged</i>	1	\$ 81.7 ✓
5	Rear boot lid lower lock <i>new</i>	1	\$ 57.6 ✗
6	Rear boot lid handle <i>new</i>	1	\$ 176.5 ✗
7	Rear boot lid centre logo <i>not new</i>	1	\$ 65.7 ✗
8	Rear boot lid COROLLA emblem	1	\$ 24.1 ✓
9	Rear boot lid ALTIS emblem	1	\$ 41.7 ✓
10	Rear boot lid 1.6E emblem	1	\$ 44.5 ✓
11	Rear boot lid VVTI emblem	1	\$ 41.7 ✓
12	Rear boot lid reflector @ \$80.60 <i>cracked</i>	2	\$ 161.2 ✓
13	Rear boot lid weather strip <i>ut</i>	1	\$ 143.1 ✓
14	Rear lamp @ \$385.30 <i>cracked</i>	2	\$ 770.6 <i>579</i>
15	Rear lamp housing @ \$487.00 <i>Buckled</i>	2	\$ 974 <i>898</i>
16	Rear lamp lower panel @ \$92.30 <i>Bent</i>	2	\$ 184.6 ✓
17	Rear lamp lower panel rivet <i>new</i>	1	\$ 70.4 <i>50</i>
18	Rear end panel <i>Distorted</i>	1	\$ 708.3 ✓
19	Rear end panel inner top garnish <i>Distorted</i>	1	\$ 26.5 ✓
20	Rear bumper <i>Distorted</i>	1	\$ 385.3 ✓
21	Rear bumper side holder @ \$17.20 <i>new</i>	2	\$ 34.4 ✓
22	Rear bumper bracket @ \$51.10 <i>Dented</i>	2	\$ 102.2 ✓
23	Rear bumper clips (1set) <i>new</i>	1	\$ 55 <i>30</i>
24	Rear fender @ \$758.20 <i>Repair</i>	2	\$ 1516.4 ✗
25	Rear fender inner trim @ \$161.20 <i>not new</i>	2	\$ 322.4 ✗
26	Rear fender inner shield @ \$35.10 <i>not new</i>	2	\$ 70.2 ✗
27	Rear exhaust pipe <i>Bent</i>	1	\$ 387.5 ✓
28	Rear centre exhaust pipe <i>not new</i>	1	\$ 458.5 ✗
29	Rear exhaust mounting <i>not new</i>	1	\$ 55 ✗
30	Rear spare tyre top cover <i>tear</i>	1	\$ 49.1 ✓
31	Rear spare tyre well <i>Buckled</i>	1	\$ 757 ✓
32	Rear spare tyre well insulation @ \$57.20 <i>new</i>	3	\$ 171.6 <i>120(120)</i>
33	Front bumper <i>Deformed</i>	1	\$ 344 ✓
34	Front bumper side holder @ \$43.90 <i>new</i>	2	\$ 87.8 ✓
			9390.5

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

SHILOH CASKET SERVICES
22 SIN MING LANE
#06-76 MIDVIEW CITY
S 573969

Date :02.01.2018
Vehicle no :SGL 3200 Z
Make/Model :TOYOTA ALTIS
Accident date :01.12.2017

No	Description	Qty	Amount (\$\$)
35	Front bumper reinforcement <i>Best</i>	1	\$ - 343.7 ✓
36	Front bumper clips (1set) <i>new</i>	1	\$ - 25 ✓
37	Front bumper bracket @ \$75.00 <i>new</i>	2	\$ - 150 ✗
38	Front bumper lower fog lamp garnish @ \$95.00 <i>new</i>	2	\$ - 190 ✗
39	Front grille <i>Coated</i>	1	\$ - 271.9 ✓
40	Front grille logo <i>new</i>	1	\$ - 44.7 ✓
41	Front grille clips (1set) <i>new</i>	1	\$ - 28 ✓
42	Front head lamp @ \$335.30 <i>LH coated</i>	2	\$ - 670.6 335.30
43	Front support panel <i>Repair</i>	1	\$ - 2154.5 ✗
44	Front bonnet <i>Repair</i>	1	\$ - 1429 ✗
45	Front bonnet lock <i>new</i>	1	\$ - 30 ✗
46	Front bonnet lock bracket <i>new</i>	1	\$ - 103.4 ✓
47	Front LH fender <i>Repair</i>	1	\$ - 156 ✗
48	Air con condenser <i>new</i>	1	\$ - 1372.8 ✗
49	Radiator <i>new</i>	1	\$ - 1025.4 ✗
50	Radiator top bracket @ \$55.00 <i>new</i>	2	\$ - 110 ✓
			\$ 17495.5
		Less 25% Disc	\$ 3499.1
		Total	\$ 13996.4
Special Nett Items			
1	Rear bumper reverse sensor(1set) <i>Damaged</i>	1	\$ - 380 200
2	Front number plate <i>Best</i>	1	\$ - 50 30
3	Front number plate holder <i>Coated</i>	1	\$ - 50 30
		Total	\$ 480

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

SHILOH CASKET SERVICES
22 SIN MING LANE
#06-76 MIDVIEW CITY
S 573969

Date :02.01.2018
Vehicle no :SGL 3200 Z
Make/Model :TOYOTA ALTIS
Accident date :01.12.2017

No	Description	Qty	Amount (S\$)
Labour Cost			
1	To supply rear end panel sealant		\$ 50 ✓
2	To supply rear windscreen sealant		\$ 50 x
3	Towing fee		\$ 100 50
4	Remove & reinstall rear windscreen		\$ 150 x
5	Remove & reinstall air cond fill in gas		\$ 150 120
6	Remove & reinstall exhaust pipe		\$ 200 80
7	Remove & reinstall reverse sensor		\$ 150 50
8	Remove & reinstall roof lining & cushion		\$ 200 150
9	Remove & reinstall petrol tank		\$ 150 x
10	Remove ,replace & repair consistent to the accident		\$ 2000 1900
11	Respray painting		\$ 1800 1700
12	Tuff kote		\$ 150 50
	Total		\$ 5150
	Grand Total		\$ 19626.4

4150

18751.65

total: 9885.30

2/s: 7.9.12

11 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17023054/Atbq2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 26-03-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7519A	Veh. Inspected	SGL 3200Z
Policy No.	D-15072701MFSH	Coverage (\$)	0.00
Claim No.	D17011178MFSH	Excess (\$)	0.00
Assign From	SERENE LER	Assign Date	05/12/2017

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	MR053ZEC107130734	Colour	SILVER
Odometer	195307	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/70 R14	FALKEN	6 mm
L/H Front Tyre	185/70 R14	FALKEN	6 mm
R/H Rear Tyre	185/70 R14	FALKEN	6 mm
L/H Rear Tyre	185/70 R14	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/12/2017	Inspection Date	05/12/2017
Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **11 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGL 3200Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN RUBBER	NOT NECESSARY	53.80	-
1	REAR BOOT LID	DENTED	845.30	845.30
2	REAR BOOT LID HINGES @\$56.40	BENT	112.80	112.80
1	REAR BOOT LID UPPER LOCK	DAMAGED	81.70	81.70
1	REAR BOOT LID LOWER LOCK	NOT NECESSARY	57.60	-
1	REAR BOOT LID HANDLE	NOT NECESSARY	176.50	-
1	REAR BOOT LID CENTRE LOGO	NOT NECESSARY	65.70	-
1	REAR BOOT LID COROLLA EMBLEM	NECESSARY	24.10	24.10
1	REAR BOOT LID ALTIS EMBLEM	NECESSARY	41.70	41.70
1	REAR BOOT LID 1.6E EMBLEM	NECESSARY	44.50	44.50
1	REAR BOOT LID VVTI EMBLEM	NECESSARY	41.70	41.70
2	REAR BOOT LID REFLECTOR @\$80.60	CRACKED	161.20	161.20
1	REAR BOOT LID WEATHER STRIP	CUT	143.10	143.10
2	REAR LAMP @\$385.30	CRACKED	770.60	579.00
2	REAR LAMP HOUSING @\$487.00	BUCKLED	974.00	898.00
2	REAR LAMP LOWER PANEL @\$92.30	BENT	184.60	184.60
1	REAR LAMP LOWER PANEL RIVET	NECESSARY	70.40	50.00
1	REAR END PANEL	DISTORTED	708.30	708.30
1	REAR END PANEL INNER TOP GARNISH	DEFORMED	26.50	26.50
1	REAR BUMPER	DISTORTED	385.30	385.30
2	REAR BUMPER SIDE HOLDER @\$17.20	NECESSARY	34.40	34.40
2	REAR BUMPER BRACKET @\$51.10	DENTED	102.20	102.20
1	SET REAR BUMPER CLIPS	NECESSARY	55.00	30.00
2	REAR FENDER @\$758.20	TO REPAIR SEE LABOUR	1,516.40	-
2	REAR FENDER INNER TRIM @\$161.20	NOT NECESSARY	332.40	-
2	REAR FENDER INNER SHIELD @\$35.10	NOT NECESSARY	70.20	-
1	REAR EXHAUST PIPE	BENT	387.50	387.50
1	REAR CENTRE EXHAUST PIPE	NOT NECESSARY	458.50	-
1	REAR EXHAUST MOUNTING	NOT NECESSARY	55.00	-
1	REAR SPARE TYRE TOP COVER	TORN	49.10	49.10

Report Ref No. CS/FCI17023054/Atbq2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SPARE TYRE WELL	BUCKLED	757.00	757.00
1	FRONT BUMPER	DEFORMED	344.00	344.00
2	FRONT BUMPER SIDE HOLDER @\$43.90	NECESSARY	87.80	87.80
1	FRONT BUMPER REINFORCEMENT	BENT	343.70	343.70
1	SET FRONT BUMPER CLIPS	NECESSARY	25.00	25.00
2	FRONT BUMPER BRACKET @\$75.00	NOT NECESSARY	150.00	-
2	FRONT BUMPER LOWER FOG LAMP GARNISH @\$95.00	NOT NECESSARY	190.00	-
1	FRONT GRILLE	CRACKED	271.90	271.90
1	FRONT GRILLE LOGO	NECESSARY	44.70	44.70
1	SET FRONT GRILLE CLIPS	NECESSARY	28.00	10.00
2	FRONT HEAD LAMP @\$335.30	N/S CRACKED	670.60	335.30
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	2,154.50	-
1	FRONT BONNET	TO REPAIR SEE LABOUR	1,429.00	-
1	FRONT BONNET LOCK	NOT NECESSARY	30.00	-
1	FRONT BONNET LOCK BRACKET	NOT NECESSARY	103.40	-
1	FRONT LH FENDER	TO REPAIR SEE LABOUR	156.00	-
1	AIR CON CONDENSER	NOT NECESSARY	1,372.80	-
1	RADIATOR	NOT NECESSARY	1,025.40	-
2	RADIATOR TOP BRACKET @\$55.00	NOT NECESSARY	110.00	-
	LESS 25% DISCOUNT		-4,330.98	-1,787.60
			12,992.92	5,362.80
3	REAR SPARE TYRE WELL INSULATION @\$57.20 (SN)	NECESSARY	171.60	120.00
	LESS 25% DISCOUNT		-42.90	-
			128.70	120.00
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	380.00	200.00
1	FRONT NUMBER PLATE REAR END PANEL	BENT	50.00	30.00
1	FRONT NUMBER PLATE HOLDER REAR END PANEL	CRACKED	50.00	30.00
			480.00	260.00

Report Ref No. CS/FCI17023054/Atbq2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO SUPPLY REAR END PANEL SEALANT .		50.00	50.00
	TO SUPPLY REAR WINDSCREEN SEALANT .	NOT NECESSARY	50.00	-
	TOWING FEE.		100.00	50.00
	REMOVE & REINSTALL REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	REMOVE & REINSTALL AIR COND FILL IN GAS.		150.00	120.00
	REMOVE & REINSTALL EXHAUST PIPE.		200.00	80.00
	REMOVE & REINSTALL REVERSE SENSOR .		150.00	50.00
	REMOVE & REINSTALL ROOF LINING & CUSHION.		200.00	150.00
	REMOVE & REINSTALL PETROL TANK .	NOT NECESSARY	150.00	-
	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT .INCLUSIVE OF THE REPAIR OF REAR FENDER,FRONT SUPPORT PANEL AND FRONT BONNET AND FRONT LH FENDER .		2,000.00	1,900.00
	RESPRAY PAINTING .		1,800.00	1,700.00
	TUFF KOTE.		150.00	50.00
			5,150.00	4,150.00
	GRAND TOTAL		18,751.62	9,892.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,900.00

Report Ref No. CS/FC117023054/Atbq2

MARKET VALUE: \$28,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$20,000.00=NETT VALUE: \$8,000.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.