

INS. CASE OWNER:

JOEL

CC3/CT117023062 / K1ea3m2

ASSIGNMENT

Surveyor:

KALVIN

DOI:

04/12/17

Date / Time:

04/12/17

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

ED 699D

Claim No.:

SNM17006920C02/9

Name of Insured:

MR LIM SHAO - WEI

Policy No.:

DMPCSN3084911601

Insured Tel No.:

HP: 9795 2700

Make / Model:

AUDI A6 2.0 TFSI MU

Excess Sec II :SS

D.O.A: 02/12/17

Place of Accident:

CROSS JUNC OF BUANGKOK EAST DR
R. SENGKANG E DR

Is driver the owner?

YES / NO

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHD 1404 X



INSRS:

WSP: Premier Auto (Ldg)

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

SHD 1404 X - CC4/AXA12019758/HIV1F3C3 DOA: 04/12/17
 - CC4/SCG17018893/K1-ha2 DOA: 29/03/17
 - NA/CTI17022954/ha DOA: 02/12/17
 ED 699D - NA/CTI17022954/ha DOA: 02/12/17

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

15/12/17 (Akh)

* Please assist to obtain video footage (if any) from
 third party.

18/12/17

Email WSP to REQUEST FOR VIDEO.

RED TP VIDEO SAME IN (V. ASHER: 2011) VIDEO SHOOT ON SOME
 INFO TP LANE.

19/12/17

19/12/17 CALLED OI CONFIRMED ACCIDENT. OI CHANGED INTO TP LANE
 AND THN TP. INFORM TP CLAIM AGREED TO SETTLE AND
 AMUSE ABOUT NCD BUMP.

4/1/18

File PASS TO TYPST TO TYPE REPORT.

RECEIVED 08 APR 2018

RECEIVED 04 JAN 2018

PRELIMINARY ADVICE

Date/Time: 05/12/17

Sent By:

Shirley Hwe

FINALIZATION

Date/Time: 14/12/17

Confirm with: GARY

Confirm by: KEVIN

Repair Cost:

45

SS 3,800

(

4

days)

Reduction:

38 %

Email

Call

FINAL SETTLEMENT

Date/Time: 28/3/18

Confirm with: GARY

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

15

If NO or B 28, Ass. Lia:

Repair Cost:

20/151

SS 4,066

OI CHANGED LANE.

Loss of Rental (LOR):

SS 549.70

(

5

days) x

109.94

Loss of Use (LOU):

SS -

(\$

x

days)

Loss of Income (LOI):

SS -

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS 1.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 4,617.70

Global Sum SS:

FINAL PAYMENT

Date/Time: 28/3/18

Confirm with: GARY

Email

Call

Payee 1:

SS 4,617.70

Name 1:

PREMIER AUTOMOTIVE SERVICES PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI17023062/K1ea3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 05-12-2017	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	ED 699D	Veh. Inspected	SHD 1404X
Policy No.	DMPCSN3084911601	Coverage (\$)	0.00
Claim No.	SNM17D06920C02/9	Excess (\$)	0.00
Assign From		Assign Date	05/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	02/12/2017	Inspection Date	04/12/2017
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/CTI17023062/K1ca3

Date: 05.12.2017

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD 1404X


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 04.12.2017 at the premises of M/s Premier Automotive Services Pte Ltd (Changi South) and have the following to report:-

Workshop Estimate Amount	: S\$	6,108.38
Revised Estimate Amount	: S\$	4,802.86
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
O/S Body



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

1723.60 72.20
2017.48 72.20

100.00 30.00
60.00 30.00
20.00 160.00
50.00 100.00
50.00 100.00
400.00 450.00
1080.00 120.00
50.00 200.00
1810.00
1190.00

0.00

144.40

0.00 0.00

3741.08

3885.48
3741.08
144.40

3000.00
1810.00
1190.00

0.00
0.00
0.00

3741.08
748.22
2992.86
1810.00

4802.86

0.00
0.00
0.00

}

CHECK ITEM


0.00
0.00
0.00
0.00
0.00
0.00

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H
 Owner ID Type: Company
 Owner Name: PREMIER TAXIS PTE. LTD.
 Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
 Mailing Address: -
 Birth Date: -

Vehicle Particulars

Vehicle No.: SHD1404X
 Previous Vehicle No.: -
 Effective Date of Ownership: 29 Jun 2017
 Original Regn Date: 29 Jun 2017
 Registration Date: 29 Jun 2017
 Year of Manufacture: 2016
 Vehicle Type: Public Transport Taxi (Motor Car)
 Vehicle Scheme: Taxi (Company)
 Vehicle Attachment 1: Air-Con (Taxi)
 Vehicle Attachment 2: -
 Vehicle Attachment 3: -
 Vehicle Make: HYUNDAI
 Vehicle Model: I30 GDH 1.6 TCI 5DR DCT
 Primary Colour: Silver
 Secondary Colour: -
 Passenger Capacity: 4
 Chassis No.: TMAD281UVHJ128015
 Engine No.: D4FBGZ122114
 Engine Capacity/Power Rating: 1582 cc / -
 Maximum Power Output: 100.0 kW (134 bhp)
 Propellant: Diesel
 Max Unladen Weight: 1496 kg
 Maximum Laden Weight: 1940 kg
 Open Market Value: \$20,545.00
 PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 28 Jun 2025
 Minimum PARF Benefit: \$7,957.00
 No. of Transfers: 0
 IU Label No.: 1050700335
 COE No.: 2017062901003961Z
 COE Expiry Date: 28 Jun 2025
 COE Category: A - Car up to 1600cc & 97kW (130bhp)
 COE Registration Category: A - Car up to 1600cc & 97kW (130bhp)
 Quota Premium (QP) / Prevailing Quota Premium: - / \$50,625.00
 PQP Paid: \$40,500.00
 QP (Regn Cat): -
 OPC Cash Rebate Eligibility: No

 PREMIER TAXIS	HIRER / RELIEF / SUPER RELIEF
VEHICLE NO.	SHD1404X
CONTACT NO.	98225133
NEW MAILING ADDRESS (if any)	

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S8371061F**



Name

LIU TERENCE

Race
CHINESE

Date of birth
07-10-1983

Country/Place of birth
MALAYSIA

Sex
M



NRIC No. **S8371061F**



Date of issue
28-03-2014

Address

**APT BLK 550 HOUGANG STREET 51
#06-170
SINGAPORE 530550**

5294677

REPUBLIC OF SINGAPORE **DRIVING LICENCE**

Licence Number: **S8371061F**
Name:

LIU TERENCE

Birth Date: **07 Oct 1983**

Issue Date: **06 Jul 2004**



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class 2B Motorcycles <= 200 CC
Class 2A Motorcycles between 201 CC and 400 CC
Class 1 Motor cars <= 3500 kg with <= 7 passengers, exclusive of the driver, and motor tractors/vehicles <= 2500 kg

PASS DATE

**30 Sep 2004
03 Jan 2006
06 Jul 2004**

S / No. 9000039904

S8371061F

NP 428A



Land Transport & Authority

VOCATIONAL LICENCE

Licence No. **S8371061F**

Name: **LIU TERENCE**

Issue Date: **16/2/2016**

Please visit www.lta.gov.sg to check the status of this vocational licence



Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H
Owner ID Type: Company
Owner Name: PREMIER TAXIS PTE. LTD.
Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
Mailing Address: -
Birth Date: -

Vehicle Particulars

Vehicle No.: SHD1404X
Previous Vehicle No.: -
Effective Date of Ownership: 29 Jun 2017
Original Regn Date: 29 Jun 2017
Registration Date: 29 Jun 2017
Year of Manufacture: 2016
Vehicle Type: Public Transport Taxi (Motor Car)
Vehicle Scheme: Taxi (Company)
Vehicle Attachment 1: Air-Con (Taxi)
Vehicle Attachment 2: -
Vehicle Attachment 3: -
Vehicle Make: HYUNDAI
Vehicle Model: I30 GDH 1.6 TCI 5DR DCT
Primary Colour: Silver
Secondary Colour: -
Passenger Capacity: 4
Chassis No.: TMAD281UVHJ128015
Engine No.: D4FBGZ122114
Engine Capacity/Power Rating: 1582 cc / -
Maximum Power Output: 100.0 kW (134 bhp)
Propellant: Diesel
Max Unladen Weight: 1496 kg
Maximum Laden Weight: 1940 kg
Open Market Value: \$20,545.00
PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 Jun 2025
Minimum PARF Benefit: \$7,957.00
No. of Transfers: 0
IU Label No.: 1050700335
COE No.: 2017062901003961Z
COE Expiry Date: 28 Jun 2025
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Registration Category: A - Car up to 1600cc & 97kW (130bhp)
Quota Premium (QP) / Prevailing Quota Premium: - / \$50,625.00
PQP Paid: \$40,500.00
QP (Regn Cat): -
OPC Cash Rebate Eligibility: No

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5095103893

Cover : Third Party

1. Index mark and Registration Number of Vehicle

: **SHD1404X**

Chassis Number

: TMAD281UVHJ128015

2. Name of Policyholder

: PREMIER TAXIS PTE. LTD.

3. Effective Date of Insurance

: 20 Oct 2017

4. Expiry Date of Insurance

: 19 Oct 2018

5. Persons or Classes of Persons entitled to drive*

(a) The Policyholder.

(b) Any licensed taxi driver driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use*

(a) Use as a Taxi.

(b) Use for social domestic and pleasure purposes.

This Policy does not cover

(a) Use for racing, pace-making, reliability trial or speed-testing.

(b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION I) : N/A

EXCESS (SECTION II) : S\$3,500

INSURE WITH COE : N/A

HIRE PURCHASE COMPANY : DBS BANK LTD

SUM INSURED : N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)

Date of Issue : 16 Oct 2017 17:13 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:



Authorised Officer



Chief Executive

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

4-Dec-17

Chin

ESTIMATE REPAIR BILL FOR HYUNDAI I30A REGN NO: SHD 1404 X

1 pc	Front o/s door ✓	\$ 1,723.60
2 pcs	Front o/s door hinge @\$36.10 X	\$ 72.20
1 pc	Rear o/s door ✓	\$ 2,017.48
2 pcs	Rear o/s door hinge @\$36.10 X	\$ 72.20
		<hr/>
		\$ 3,885.48
	Less 20%	\$ 777.10
		<hr/>
		\$ 3,108.38

S/NETT

1 set	o/s door sticker ✓	\$ 100.00
1 pc	Rear o/s sticker ✓	\$ 60.00
1 pc	Front o/s fender sticker X not necessary	\$ 30.00
	Sundry	\$ 50.00 20
	To check wheel alignment	\$ 160.00 X
	To dismantle and refit the inner component of Front o/s door into new shell door	\$ 150.00 50
	To dismantle and refit the inner component of Rear o/s door into new shell door	\$ 150.00 50
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s fender, rear o/s fender, rear bumper, o/s rocker panel	\$ 850.00 400
	To putty and spray painting on front o/s fender, front o/s door, rear o/s door, o/s rocker panel, rear o/s fender, rear bumper, rear o/s wheel rim	\$ 1,200.00 100
	To apply rustproofing on the repaired and replaced panels.	\$ 250.00 50
		<hr/>
		\$ 6,108.38

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hereby notify

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

• To repair damaged parts and to resurvey

• No illegal modification is allowed

• Supplementary items must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Kalvin (LKK)
4/12/17 17:56h
3 Pcs
P/P
Before Paint photo

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG: 200707743D GST REG: 200707743D

4-Dec-17

ESTIMATE REPAIR BILL FOR HYUNDAI I30A REGN NO: SHD 1404 X

1 pc	Front o/s door — <i>Lat</i>	\$ 1,723.60
2 pcs	Front o/s door hinge @\$36.10 X <i>su</i>	\$ 72.20
1 pc	Rear o/s door — <i>PH</i>	\$ 2,017.48
2 pcs	Rear o/s door hinge @\$36.10 X <i>smc</i>	\$ 72.20
		<hr/>
		\$ 3,885.48
Less 20%		<hr/>
		\$ 777.10
		<hr/>
		\$ 3,108.38

S/NETT

1 set	o/s door sticker — <i>acc</i>	\$ 100.00
1 pc	Rear o/s sticker — <i>acc</i>	\$ 60.00
1 pc	Front o/s fender sticker X <i>not necessary</i>	\$ 30.00
Sundry <i>acc</i>		\$ 50.00 20
To check wheel alignment		\$ 160.00 X <i>acc</i>
To dismantle and refit the inner component of Front o/s door into new shell door		\$ 150.00 <i>50</i>
To dismantle and refit the inner component of Rear o/s door into new shell door		\$ 150.00 50
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s fender, rear o/s fender, rear bumper, o/s rocker panel		\$ 850.00 400
To putty and spray painting on front o/s fender, front o/s door, rear o/s door, o/s rocker panel, rear o/s fender, rear bumper, <i>Rear o/s wheel Rim</i>		\$ 1,200.00 100
To apply rustproofing on the repaired and replaced panels.		\$ 250.00 50
		<hr/>
		\$ 6,108.38

(ALL THE REPAIR COSTS ARE SUBJECT TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

- To replace damaged parts including labour
- To replace parts must be resurveyed and
- Subject to final approval from insurance company

Acknowledged by Repairer
Signature:
Date:

Kalvin (ACC)
4/12/17 13:50h
143 Reps
P/P
Before Part & photo

14/12/17
cost 45 \$3800/4 Reps

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Monday, 18 December, 2017 11:39 AM
To: 'Gary Shi'
Cc: Vic (LKKAUTO)
Subject: ACCIDENT INVOLVING SHD 1404X & ED 699D ON 02/12/2017
Attachments: OI SKETCH PLAN.pdf

Without Prejudice

Your Ref: SHD 1404X
Our Ref: CC3/CTI17023062/K1ea3

Dear Sirs,

ACCIDENT INVOLVING SHD 1404X & ED 699D ON 02/12/2017

We refer to the above matter.

Our principal we would like to request a copy of video footage/witness statement/scene photos(if any).

We shall revert upon hearing from you.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI17023062/K1ea3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 10-04-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	ED 699D	Veh. Inspected	SHD 1404X
Policy No.	DMPCSN3084911601	Coverage (\$)	0.00
Claim No.	SNM17D06920C02/9	Excess (\$)	0.00
Assign From		Assign Date	04/12/2017

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I30	c.c	1582
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	TMAD281UVHJ128015	Colour	SILVER
Odometer	62253	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	MAXXIS	7 mm
L/H Front Tyre	195/65 R15	MAXXIS	7 mm
R/H Rear Tyre	195/65 R15	MAXXIS	7 mm
L/H Rear Tyre	195/65 R15	MAXXIS	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/12/2017	Inspection Date	04/12/2017
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1404X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT O/S DOOR	DENTED	1,723.60	1,723.60
2	FRONT O/S DOOR HINGE @\$36.10	SERVICEABLE	72.20	-
1	REAR O/S DOOR	DENTED	2,017.48	2,017.48
2	REAR O/S DOOR HINGE @\$36.10	SERVICEABLE	72.20	-
	LESS 20% DISCOUNT		-777.10	-748.22
			3,108.38	2,992.86
SPECIAL NETT ITEMS				
1	SET O/S DOOR STICKER (SN)	NECESSARY	100.00	100.00
1	REAR O/S STICKER (SN)	NECESSARY	60.00	60.00
1	FRONT O/S FENDER STICKER (SN)	NOT NECESSARY	30.00	-
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			240.00	180.00
LABOUR				
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	160.00	-
	TO DISMANTLE AND REFIT THE INNER COMPONENT OF FRONT O/S DOOR INTO NEW SHELL DOOR.		150.00	50.00
	TO DISMANTLE AND REFIT THE INNER COMPONENT OF REAR O/S DOOR INTO NEW SHELL DOOR.		150.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE FRONT O/S FENDER, REAR O/S FENDER, REAR BUMPER, O/S ROCKER PANEL.		850.00	400.00
	TO PUTTY AND SPRAY PAINTING ON FRONT O/S FENDER, FRONT O/S DOOR, REAR O/S DOOR, O/S ROCKER PANEL, REAR O/S FENDER, REAR BUMPER, REAR O/S WHEEL RIM.		1,200.00	1,080.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		250.00	50.00
			2,760.00	1,630.00
GRAND TOTAL			6,108.38	4,802.86
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,800.00

Report Ref No. CC3/CT117023062/K1ea3n2



Report Ref No. CC3/CTI17023062/K1ea3n2

A handwritten signature in black ink, appearing to be 'W' followed by a stylized 'A'.

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

A handwritten signature in black ink, appearing to be 'Ho Leong Chuan'.

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.