

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

4-Dec-17

China

ESTIMATE REPAIR BILL FOR HYUNDAI I30A REGN NO: SHD 1404 X

1 pc	Front o/s door ✓	\$	1,723.60
2 pcs	Front o/s door hinge @\$36.10 X	\$	72.20
1 pc	Rear o/s door ✓	\$	2,017.48
2 pcs	Rear o/s door hinge @\$36.10 X	\$	72.20
		\$	3,885.48
	Less 20%	\$	777.10
		\$	3,108.38

S/NETT

1 set	o/s door sticker ✓	\$	100.00
1 pc	Rear o/s sticker ✓	\$	60.00
1 pc	Front o/s fender sticker X not necessary	\$	30.00
	Sundry	\$	50.00 20
	To check wheel alignment	\$	160.00 X
	To dismantle and refit the inner component of Front o/s door into new shell door	\$	150.00 50
	To dismantle and refit the inner component of Rear o/s door into new shell door	\$	150.00 50
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s fender, rear o/s fender, rear bumper, o/s rocker panel	\$	850.00 400
	To putty and spray painting on front o/s fender, front o/s door, rear o/s door, o/s rocker panel, rear o/s fender, rear bumper, Rear o/s wheel Rim	\$	1,200.00 1080
	To apply rustproofing on the repaired and replaced panels.	\$	250.00 50
		\$	6,108.38

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify

the Reparer of the following

• To resurvey damaged parts during resurvey

• To display damaged parts during resurvey

• This is on a "Without Prejudice" basis

• No illegal modification is allowed

• Supplementary items must be resurveyed and

is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kalvin (LKK)
4/12/17 135hrs
3 Reps
P/P
Before Part & photo