

SIN 2005

REF:

NS/INC17033063 / SH62

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

SU 1405E

Policy No.

50454644542 30.10.17 - 29.10.18

Claims No.

MT/097243-003

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNC 4561K

Yr Regn:

8/7/2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius.

cc 1798

Colour

Maroon.

A/C:

Insured / Std / NI / NA

Sp. Reading

No Display

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKN3CU405748677

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 175/65R15

R:

4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fallen

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

1/12/2017

D.O.I.

4/12/2017

Survey held at

SMR

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

SNC 4561K - NA / ALB17033063 / 13

DCA: 011017

TAX / 12 / 17 / 2006

SU 1405E - NF / DIS614620054 / 64

DCA: 251014

LKK

NTUC.

Lump Sum \$18,600/- (Red: 12816.66 40%)

RECEIVED

Date/Time, File Pass to?



Preli. Report

1) 11/11/2017



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 16

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$

) \$ + RS. SI



Interview (\$

) Photos



Tech. Invs (\$

) Others



Weekend (\$

)

Report Format:

TP

Lump Sum / I.B.I. (\$

18,600/-

TOTAL

195



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17023063/Stb				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 05-12-2017	
			Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJU 1405E	Veh. Inspected	SHC 4561K	
Policy No.	5095464542	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	04/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/12/2017	Inspection Date	04/12/2017	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Denise Tay (LKKAuto)

From: mtreg <mtreg@income.com.sg>
Sent: Monday, 8 January, 2018 12:32 PM
To: Denise Tay (LKKAuto)
Subject: FW: REQUEST CLAIM NUMBER

Hi,

All claims created.

With Regards

Samsia
Senior Admin Assistant, Motor Insurance
www.income.com.sg



From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: Monday, January 08, 2018 11:54 AM
To: mtreg <mtreg@income.com.sg>
Subject: REQUEST CLAIM NUMBER

Dear Sir,

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Da
1	MT/0962198-003	SMRT TAXIS PTE LTD	SHB 380Y	SJH 7428T	
2	MT/0972413-003	SMRT TAXIS PTE LTD	SHC 4561K	SJU 1405E	
3	MT/0974252-002	SMRT TAXIS PTE LTD	SHB920P	SGL 7859Y	
4	MT/0974178-002	SMRT TAXIS PTE LTD	SHF 18Z	PC 1481H	
5	MT/0976742-001	SMRT TAXIS PTE LTD	SHC 4989K	SHC 6941J	

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.

Date of Accident

01/12/2017 15:13

Vehicle No.(For Motor)

SJU1405E

Search

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5095464542	TW PREMIUM AUTOMOBILE PTE LTD	201320430G	GPC	Third Party	SJU1405E	SJU1405E	30/10/2017	29/10/2018

Continue

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/12/2017 11:00
Date Of Accident	01/12/2017 17:00
Exact Location Of Accident	ECP TOWARDS CHANGI BEFORE MARINE PARADE EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4561K
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	
Driver	
Name of Driver	TAN ENG SENG
NRIC No	S1618601E
Date Of Birth	27/03/1963
Occupation	OUTDOOR
Date Of Driving Pass	01/06/1996
Driving Experience	21 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name PUNGGOL N.P.C
 Police Station Address ROAD: 21A TEBING LANE , POSTCODE: 828837 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT - T/20171202/2025 On 01/12/2017 at about 1700hrs, I was driving my taxi (SHC4561K0 travelling on the lane 1 along ECP expressway towards Changi Airport. While travelling the vehicle (SGL8291U) in front of me were slowing down as such it causes me to slow down too. This resulted in a 4-car chain accident, I do not know the order of collision because it happened too fast. It is a fact that a vehicle (SJU1405E) from the back collided onto the rear portion of my vehicle, the impact was too strong as such it causes me to collide onto the front vehicle (SLG8291U) which I cannot be at fault. The vehicle (SLG8291U) then collided onto the vehicle (SGT4605R) in front of him. I wish to inform that there were a total of 4 vehicle including mine involved in the chain collision accident.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJU1405E
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver ZHUO RONG ZHEN
 NRIC/Passport Number S8307290C
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLG8291U

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver CHAN SG

NRIC/Passport Number S0176224I

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SGT4605R

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver DAVID WANG

NRIC/Passport Number S7897032D

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name UNKNOWN PASSENGER

Approximate Age

Injuries Sustain

Injured person in which vehicle? SJU1405E

Were seat belts worn?

Was injured conveyed to hospital by ambulance? YES

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN

EXIT 10B

MAINE PARADE

ECP CHANGI AIRPORT

D - SGT 4605R
C - SGT 2291U
A - SMC 4561K
B - SJA 1405E


D
C
A
B

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT - 7/2017/202/2025

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

QATAR CHANGI AIRPORT



**SINGAPORE
POLICE FORCE**



T/20171202/2025

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

1 of 4

Report No. T/20171202/2025

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 02/12/2017 09:18	Vide Report No.: G/20171201/0166	Station Diary No.: 27
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: TAN ENG SENG			Address: APT BLK 107D EDGEFIELD PLAINS #14-136 SINGAPORE 824107		
ID Type / ID No.: NRIC NO / S1618601E			Contact No.: Home/Office: Mobile: 91128256		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 54	Date of Birth: 27/03/1963	Type of Informant: Driver		
Race: Chinese			Language:	Institution / School Name:	
Occupation: Taxi driver			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 01/12/2017 17:00	Type of Location: Straight Road
Location: Along Road 1 EAST COAST EXPRESSWAY				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SGT4605R	Car					1
SHC4561K	Car					0
SJU1405E	Car					4
SLG8291U	Car					0



**SINGAPORE
POLICE FORCE**



T/20171202/2025

2 of 4

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

Report No. T/20171202/2025

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	DAVID WANG	ID No.	S7897032D
Related Vehicle	SGT4605R (Car)	Contact No.	90094508
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TAN ENG SENG	ID No.	S1618601E
Related Vehicle	SHC4561K (Car)	Contact No.	91128256
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	ZHUO RONG ZHEN	ID No.	S8307290C
Related Vehicle	SJU1405E (Car)	Contact No.	86932883
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL



**SINGAPORE
POLICE FORCE**



T/20171202/2025

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

3 of 4

Report No. T/20171202/2025

CONTINUATION OF REPORT

Driver			
Name	CHAN SG	ID No.	S0176224I
Related Vehicle	SLG8291U (Car)	Contact No.	97393697
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 01/12/2017 at about 1700hrs, I was driving my taxi (SHC4561K) traveling on the lane 1 along ECP express way towards Changi Airport. While travelling the vehicle (SLG8291U) in front of me were slowing down as such it causes me to slow down too. This resulted in a 4-car chain accident, I do not know the order of collision because it happened too fast. It is a fact that a vehicle (SJU1405E) from the back collided onto the rear portion of my vehicle, the impact was too strong as such it causes me to collide onto the front vehicle (SLG8291U) which I cannot be at fault. The vehicle (SLG8291U) then collided onto the vehicle (SGT4605R) in front of him. I wish to inform that there were a total of 4 vehicle including mine involved in the chain collision accident.

I then get off from my vehicle and took pictures of the accident. I also exchange the other driver's particulars. I also wish to inform that police attended vide incident report number G/20171201/0166 the scene and the driver from SLG8291U and a passenger from SJU1405E were conveyed by ambulance to the nearest hospital. I also wish to inform that I have a THIRD PARTY EYE WITNESS, however I only have his particulars such as him name Imran and C/N: 82992269.

First and foremost, the video clips I provided to the Traffic Police would be able to determine I was neither tailgating nor driving beyond the speed limit of Express Way. However, it would be safe to assume that before my taxi (SHC4561K) collided with SLG8291U, my vehicle is at a speed of near-stop or stop position base on the following two evidents :

Evident One - The Third Party Eye Witness Mr Imran, is able to testify that it was SJU1405E which collided into my rear, plunging my taxi forward to hit the front vehicle SLG8291U.

Evident Two - The minor damage on the front of my taxi indicated that my car was either at near-stop or stopped position, otherwise the damage would be a lot more severe. It would seems to implied that the collision force came from my rear being rammed pushing my car forward.



**SINGAPORE
POLICE FORCE**



T/20171202/2025

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

4 of 4

Report No. T/20171202/2025

CONTINUATION OF REPORT


Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgt 2 KOH JING LI	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 02/12/2017 09:18
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt ONG YONG HOCK Contact No.: 65476436	Classification Of Case:
Authentication Stamp NP168	

Accident Photo



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	5369K

Vehicle Details

Vehicle No.	SHC4561K
Vehicle to be Exported	No
Intended De-registration Date	05 Dec 2017
Vehicle Make	TOYOTA
Vehicle Model	PRIUS TAXI (SMRT)
Primary Colour	Maroon
Manufacturing Year	2014
Engine No.	2ZR6128515
Chassis No.	JTDKN36U405748677
Maximum Power Output	100.0 kW (134 bhp)
Open Market Value	\$32,920.00
Original Registration Date	08 Sep 2014
First Registration Date	08 Sep 2014
Transfer Count	0
Actual ARF Paid	\$8,088.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	07 Sep 2022
PARF Rebate Amount	\$6,066.00

Intended COE Rebate Details

COE Expiry Date	07 Sep 2022
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	8
PQP Paid	\$50,704.00
COE Rebate Amount	\$30,140.00
Total Rebate Amount	\$36,206.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 05 Dec 2017

OK



Please read through the Privacy Statement, Terms of Use, and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 19 Nov 2017 at 12:12 AM

18-12-17 / 13:00


19-12-17 / 08:00

54-12-17 / 08:00

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SJC4561K
 Ref. No : TAX/12/17/2006
 Reg. Date : 08/09/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : TAN ENG SENG
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 01/12/2017 05:00:00 PM
 Accident Reported Date / Time : 02/12/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Sebastian
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 01/12/2017
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024093404
 Special Instruction to ARC, if any :



TOWED \$80 / SJU1405E NTUC 4S
 AFTER PAINT PHOTO, LUMP SUM REPAIR, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
 SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang @lkkauto.com HP:90036121

Prepared Date : 02/12/2017 11:31:35 AM

Shun.

26/12/17 11:00 Pass

439823
 439790

Recording Camera

☐
☒

Radio Antenna

☐
☒

1st witness

Date

4-12-17

2nd witness

Date

1 1/2 2 3/4

Supplementary

+ Refer to the Supplementary part list

Qc 23/12/17 10:00 Reject

FR Lower Grille Paint Peel LEE SHENG AUTO PTE LTD

hood Hinge L&R Adjust

Vehicle Return Date:

26/12/17


RR Bumper Paint Peel

Vehicle Return Time:

10 26

Tail Gate

SMRT staff sign:



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U405748677

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 2,704.00	1,900.00
Total Spray Painting Charges	: 6,282.00	2,500.00
Total Material Charges	: 26,189.26	17,542.15
Other Charges	: 2,890.00	-3,342.15
TOTAL	: 38,065.26	18,600.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 16.00	16.00 /
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	: 04/12/2017 01:57:19 AM	04/12/2017 04:48:01 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 04/12/2017 01:57:19 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1712-0757

Invoice No :

Quotation Date : 29/12

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 12/4/2017 1:56:52 PM

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	676.00	300.00 /
TO REPAIR REAR PORTION	2,028.00	1,600.00 /
Total Labour	2,704.00	1,900.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	200.00 /
TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	100.00 /
TO REPSRAY FRONT HOOD	378.00	200.00 /
TO RESPRAY FRONT SUPPORT PANEL	180.00	100.00 /
TO RESPRAY FRONT FENDER LH	378.00	0.00
TO RESPRAY REAR DOOR LH	378.00	200.00 /
TO RESPRAY REAR DOOR RH	378.00	200.00 /
TO RESPRAY LH RAIL ROOF SIDE	180.00	100.00 /
TO RESPRAY TROUGH BACK DOOR LH	180.00	50.00 /
TO RESPRAY TROUGH BACK DOOR RH	180.00	50.00 /
TO RESPRAY REAR RH WHEEL HOUSE	180.00	100.00 /
TO RESPRAY REAR LH WHEEL HOUSE	180.00	100.00 /
TO RESPRAY REAR FENDER RH	378.00	200.00 /
TO RESPRAY REAR FENDER LH	378.00	200.00 /
TO RESPRAY FUEL LID COVER	180.00	0.00
TO RESPRAY TAIL GATE	378.00	200.00 /
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100.00 /
TO REPSRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY BUMPER BEAM	180.00	100.00 /
TO RESPRAY REAR PANEL	180.00	100.00 /
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00
TO RESPRAY REAR CHASSIS LH	180.00	0.00
TO RESPRAY REAR CHASSIS RH	180.00	0.00
TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0.00
TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0.00
Total Spray Painting & Panel Beating	6,282.00	2,500.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

b4623-38

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	40.00 /
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60.00 /
TO REMOVE & REFIT EXHAUST	120.00	0.00
TO REMOVE & REFIT ROOF LINING	120.00	40.00 /
TO ALIGN CHASSIS	350.00	200.00 /
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	250.00	250.00 /
TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	30.00 /
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	30.00 /
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	160.00 /
TO TRANSFER REAR TAILGATE MECHANISM	120.00	50.00 /
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 /
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	40.00 /
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	40.00 /
REMOVE AND REPLACE BOTH RR EXHAUST MUFFLER	120.00	50.00 /
TO REMOVE AND REFIT TYRE	240.00	60.00 /
TO REMOVE AND REFIT BATTERY ASSY HV	250.00	180.00 /
TO REPLACE SUNDRY PARTS	100.00	20.00 /
TO WASH AND VACUUM	60.00	0.00
TO REMOVE / REFIT SEAT	120.00	50.00 /
Lump Sum Adjustment by Surveyor	0.00	-4,672.15
Total Other Costs	2,890.00	-3,342.15

11826

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace	No	✓ MN
90467-07211			BUMPER CLIPS	10	2.10 (21)	25.00	15.75	Replace	Replace	No	✓ NEC
52116-47040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Check	No	X AN
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace	Check	No	X AN
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace S	No	✓ CRK
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Check	No	X
57014-47030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80	Replace	Check	No	X AN
57013-47030			ARM SUB-ASSY, FR BUMPER RH	1	250.40	25.00	187.80	Replace	Check	No	X AN
52114-47140			BRACKET, FR BUMPER	1	110.40	25.00	82.80	Replace	Replace S	No	✓ CRK
			NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace	No	✓ DT
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace	No	✓ CRK
52128-47903			COVER, FR BUMPER HOLE LH	1	18.50	25.00	13.87	Replace	Replace	No	✓ MS
52127-47903			COVER, FR BUMPER HOLE RH	1	18.50	25.00	13.87	Replace	Replace	No	✓ MS
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.33	Replace	Replace S	No	✓ CRK
81521-47050			LENS & BODY, FR TURN LH	1	511.80	10.00	460.62	Replace	Check	No	X AN
81511-47050			LENS & BODY, FR TURN RH	1	511.80	10.00	460.62	Replace	Check	No	X AN
75310-47010		6505638	EMBLEM FRONT	1	66.50	25.00	64.87	Replace	Replace	No	✓ NEC
53111-47040		6505573	GRILLE, RADIATOR	1	310.60	25.00	232.95	Replace	Check	No	X AN
53113-47040			GRILLE RADIATOR LOWER NO.2	1	94.60	25.00	70.95	Replace	Replace S	No	✓ CRK
52618-47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.78	Replace	Replace S	No	Defect CRK
51410-12105			UNDER COVER CENTER	1	448.30	25.00	336.23	Replace	Replace S	No	✓ CRK
53301-47060		6505555	HOOD PANEL	1	748.10	100.00	0.00	Replace	Repair	No	R
53420-47070			HOOD HINGE LH	1	55.90	25.00	41.93	Replace	Replace S	No	✓
53410-47070			HOOD HINGE RH	1	55.90	25.00	41.93	Replace	Replace S	No	✓ B7
53510-47102			HOOD LOCK	1	128.90	25.00	96.68	Replace	Check	No	X AN
53201-47902			SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Check	No	X AN
81170-47500		6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Replace S	No	✓ CRK
53802-47050		6505558	FENDER FRT/LH	0	723.40	25.00	0.00	Replace	Not given	No	X AN
75374-47051			NAME PLATE (HYBRID)	0	51.90	25.00	0.00	Replace	Not given	No	X AN

8080-30

Page:

5

2309.5

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
53876-47030		6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace	No ✓ <i>IN</i>
53852-47020			FENDER LINER PAD, FR WHEEL LH	1	49.30	25.00	36.98	Replace	Check	No X <i>NN</i>
67004-47080		6505487	DOOR RR/LH	1	954.50	100.00	0.00	Replace	Repair	No R
61218-47010			RAIL, ROOF SIDE LH	1	273.60	100.00	0.00	Replace	Repair	No R
61712-47020			PANEL, ROOF SIDE OUTER LH	1	134.80	100.00	0.00	Replace	Repair	No R
61734-47020			PANEL, ROOF SIDE,	1	134.80	100.00	0.00	Replace	Repair	No R
61732-47030			PANEL, ROOF SIDE, INNER LH	1	134.80	100.00	0.00	Replace	Repair	No R
61714-47020			REINFORCE, ROOF SIDE OUTER LH	1	91.90	100.00	0.00	Replace	Repair	No R
61744-47010			REINFORCEMENT, BACK DOOR SIDE LH	1	89.50	25.00	67.13	Replace	Check	No X
61624-47010			EXTENSION, QUARTER PANEL FRONT LH	1	83.50	25.00	62.63	Replace	Check	No X
6162647020			EXTENSION, QUARTER PANEL REAR LH	1	108.50	10.00	97.65	Replace	Check	No X
61738-47020			REINFORCEMENT, ROOF SIDE INNER LH	1	60.30	25.00	45.23	Replace	Check	No X
61608-47061			PANEL SUB-ASSY, QTR WHEEL HOUSE	1	588.40	25.00	441.30	Replace	Check	No X
61606-47010			PANEL, QUARTER WHEEL HOUSE, OUTER LH	1	326.70	25.00	245.03	Replace	Check	No X
61602-47091		6505476	FENDER RR/LH	1	766.80	25.00	575.10	Replace	Replace	No ✓ <i>DT</i>
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace	No ✓
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No ✓
62720-47031			QUARTER GLASS RR/LH	1	168.10	25.00	126.07	Replace	Replace	No ✓ <i>NE</i>
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace	No ✓
65638-47021		6505477	FENDER LINER RR/LH	1	141.30	25.00	105.97	Replace	Replace	No ✓ <i>TW</i>
		6503707	TYRE	1	126.74	0.00	126.74	Replace	Replace	No ✓ <i>MW</i>
81561-47170		6505461	TAIL LAMP LH	1	548.40	10.00	493.56	Replace	Replace	No ✓ <i>CR</i>
52563-47010			TAIL LAMP BRACKET, LH	1	30.70	25.00	23.02	Replace	Replace	No ✓
62940-16060			DUCT ASSY, QUARTER	1	70.40	25.00	52.80	Replace	Replace	No ✓ <i>Def</i>
77350-47030			LID ASSY, FUEL	1	102.00	25.00	76.50	Replace	Check	No X
77226-47040			TUBE, FUEL TANK	1	36.10	25.00	27.08	Replace	Check	No X
77035-47090			CABLE SUB-ASSY, FUEL LID	1	63.90	25.00	47.93	Replace	Check	No X
77377-75010			RETAINER, FUEL LID CABLE	1	5.90	25.00	4.43	Replace	Check	No X <i>N</i>
77201-47250			PIPE SUB-ASSY, FUEL NECK	1	230.80	25.00	173.10	Replace	Check	No X

5559.26

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached	
23814-37061			PIPE, FUEL DELIVERY	1	186.10	25.00	139.58	Replace	Check	No X	MM
67005-47241			TAILGATE ASY	1	1,007.90	25.00	755.92	Replace	Replace	No	BT
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25.00	22.05	Replace	Replace	No	
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25.00	22.05	Replace	Replace	No	
75575-47030			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25.00	22.05	Replace	Replace	No	
	COMMO N		SEALANT W/SCREEN	3	37.00 (111)	0.00	111.00	Replace	Replace	No	
69350-47030			TAILGATE DOOR LOCK	1	444.10	25.00	333.07	Replace	Replace	No	DMF
69415-47020			TAILGATE LOCK, COVER	1	15.70	25.00	11.77	Replace	Replace	No	NEC
69431-47010			STRIKER, BACK DOOR	1	48.90	25.00	36.67	Replace	Replace	No	BT
67881-47022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Replace	No	NEC
67938-47031C0			TAILGATE TRIM, LH	1	85.90	25.00	64.43	Replace	Check	No X	
67937-47031C0			TAILGATE TRIM, RH	1	88.30	25.00	66.23	Replace	Check	No X	
67751-47040C0			TAILGATE TRIM, LOWER	1	180.70	25.00	135.53	Replace	Check	No X	
64790-47030C0			TAILGATE TRIM, UPPER	1	49.60	25.00	37.20	Replace	Check	No X	
67750-47071C0			TAILGATE, BOARD ASSY	1	246.90	25.00	185.18	Replace	Replace S	No	Def
76801-47070-B0			TAILGATE OUTSIDE GARNISH	1	504.90	100.00	0.00	Replace	Repair	No	R
75310-47020		6505639	EMBLEM REAR	1	60.30	25.00	45.22	Replace	Replace	No	
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No	
75442-47030			NAME PLATE (PRIUS)	1	60.80	25.00	45.60	Replace	Replace	No	MM
75443-47030			NAME PLATE (TOYOTA)	1	51.90	25.00	38.92	Replace	Replace	No	
	REAR		NUMBER PLATE	0	30.00	0.00	0.00	Replace	Not given	No X	MM
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace	No	CMF
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace	No	
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No	NEC
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No	CRK
			PIXEL STICKER	2	60.00 (120)	0.00	120.00	Replace	Replace	No	NEC
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace	No	BT
52018-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace S	No	
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace S	No	BT

1721.00

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached	
89997-30070			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10.00	141.66	Replace	Replace <i>S</i>	No <i>/</i>	<i>DMG</i>
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No <i>/</i>	<i>DMG</i>
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No <i>/</i>	<i>CR</i>
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	No <i>/</i>	<i>CR</i>
52592-47021			BUMPER SEAL, RR LH	1	88.90	25.00	66.68	Replace	Replace <i>S</i>	No <i>/</i>	<i>CRK</i>
52591-47021			BUMPER SEAL, RR RH	1	65.70	25.00	49.28	Replace	Check	No <i>X</i>	<i>nn</i>
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace	No <i>/</i>	<i>qy</i>
76087-47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57	Replace	Replace	No <i>/</i>	<i>qy</i>
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No <i>/</i>	<i>qy</i>
58308-47011			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	25.00	385.87	Replace	Replace	No <i>/</i>	<i>qy</i>
58307-47060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace	No <i>/</i>	<i>DT</i>
64718-47031B0			END PANEL COVER, DECK TRIM HOLE	1	46.10	25.00	34.58	Replace	Replace <i>S</i>	No <i>/</i>	<i>Def</i>
64716-47031B0			END PANEL COVER, DECK TRIM, RR	1	121.10	25.00	90.83	Replace	Replace <i>S</i>	No <i>/</i>	<i>Def</i>
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No <i>/</i>	<i>NEC</i>
64993-47020			BOX, DECK FLOOR, RR	1	649.70	25.00	487.28	Replace	Replace <i>S</i>	No <i>/</i>	<i>Def</i>
58416-47030B3			BOX, RR FLOOR, BOARD	1	679.60	25.00	509.70	Replace	Check	No <i>X</i>	<i>nn</i>
64997-47020			BOX, DECK FLOOR, LH	1	196.80	25.00	147.60	Replace	Replace <i>S</i>	No <i>/</i>	<i>Def</i>
58418-47070B0			BOX, DECK FLOOR, COVER LH	1	230.10	25.00	172.58	Replace	Check	No <i>X</i>	<i>nn</i>
64740-47031B2			PANEL ASSY, DECK LH	1	307.00	25.00	230.25	Replace	Replace <i>S</i>	No <i>/</i>	<i>Def</i>
64730-47031B2			PANEL ASSY, DECK RH	1	307.00	25.00	230.25	Replace	Replace <i>S</i>	No <i>/</i>	<i>Def</i>
58311-47071		6505523	SPARE TYRE PANEL	1	667.70	25.00	500.78	Replace	Replace <i>S</i>	No <i>/</i>	<i>Def</i>
64777-47090			CUSHION, SPARE WHEEL	1	230.80	25.00	173.10	Replace	Check	No <i>X</i>	<i>nn</i>
51931-47020			CARRIER, SPARE	1	19.70	25.00	14.78	Replace	Check	No <i>X</i>	<i>nn</i>
64778-47050			PROTECTOR, SPARE	1	143.70	25.00	107.78	Replace	Replace <i>S</i>	No <i>/</i>	<i>Def</i>
57604-47030			MEMBER SUB-ASSY, RR LH	1	174.10	25.00	130.58	Replace	Replace <i>S</i>	No <i>/</i>	<i>DT</i>
57603-47030			MEMBER SUB-ASSY, RR RH	1	174.10	25.00	130.58	Replace	Replace <i>S</i>	No <i>/</i>	<i>DT</i>
58303-47301			FLOOR PANEL RR/LH	1	102.00	25.00	76.50	Replace	Replace <i>S</i>	No <i>/</i>	<i>Def</i>
58302-47030			FLOOR PANEL RR/RH	1	209.90	25.00	157.43	Replace	Check	No <i>X</i>	<i>nn</i>
58336-12090			REINFORCEMENT, RR	2	34.60	25.00	51.90	Replace	Check	No <i>X</i>	<i>nn</i>
61605-47010			PANEL SUB-ASSY, QTR	1	326.70	25.00	245.03	Replace	Check	No <i>X</i>	<i>nn</i>

6909.20

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
62940-16060			DUCT ASSY, QUARTER	1	70.40	25.00	52.80	Replace	Replace	No
61604-47090			FENDER RR/RH	1	766.80	25.00	575.10	Replace	Replace	No
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace	No
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No
62710-47130			QUARTER GLASS RR/RH	1	846.50	25.00	634.87	Replace	Replace	No
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace	No
61621-47030			TROUGH, BACK DOOR	1	110.90	25.00	83.18	Replace	Check	No X
81551-47180		6505462	TAIL LAMP RH	1	557.80	10.00	502.02	Replace	Check	No X
52562-47010			TAIL LAMP BRACKET, RH	1	30.70	25.00	23.03	Replace	Check	No X
		6503707	TYRE	0	126.74	0.00	0.00	Replace	Not given	No X
67003-47080		6505486	DOOR RR/RH	1	954.50	100.00	0.00	Replace	Repair	No R
58327-47020			EXHAUST HEAT SHIELD, REAR	1	107.40	25.00	80.55	Replace	Check	No X
17430-37380			EXHAUST TAIL PIPE	1	656.20	25.00	492.15	Replace	Check	No X
17565-22030			SUPPORT, EXHAUST REAR	2	33.60	25.00	50.40	Replace	Check	No X
69060-47080			DOOR LOCK RR/LH	1	709.30	25.00	531.98	Replace	Check	No X
69050-47080			DOOR LOCK RR/RH	1	709.30	25.00	531.98	Replace	Check	No X
76851-47020		6505616	BUMPER LIP FRT	1	139.60	25.00	104.70	Replace	Replace S	No
G9510-47060			BATTERY ASSY, HV	1	5,544.40	10.00	4,989.96	Replace	Replace S	No
58651-22H91			INSULATOR SHEET	3	170.00	25.00	382.50	Replace	Replace S	No
G3834-48010			GRIP, SERVICE PLUG	1	52.00	25.00	39.00	Replace	Replace S	No
TOTAL MATERIALS					12026.44		26,189.36	17,542.15		
TOTAL MATERIALS(Discounted)							26,189.26	17,542.15		

Added Spare Parts / Material Usage After Surveyor Signed off

6845.33

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
76851-47020		BUMPER LIP FRT	1	139.60	25.00	104.70	Replace	Replace	No
39510-47060		BATTERY ASSY, HV	1	5,544.40	10.00	4,989.96	Replace	Replace	No
58651-22H91		INSULATOR SHEET	3	170.00	25.00	382.50	Replace	Replace	No
33834-48010		GRIP, SERVICE PLUG	1	52.00	25.00	39.00	Replace	Replace	No
TOTAL SUPPLEMENTARY MATERIALS						5,516.16			

17,542.15
 + 1,900.00
 + 3,830.00

 23,272.15
 - 202

18,617.66
 45 \$18,600/-


Sebastian
 8/11/18

SMRT Accident Vehicle Repair Estimates

NTUC

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4561K
 Ref. No : TAX/12/17/2006
 Reg. Date : 08/09/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : TAN ENG SENG
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 01/12/2017 05:00:00 PM
 Accident Reported Date / Time : 02/12/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 01/12/2017
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024093404
 Special Instruction to ARC, if any :
 TOWED \$80 / SJU1405E
 Prepared Date : 02/12/2017 11:31:35 AM



Sebastian .
4/12/2017 .

- Lump Sum Repair .
- Question Mark Item
- Photo
- Photo After Paint .

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U405748677

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 2,704.00	0.00
Total Spray Painting Charges	: 6,282.00	0.00
Total Material Charges	: 19,428.66	19,428.66
Other Charges	: 3,002.00	0.00
TOTAL	: 31,416.66	0.00
Lum Sum Total	: 31,400.00	0.00
No. of Repair Days	: 16.00	0.00
Prepared / Adjusted By	:	12 days
Arc / Surveyor Sign Off Date	: 04/12/2017 01:57:19 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 04/12/2017 01:57:19 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 12/4/2017 1:56:52 PM

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	676.00	0.00 200
TO REPAIR REAR PORTION	2,028.00	0.00 1600
Total Labour	2,704.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0.00 100
TO REPSRAY FRONT HOOD	378.00	0.00 200
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00
TO RESPRAY FRONT FENDER LH	378.00	0.00 X
TO RESPRAY REAR DOOR LH	378.00	0.00 200
TO RESPRAY REAR DOOR RH	378.00	0.00 200
TO RESPRAY LH RAIL ROOF SIDE	180.00	0.00 100
TO RESPRAY TROUGH BACK DOOR LH	180.00	0.00 50
TO RESPRAY TROUGH BACK DOOR RH	180.00	0.00 50
TO RESPRAY REAR RH WHEEL HOUSE	180.00	0.00 100
TO RESPRAY REAR LH WHEEL HOUSE	180.00	0.00 100
TO RESPRAY REAR FENDER RH	378.00	0.00 200
TO RESPRAY REAR FENDER LH	378.00	0.00 200
TO RESPRAY FUEL LID COVER	180.00	0.00 X
TO RESPRAY TAIL GATE	378.00	0.00 200
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 100
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 100
TO RESPRAY REAR PANEL	180.00	0.00 100
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00
TO RESPRAY REAR CHASSIS LH	180.00	0.00
TO RESPRAY REAR CHASSIS RH	180.00	0.00
TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0.00
TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0.00
Total Spray Painting & Panel Beating	6,282.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	112.00	0.00 X
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 40
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 60
TO REMOVE & REFIT EXHAUST	120.00	0.00 X
TO REMOVE & REFIT ROOF LINING	120.00	0.00 40
TO ALIGN CHASSIS	350.00	0.00 200
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	250.00	0.00 ✓
TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	0.00 30
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0.00 30
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00 160
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 50
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 40
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 40
REMOVE AND REPLACE BOTH RR EXHAUST MUFFLER	120.00	0.00 50
TO REMOVE AND REFIT TYRE	240.00	0.00 60
TO REMOVE AND REFIT BATTERY ASSY HV	250.00	0.00 180
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
TO REMOVE / REFIT SEAT	120.00	0.00 50
Total Other Costs	3,002.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace ✓ <i>TW</i>	No
90467-07211			BUMPER CLIPS	10	2.10	25.00	15.75	Replace	Replace ✓ <i>ARC</i>	No
52116-47040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace ?	No
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace	Replace ?	No
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace ?	No
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace ?	No
57014-47030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80	Replace	Replace ?	No
			1234	1	0.00	0.00	0.00	Replace	Replace X	No
52114-47140			BRACKET, FR BUMPER	1	110.40	25.00	82.80	Replace	Replace ?	No
			NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace ✓ <i>DT</i>	No
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace ✓ <i>cek</i>	No
52128-47903			COVER, FR BUMPER HOLE LH	1	18.50	25.00	13.87	Replace	Replace ✓ <i>ms</i>	No
52127-47903			COVER, FR BUMPER HOLE RH	1	18.50	25.00	13.87	Replace	Replace ✓ <i>ms</i>	No
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.32	Replace	Replace ?	No
81521-47050			LENS & BODY, FR TURN LH	1	511.80	10.00	460.62	Replace	Replace ?	No
81511-47050			LENS & BODY, FR TURN RH	1	511.80	10.00	460.62	Replace	Replace ?	No
75310-47010		6505638	EMBLEM FRONT	1	86.50	25.00	64.87	Replace	Replace ✓ <i>ARC</i>	No
53111-47040		6505573	GRILLE, RADIATOR	1	310.60	25.00	232.95	Replace	Replace ?	No
53113-47040			GRILLE RADIATOR LOWER NO.2	1	94.60	25.00	70.95	Replace	Replace ?	No
52618-47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.77	Replace	Replace ?	No
51410-12105			UNDER COVER CENTER	1	448.30	25.00	336.22	Replace	Replace ?	No
53301-47060		6505555	HOOD PANEL	1	748.10	25.00	561.07	Replace	Replace R	No
53420-47070			HOOD HINGE LH	1	55.90	25.00	41.92	Replace	Replace X	No
53410-47070			HOOD HINGE RH	1	55.90	25.00	41.92	Replace	Replace X	No
53510-47102			HOOD LOCK	1	128.90	25.00	96.67	Replace	Replace ?	No
53201-47902			SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Replace ?	No
31170-47500		6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Replace ?	No
53802-47050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace X	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace X	No

Part Number	Location	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
53876-47030		6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace ✓ TN	No
53852-47020			FENDER LINER PAD, FR WHEEL LH	1	49.30	25.00	36.97	Replace	Replace ?	No
67004-47080		6505487	DOOR RR/LH	1	954.50	25.00	715.88	Replace	Replace R	No
61218-47010			RAIL, ROOF SIDE LH	1	273.60	25.00	205.20	Replace	Replace R	No
61712-47020			PANEL, ROOF SIDE OUTER LH	1	134.80	25.00	101.10	Replace	Replace R	No
61734-47020			PANEL, ROOF SIDE,	1	134.80	25.00	101.10	Replace	Replace R	No
61732-47030			PANEL, ROOF SIDE, INNER LH	1	134.80	25.00	101.10	Replace	Replace R	No
61714-47020			REINFORCE, ROOF SIDE OUTER LH	1	91.90	10.00	82.71	Replace	Replace R	No
61744-47010			REINFORCEMENT, BACK DOOR SIDE LH	1	89.50	25.00	67.12	Replace	Replace ?	No
61624-47010			EXTENSION, QUARTER PANEL FRONT LH	1	83.50	25.00	62.62	Replace	Replace ?	No
6162647020			EXTENSION, QUARTER PANEL REAR LH	1	108.50	10.00	97.65	Replace	Replace ?	No
61738-47020			REINFORCEMENT, ROOF SIDE INNER LH	1	60.30	25.00	45.22	Replace	Replace ?	No
61622-47030			TROUGH, BACK DOOR LH	1	110.90	10.00	99.81	Replace	Replace ?	No
61608-47061			PANEL SUB-ASSY, QTR WHEEL HOUSE	1	588.40	25.00	441.30	Replace	Replace ?	No
61606-47010			PANEL, QUARTER WHEEL HOUSE, OUTER LH	1	326.70	25.00	245.02	Replace	Replace ?	No
61602-47091		6505476	FENDER RR/LH	1	766.80	25.00	575.10	Replace	Replace ✓ DT	No
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace ✓ NEC	No
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓ NEC	No
62720-47031			QUARTER GLASS RR/LH	1	168.10	25.00	126.07	Replace	Replace ✓ NEC	No
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace ✓ NEC	No
35638-47021		6505477	FENDER LINER RR/LH	1	141.30	25.00	105.97	Replace	Replace ✓ TN	No
		6503707	TYRE	1	126.74	0.00	126.74	Replace	Replace / PUN	No
31561-47170		6505461	TAIL LAMP LH	1	548.40	10.00	493.56	Replace	Replace ✓ CRK	No
52563-47010			TAIL LAMP BRACKET, LH	1	30.70	25.00	23.02	Replace	Replace ✓ CRK	No
32940-16060			DUCT ASSY, QUARTER	1	70.40	25.00	52.80	Replace	Replace ✓ Defon.	No
77350-47030			LID ASSY, FUEL	1	102.00	25.00	76.50	Replace	Replace ?	No
77226-47040			TUBE, FUEL TANK	1	36.10	25.00	27.07	Replace	Replace ?	No
77035-47090			CABLE SUB-ASSY, FUEL LID	1	63.90	25.00	47.92	Replace	Replace ?	No
77377-75010			RETAINER, FUEL LID CABLE	1	5.90	25.00	4.42	Replace	Replace ?	No

Part Number	Location	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
77201-47250			PIPE SUB-ASSY, FUEL NECK	1	230.80	25.00	173.10	Replace	Replace ?	No
23814-37061			PIPE, FUEL DELIVERY	1	186.10	25.00	139.57	Replace	Replace ?	No
67005-47241			TAILGATE ASY	1	1,007.90	25.00	755.92	Replace	Replace ✓	No BT
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25.00	22.05	Replace	Replace ✓	No NEC
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25.00	22.05	Replace	Replace ✓	No NEC
75575-47030			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25.00	22.05	Replace	Replace ✓	No NEC
	COMMON		SEALANT W/SCREEN	3	37.00	0.00	111.00	Replace	Replace ✓	No NEC
69350-47030			TAILGATE DOOR LOCK	1	444.10	25.00	333.07	Replace	Replace ✓	No DMC
69415-47020			TAILGATE LOCK, COVER	1	15.70	25.00	11.77	Replace	Replace ✓	No NEC
69431-47010			STRIKER, BACK DOOR	1	48.90	25.00	36.67	Replace	Replace ✓	No BT
67881-47022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Replace ✓	No NEC
67938-47031C0			TAILGATE TRIM, LH	1	85.90	25.00	64.42	Replace	Replace ?	No
67937-47031C0			TAILGATE TRIM, RH	1	88.30	25.00	66.22	Replace	Replace ?	No
67751-47040C0			TAILGATE TRIM, LOWER	1	180.70	25.00	135.52	Replace	Replace ?	No
64790-47030C0			TAILGATE TRIM, UPPER	1	49.60	25.00	37.20	Replace	Replace ?	No
67750-47071C0			TAILGATE, BOARD ASSY	1	246.90	25.00	185.17	Replace	Replace ?	No
76801-47070-B0			TAILGATE OUTSIDE GARNISH	1	504.90	25.00	378.67	Replace	Replace R	No
75310-47020		6505639	EMBLEM REAR	1	60.30	25.00	45.22	Replace	Replace ✓	No NEC
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace ✓	No NEC
75442-47030			NAME PLATE (PRIUS)	1	60.80	25.00	45.60	Replace	Replace ✓	No NEC
75443-47030			NAME PLATE (TOYOTA)	1	51.90	25.00	38.92	Replace	Replace ✓	No NEC
	REAR		NUMBER PLATE	1	30.00	0.00	30.00	Replace	Replace X	No
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace ✓	No cut
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace ✓	No NEC
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓	No NEC
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace ✓	No CRK
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace ✓	No NEC
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace ✓	No BT
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace ?	No

Part Number	Location	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace	No
89997-30070			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10.00	141.66	Replace	Replace	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	No
52592-47021			BUMPER SEAL, RR LH	1	88.90	25.00	66.67	Replace	Replace	No
52591-47021			BUMPER SEAL, RR RH	1	65.70	25.00	49.27	Replace	Replace	No
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace	No
76087-47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57	Replace	Replace	No
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No
58308-47011			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	25.00	385.87	Replace	Replace	No
58307-47060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace	No
64718-47031B0			END PANEL COVER, DECK TRIM HOLE	1	46.10	25.00	34.57	Replace	Replace	No
64716-47031B0			END PANEL COVER, DECK TRIM, RR	1	121.10	25.00	90.82	Replace	Replace	No
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No
64993-47020			BOX, DECK FLOOR, RR	1	649.70	25.00	487.27	Replace	Replace	No
58416-47030B3			BOX, RR FLOOR, BOARD	1	679.60	25.00	509.70	Replace	Replace	No
64997-47020			BOX, DECK FLOOR, LH	1	196.80	25.00	147.60	Replace	Replace	No
58418-47070B0			BOX, DECK FLOOR, COVER LH	1	230.10	25.00	172.57	Replace	Replace	No
34740-47031B2			PANEL ASSY, DECK LH	1	307.00	25.00	230.25	Replace	Replace	No
34730-47031B2			PANEL ASSY, DECK RH	1	307.00	25.00	230.25	Replace	Replace	No
58311-47071		6505523	SPARE TYRE PANEL	1	667.70	25.00	500.77	Replace	Replace	No
34777-47090			CUSHION, SPARE WHEEL	1	230.80	25.00	173.10	Replace	Replace	No
51931-47020			CARRIER, SPARE	1	19.70	25.00	14.77	Replace	Replace	No
34778-47050			PROTECTOR, SPARE	1	143.70	25.00	107.77	Replace	Replace	No
57604-47030			MEMBER SUB-ASSY, RR LH	1	174.10	25.00	130.57	Replace	Replace	No
57603-47030			MEMBER SUB-ASSY, RR RH	1	174.10	25.00	130.57	Replace	Replace	No
58303-47301			FLOOR PANEL RR/LH	1	102.00	25.00	76.50	Replace	Replace	No
58302-47030			FLOOR PANEL RR/RH	1	209.90	25.00	157.42	Replace	Replace	No
58336-42090			REINFORCEMENT, RR	2	34.60	25.00	51.90	Replace	Replace	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
61605-47010			PANEL SUB-ASSY, QTR	1	326.70	25.00	245.02	Replace	Replace ?	No
62940-16060			DUCT ASSY, QUARTER	1	70.40	25.00	52.80	Replace	Replace ✓	No Deform
61604-47090			FENDER RR/RH	1	766.80	25.00	575.10	Replace	Replace ✓	No Deform
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace ✓	No NEC
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓	No NEC
62710-47130			QUARTER GLASS RR/RH	1	846.50	25.00	634.87	Replace	Replace ✓	No NEC
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace ✓	No NEC
61621-47030			TROUGH, BACK DOOR	1	110.90	25.00	83.17	Replace	Replace ?	No
81551-47180		6505462	TAIL LAMP RH	1	557.80	10.00	502.02	Replace	Replace ?	No
52562-47010			TAIL LAMP BRACKET, RH	1	30.70	25.00	23.02	Replace	Replace ?	No
		6503707	TYRE	1	126.74	0.00	126.74	Replace	Replace X	No
67003-47080		6505486	DOOR RR/RH	1	954.50	25.00	715.87	Replace	Replace R	No
58327-47020			EXHAUST HEAT SHIELD, REAR	1	107.40	25.00	80.55	Replace	Replace ?	No
17430-37380			EXHAUST TAIL PIPE	1	656.20	25.00	492.15	Replace	Replace ?	No
17565-22030			SUPPORT, EXHAUST REAR	2	33.60	25.00	50.40	Replace	Replace ?	No
69060-47080			DOOR LOCK RR/LH	1	709.30	25.00	531.97	Replace	Replace ?	No
69050-47080			DOOR LOCK RR/RH	1	709.30	25.00	531.97	Replace	Replace ?	No
TOTAL MATERIALS								24,286.14	24,285.84	
TOTAL MATERIALS(Discounted)								19,428.66	19,428.66	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Thatcham escribe

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17023063/Stbe2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 16-01-2018
189556



Code: INC4

1. Policy Particulars : THIRD PARTY CLAIM

Insured Veh.	SJU 1405E	Veh. Inspected	SHC 4561K
Policy No.	5095464542	Coverage (\$)	0.00
Claim No.	MT/0972413-003	Excess (\$)	0.00
Assign From		Assign Date	04/12/2017

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U405748677	Colour	MAROON
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	01/12/2017	Inspection Date	04/12/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	16 Working Days
-------------------------------------	-----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4561K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER FRT (DISC 25%)	TORN	482.00	361.50
10	BUMPER CLIPS (DISC 25%)	NECESSARY	21.00	15.75
1	BUMPER ENERGY ABSORBER FRT (DISC 25%)	CRACKED	78.80	59.10
1	BRACKET, FR BUMPER (DISC 25%)	CRACKED	110.40	82.80
1	COVER, FR BUMPER HOLE LH (DISC 25%)	MISSING	18.50	13.87
1	COVER, FR BUMPER HOLE RH (DISC 25%)	MISSING	18.50	13.87
1	BUMPER GRILLE SUB-ASSY, LOWER (DISC 25%)	CRACKED	311.10	233.33
1	EMBLEM FRONT (DISC 25%)	NECESSARY	86.50	64.87
1	GRILLE RADIATOR LOWER NO. 2 (DISC 25%)	CRACKED	94.60	70.95
1	BUMPER FRT ABSORBER LOWER (DISC 25%)	DEFORMED	127.70	95.78
1	UNDER COVER CENTER (DISC 25%)	CRACKED	448.30	336.23
1	HOOD HINGE LH (DISC 25%)	BENT	55.90	41.93
1	HOOD HINGE RH (DISC 25%)	BENT	55.90	41.93
1	HEAD LAMP LH (DISC 25%)	CRACKED	945.20	850.68
1	FENDER LINER FRT/LH (DISC 25%)	TORN	171.70	128.77
1	FENDER RR/LH (DISC 25%)	DENTED	766.80	575.10
1	QUARTER GLASS RR/LH (DISC 25%)	NECESSARY	168.10	126.07
1	FENDER LINER RR/LH (DISC 25%)	TORN	141.30	105.97
1	TAIL LAMP BRACKET, LH (DISC 25%)	DEFORMED	30.70	23.02
1	DUCT ASSY, QUARTER (DISC 25%)	DEFORMED	70.40	52.80
1	TAILGATE ASY (DISC 25%)	DENTED	1,007.90	755.92
1	TAIL GATE DOOR GLASS MOULDING, LH (DISC 25%)	NECESSARY	29.40	22.05
1	TAIL GATE DOOR GLASS MOULDING, RH (DISC 25%)	NECESSARY	29.40	22.05
1	MOULDING BACK WINDOW, LOWER NO. 1 (DISC 25%)	NECESSARY	29.40	22.05
1	TAILGATE DOOR LOCK (DISC 25%)	DAMAGED	444.10	333.07
1	TAILGATE LOCK, COVER (DISC 25%)	NECESSARY	15.70	11.77
1	STRIKER, BACK DOOR (DISC 25%)	BENT	48.90	36.67
1	TAILGATE DOOR WEATHER STRIP (DISC 25%)	NECESSARY	353.40	265.05
1	TAILGATE, BOARD ASSY (DISC 25%)	DEFORMED	246.90	185.18
1	EMBLEM REAR (DISC 25%)	NECESSARY	60.30	45.22

Report Ref No. NS/INC17023063/Stbe2

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.92
1	NAME PLATE (PRIUS) (DISC 25%)	NECESSARY	60.80	45.60
1	NAME PLATE (TOYOTA) (DISC 25%)	NECESSARY	51.90	38.92
1	BUMPER REAR (DISC 25%)	CRACKED	458.60	343.95
1	BUMPER REINFORCEMENT REAR (DISC 25%)	BENT	205.70	154.27
1	ARM SUB-ASSY, RR BUMPER LH (DISC 25%)	BENT	139.60	104.70
1	ARM SUB-ASSY, RR BUMPER RH (DISC 25%)	BENT	139.60	104.70
1	BUMPER SIDE RETAINER RR/LH (DISC 25%)	CRACKED	94.80	71.10
1	BUMPER SIDE RETAINER RR/RH (DISC 25%)	CRACKED	94.80	71.10
1	BUMPER SEAL, RR LH (DISC 25%)	CRACKED	88.90	66.68
1	BUMPER LIP COVER RR/LH (DISC 25%)	DEFORMED	72.20	54.15
1	BUMPER LIP COVER RR/RH (DISC 25%)	DEFORMED	118.10	88.57
1	BUMPER LIP REAR (DISC 25%)	DEFORMED	228.90	171.67
1	UNDER COVER SUB-ASSY, RR FLOOR (DISC 25%)	DENTED	514.50	385.87
1	END PANEL (DISC 25%)	DENTED	602.10	451.57
1	END PANEL COVER, DECK TRIM HOLE (DISC 25%)	DEFORMED	46.10	34.58
1	END PANEL COVER, DECK TRIM, RR (DISC 25%)	DEFORMED	121.10	90.83
1	BOX, DECK FLOOR, RR (DISC 25%)	DEFORMED	649.70	487.28
1	BOX, DECK FLOOR, LH (DISC 25%)	DEFORMED	196.80	147.60
1	PANEL ASSE, DECK LH (DISC 25%)	DEFORMED	307.00	230.25
1	PANEL ASSY, DECK RH (DISC 25%)	DEFORMED	307.00	230.25
1	SPARE TYRE PANEL (DISC 25%)	DEFORMED	667.70	500.78
1	PROTECTOR, SPARE (DISC 25%)	DEFORMED	143.70	107.78
1	MEMBER SUB-ASSY, RR LH (DISC 25%)	BENT	174.10	130.58
1	MEMBER SUB-ASSY, RR RH (DISC 25%)	BENT	174.10	130.58
1	FLOOR PANEL RR/LH (DISC 25%)	DEFORMED	102.00	76.50
1	DUCT ASSY, QUARTER (DISC 25%)	DEFORMED	70.40	52.80
1	FENDER RR/RH (DISC 25%)	DEFORMED	766.80	575.10
1	QUARTER GLASS RR/RH (DISC 25%)	NECESSARY	846.50	634.87
1	BUMPER LIP FRT (DISC 25%)	CRACKED	139.60	104.70
3	INSULATOR SHEET @\$170.00 (DISC 25%)	CRACKED	510.00	382.50
1	GRIP, SERVICE PLUG (DISC 25%)	CRACKED	52.00	39.00
1	TAIL LAMP LH (DISC 10%)	CRACKED	548.40	493.56

Report Ref No. NS/INC17023063/Stbe2

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ANTENNA, ELECTRICAL LOWER REAR (DISC 10%)	DAMAGED	157.40	141.66
1	BATTERY ASSY, HV (DISC 10%)	CRACKED	5,544.40	4,989.96
1	NUMBER PLATE (SN)	DENTED	15.00	15.00
1	NUMBER PLATE FRAME (SN)	CRACKED	12.00	12.00
1	STICKER DECAL SMRT (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	SEALANT W/SCREEN (SN)	NECESSARY	37.00	37.00
1	TYRE (SN)	PUNCTURE	126.74	126.74
3	SEALANT W/SCREEN @\$37.00 (SN)	NECESSARY	111.00	111.00
1	NUMBER PLATE FRAME (SN)	CUT	12.00	12.00
1	STICKER DECAL SMRT (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
1	SEALANT SILAFLEX (SN)	NECESSARY	37.00	37.00
1	STICKER DECAL SMRT (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	SEALANT W/SCREEN (SN)	NECESSARY	37.00	37.00
1	BUMPER SUPPORT F/LH	NOT NECESSARY	76.40	-
1	BUMPER SUPPORT F/RH	NOT NECESSARY	76.40	-
1	BUMPER REINFORCEMENT FRT	NOT NECESSARY	498.40	-
1	ARM SUB-ASSY, FR BUMPER LH	NOT NECESSARY	250.40	-
1	ARM SUB-ASSY, FR BUMPER RH	NOT NECESSARY	250.40	-
1	LENS & BODY, FR TURN LH	NOT NECESSARY	511.80	-
1	LENS & BODY, FR TURN RH	NOT NECESSARY	511.80	-
1	GRILLE, RADIATOR	NOT NECESSARY	310.60	-
1	HOOD LOCK	NOT NECESSARY	128.90	-
1	SUPPORT SUB-ASSY	NOT NECESSARY	1,460.40	-
1	FENDER FRT/ LH	NOT NECESSARY	723.40	-
1	NAME PLATE (HYBRID)	NOT NECESSARY	51.90	-
1	FENDER LINER PAD, FR WHEEL LH	NOT NECESSARY	49.30	-
1	REINFORCEMENT, BACK DOOR SIDE LH	NOT NECESSARY	89.50	-
1	EXTENSION, QUARTER PANEL FRONT LH	NOT NECESSARY	83.50	-

Report Ref No. NS/INC17023063/Stbe2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXTENSION, QUARTER PANEL REAR LH	NOT NECESSARY	108.50	-
1	REINFORCEMENT, ROOF SIDE INNER LH	NOT NECESSARY	60.30	-
1	PANEL SUB-ASSY, QTR WHEEL HOUSE	NOT NECESSARY	588.40	-
1	PANEL, QUARTER WHEEL HOUSE, OUTER LH	NOT NECESSARY	326.70	-
1	LID ASSY, FUEL	NOT NECESSARY	102.00	-
1	TUBE, FUEL TANK	NOT NECESSARY	36.10	-
1	CABLE SUB-ASSY, FUEL LID	NOT NECESSARY	63.90	-
1	RETAINER, FUEL LID CABLE	NOT NECESSARY	5.90	-
1	PIPE SUB-ASSY, FUEL NECK	NOT NECESSARY	230.80	-
1	PIPE, FUEL DELIVERY	NOT NECESSARY	186.10	-
1	TAILGATE TRIM, LH	NOT NECESSARY	85.90	-
1	TAILGATE TRIM, RH	NOT NECESSARY	88.30	-
1	TAILGATE TRIM, LOWER	NOT NECESSARY	180.70	-
1	TAILGATE TRIM, UPPER	NOT NECESSARY	49.60	-
1	NUMBER PLATE	NOT NECESSARY	30.00	-
1	BUMPER SEAL, RR RH	NOT NECESSARY	65.70	-
1	BOX, RR FLOOR, BOARD	NOT NECESSARY	679.60	-
1	BOX, DECK FLOOR, COVER LH	NOT NECESSARY	230.10	-
1	CUSHION, SPARE WHEEL	NOT NECESSARY	230.80	-
1	CARRIER, SPARE	NOT NECESSARY	19.70	-
1	FLOOR PANEL RR/RH	NOT NECESSARY	209.90	-
2	REINFORCEMENT, RR @\$34.60	NOT NECESSARY	69.20	-
1	PANEL SUB-ASSY, QTR	NOT NECESSARY	326.70	-
1	TROUGH, BACK DOOR	NOT NECESSARY	110.90	-
1	TAIL LAMP RH	NOT NECESSARY	557.80	-
1	TAIL LAMP BRACKET, RH	NOT NECESSARY	30.70	-
1	TYRE	NOT NECESSARY	126.74	-
1	EXHAUST HEAT SHIELD, REAR	NOT NECESSARY	107.40	-
1	EXHAUST TAIL PIPE	NOT NECESSARY	656.20	-
2	SUPPORT, EXHAUST REAR @\$33.60	NOT NECESSARY	67.20	-
1	DOOR LOCK RR/LH	NOT NECESSARY	709.30	-
1	DOOR LOCK RR/RH	NOT NECESSARY	709.30	-
1	HOOD PANEL	TO REPAIR	748.10	-

Report Ref No. NS/INC17023063/Stbe2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR RR/LH	TO REPAIR	954.50	-
1	RAIL , ROOF SIDE LH	TO REPAIR	273.60	-
1	PANEL, ROOF SIDE OUTER LH	TO REPAIR	134.80	-
1	PANEL, ROOF SIDE	TO REPAIR	134.80	-
1	PANEL, ROOF SIDE, INNER LH	TO REPAIR	134.80	-
1	REINFORCE, ROOF SIDE OUTER LH	TO REPAIR	91.90	-
1	TAILGATE OUTSIDE GARNISH	TO REPAIR	504.90	-
1	DOOR RR/RH	TO REPAIR	954.50	-
			37,747.38	17,542.22
	LABOUR			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		5,434.00	3,210.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		6,282.00	2,500.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			11,876.00	5,730.00
GRAND TOTAL			49,623.38	23,272.22

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			18,600.00
---	--	--	------------------

Report Ref No. NS/INC17023063/Stbe2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.