

REF: NB/INC17023064/Sgbe2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SJJ 3624JPolicy No. 5093027110 04092017Claims No. M4/0973779-01

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SH B 4635Yr Regn: 13/10/2014Type: M.Car / M.Cycle / Bus / Van / Lorry / (X) Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Priusc.c. 1798Colour: Maroon

A/C: Insured / Std / NI / NA

Sp. Reading: No Display

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKN36U 705752252Gen. Cond: Good / (X) Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: 1.8 / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: h

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fallen

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 1/12/2017D.O.I. 4/12/2017Survey held at SMART

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

SJB 1163 - NB/INC17023064/Sgbe2

YR 13317 TAX/12/17/2002

SJJ 3624J - X

Lick

NTUC

18/1/18 US \$ 950 (Red \$ 7314.72, 89%)
Re-Insured US \$ 1050, 2 days (Red \$ 7314.72, 89%)

RECEIVED

RECEIVED

Date/Time, File Pass to?

☐

Prel. Report

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2Resurvey No. of Trip: 1Survey Fee: 160

Transportation:

Report Format: TPLump Sum / I.B.A. (\$) 1050

Add Fee:

☐

Site Insp (\$

) S + RS. SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

TOTAL

105



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17023064/Sqb				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 05-12-2017	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJJ 3624J	Veh. Inspected	SHB 463S	
Policy No.	5093027210	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	04/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/12/2017	Inspection Date	04/12/2017	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Survey Department Check List (Case Handler)

Reference No.: NS/INC/7023064/Sab
Policy Type: OD (TP) / TP RES / TL / EVA

SHB 4635

Case Handler

Typist

Admin (Cathy): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Sebastian): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			
✓			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

✓			
---	--	--	--

Check By:

Cathy 11/12/17

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014

TP Claims against NTUC Income: Follow-Through Survey

Date : 12/12/2017

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate
1	MT/0973279-001	SMRT TAXI PTE LTD	SHB 463S	SJ3624J	1/12/2017	23:15	\$ 8,264.22
2	MT/0971757-002	SMRT TAXI PTE LTD	SHB 5563D	SJC 8130X	27/11/2017	22:15	\$ 2,539.53
3	MT/0972130-002	COMFORT TRANSPORTATION PTE LTD	SH 8264K	SKG 779U	3/12/2017	16:10	\$ 1,436.18
4	MT/0972199-002	COMFORT TRANSPORTATION PTE LTD	SH 8500D	SH88931E	3/12/2017	17:20	\$ 3,338.00

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident

Vehicle No. (For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5093027210	SLEEK RIDE LLP	T17LL1138K	GFT	drive CLASSIC	SJ33624J	SJ33624J	04/09/2017	

Shiau Chan (LKKAuto)

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>
Sent: Thursday, 18 January 2018 2:59 PM
To: Sebastian Yeang (LKK Auto)
Cc: Shiau Chan (LKKAuto)
Subject: RE: Finalization SHB463S

Hi Sebastian and Shiau Chan,

The repair cost confirm at \$1050/- (2 days) as per your recommendation.

Regards
Poh Suan

From: Sebastian Yeang (LKK Auto) [mailto:SebastianYeang@lkkauto.com]
Sent: 09 January 2018 10:16
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Cc: Shiau Chan (LKKAuto)
Subject: Finalization SHB463S

Dear Poh Suan

Please refer to updated attachment for the finalization.

Dear Shiau Chan

Please proceed to edit the report upon Poh Suan's confirmation.

Thank You

Best Regards,

Sebastian | Automotive Assessor

LKK Auto Consultants

phone: 6256-3561 email: sebastianyeang@lkkauto.com fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	5369K

Vehicle Details

Vehicle No.	SHB463S
Vehicle to be Exported	No
Intended De-registration Date	05 Dec 2017
Vehicle Make	TOYOTA
Vehicle Model	PRIUS TAXI (SMRT)
Primary Colour	Maroon
Manufacturing Year	2014
Engine No.	2ZR6202076
Chassis No.	JTDKN36U305752252
Maximum Power Output	100.0 kW (134 bhp)
Open Market Value	\$32,920.00
Original Registration Date	13 Oct 2014
First Registration Date	13 Oct 2014
Transfer Count	0
Actual ARF Paid	\$8,088.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	12 Oct 2022
PARF Rebate Amount	\$6,066.00

Intended COE Rebate Details

COE Expiry Date	12 Oct 2022
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	8
PQP Paid	\$50,938.00
COE Rebate Amount	\$30,894.00
Total Rebate Amount	\$36,960.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 05 Dec 2017

OK



Please read through the Privacy Statement, Terms of Use, and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 19 Nov 2017 at 12:12 AM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/12/2017 10:34
Date Of Accident	01/12/2017 23:15
Exact Location Of Accident	SEMBAWANG ROAD (LP268)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB463S
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

Driver

Name of Driver	ONG HONG FATT
NRIC No	S1469194D
Date Of Birth	03/09/1961
Occupation	OUTDOOR
Date Of Driving Pass	27/09/1988
Driving Experience	29 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - RELIEF
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name WOODLANDS EAST N.P.C
 Police Station Address ROAD: 3 WOODLANDS DRIVE 63 , POSTCODE: 737890 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT - T/20171202/2007 On 1/12/2017 at around 2317hrs, I was driving my taxi bearing vehicle plate number SHB463S driving on Sembawang Road towards Canberra Road. I was driving on the centre lane. Upon seeing a passenger flagging a taxi in front, I switched to the left lane and stopped my vehicle at lamp post 268. When the passenger opened the door of my taxi, I heard a loud bang. A silver Suzuki Swift bearing plate number SJJ3624J had hit my car in the process of switching from the left lane to the center lane. The driver did not stop his car so I chased after him and he finally stopped his car at the first bus stop at Canberra Road beside Blk 311. He apologized to me and we exchanged particulars. The right rear of my car had slight scratches and the cover of my right mirror was detached from the mirror as a result of the collision. The Suzuki Swift suffered slight scratches on its left side near its front and rear tyres. Nobody was injured in the accident.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJJ3624J
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver MUHAMMAD NOOR HARIS BIN RAMLAN
 NRIC/Passport Number S9820956E
 Contact Number
 Address
 Postcode
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness


Name

Phone Number

Email Address

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20171202/2007

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

1 of 3

Report No. T/20171202/2007

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 02/12/2017 01:12	Vide Report No.:	Station Diary No.: 13
--	------------------	--------------------------

Informant's Particulars			
Name of Informant: ONG HONG FATT		Address: APT BLK 786D WOODLANDS DRIVE 60 #13-43 SINGAPORE 734786	
ID Type / ID No.: NRIC NO / S1469194D		Contact No.: Home/Office: Mobile: 91130961	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 56	Date of Birth: 03/09/1961	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 3,4 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 01/12/2017 23:15	Type of Location: Straight Road
Location: Along Road 1 SEMBAWANG ROAD				
Lamp Post Number: 268				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working	Traffic Volume: Light	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHB463S	Car				Slightly Damaged	0
SJJ3624J	Car				Slightly Damaged	3

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20171202/2007

2 of 3

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

Report No. T/20171202/2007

CONTINUATION OF REPORT

Driver			
Name	ONG HONG FATT		ID No. S1469194D
Related Vehicle	NIL		Contact No. 91130961
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	MUHAMMAD NOOR HARIS BIN RAMLAN		ID No. S9820956E
Related Vehicle	NIL		Contact No. 93282005
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 1/12/2017 at around 2317 hrs, I was driving my taxi bearing vehicle plate number SHB463S driving on Sembawang Road towards Canberra Road. I was driving on the centre lane. Upon seeing a passenger flagging a taxi in front, I switched to the left lane and stopped my vehicle at lamp post 268. When the passenger opened the door of my taxi, I heard a loud bang. A silver Suzuki Swift bearing plate number SJJ3624J had hit my car in the process of switching from the left lane to the center lane.

The driver did not stop his car so I chased after him and he finally stopped his car at the first bus stop at Canberra Road beside Blk 311. He apologized to me and we exchanged particulars.

The right rear of my car had slight scratches and the cover of my right mirror was detached from the mirror as a result of the collision. The Suzuki Swift suffered slight scratches on its left side near its front and rear tyres.

Nobody was injured in the accident.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999



T/20171202/2007

3 of 3

Report No. T/20171202/2007

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report. J / ASP SHERMEEN ONG	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 02/12/2017 01:12
Officer In Charge Of Case: TP / GIA / Staff Sgt TANG SIEW PING Contact No.: 65476430	Classification Of Case:
Authentication Stamp NP168	

Signature :

SN 130


Singapore Police Force

SMRT Accident Vehicle Repair Estimates

NTUC

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB463S
 Ref. No : TAX/12/17/2002
 Reg. Date : 13/10/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : ONG HONG FATT
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 01/12/2017 11:15:00 PM
 Accident Reported Date / Time : 02/12/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024093402
 Special Instruction to ARC, if any :
 DROVE IN /SJJ3624J - NTUC IDAC
 Prepared Date : 02/12/2017 10:28:47 AM




Sebastian
 4/12/2017
 - Lug Nut Repair
 - Question Mark Item
 Photo
 - Photo After Paint

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


 5/12/17

Chassis No : JTDKN36U305752252

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	0.00
Total Spray Painting Charges	: 1,494.00	0.00
Total Material Charges	: 2,535.98	2,996.06
Other Charges	: 996.88	0.00
TOTAL	: 5,871.86	0.00
Lum Sum Total	: 5,850.00	0.00
No. of Repair Days	: 5.00	0.00
Prepared / Adjusted By	:	2 days
Arc / Surveyor Sign Off Date	: 04/12/2017 09:26:08 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 04/12/2017 09:25:00 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	845.00	0.00 300
Total Labour	845.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 X
TO RESPRAY VIEW MIRROR	180.00	0.00 X
TO RESPRAY REAR FENDER RH	378.00	0.00 200
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY RIM	180.00	0.00 50
Total Spray Painting & Panel Beating	1,494.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 X
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 60
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	0.00 ✓
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 X
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	996.88	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace X	No NC
87910-47330		6505600	MIRROR ASSY, RH	1	1,307.10	25.00	980.32	Replace	Replace X	No NC
81730-52090		6505466	MIRROR LAMP RH	1	65.30	10.00	58.77	Replace	Replace X	No NC
879157-4010		6505598	COVER, OUTER MIRROR, RH	1	107.40	25.00	80.55	Replace	Replace X	No NC
61604-47090			FENDER RR/RH	1	766.80	25.00	575.10	Repair	Replace R	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace /	No NC
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace /	No NC
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace R	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace ?	No
		6503707	TYRE	1	126.74	0.00	126.74	Replace	Replace X	No
42611-47140		6505658	WHEEL, DISC	1	1,490.20	25.00	1,117.65	Replace	Replace R	No
TOTAL MATERIALS								3,169.99	3,745.08	
TOTAL MATERIALS(Discounted)								2,535.98	2,996.06	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									



6.12.17/12.04 ADV


6.12.17/16.04

4.12.17/16.04


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB463S
Ref. No : TAX/12/17/2002
Reg. Date : 13/10/2014
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : ONG HONG FATT
Type of Accident : HEAD TO REAR
Date / Time of Accident : 01/12/2017 11:15:00 PM
Accident Reported Date / Time : 02/12/2017 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Sebastian
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024093402
Special Instruction to ARC, if any :
DROVE IN /SJJ3624J - NTUC IDAC
AFTER PAINT PHOTO, LUMP SUM REPAIR, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
SURVEYOR SEBASTIAN (LKK) & Email :sebastianyeang @lkkauto.com HP:90036121
Prepared Date : 02/12/2017 10:28:47 AM



400328-KM



[Large handwritten signature]

LEE SHENG AUTO PTE LTD

Vehicle Return Date: 5/12/17

Vehicle Return Time: 16.30 P.M



SMRT staff sign: _____

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U305752252 Mileage : 0

Work Shop, : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	300.00
Total Spray Painting Charges	: 1,494.00	450.00
Total Material Charges	: 64.32	29.40
Other Charges	: 996.88	170.60
TOTAL	: 3,400.20	950.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 5.00	2.00 /
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sing Off Date	: 04/12/2017 09:26:03 AM	04/12/2017 04:04:09 AM
		

Prepared / Adjusted Date :

Remarks :

Prepared Date : 04/12/2017 09:25:00 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1712-0219 Invoice No :
Quotation Date : 8/12 Invoice Date :
Invoice Amount : Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O REPAIR RH PORTION	845.00	300.00 /
Total Labour	845.00	300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O REPSRAY FRONT BUMPER	378.00	0.00
O RESPRAY VIEW MIRROR	180.00	0.00
O RESPRAY REAR FENDER RH	378.00	200.00 /
O REPSRAY REAR BUMPER	378.00	200.00 /
O RESPRAY RIM	180.00	50.00 /
Total Spray Painting & Panel Beating	1,494.00	450.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
O APPLY RUST-PROOFING ON AFFECTED REA	100.00	0.00
O DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60.00 /
O PROVIDE LABOUR & MATERIAL FOR OVERTISEMENT STICKER(NET)	296.88	296.88 /
O TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00
O REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30.00 /
O REPLACE SUNDRY PARTS	100.00	0.00
O WASH AND VACUUM	60.00	0.00
Imp Sum Adjustment by Surveyor	0.00	-216.28
Total Other Costs	996.88	170.60

2264 22

art 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
2119-7930		6505517	BUMPER FRT	0	482.00	25.00	0.00	Replace	Not given	No X
7910-7330		6505600	MIRROR ASSY, RH	0	1,307.10	25.00	0.00	Replace	Not given	No X
1730-2090		6505466	MIRROR LAMP RH	0	65.30	10.00	0.00	Replace	Not given	No X
79157-110		6505598	COVER, OUTER MIRROR, RH	0	107.40	25.00	0.00	Replace	Not given	No X
1604-7090			FENDER RR/RH	1	766.80	100.00	0.00	Repair	Repair	No R
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No
	COMMON		STICKER DECAL 65558888	1	21.60	0.00	21.60	Replace	Replace	No
2159-7905		6505548	BUMPER REAR	1	458.60	100.00	0.00	Replace	Repair	No R
2575-7020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Check	No X
		6503707	TYRE	0	126.74	0.00	0.00	Replace	Not given	No X
2611-7140		6505658	WHEEL, DISC	1	1,490.20	100.00	0.00	Replace	Repair	No R
TOTAL MATERIALS							100.50	29.40		
TOTAL MATERIALS(Discounted)							64.32	29.40		

dded Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

29.40 /
+ 300.00 /
+ 836.88 /

1166.28 /
- 207

933.02 /
US \$950 / 7

8264.22

Sebastian
11/12/2017

8264.22

6.12.17/12.04 - ADV


6.12.17/16.04

SMRT Accident Vehicle Repair Estimates

4.12.17/16.04

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB463S
Ref. No : TAX/12/17/2002
Reg. Date : 13/10/2014
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : ONG HONG FATT
Type of Accident : HEAD TO REAR
Date / Time of Accident : 01/12/2017 11:15:00 PM
Accident Reported Date / Time : 02/12/2017 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Sebastian
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024093402
Special Instruction to ARC, if any :



DROVE IN /SJJ3624J - NTUC IDAC
AFTER PAINT PHOTO, LUMP SUM REPAIR FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
SURVEYOR SEBASTIAN (LKK) & Email : sebastianeang @lkkauto.com HP: 90036121
Prepared Date : 02/12/2017 10:28:47 AM

400328-KM

1/4 1/2 3/4 → F



LEE SHENG AUTO PTE LTD

Vehicle Return Date: 5/12/17

Vehicle Return Time: 16.30 P.M

SMRT staff sign:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U305752252

Mileage


0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	845.00	300.00
Total Spray Painting Charges	1,494.00	450.00
Total Material Charges	64.32	29.40
Other Charges	996.88	170.60
TOTAL	3,400.20	950.00
Lum Sum Total	0.00	0.00
No. of Repair Days	5.00	2.00 /
Prepared / Adjusted By		SEBASTIAN (LKK)
Appr / Surveyor Sign Off Date	04/12/2017 09:26:08 AM	04/12/2017 04:04:09 AM



Prepared / Adjusted Date

Remarks

Prepared Date : 04/12/2017 09:26:00 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1712-0219
Quotation Date : 8/12
Invoice Amount :

Invoice No :
Invoice Date :
Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	845.00	300.00 /
Total Labour	845.00	300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00
TO RESPRAY VIEW MIRROR	180.00 S	0.00 50
TO RESPRAY REAR FENDER RH	378.00	200.00 /
TO REPSRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY RIM	180.00	50.00 /
Total Spray Painting & Panel Beating	1,494.00	450.00 500

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60.00 /
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88 /
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30.00 /
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	80.00	0.00
ump Sum Adjustment by Surveyor	0.00	-216.28
Total Other Costs	996.88	170.60 386.88

8264.22

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
2119-7930		6505517	BUMPER FRT	0	482.00	25.00	0.00	Replace	Not given	No X
7910-7330		6505600	MIRROR ASSY, RH	0	1,397.10	25.00	0.00	Replace	Not given	No X
1730-2090		6505466	MIRROR LAMP RH	0	65.30	10.00	0.00	Replace	Not given	No X
79157-010		6505598	COVER, OUTER MIRROR, RH S	0	107.40	25.00	0.00 80.55	Replace	Not given MS	No X
1804-7090			FENDER RR/RH	1	766.80	100.00	0.00	Repair	Repair	No R
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No
2159-7905		6505548	BUMPER REAR	1	458.60	100.00	0.00	Replace	Repair	No R
2575-7020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Check	No X
		6503707	TYRE	0	126.74	0.00	0.00	Replace	Not given	No X
2611-7140		6505858	WHEEL DISC	1	1,490.20	100.00	0.00	Replace	Repair	No R
TOTAL MATERIALS							100.50	29.40		
TOTAL MATERIALS(Discounted)							64.32	29.40		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LI Check
TOTAL SUPPLEMENTARY MATERIALS									

$$\begin{array}{r}
 109.95 \\
 + 300.00 \\
 + 886.88 \\
 \hline
 1296.83 \\
 - 20\% \\
 \hline
 1037.46
 \end{array}$$

L/S : \$ 1050

$$\begin{array}{r}
 29.40 / \\
 + 300.00 / \\
 + 836.88 / \\
 \hline
 1166.28 /
 \end{array}$$

$$\begin{array}{r}
 - 20\% \\
 \hline
 933.02 /
 \end{array}$$

L/S \$950/7

Sebastian
11/11/2017

REQUEST FOR SUPPLEMENT PARTS

Contractor:		Date of Collection	/ /
Accident Case Number	TAX/12/12/2002	Date of Request	04/10/2018
Vehicle No	SHB 463.S	Number of Days to Extend (if any)	/
Vehicle Model	TOWIN PRUS		

107-90
80-55

S/N	Part Number	Part Description	Quantity	Unit Price
		COVER OUTER MIRROR RM	1	MISSING
		Lamin to SPRAY SIDE mirror cover, RM		\$ 100.50

✓ my

<<<Please submit photographs for damaged parts>>>

I, (Name)

(Position)

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / FO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

1030-55

**National Assessment Centre Services**


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Thatcham describe

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17023064/Sqbe2			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 18-01-2018	
		Code: INC4	
1. Policy Particulars : THIRD PARTY CLAIM			
Insured Veh.	SJJ 3624J	Veh. Inspected	SHB 463S
Policy No.	5093027210	Coverage (\$)	0.00
Claim No.	MT/0973279-001	Excess (\$)	0.00
Assign From		Assign Date	04/12/2017
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U305752252	Colour	MAROON
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	01/12/2017	Inspection Date	04/12/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 463S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	BUMPER FRT	NOT NECESSARY	482.00	-
1	MIRROR ASSY, RH	NOT NECESSARY	1,307.10	-
1	MIRROR LAMP RH	NOT NECESSARY	65.30	-
1	BUMPER SIDE RETAINER RR/RH	NOT NECESSARY	94.80	-
1	TYRE	NOT NECESSARY	126.74	-
1	FENDER RR/RH	TO REPAIR	766.80	-
1	BUMPER REAR	TO REPAIR	458.60	-
1	WHEEL, DISC	TO REPAIR	1,490.20	-
1	COVER, OUTER MIRROR, RH (DISC 25%)	MISSING	107.40	80.55
			4,928.34	109.95
	<u>LABOUR</u>			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		1,581.88	686.88
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		1,594.00	500.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.		60.00	-
			3,335.88	1,186.88
GRAND TOTAL			8,264.22	1,296.83
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,050.00

Report Ref No. NS/INC17023064/Sqbe2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)**BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE****REGD Auto Consultant-SAE, Licensed Appraiser****DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.