

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHC 8133L

DATE 1/12/2017 14:23

MODEL : HYUNDAI i40

| Qty                                                                                                                                                                                                            | Parts Description/ Labour                               | Type | Unit Price | Amount                   |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------|------|------------|--------------------------|
|                                                                                                                                                                                                                | Boot Lid <del>x 142.2</del>                             |      |            | \$ 1,681.40              |
|                                                                                                                                                                                                                | Boot Lid Rubber <del>x</del>                            |      |            | \$ 115.80                |
|                                                                                                                                                                                                                | Boot Lid Lock Upper <del>x</del>                        |      |            | \$ 137.90                |
|                                                                                                                                                                                                                | Boot Lid Lock Lower <del>x</del>                        |      |            | \$ 31.70                 |
|                                                                                                                                                                                                                | Boot Lid 'H' Emblem <del>—</del>                        |      |            | \$ 27.20                 |
|                                                                                                                                                                                                                | Boot Lid CRDI Plate <del>—</del>                        |      |            | \$ 41.00                 |
|                                                                                                                                                                                                                | Boot Lid Trimboard <del>x</del>                         |      |            | \$ 172.70                |
|                                                                                                                                                                                                                | Boot Lid Trimboard Clips (11pcs) <del>x</del>           |      |            | \$ 11.00                 |
|                                                                                                                                                                                                                | Bootlid Moulding <del>—</del>                           |      |            | \$ 85.00                 |
|                                                                                                                                                                                                                | Bootlid i40 Emblem <del>—</del>                         |      |            | \$ 41.00                 |
|                                                                                                                                                                                                                | Bootlid Lower Garnish <del>—</del>                      |      |            | \$ 398.00                |
|                                                                                                                                                                                                                | Rear Bumper <del>—</del>                                |      |            | \$ 603.60                |
|                                                                                                                                                                                                                | Rear Bumper Reinforcement <del>?</del>                  |      |            | \$ 504.35                |
|                                                                                                                                                                                                                | Rear Bumper Reinforcement Bracket (LH/RH) <del>1</del>  |      | \$ 180.00  | \$ 360.00                |
|                                                                                                                                                                                                                | Rear Bumper Side Bracket <del>?</del>                   |      | \$ 49.00   | \$ 98.00                 |
|                                                                                                                                                                                                                | Rear Bumper Clips <del>—</del>                          |      |            | \$ 22.00                 |
|                                                                                                                                                                                                                | Rear Bumper Sponge <del>?</del>                         |      |            | \$ 143.40                |
|                                                                                                                                                                                                                | Rear Bumper Under Cover <del>—</del>                    |      |            | \$ 225.00                |
|                                                                                                                                                                                                                | Rear Bumper Reflector Lamp (LH/RH) <del>LH ✓ RH x</del> |      | \$ 32.00   | \$ 64.00                 |
|                                                                                                                                                                                                                | Rear Panel <del>x 142.2</del>                           |      |            | \$ 592.30                |
|                                                                                                                                                                                                                | Rear Panel Garnish <del>?</del>                         |      |            | \$ 57.70                 |
|                                                                                                                                                                                                                | Rear Panel Lower Panel <del>x 142.2</del>               |      |            | \$ 495.50                |
|                                                                                                                                                                                                                | Exhaust Pipe Insulator, RH <del>?</del>                 |      |            | \$ 58.55                 |
|                                                                                                                                                                                                                | Exhaust Silencer, RH <del>?</del>                       |      |            | \$ 954.00                |
|                                                                                                                                                                                                                | Exhaust Pipe Hanger, RH <del>?</del>                    |      |            | \$ 58.55                 |
|                                                                                                                                                                                                                | <b>SUB TOTAL</b>                                        |      |            | <b>\$ 6,979.65</b>       |
|                                                                                                                                                                                                                | <b>LESS 20%</b>                                         |      |            | <b>\$ 1,395.93</b>       |
|                                                                                                                                                                                                                | <b>DISCOUNTED TOTAL</b>                                 |      |            | <b>\$ 5,583.72</b>       |
|                                                                                                                                                                                                                | Boot Lid Comfort Logo & Tel No. Sticker <del>—</del>    |      |            | \$ 30.00 <b>Nett</b>     |
|                                                                                                                                                                                                                | Rear Bumper Reverse Sensor <del>—</del>                 |      |            | \$ 135.70 <b>Nett</b>    |
|                                                                                                                                                                                                                | Rear Bumper Rubber Mat <del>—</del>                     |      |            | \$ 50.00 <b>Nett</b>     |
|                                                                                                                                                                                                                | <b>Labour Charge</b>                                    |      |            | <b>\$ 215.70</b>         |
|                                                                                                                                                                                                                | Panel Beating                                           |      |            | <del>\$ 850.00</del> 600 |
|                                                                                                                                                                                                                | Spray Painting Charge                                   |      |            | <del>\$ 600.00</del> 540 |
|                                                                                                                                                                                                                | Wiring Charge                                           |      |            | <del>\$ 50.00</del> x    |
|                                                                                                                                                                                                                | Tuff Kote                                               |      |            | <del>\$ 50.00</del> x    |
|                                                                                                                                                                                                                | Remove/Refix Reverse Sensor                             |      |            | <del>\$ 120.00</del> 20  |
|                                                                                                                                                                                                                | Remove/Refix Exhaust Pipe                               |      |            | <del>\$ 150.00</del> x   |
|                                                                                                                                                                                                                | <b>TOTAL LABOUR</b>                                     |      |            | <b>\$ 1,820.00</b>       |
|                                                                                                                                                                                                                | <b>ESTIMATE TOTAL</b>                                   |      |            | <b>\$ 7,619.42</b>       |
| This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. |                                                         |      |            |                          |