

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD5776X - AXA**AAD1712-012***Not Authored
C/Sy 82800h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD5776X - CANDY

JTDGJ20WX05002935

TOYOTA

WISH 2.0 BI-FUEL

01.12.2017

AXA

		PART		LIST
1	1	Front door LH	\$	<i>R</i> 1,554.00 <i>X</i>
2	1	Rocker panel outer LH	\$	<i>Sn</i> 854.28 <i>X</i>
3	1	Side rocker panel garnish LH	\$	<i>Sn</i> 614.28 <i>X</i>
4	1	Rear door LH	\$	<i>R</i> 1,289.70 <i>✓</i>
5	1	Rear door weatherstrip LH	\$	<i>Sn</i> 193.68
6	1	Rear door top hinge LH	\$	<i>R</i> 91.68
7	1	Rear door bottom hinge LH	\$	<i>R</i> 91.68
8	1	Rear door inner lock LH	\$	<i>R</i> 511.92
9	1	Rear door outer moulding LH	\$	<i>Sn</i> 193.68
10	1	Rear door outer handle LH	\$	<i>R</i> 95.52 <i>X</i>
11	1	Rear door outer handle inner seal LH	\$	<i>Sn</i> 46.44
12	1	Rear door outer key lock LH	\$	<i>R</i> 260.04
13	1	Rear door inner lock latch LH	\$	<i>R</i> 117.84
14	1	Rear door check / arrestor LH	\$	<i>R</i> 156.00
15	1	Rear door weatherstrip LH	\$	<i>Sn</i> 189.36
16	1	Rear door regulator gear LH	\$	<i>R</i> 158.16
17	1	Rear fender LH	\$	<i>R</i> 1,216.32 <i>✓</i>
18	1	Tail lamp LH	\$	<i>C/M</i> 595.72 <i>✓</i>
19	1	Rear bumper	\$	<i>Bu</i> 585.36 <i>✓</i>
20	1	Rear bumper side retainer LH	\$	<i>Bu</i> 68.76 <i>✓</i>
21	1	Rear bumper reflectors LH	\$	<i>Sn</i> 66.00 <i>X</i>
TOTAL			\$	8,950.42
25%			\$	2,237.61
			\$	6,712.82

Special Nett

1	1Set	Front Bumper Fastener Clip	\$	<i>nn</i> 50.00 <i>X</i>
2	1 Set	Front fender Liner clip LH	\$	<i>nn</i> 30.00 <i>X</i>
3	1	Front bumper CNG Sticker	\$	<i>nn</i> 30.00 <i>155h</i>
4	1 Set	Rocker panel outer Garnish Clip LH	\$	<i>nn</i> 40.00 <i>X</i>

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD5776X - AXA**AAD1712-012**

5	1	Door Sticker "TRANS-CAB" LH	\$	nn 80.00 X
6	1	Door Sticker "6555-3333" LH	\$	nn 80.00 60sn
7	1	Front fender advertisement sticker LH	\$	nn 250.00 X
8	1	Rear door advertisement sticker LH	\$	nn 250.00 150sn

TOTAL	\$	810.00
TOTAL PARTS	\$	7,522.82

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 2,700.00 80d

To Rust-Proofing Of The Affected Areas.

\$ 170.00 60d

To Check Electrical Lighting Concerned.

\$ 120.00 20d

Putty And Spray Painting Of The Affected

\$ 2,800.00 60d

To Transfer Of Door Fittings, Attachments And
Perform Water Seepage Test.

\$ 170.00 60d

To remove and replace corporate sticker

\$ 330.00 30d

To Transfer Of Fender Fittings, Attachments And
Perform Water Seepage Test.

\$ 170.00 100d

	\$	6,460.00
TOTAL	\$	13,982.82

REPAIR DAYS**10 DAYS***60days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: